# The Dalles Dam Fishway Status Report

5/6/2017

Inspection Period: 04/30/2017-05/06/2017

## THE DALLES DAM



The Dalles Project-Fisheries P.O. Box 564 The Dalles, OR 97058-9998 Phone: 541-506-3800

				e daily plus one SCA						
The Dalles Dam	Inspections Out of Criteria	Criteria Limit	Total Numb	er of Inspections:	21	Temperat Secchi:		51.9 feet	°F	
	Out of Criteria	Liiiiii		FISHWAY		Seconi:	3.0	ieet		
Exit differential	0	≤ 0.5'	I	FISHWAI						
Count station differential	0	≤ 0.3'								
Weir crest depth	0	1.0' ± 0.1'								
Entrance differential	0	1.0' - 2.0'	1.4							
Entrance weir N1	0	depth (≥ 8')	10.8							
Entrance weir N2	0	Closed	10.0							
PUD Intake differential	0	≤ 0.5'								
			EAST	FISHWAY						
Exit differential	0	≤ 0.5'								
Removable weirs 154-157	1		Auto adjusts 1'	increments Work cle	aning circ	cuit boxes per	formed.			
Weir 158-159 differential	0	1.0' ± 0.1'	158 callibrated	and adjusted.	<u> </u>					
Count station differential	4	≤ 0.3'	Picket leads ra							
Weir crest depth	0	1.0' ± 0.1'								
Junction pool weir JP6	0	depth (≥ 7')	15.7							
East entrance differential	0	1.0' - 2.0'	1.4							
Entrance weir E1	0	No criteria	4.3	One fish unit operation to 5/2 - MFR provided to FPOM						
Entrance weir E2	9	depth (≥ 8')	9.9							
Entrance weir E3	1	depth (≥ 8')	10.2							
Collection channel velocity	0	1.5 - 4 fps	2.59							
Transportation channel velocity	0	1.5 - 4 fps	2.34							
North channel velocity	0	1.5 - 4 fps	2.23							
South channel velocity	0	1.5 - 4 fps	3.10							
West entrance differential	0	1.0' - 2.0'	1.6							
Entrance weir W1	0	depth (≥ 8')		W1 weir out of service	e. Bulkhe	ead installed.	W3 in se	rvice in to I	replace W1.	
Entrance weir W2	9	depth (≥ 8')	8.2							
Entrance weir W3	0	depth (>8')	1.0		<u> </u>					
South entrance differential	0	1.0' - 2.0'	1.5		<u> </u>					
Entrance weir S1	9	depth (≥ 8')			<u> </u>					
Entrance weir S2	0	depth (≥ 8')	9.6		<u> </u>					
				E PASSAGE						
Sluicegate operation	0	Units 1, 8, 18			<u> </u>					
Turbine trashrack drawdown	0	<1.5', wkly	range: 0.1-0.8		<u> </u>					
Spill volume/pattern	13					6 due to high	flows			
Turbine Unit Priority	14		MU 2, 3, 6, 9, 1	2, 15, 16, 21 out of s	service					
Turbine 1% Efficiency	0	per FPP								

#### **OTHER ISSUES:**

#### Birds/Sea lions:

Sea lions (C014, 1-31, and 1 with ID yet to be confirmed) observed daily near east and west entrance. USDA hazing attempted.

Gulls increasing downstream of spillway. USDA hazing by boat. Bird observation data collected once daily. Refer to Avian Zone map and bird count.

#### Operations:

North in full operation. East fishway in 1 fish unit operation until 5/2. Crowbar thyristor (control box) replaced.

Spillway open with involuntary spill.

### Current Outages;

F2 forced out for exciter problems. Reparied and returned 5/2.

MU2 out for hydraulic diagnosis. Return 6/1/17

MU12 out for hydraulic diagnosis. Return 6/23/17.

T8 (MU15 & MU16) out for transformer failure. Transformer replacement spring 2018.

MU21 out for exciter failure. Return 6/8/17

MU3 out for governor oil level. Return 5/14/17.

MU9 out for oil leak. Return 5/11/17.

MU11 out for annual maint. Return 5/11/17

MU19 out for annual maint. Return 5/18/17

#### Maintenance:

Weir W1 installed with new wheels and in service. W3 closed.

East exit weir electrical panel FCQ7 installation/design resuming design completion.

PUD crane rake repainting to start this month.

Rebuilding spare entrance weir gearbox.

Other repair maintenance plans; 154-157 rehab/weir wheel replace, diffuser valve overhaul (rehab and decommission).

Fish related /non-fish funded items; Spillway crane and spillgate 9, both awaiting funding.

All spillway items on Critical Infrastructure list.

#### Research/Construction/Contractors:

AWS contruction - all work complete for season 1.

Lamprey minor mods - Rounded entrance weir cap parts for all entrances on order. Tribal lamprey trap hoist design 90%. Fab FY17 and install FY18.


Railroad track removal - Remaining tailrace deck next winter. Intake deck rail removal at units 9-12.

Fish unit breaker replace.- Manufacture this summer. Install fall 2017. Switchover Jan 2018. Schedule approved through FPOM.

Fish unit rehab - Phase 1A report Jan 2018. Award 2020. Completion 2022. Possible increase flow capacity for redundancy. Data collection continues. Transformer replacement - Install start May 2018. Coordinated through FPOM.

Approved by: Ron Twiner

Operation Project Manager The Dalles Dam




								F	=foraging	, NF=non-f	foraging						
		Time	_	G	ull	Cormorant		Caspian tern			ebe	Pel	Pelican		her	Total	
ate	observer	(24 hr)	Zone	F	NF	F	NF	F	NF	F	NF	F	NF	F	NF	birds in zone	Notes
			FB	0	0	0	21	0	0	0	0	0	0	0	0	21	
			PH1	0	0	0	7	0	0	0	0	0	0	0	0	7	
			PH2	0	0	0	0	0	0	0	0	0	0	0	0	0	
30	JWR	AM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	11	0	0	0	0	0	0	0	0	0	0	0	11	
			SW4	44	0	0	0	0	0	0	0	0	0	0	0	44	
			FB	0	0	1	24	0	0	0	2	0	0	0	0	27	
			PH1	0	0	0	10	0	0	0	0	0	0	0	0	10	
			PH2	0	0	0	0	0	0	0	0	0	0	0	0	0	
1	JWR	РМ	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	3	22	0	0	0	0	0	0	0	0	0	0	25	
			SW4	32	0	0	0	0	0	0	0	0	0	0	0	32	
			FB	0	0	3	25	0	0	0	0	0	0	0	0	28	
			PH1	0	0	1	7	0	0	0	0	0	0	0	0	8	
			PH2	2	1	1	0	0	0	0	0	0	0	0	0	4	
5/2 GJF	GJF	AM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	1	0	0	0	0	0	0	0	0	0	1	
			SW3	5	0	0	0	0	0	0	0	0	0	0	0	5	
		SW4	29	0	0	0	0	0	0	0	0	0	0	0	29		
		FB	0	0	0	9	0	0	0	8	0	0	0	0	17		
			PH1	0	0	0	2	0	0	0	0	0	0	0	0	2	
			PH2	0	1	0	0	0	0	0	0	0	0	0	0	1	
3	GJF	РМ	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	4	0	0	0	0	0	0	0	0	0	0	0	4	
			SW4	16	0	0	0	0	0	0	0	0	0	0	0	16	
			FB	0	0	0	22	0	0	0	0	0	0	0	0	22	
			PH1	0	2	0	3	0	0	0	0	0	0	0	0	5	
			PH2	1	0	0	0	0	0	0	0	0	0	0	0	1	
4	GJF	AM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	2	0	0	0	0	0	0	0	0	0	0	0	2	
			SW3	6	0	0	0	0	0	0	0	0	0	0	0	6	
			SW4	57	0	0	0	0	0	0	0	0	0	0	0	57	
			FB	0	0	2	21	0	0	0	7	0	0	0	0	30	
			PH1	0	1	0	8	0	0	0	0	0	0	0	0	9	
			PH2	3	0	0	2	0	0	0	0	0	0	0	0	5	
5	GJF	PM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	0	0	0	0	0	0	0	1	0	0	1	
			SW3	7	0	0	2	0	0	0	0	0	0	0	0	9	
			SW4	101	0	0	0	0	0	0	0	0	0	0	0	101	
			FB	0	1	2	27	0	0	0	0	0	0	0	0	30	
			PH1	0	0	2	1	0	0	0	0	0	0	0	0	3	
			PH2	2	0	1	0	0	0	0	0	0	0	0	0	3	
6	GJF	AM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	1	0	1	0	0	0	0	0	0	0	0	0	2	
			SW3	11	0	0	0	0	0	0	0	0	0	0	0	11	
			SW4	110	0	0	0	0	0	0	0	0	0	0	0	110	


	The Dalles East											
Date	All Chinook	Adult Chinook	Jack Chinook	All Steelhead	Clipped Steelhead	Unclipped Steelhead	All Coho	Adult Coho	Jack Coho	Sockeye	Chum	Pink
4/30	104	102	2	1	0	1	0	0	0	0	0	0
5/1	86	84	2	2	1	1	0	0	0	0	0	0
5/2	89	85	4	0	0	0	0	0	0	0	0	0
5/3	249	245	4	3	2	1	0	0	0	0	0	0
5/4	356	349	7	0	0	0	0	0	0	0	0	0
5/5	328	318	10	2	2	0	0	0	0	0	0	0
5/6	1062	1001	61	2	1	1	0	0	0	0	0	0
total	2274	2184	90	10	6	4	0	0	0	0	0	0


# The Dalles North

Date	All Chinook	Adult Chinook	Jack Chinook	All Steelhead	Clipped Steelhead	Unclipped Steelhead	All Coho	Adult Coho	Jack Coho	Sockeye	Chum	Pink
4/30	0	0	0	0	0	0	0	0	0	0	0	0
5/1	0	0	0	0	0	0	0	0	0	0	0	0
5/2	0	0	0	0	0	0	0	0	0	0	0	0
5/3	0	0	0	0	0	0	0	0	0	0	0	0
5/4	2	2	0	0	0	0	0	0	0	0	0	0
5/5	1	1	0	0	0	0	0	0	0	0	0	0
5/6	1	1	0	0	0	0	0	0	0	0	0	0
total	4	4	0	0	0	0	0	0	0	0	0	0
% North	0	0	0	0	0	0	0	0	0	0	0	0

http://www.fpc.org/environment/fcounts.asp?fr\_cdy=2017&fr\_cdm=4&fr\_cdd=30&to\_cdm=5&to\_cdd=6&subbtn=salmon&op=sdaily







			USGS:
	Secchi:		Temperatures
4/30	3.0	Sun	50.9
5/1	3.0	Mon	50.8
5/2	3.0	Tue	51.1
5/3	3.0	Wed	51.9
5/4	3.0	Thurs	52.6
5/5	3.0	Fri	53.1
5/6	3.0	Sat	53.0
	3.0	AVG	51.9

http://www.nwd-wc.usace.army.mil/tmt/documents/ops/temp/201704.lcol.html

The Dalles Dam Daily Readings and Averages for Temperatures, Secchi, Entrances, and Spill

= Out of criteria

Spill link

http://www.nwdwc.usace.army.mil/dd/nwdp/project\_hourly/webexec/rep?r=tda&ago=0 North Ladder East Ladder 24 hr avg North Entrance East Entrance West Entrance South Entrance Differential N1 Depth Differential E1 Depth E2 Depth E3 Depth JP 6 Differential W1 Depth W2 Depth W3 Depth Differential S1 Depth S2 Depth Date: 1.3 0.0 8.2 14.1 1.7 8.3 1.7 10.1 4/30 10.7 1.3 0.0 8.1 14.4 1.7 8.5 10.2 45.2 1.4 5.7 0.0 1.6 1.4 10.9 1.2 0.0 Closed 8.1 14.8 1.7 8.2 5.5 0.0 1.7 10.0 1.2 0.0 8.1 13.7 1.6 8.3 0.0 1.7 10.2 5.6 5/1 1.4 10.9 1.2 0.0 8.0 13.5 1.7 8.3 5.4 0.0 1.7 Closed 10.0 44.3 1.4 10.9 1.4 0.0 4.0 8.0 13.3 1.5 8.2 0.0 1.3 10.1 1.3 0.0 8.2 10.0 4.0 14.0 1.6 8.3 0.0 1.5 5.6 5/2 1.4 10.8 1.7 0.0 4.0 7.1 15.8 1.5 8.2 4.9 1.4 1.4 10.1 50.8 1.4 10.9 1.4 0.0 5.1 8.2 16.0 1.3 8.3 6.1 1.7 1.4 10.0 1.3 7.9 12.0 12.0 16.6 1.6 9.9 9.9 1.2 1.3 9.9 10.0 7.9 43.8 5/3 1.4 10.7 1.3 12.0 12.0 16.6 1.6 10.4 10.4 1.8 1.4 8.6 8.6 7.9 1.5 1.4 10.7 1.3 11.9 15.7 10.5 10.6 0.5 1.4 9.1 9.1 12.0 5/4 1.4 10.6 1.4 6.0 12.0 12.1 17.6 1.6 10.4 10.6 8.0 1.5 9.1 9.1 41.3 1.5 6.9 12.0 11.9 16.0 1.7 10.5 10.5 0.7 1.5 9.0 9.0 1.4 10.7 1.6 1.5 7.3 12.0 12.0 16.4 10.6 10.6 1.1 1.3 9.3 9.3 5/5 12.0 43.4 1.2 10.7 1.4 6.6 12.1 16.7 1.6 10.6 10.6 1.3 1.4 9.2 9.2 1.4 7.6 12.1 12.0 16.7 1.6 10.6 10.6 1.3 1.5 9.2 1.3 10.7 9.1 1.4 8.5 11.9 12.0 17.6 1.7 10.4 10.4 2.3 1.5 9.3 9.2 5/6 51.3 1.5 10.7 1.4 8.7 11.9 12.0 15.8 1.6 10.6 10.6 2.5 1.6 9.2 9.1 1.4 10.8 1.5 10.4 12.0 12.0 18.5 1.7 8.6 8.6 3.3 1.6 9.1 9.1 AVG: 1.4 10.8 1.4 4.3 9.9 10.2 15.7 1.6 8.2 1.0 9.2 9.6 1.5 45.7

Fishways are inspected twice daily plus one SCADA inspection.