The Da	lles Dam F	THE DALLES DAM							
	Ϊ. <del>Υ</del>	H		es Project	-Fisheries				
		my Corps	P.O. Box	k 564 es, OR 97	058-0008				
lass	of En Portiar	gineers id District		541-506-38					
Inspection Period: 01/07/2017-01/13/2018									
The Delles Dem	Inspections	Criteria	Total Number	5	Tempera	ture:	39.9	°F	
The Dalles Dam	Out of Criteria	Limit	Comments			Secchi:	5.0	feet	
	-	-	NORTH	I FISHWAY					
Exit differential	0	≤ 0.5'							
Count station differential	0	≤ 0.3'							
Weir crest depth	0	1.0' ± 0.1'							
Entrance differential	0	1.0' - 2.0'	1.3						
Entrance weir N1	0	depth (≥ 8')	9.5						
Entrance weir N2	0	Closed							
PUD Intake differential	0	≤ 0.5'							
		E.	AST FISHWAY	Out of service Dec1					
Exit differential	0	≤ 0.5'							
Removable weirs 154-157	0	Per forebay	Gearbox rehab	start on 155 and 156					
Weir 158-159 differential	0	1.0' ± 0.1'	Gearbox rehab	start on 158					
Count station differential	0	≤ 0.3'							
Weir crest depth	0	1.0' ± 0.1'							
Junction pool weir JP6	0	0.0							
East entrance differential	0	1.0' - 2.0'							
Entrance weir E1	0	No criteria							
Entrance weir E2	0	depth (≥ 8')							
Entrance weir E3	0	depth (≥ 8')							
Collection channel velocity	0	1.5 - 4 fps							
Transportation channel velocity	0	1.5 - 4 fps							
North channel velocity	0	1.5 - 4 fps							
South channel velocity	0	1.5 - 4 fps							
West entrance differential	0	1.0' - 2.0'							
Entrance weir W1	0	depth (≥ 8')		Weir removed for cap	s and reha	ab			
Entrance weir W2	0	depth ( $\geq 8'$ )		Weir removed for cap					
Entrance weir W3	0	No criteria		Weir removed for cap					
South entrance differential	0	1.0' - 2.0'							
Entrance weir S1	0	depth (≥ 8')							
Entrance weir S2	0	depth ( $\geq 8'$ )							
Sluicegate operation	0	Units 1, 8, 18							
Turbine trashrack drawdown	0		range: 0.1-0.8	1					
Spill volume/pattern	0	_ , <b>j</b>			vay closed	midnight A	vug31		
Turbine Unit Priority	0	per FPP	MU 13-16 oos		.,		3-1		
Turbine 1% Efficiency	0	per FPP							

# **OTHER ISSUES:**

#### Birds and Sea lions:

No sea lion sightings this week. Numerous eagles on project, primarily at westrick park. ~70 cormorant rest in SW3. Gull numbers <20 near dam. Approx 500 seen near The Dalles Marina

### Operations

North fishway in full operation. Tailwater sensor failed, but PUD repaired within 1 day. Entrance flow appeared to remain in criteria. Sluiceway endgate closed Dec18. Sluicegates open at unit 1 and 18 to equalize with forebay.

## Current Outages;

T8 (MU15 & MU16) out for transformer failure. Transformer replacement 6/28/18.

MU17 and MU18 out for overhaul. Return 4/26/18.

MU21 and 22 out for annual. Return 1/18/18.

Fish unit 1 and 2 out 12/1/17 for annual fishway outage. East fishladder dewatered 12/1/17.

## Maintenance;

East exit weir electrical panel FCQ7 partially installed. Final design drawings near complete. Installation to continue in Feb.

West entrance weirs removed and lamprey weir caps installed. South lamprey weir caps underway.

East exit oil boom installation by AWS contract end of Feb. Scope reviewed.

Fish lock upper and lower bulkhead replacement delayed due to budget.

East exit 155, 156, 158 weir gearboxes removed and in rehab.

Work starting on a collection diffuser valve rehab for scoping purposes on remaining valves

Collection channel removal of stuck dewater pump end Jan.

Long term repair items; 154 -157 rehab/weir wheel replace, diffuser valve overhaul (rehab and decommission).

Fish related /non-fish funded items; Spillway assessment, spillway crane replace and spillgate 9. All awaiting funding.

All spillway items on Critical Infrastructure. Spillgate 9 on large cap list, projected for 2022. Charter in place for comprehensive spillway assessment.

## Research/Construction/Contractors:

Fish Counters - Normandau video review counting through the winter.

*Pikeminnow dam angling* - Done for season with a total catch at 1776. Highest invasive walleye by-catches do date being released. Concern brought to FPOM. *AWS construction* - Construction progress continues. Commissioning testing Mar 31.

Lamprey minor mods - Rounded entrance weir caps on sight. Working on attaching to west weirs. South and north to follow.

Railroad track removal - Tailrace deck rail removal approx half complted.


Fish unit breaker replace .- Work in progress. Completion Feb18, 2018. Two weeks commission testing required.

Fish unit rehab - Phase 1A report Jan 2018. Award 2020. Completion 2022.


Transformer replacement - Install start May 2018.

Approved by: Ron Twiner Operation Project Manager The Dalles Dam


The Dalles North													
Date	All Chinook	Adult Chinook	Jack Chinook	All Steelhead	Clipped Steelhead	Unclipped Steelhead	All Coho	Adult Coho	Jack Coho	Sockeye	Chum	Pink	Lamprey
1/7	0	0	0	1	1	0	0	0	0	0	0	0	0
1/8	1	1	0	1	1	0	0	0	0	0	0	0	0
1/9	0	0	0	0	0	0	0	0	0	0	0	0	0
1/10	0	0	0	0	0	0	0	0	0	0	0	0	0
1/11	0	0	0	1	1	0	0	0	0	0	0	0	0
1/12	2	2	0	1	0	1	0	0	0	0	0	0	0
1/13	-1	-1	0	0	0	0	0	0	0	0	0	0	0
total	2	2	0	4	3	1	0	0	0	0	0	0	0



				USGS:	USGS LCR temperature report							
		Secchi:		Temperatures								
	1/7 1/8	5.0 5.0	Sun Mon	40.2 40.1								
	1/8	5.0	Tue	39.9	The Dalles Dam Daily Readings and Averages for							
	1/10	5.0 5.0	Wed Thurs	39.7 39.6	Temperatures, Secchi, Entrances, and Spill							
	1/11 1/12	5.0	Fri	39.7								
	1/13	5.0	Sat	40.0	Out of within							
		5.0	AVG	39.9	= Out of criteria							
	North	Ladder			East Ladder							
Date:		ntrance		East Entrance West Entrance South Entrance								
	Differential	N1 Depth	Differential	E1 Depth	E2 Depth E3 Depth JP 6 Differential W1 Depth W2 Depth W3 Depth Differential S1 Depth S2 Depth							
1/7	1.3	9.3										
1/8	1.3	9.7										
1/9	1.3	9.4										
1/10	1.3	9.5	East Ladder dewatered for winter									
1/11	1.3	9.5										
1/12		Operations ed north										
1/13	fish											
AVG:	1.3	9.5										
					Fishways are inspected twice daily plus one SCADA inspection.							



Bulkheads installed. Ready to finish boring hole at bottom of dam.



Installing pipe section into AWS chamber.



West entranc weir caps installed