The Dalles Dam Fishway Status Report

06/08/19

Inspection Period: June 09 - June 15, 2019

THE DALLES DAM



The Dalles Project-Fisheries P.O. Box 564 The Dalles, OR 97058-9998 Phone: 541-506-3800

The Dalles Dam	Inspections		Total Number of Inspections: 21 Temperature: 62.0 °F						
	ooc	Limit	Comments: High shad numbers passing. Secchi: 3.6 feet						
			NORTH FISHWAY						
Exit differential	0	≤ 0.5'							
Count station differential	0	≤ 0.3'							
Weir crest depth	0	1.0' ± 0.1'							
Entrance differential	0	1.0' - 2.0'	1.4						
Entrance weir N1	0	depth (≥ 8')	10.0						
Entrance weir N2	0	Closed							
PUD Intake differential	0	≤ 0.5′							
			EAST FISHWAY						
Exit differential	0	≤ 0.5'							
Removable weirs 154-157	0	Per forebay							
Weir 158-159 differential	0	1.0' ± 0.1'							
Count station differential	0	≤ 0.3'							
153 Weir crest depth	0	1.3' ± 0.1'	1.3' criteria to allow shad passage; 1x too low						
Junction pool weir JP6	0	0.0							
East entrance differential	0	1.0' - 2.0'							
Entrance weir E1	0	No criteria							
Entrance weir E2	0	depth (≥ 8')							
Entrance weir E3	0	depth (≥ 8')							
Collection channel velocity	0	1.5 - 4 fps	2.29 fps on 6/12; range 1.7 fps at MU14, to 2.77 fps at MU4						
Transportation channel velocity	0		2.49 fps on 6/12.						
North channel velocity	0	1.5 - 4 fps	1.97 fps on 6/12.						
South channel velocity	0	1.5 - 4 fps	3.94 fps on 6/12.						
West entrance differential	0	1.0' - 2.0'							
Entrance weir W1	0	depth (≥ 8')							
Entrance weir W2	0	depth (≥ 8')							
Entrance weir W3	closed	No criteria							
South entrance differential	0	1.0' - 2.0'							
Entrance weir S1	0	depth (≥ 8')							
Entrance weir S2	0	depth (≥ 8')							
		· · · · /	JUVENILE PASSAGE						
Sluicegate operation	0	Units 1, 8, 18;							
Turbine trashrack drawdown	0	<1.5', biwkly	Gatewells inspection 6/15/19. Live smolts, mini jacks and shad in most wells.						
Spill volume/pattern	0	None	Gates 1 through 8 open to flex spill pattern. Collecting data from dials atop spill gates.						
Turbine Unit Priority	0	per FPP	MU 5 and 6 OOS for maintenance						
Turbine 1% Efficiency	0	per FPP							

OTHER ISSUES:

Operation:

East & North fish ladders in full operation.

Sluiceway open with 8 gates MU16 used for MU18 Sluice gates moved

Spillway open for juvenile passage.

Smolt mortalities found in gatewells 3-3 (1),18-1 (5), 18-1(3), 2-1(1)

Spill KCFS beginning to stay below 100 total

Outages

MU5 FOOS through 1700 8/29/2019 for T3 GSU transformer replacement

MU6 OOS 0830 11/19/2018 - 1700 8/29/2019 for T3 GSU transformer replacement

T10 (MU19 & 20) FOOS through 10/28/2021 due to acetylene levels

SSO2 OOS 0630 6/3/2019 - 1700 7/11/2019 for O/H.

MU17 & MU18 OOS 0001 6/10/2019 - 1700 6/20/2019 for Annuals

Maintenance:

East count station window/crowder brush repaired and functioning. Looking into improvements for long term reliability.

Calibration check 6/15: inaccuracy issue with east entrance tailwater reading adjusted. West entrance PLC setpoint inaccuracy, not OOC.

Collection channel dewatering pumps 5 and 6 rehab in progress.

Fishway automation parts purchase ongoing. Labor for assembly and install FY20.

Engineering evaluation of east fishway diffuser valve status to resume.

Spillway assessment in progress. Spillway crane replace and spillgate 9 repair included. Prioritizing gates 1-9 as first for rehab.

North trashrack rake OOS, RTS~06/20

Predators:

USDA hazing from boat and shore appears very effective w/ addition of continual hazing from project, comparatively small numbers of gull and pelican foraging Sea Lions not observed by fisheries yet to date, bird hazers see them ~once a week, reliable claim of stellars spotted

Research/Construction/Contractors:

Forebay temperature monitoring commenced for second and final year of testing

Fish counting contractors (Four Peaks) on site and counting.

For fish count data refer to; FPC FISH COUNTS

AWS backup - All deficiencies corrected by contractor. Compiling list for follow on contract items and spare parts.

Transformer replacement - T3 ongoing. Testing after august completion. Date to be determined

PSMFC weekly sampling for North Wasco County PUD continues. Refer to PCMFC weekly sample report.

PITAGS north and east fishladder data collection at count stations continues.

Pikeminnow dam angling - 37 Pikeminnow week of June 9. Total 135 YTD. Bass/Walleye release continues, unlike dam angling conducted at PUD projects.

ODFW monthly fishway inspections ongoing.

Lamprey minor mods - Planning for potential LPS in junction pool.

Univ of Idaho lamprey radiotelemetry - Second season of lamprey passage night flow started 6/4. Total of 18 nights of adjsutment planned.


Lamprey trapping - hoist system installed, thanks to ingenuity of project engineer and execution of Mechanic. Lifts being utilized successfully

Fish unit breaker replace.- Fish units returned to service. Substantial cleanup likely next winter. Awaiting schedule from contractor.

Fish unit rehab - Ongoing for phase 1A.

Approved by: Mike Colesar acting for Ron Twiner

Operation Project Manager The Dalles Dam





Red lines = avian zones


Yellow lines = current wires


Orange lines = down or missing wires

Additional avian lines installed 9/2018









			USGS:
	Secchi:		Temperatures
6/9	4.0	Sun	60.9
6/10	3.5	Mon	61.4
6/11	3.5	Tue	61.7
6/12	3.0	Wed	62.1
6/13	3.0	Thurs	62.5
6/14	4.0	Fri	62.5
6/15	4.5	Sat	62.6
	3.6	AVG	62.0

<u>June</u>

The Dalles Dam Daily Readings and Averages for Temperatures, Secchi, Entrances, and Spill

SCADA INSPECTION

Out of criteria

Lamprey passage modifications


Data omited

Date:	North Ladder Entrance		East Ladder											
			East Entrance- open				West Entrance				South Entrance			
	Differential	N1 Depth	Differential	E1 Depth	E2 Depth	E3 Depth	JP 6	Differential	W1	W2	W3	Differential	S1	S2
6/9			1.5		13.3	13.3	13.6	1.4	8.5	8.5		1.4	8.9	9.0
	1.4	9.8	1.4		13.3	13.4	13.5	1.5	8.2	8.2		1.5	8.9	9.0
	1.4	9.9	1.5		13.2	13.3	13.4	1.5	8.3	8.3		1.4	9.0	9.1
6/10			1.4		13.3	13.3	13.3	1.4	8.2	8.2		1.5	8.9	8.9
	1.4	10.0	1.4		13.3	13.3	13.3	1.6	8.2	8.2		1.4	9.0	9.0
	1.3	10.0	1.7		13.3	13.3	14.2	1.6	8.3	8.3		1.5	9.0	9.0
			1.5		13.2	13.2	12.5	1.4	8.5	8.5		1.4	9.0	9.0
6/11	1.3	9.9	1.8		13.4	13.4	12.4	1.5	8.5	8.5		1.3	8.6	8.6
	1.4	10.0	1.3		13.4	13.4	12.9	1.5	8.3	8.3		1.3	9.2	9.2
6/12			1.2		13.3	13.3	12.3	1.3	8.2	8.2		1.4	8.9	8.9
	1.3	10.0	1.3		13.2	13.2	12.2	1.4	8.2	8.2		1.5	8.9	8.9
	1.5	10.0	1.6		13.2	13.1	13.4	1.4	8.4	8.4		1.5	9.0	9.0
6/13			0.7		14.0	14.0	12.3	0.5	11.1	11.1		0.6	12.0	12.0
	1.3	10.0	1.5		13.5	13.5	11.9	1.4	8.4	8.4		1.4	8.8	8.8
	1.3	9.9	1.5		13.4	13.5	12.8	1.5	8.4	8.4		1.5	8.8	8.7
6/14			0.7		14.0	14.0	12.5	0.7	10.2	10.2		0.6	12.5	12.5
	1.3	10.0	1.3		13.4	13.4	12.8	1.5	8.3	8.3		1.5	9.0	9.0
	1.4	9.9	1.6		13.5	13.5	12.2	1.4	8.4	8.4		1.5	9.0	9.0
6/15			1.5		13	13.1	12.9	1.4	8.5	9		1.4	9.0	9.0
	1.4	10.0	1.7		13.1	13	13	1.5	8.9	8.9		1.5	8.9	8.9
	1.3	10.0	1.5		13	13	12.9	1.5	8.9	8.9		1.4	9.1	9.0
AVG:	1.4	10.0	1.5		13.3	13.3	12.9	1.5	8.4	8.4		1.4	8.9	8.9

Fishways are inspected twice daily plus one SCADA inspection.



Floating temperature profile strings in the BRZ-East Exit Temperature profile data to be analyzed for thermal statification



Sea Lion observed by USDA at The Dalles Marina