The Dalles Dam Fishway Status Report

12/21/19

Inspection Period: 12/15-12/21, 2019

THE DALLES DAM



The Dalles Project-Fisheries P.O. Box 564 The Dalles, OR 97058-9998 Phone: 541-506-3800

| The Dalles Dam | Inspections | Criteria | Total Number of Ins | spections: 7 | Temperature | | 43.4 | °F | |
|---------------------------------|-------------|----------------|---------------------|---------------------------------|-------------------|--------|------|----|--|
| The Bance Ban | OOC | Limit | Comments: FU's of | ff 12/1 for dewatering | Secchi: | 5.0 fe | eet | | |
| | | | NORTH F | ISHWAY | | | | | |
| Exit differential | 0 | ≤ 0.5' | | | | | | | |
| Count station differential | 0 | ≤ 0.3' | | | | | | | |
| Weir crest depth | 0 | 1.0' ± 0.1' | | | | | | | |
| Entrance differential | 0 | 1.0' - 2.0' | Average for week = | 1.37 | | | | | |
| Entrance weir N1 | 0 | | Average for week = | 9.3 | | | | | |
| Entrance weir N2 | 0 | Closed | | | | | | | |
| PUD Intake differential | 0 | ≤ 0.5' | | .4 to .5' | | | | | |
| | | EAST | FISHWAY - Dewatere | ed for annual maintenance | | | | | |
| Exit differential | NA | ≤ 0.5' | | | | | | | |
| Removable weirs 154-157 | NA | Per forebay | | | | | | | |
| Weir 158-159 differential | NA | 1.0' ± 0.1' | | | | | | | |
| Count station differential | NA | ≤ 0.3' | | | | | | | |
| 153 Weir crest depth | NA | 1.1' ± 0.1' | | | | | | | |
| Junction pool weir JP6 | NA | 0.0 | | | | | | | |
| East entrance differential | NA | 1.0' - 2.0' | | | | | | | |
| Entrance weir E1 | NA | No criteria | | | | | | | |
| Entrance weir E2 | NA | depth (≥ 8') | | | | | | | |
| Entrance weir E3 | NA | depth (≥ 8') | | | | | | | |
| Collection channel velocity | NA | 1.5 - 4 fps | | | | | | | |
| Transportation channel velocity | NA | 1.5 - 4 fps | | | | | | | |
| North channel velocity | NA | 1.5 - 4 fps | 12/14/19 3.62fps | | | | | | |
| South channel velocity | NA | 1.5 - 4 fps | · | | | | | | |
| West entrance differential | NA | 1.0' - 2.0' | | | | | | | |
| Entrance weir W1 | NA | depth (≥ 8') | | | | | | | |
| Entrance weir W2 | NA | depth (≥ 8') | | | | | | | |
| Entrance weir W3 | NA | 1.0' - 2.0' | | | | | | | |
| South entrance differential | NA | 1.0' - 2.0' | | | | | | | |
| Entrance weir S1 | NA | depth (≥ 8') | | | | | | | |
| Entrance weir S2 | NA | depth (≥ 8') | | | | | | | |
| | | | JUVENILE | PASSAGE | | | | | |
| Sluicegate operation | NA | Units 1, 8, 18 | Closed | | | | | | |
| Turbine trashrack drawdown | NA | | 12/15/19 some shad | morts. | | | | | |
| Spill volume/pattern | 0 | None | No spill | | | | | | |
| Turbine Unit Priority | 0 | per FPP | | | | | | | |
| Gatewells | 0 | | 12/13 fish check MU | 2, 5, 8, 21 and 22 Juv. shad pr | esent with mortal | itv. | | | |

OTHER ISSUES:

Operations

North fish ladder in full operation

East fishway dewatered

Spillway closed

Outages

T10 (MU19 & 20) FOOS through 10/28/2021 due to acetylene levels

MU1 and MU2 restricted to 160 MW combined through 5/28/2020

MU13 OOS 0600 9/23/2019 - 1700 7/22/2020 for Hydraulic Oil System Repairs

MU2 FOOS through 1/2/2019 for hydraulic repairs

MU12 OOS 0001 11/26/2019 - 1700 2/10/2020 T6 GSU Replacement & Annual

MU11 OOS 0400 11/26/2019 - 1700 2/20/2020 T6 GSU Replacement & O/H

F1 & F2 OOS 0001 12/1/2019 - 1700 2/10/2020 for Annual, O/H, FUBB

T1 & T3 OOS 0600 12/2/2019 - 1700 1/7/2020 for FUBB Upgrades

Maintenance

No calibration check

Collection channel dewatering pumps 5 and 6 removed for rehab. Awaiting new pump motor.

Fishway automation installation underway. Brackets and sensor installation complete at east entrance.

Evaluating east fishway diffuser valve status for maintenance plan.

Dewatering south entrance auxiliary water conduit to repair failed diffuser valves.

Preparing for repair of 3 expansion joints east fishladder.

Repair damaged weir cap on east entrance.

Spillway assessment (MRER); No funding for FY20. Importance of spillgate 9 fish priority included.

Weir 157 brake repair in progress. Removing weirs 154 and 155 for wheel replacement. Will also install plate on lift connection for lamprey.

West entrance weir W1 closed due to cable problems. Repair during winter outage. Weir W3 operated in its place providing two wiers at >8' depth

Predators

Green laser used to haze piscivorous birds for effectiveness testing. Report to follow.

USA hazing resumes 4/15/20

Cormorant and gull numbers fluctuating daily, with expected fall numbers.

No sea ion observations this week. Last sighting May9.

Research/Construction/Contractors

Four Peaks fish counting concluded October 31. Cleaning count stations

AWS backup - Follow on contract in progress. Return to service delayed due to parts delivery. Commissioning scheduled third week Feb.

PITAGS north and east fishladder data collection at count stations continues.


WDFW dam angling 2019 total 2228 pikeminnow, 98 smallmouth bass and 6 walleye caught. Invasive Bass/Walleye were released.

Fish unit breaker replace.- Planning third season work Dec1-end Jan. Commissioning first week of Feb.


Fish unit rehab - Phase 1A. Planning operation scenario during construction. No funding.

Approved by: Mike Colesar

Operation Project Manager The Dalles Dam



Note increased numbers of birds feeding on salmon in May as opposed to non feeding on juvenile shad in the fall. Daily fluctuations may be due to AM versus PM daily count time.




Red lines = avian zones

Yellow lines = current wires

Orange lines = down or missing wires

Additional avian lines installed 9/2018



USGS: Temperatures Secchi: 12/15 5.0 Sun 43.7 43.6 12/16 5.0 Mon 43.4 5.0 12/17 Tue 43.2 12/18 5.0 Wed 5.0 43.2 12/19 Thurs 12/20 5.0 Fri 43.3 5.0 Sat 43.4 12/21 5.0 AVG 43.4

Dec temps

The Dalles Dam Daily Readings and Averages for Temperatures, Secchi, Entrances, and Spill

| Date: | New House Entreme | | East Ladder | | | | | | | | | | | |
|-------|-------------------|-----------------------|---|----------|----------|----------|------|---------------|----|----|----|----------------|----|----|
| | North Ladde | North Ladder Entrance | East Entrance | | | | | West Entrance | | | | South Entrance | | |
| | Differential | N1 Depth | Differential | E1 Depth | E2 Depth | E3 Depth | JP 6 | Differential | W1 | W2 | W3 | Differential | S1 | S2 |
| 12/15 | 1.4 | 9.2 | | | | | | | | | | | | |
| 12/16 | 1.4 | 9.1 | | | | | | | | | | | | |
| 12/17 | 1.5 | 9.1 | | | | | | | | | | | | |
| 12/18 | 1.4 | 9.1 | Ladder dewatered for winter maintenance | | | | | | | | | | | |
| 12/19 | 1.3 | 10.0 | | | | | | | | | | | | |
| 12/20 | 1.3 | 9.2 | | | | | | | | | | | | |
| 12/21 | 1.3 | 9.1 | | | | | | | | | | | | |
| | 1.4 | 9.3 | | | | | | | | | | | | |

Fishways are inspected once daily during winter maintenance period.