The Dalles Dam Fishway Status Report

Date: 6/22/2014 **Inspection Period:** 6/15/2014 to 6/21/2014

THE DALLES DAM



The Dalles Project-Fisheries P.O. Box 564

The Dalles, OR 97058-9998 Phone: 541-506-3800

Fishways are inspected twice daily plus one SCADA inspection
--

				aily plus one SCAD	A inspection	<u>1</u>			
The Dalles Dam	Inspections	Criteria		er of Inspections:	20	Temperatur		60.8	F
The Dailes Daili	Out of Criteria	Limit	Comments			Secchi:	3.8	feet	
			NORTH F	ISHWAY					
Exit differential	0	≤ 0.5'							
Count station differential	0	≤ 0.3'							
Weir crest depth	0	1.0' ± 0.1'							
Entrance differential	0	1.0' - 2.0'	Average	1.3					
Entrance weir N1	0	depth (≥ 8')	Average	9.9					
Entrance weir N2	0	Closed							
PUD Intake differential	0	≤ 0.5'							
			EAST FI	SHWAY					
Exit differential	0	≤ 0.5'							
Removable weirs 154-157	1	,	Auto adjusts 1' ir	ncrements.	Out at 15	8.3			
Weir 158-159 differential	0	1.0' ± 0.1'							
Count station differential	0	≤ 0.3'	raked on 06/17/1	4					
Weir crest depth	0	1.0' ± 0.1'							
Junction pool weir JP6	0	depth (≥ 7')	Average	11.2	Manually	adjusted as n	eeded.		
East entrance differential	0	1.0' - 2.0'	Average	1.5					
Entrance weir E1	0	No criteria	Average	7.6		Set in auto			
Entrance weir E2	0	depth (≥ 8')	Average	12.5		Set in auto			
Entrance weir E3	0	depth (≥ 8')	Average	10.8					
Collection channel velocity	0	1.5 - 4 fps	Average	2.3					
Transportation channel velocity	0	1.5 - 4 fps	Average	2.5					
North channel velocity	0	1.5 - 4 fps	Average	2.5					
South channel velocity	0	1.5 - 4 fps	Average	3.2					
West entrance differential	0	1.0' - 2.0'	Average	1.5					
Entrance weir W1	0	depth (≥ 8')	Average	9.5					
Entrance weir W2	0	depth (≥ 8')	Average	9.5					
Entrance weir W3	closed	No criteria	closed						
South entrance differential	0	1.0' - 2.0'	Average	1.5					
Entrance weir S1	0	depth (≥ 8')	Average	9.7					
Entrance weir S2	0	depth (≥ 8')	Average	9.7					
			JUVENILE	PASSAGE					
Sluicegate operation	0	1, 8, 18							
Turbine trashrack drawdown	0	<1.5', wkly	Range	0-0.4'					
Spill volume	0	40%+-1%	Average	0.4					
Spill Pattern	0	per FPP							
Turbine Unit Priority	0	per FPP							
Turbine 1% Efficiency	0	per FPP							

OTHER ISSUES:

Birds/Sea lions:

Bird observation data collected once daily. Refer to Avian Zone Map.

With lower tailwater, gulls moving upstream of bridge within avian lines. Hazing pyros reducing numbers by 10-20% after 10minutes.

Operations:

Spill attraction flow being proposed for October to provide more attraction to the north fishladder. Trip to ERDC model planned for end of August. Gatewell drawdown completed on 6/21/14. All values were within criteria.

Current Outages:

T8 (MU15 & MU16) de-rated to single unit full load ops through 9/14/2017

MU20 out of service 5/19/14 to 6/26/14 for overhaul

Maintenance:

Fabrication of new weir 159 ahead of schedule and cost estimate. Completion by Oct1. Installation mid Dec.

North fishway pump motor replacement ordered. Delivery expected prior to Jan dewatering.

Collection channel pump #1 to be removed 8/4 for repair of grounded motor.

Purchasing oil boom for install at east exit. FPOM approved.

Planning for install equalizing valve on PUD intake bulkhead for next winter dewatering.

East entrance weir E3 lowered to 13' depth but remains in manual due to sticking problem. Entrance weir E1 in auto.

Long term repair plans funding dependent; Upgrade east exit weirs 154-157, charter submitted tp stabilize north ladder rock walls, remove collection channel diffusers, replace all entrance weir wheels with plastic composite wheels and repair/modify all east fishway dewatering pumps. Fish related but non-fish funded items; spillway evaluation, spillway crane rehab, spillgate 10/11 wire rope replacement, HDC update fish unit reliability assessment, planning upgrade fish unit breakers and fish unit transformer replacement.

All spillway items on Critical Infrastructure list and Unfunded Requirement list

Studies:

EFL Backup. Hole through dam, under roadway and into AWS conduit at junction pool. Starting Plans and Specs. Construction winter 2015.

Test pits excavation between fishladder and fishlock parking area in Nov. ADCP flow velocity survey in Aug. Both FPOM approved.

PUD - PUD 'freedom' second turbine proposal for north fishway in FERC review process. No new developments.

Research/Contractors:

PSMFC PIT tag monitoring continues at count stations. No issues.

Columbia River Northern Pikeminnow Management Dam Angling: Twenty one hours fishing for 68 pikeminnow.

CTUIR, YN, and NPT will started lamprey collection June 20. Total catch 46 lamprey from east count station. Allocation for 2014 is 374.

ODFW Northern Pikeminnow Management Program evaluation electrofishing; No sampling at The Dalles this week.

Fish counters on site at north and east count stations 16 hours a day 1 April through 30 October.

PSMFC PUD weekly sampling: 3 Chinook smolt.

Normandeau fish counting program 4/1 through 10/31. Night video starts mid June.

USDA hazer's launching pyrotechnics from downstream navlock peninsula. Also on call for sea lion hazing and pigeon removal as needed.


University of Idaho maintaining antennas and continuing downloads.

Removal last set of 3 derelict Vertical Barrier Screens from MU 12 gate well slot scheduled week of Aug11. Funding allocated.

Approved by:

Ron D. Twiner

Operation Project Manager




Hazing activity primarily in SW-T4 Numbers reflect weekly range of daily average


DART The Dalles Adult Ladders Daily Usage with Spill Percent and Outflow

		Chinook			Chinook Jack Chinook					Steelhead				Steelhead Wild				Sockeye				Adult & Jack	Lamprey				Outflow
	Le	eft	Rig	ht	Le	ft	Rig	ht	Le	ft	Rig	ht	Let	ft	Righ	nt	Le	eft	Ri	ght	Coho	Le	eft	Rig	ght	(kcfs)	
Date	Lac	lder	Lad	der	Lade	der	Lado	der	Lado	der	Lad	der	Lado	der	Ladd	er	Lad	der	Lac	lder		Lad	der	Lad	der		
	Pct	#	Pct	#	Pct	#	Pct	#	Pct	#	Pct	#	Pct	#	Pct	#	Pct	#	Pct	#		Pct	#	Pct	#		
6/15	60.4	1789	39.6	1171	67.5	308	32.5	148	83.5	71	16.5	14	73.3	22	26.7	8	76.8	3119	23.2	941			97.4	37	2.6	1	198.2
6/16	79.1	1518	20.9	402	82.4	257	17.6	55	83.9	52	16.1	10	100	24	0	0	77.3	2610	22.7	766			100	10	0	0	190.5
6/17	67	888	33	438	94.6	335	5.4	19	90.7	78	9.3	8	100	29	0	0	88.3	2993	11.7	396		75	18	25	6	213.2	
6/18	88.4	1432	11.6	188	91.7	210	8.3	19	90.3	65	9.7	7	96	24	4	1	97.1	3798	2.9	115		72	18	28	7	250.2	
6/19	78.8	1284	21.2	346	98.8	491	1.2	6	95.6	86	4.4	4	94.9	37	5.1	2	96.2	4848	3.8	190	not present YTD	29	18	71	44	235	
6/20	67.2	1728	32.8	842	78.5	263	21.5	72	86.7	85	13.3	13	79.5	31	20.5	8	90.5	6734	9.5	709		12.1	8	87.9	58	222.2	
6/21	69	1229	31	552	97.2	385	2.8	11	93	107	7	8	85.7	42	14.3	7	94	7481	6	475		20	8	80	32	246.4	
		Chin	ook		J	ack Cl	ck Chinook Steelhead				Steelhead Wild		t	Sockeye		eye			Lam		mprey		Outflow				
YTD	Left Ri		Left Right Left Right			Left Right		Left Ri		_	Right		Left Righ				Left		Right								
5		lder	Lad			Ladder Ladder			Ladder		Ladder		Lado		Ladd	_		der	Ladder				der		der	AVG	
		ct	Po		Po		Pc		Po	-	P0		Pc	-	Pct			ct		ct		Pct 44.2		Pct 55.8		222.2	
	71.5 28.5		87	.∠	12	.ŏ	89	.э	10	.э	88.	.9	11.	11.1		89.8 10.2			44	·.Z	55	0.8	222.2				

NOTES:

- 1. The species passage percent is not calculated for either ladder on a day, if either the Right Ladder or Left Ladder species count is: negative or null for the day.
- 2. Ladder orientations reference the side of the river when facing downstream.
- 3. Data Provided Courtesy of U.S. Army Corps of Engineers





	Forebay	Tailwater						
	61.1	61.2						
	61.0	61.2						
USGS	60.7	60.8						
	60.5	60.6						
	60.8	60.8						
DATA	60.9	60.9						
	60.6	60.7						
AVG:	60.8							

	Secchi:
SUN	4.0
MON	4.0
TUES	4.0
WED	4.0
THUR	4.5
FRI	3.0
SAT	3.0
AVG:	3.8

The Dalles Dam Daily Readings and Averages for Temperatures, Secchi, Entrances, and Spill

= out of criteria

	North Fish	h Ladder													
	North Er	ntrance		Eas	st Entrance)			West Er	ntrance		Sou	Spill%		
Date:	Differential	N1 Depth	Differential E1 Depth E2 Depth E3 Depth				JP 6	Differential	W1 Depth	W2 Depth	W3 Depth	Differential	S1 Depth	S2 Depth	
			1.6	6.4	12.4	10.1	10.6	1.5	9.5	9.4		1.5	9.6	9.6	
6/15/14	1.3	9.9	1.5	7.9	12.5	10.0	10.5	1.5	9.5	9.5		1.5	9.5	9.5	40.0
	1.3	9.9	1.5	8.0	12.4	9.9	10.4	1.5	9.6	9.4		1.6	9.4	9.4	
			1.6	8.0	12.6	9.2	9.7	1.5	9.0	9.0		1.5	9.5	9.5	
6/16/14	1.3	10.0	1.6	8.0	12.4	9.2	9.7	1.5	8.9	8.9		1.6	9.6 9.4	9.4	40.0
	1.3	9.9	1.6	10.0	12.4	9.9	10.4	1.4	9.1	9.1		1.5	9.5	9.6	
			1.4	10.1	12.7	9.7	10.2	1.5	9.0	9.0		1.5	9.5	9.5	
6/17/14	1.3	9.9	1.8	8.0	12.5	10.3	10.8	1.6	9.0	9.0	•	1.6	9.5	9.5	40.0
	1.4	9.9	1.4	8.1	12.5	12.0	12.5	1.7	9.0	9.0	C	1.6 9	9.4	9.4	
			1.4	8.0	12.6	11.2	11.7	1.5	9.9	9.9	1	1.6	9.5	9.4	40.0
6/18/14	1.4	10.0	1.5	5.9	12.4	11.8	12.3	1.6	10.0	9.9	0	1.6	9.4	9.5	
	1.3	10.0	1.4	5.0	12.4	13.4	13.4	1.6	10.6	10.6	S	1.5	1.5 10.0 10	10.1	
			1.8	8.8	12.6	9.8	10.3	1.5	9.6	9.6	е	1.5	10.0	10.1	
6/19/14	1.3	9.9	1.5	7.0	12.6	11.8	12.9	1.6	9.5	9.6		1.5	10.0	10.0	39.9
	1.3	9.9	1.3	7.2	12.5	12.2	10.7	1.3	9.9	9.9	d _{1.5}	1.5	9.9	10.0	
			1.5	7.1	12.6	10.4	10.9	1.5	9.5	9.5		1.4	10.1	10.1	
6/20/14	1.3	10.0	1.6	7.0	12.5	10.3	10.8	1.4	9.5	9.5		1.5	10.0	10.0	40.1
	1.4	9.9	1.7	7.0	12.5	11.1	11.6	1.5	9.5	9.6		1.5 10.1	10.1	10.1	
			1.5	6.9	12.4	11.3	11.8	1.7	9.5	9.5		1.5	9.9	10.0	
6/21/14	1.3	9.9	1.5	7.0	12.4	11.4	11.9	1.6	9.5	9.5		1.4	10.0	10.0	39.9
AVG:	1.3	9.9	1.5	7.6	12.5	10.8	11.2	1.5	9.5	9.5		1.5	9.7	9.7	40.0



First recorded lamprey mortality removed from downstream picket lead at east counts station. Investigation underway. Memo provided to FPOM.



Dying sturgeon found in downstream entrance to navlock with bloated stomach. Cause unknown. Consulted USGS - possible cause from being pulled up from depth by angler.