The Dalles Dam Fishway Status Report

2/9/2015

Inspection Period: 2/8/2015 to 2/14/2015

NA

NA

NA

NA

40% ±1%

per FPP

per FPP

per FPP

Average


Spillbay

Spill volume

Spill Pattern

Turbine Unit Priority.

Turbine 1% Efficiency



US Army Corps of Engineers Portland District

The Dalles Project-Fisheries P.O. Box 564 The Dalles, OR 97058-9998

Phone: 541-506-3800

	Fishw	ays are inspe	ected once per da	ay during i	he winter mai	ntenance _l	period.				
The Dalles Dam	Inspections	Criteria	Total Number of Inspections: 7				Temperature: 41.1 F				
	Out of Criteria		Comments		Secchi: 4.1 feet						
NC	RTH FISHWA	Y - Out of Sei	rvice Feb 2, 201	5 through	Feb 26, 201	for winte	er mainten	ance.			
Exit differential	NA	≤ 0.5'									
Count station differential	NA	≤ 0.3'									
Weir crest depth	NA	1.0' ± 0.1'									
Entrance differential	NA		Average		Daily differe	ntials and	weir depth	s, see AV	GS tab.		
Entrance weir N1	NA	depth (≥ 8')									
Entrance weir N2	NA	Closed	Bulkhead install	ed.							
PUD Intake differential	NA	≤ 0.5'	Average								
			EAST I	FISHWAY							
Exit differential	0	≤ 0.5'									
Removable weirs 154-157	0	•	Auto adjusts 1' i								
Weir 158-159 differential	1		OOC at 1.3'; set	t point was	s changed.						
Count station differential	0	≤ 0.3'									
Weir crest depth	0	1.0' ± 0.1'									
Junction pool weir JP6	0		Average	12.9							
East entrance differential	0	1.0' - 2.0'	Average	1.7							
Entrance weir E1	0		Average	2.3	Manually ad	justed as r	needed.				
Entrance weir E2	0	depth (≥ 8')		11.9							
Entrance weir E3	0	depth (≥ 8')		11.9							
Collection channel velocity	NA	1.5 - 4 fps									
Transportation channel velocity	NA	1.5 - 4 fps		Fishway velocities concluded Dec 1 and will resume Mar 1, 2015 as per Fish Passage Plan.							
North channel velocity	NA	1.5 - 4 fps									
South channel velocity	NA	1.5 - 4 fps									
West entrance differential	0		Average	1.7							
Entrance weir W1	0	depth (≥ 8')		10.0							
Entrance weir W2	0	depth (≥ 8')		9.9							
Entrance weir W3	0		Average	5.6	Manually ad	justed as r	needed.				
South entrance differential	0		Average	1.5							
Entrance weir S1	0	depth (≥ 8')		12.1							
Entrance weir S2	0	depth (≥ 8')		12.7							
			JUVENIL								
Sluicegate operation	0	•	Sluicegates 1-1		are open to fo	rebay, end	dgate is clo	sed			
Turbine trashrack drawdown	NA	<1.5', wkly	Resume on Mar	rch 1							

On seal.

On seal.

Fish passage season resumes March1

Fish passage season resumes March1

OTHER ISSUES:

Birds/Sea lions:

Bird observation data collected once daily. Few eagles remain. Refer to Avian Zone Map.

Operations:

Gatewell drawdown and routine weir calibrations to resume March 1, 2015.

North ladder dewatered below tailwater. Maintenance near complete.

East fishway in full service. Flow recudtion test of 1400 cfs to occur Feb 23.

Paul Keller coordinating north count station mods for video counting tests in March.

Feb 11, East Fishladder AWS Backup System Plan-in-Hand Walkthrough (1000-1400); Westrick.

Current Outages:

T8 (MU15 & MU16) de-rated to single unit full load ops through 9/14/2017.

MU8 out of service 2/2/2015 to 3/26/2015 for overhaul.

North fish ladder out of service 2/3/2015 to 2/26/2015 for Annual.

Maintenance:

East exit weirs calibrated.

Half of east fishway entrance weirs rehabbed with new wheels. 1 of 8 east entrance weir guides rehabbed.

Three collection channel dewatering pumps on deck for rehab, repair delayed due to lack of funding. Two of 6 collection channel pumps remain stuck.

Permanent east fishway exit boom delivered. Delays in contracting resulted in missing in water work window. Install planned for next winter.

FCQ7 electrical panel for east exit upgrade prep work completed. Planning and parts purchase underway. Installation planned for next outage season.

One of 6 east entrance diffuser valves in need of repair. Valve opened for remainder of passage season. Possible repair planned next outage season.

North fishway tree removal from ladder walls in progress. Expect completion week of Feb 17.

PMs underway on north count station equipment.

Future repair plans; Upgrade east exit weirs 154-157, removal/permanent closure of collection channel diffusers

Fish related but non-fish funded items; spillway evaluation, spillway crane rehab, spillgate 9 wire rope replacement, HDC update fish unit reliability assessment, planning upgrade fish unit breakers and fish unit transformer replacement.

All spillway items on Critical Infrastructure list and Unfunded Requirement list.

Studies:

North fishladder rock stabilization development team site visit Feb 18. Alternatives for repair of vulnerable areas to be determined and provided to FPOM. Investigating PIT tag 15 mile creek steelhead overshooting The Dalles. FPOM discussion continues.

Investigating north fish count station mods for visibility improvement and use of video. Equipment purchase underway. Install Feb for testing in March.

EFL Backup; Plans/Specs underway. Includes 10'pipe from forebay to AWS. A 1400cfs flow test planned Feb 23. Coordinated through FPOM.

PUD 'freedom' second turbine; Field test proposal summer 2015 proposed through FPOM and SRWG. Rock plunge pool inspection Feb 16

Spill test for more fish passage to north fishladder completed using fish counts. Potential benefit. FPOM discussion to continue for when to implement.

Research/Contractors:


PSMFC PIT tag monitoring continues at north count station.

Normandeau fish counters to resume Apr1.

University of Idaho maintaining antennas. Continuing downloads of winter steelhead.


Approved by: Ron Twiner

Operation Project Manager The Dalles Dam



Avian lines in yellow, zones in red, river flow in blue.

2015 Piscivorous Bird Counts													
F=foraging, NF=non-foraging													
	1	Time	_	Gull Cormorant Caspian						Of	ther	Total	Notes
Date	Observer	(24 hr)	Zone	F	NF	F	NF	F	NF	F	NF	birds in	
		15:47	FB	0	0	0	0	0	0	0	94	94	Ducks
		14:15	PH1	0	0	0	0	0	0	0	2	2	Ducks
		14:25	PH2	0	0	0	0	0	0	0	4	4	1 GBHE, 3 BAEA
2/8/15	PSK	15:45	SW1	0	103	0	0	0	0	0	0	103	. 02.12, 02.12.1
2,0,10		14:34	SW2	0	0	0	0	0	0	0	28	28	Ducks
		14:36	SW3	0	0	5	22	0	0	Ö	0	27	Duono
		15:48	SW4	0	0	0	0	0	0	Ö	0	0	
	1	10:38	FB	0	0	1	5	0	0	0	6	12	BAEA
		10:05	PH1	0	0	0	0	0	0	Ö	0	0	D/ (L/ (
		10:12	PH2	0	0	0	0	0	0	0	2	2	BAEA
2/9/15	JWR.	10:33	SW1	0	2	0	0	0	0	0	0	2	DALA
2,0,10),,,,	10:15	SW2	0	0	0	0	0	0	0	0	0	
		10:16	SW3	0	0	0	17	0	0	0	0	17	
		10:10	SW4	0	3	0	0	0	0	0	0	3	
		12:51	FB	0	1	0	0	0	0	0	4	5	BAEA
		12:18	PH1	0	0	0	0	0	0	0	5	5	DALA
		12:10	PH2	0	0	0	0	0	0	0	3	3	BAEA
2/10/15	/WR	12:47	SW1	0	0	0	0	0	0	0	0	0	BALA
2/10/10	JWK	12:22	SW2	0	0	0	0	0	0	0	0	0	
		12:23	SW3	0	0	0	25	0	0	0	0	25	
		12:24	SW4	0	0	0	0	0	0	0	0	0	
	1	10:07	FB	0	0	1	0	0	0	0	4	5	BAEA
		9:18	PH1	0	0	0	0	0	0	0	0	0	DALA
		9:24	PH2	0	0	0	0	0	0	0	0	0	
2/11/15	JWR	10:11	SW1	0	6	0	0	0	0	0	0	6	
2/11/13		9:31	SW2	0	0	0	0	0	0	0	0	0	
		9:32	SW3	0	0	0	20	0	0	0	0	20	
		9:35	SW4	0	0	0	0	0	0	0	0	0	
		14:15	FB	0	1	0	0	0	0	0	3	4	1 BAEA, 2 Ducks
		13:48	PH1	0	0	0	0	0	0	0	1	1	Duck
		13:53	PH2	0	0	0	0	0	0	0	2	2	BAEA
2/12/15	PSK	14:18	SW1	0	128	0	0	0	0	0	0	128	DAEA
2/12/13	FSK	14:10	SW2	0	0	0	0	0	0	0	19	19	Ducks
		14:00	SW3	0	0	0	20	0	0	0	0	20	Ducks
		14:44	SW4	0	2	0	8	0	0	0	0	10	
		10:02	FB	0	0	1	0	0	0	0	1	2	BAEA
		9:03	PH1	0	0	0	0	0	0	0	0	0	DVEX
		9.03 9:08	PH1 PH2	0	0	0	0	0	0	0	1	1	GBHE
2/13/15	/WR	9.06 9:56	SW1	0	0	0	0	0	0	0	0	0	GDUE
2,10,10	J 777.C	9.56 9:11	SW1	0	0	0	0	0	0	0	0	0	
		9.11 9:16	SW2 SW3	0	0	0	19	0	0	0	0	19	
		9:17	SW4	0	0	0	0	0	0	0	0	0	
		14:07	FB	0	0	0	0	0	0	0	0	0	
		13:14	PH1	0	0	0	0	0	0	0	0	0	
		13:14	PH1	0	0	0	1	0	0	0	0	1	
2/14/15	EK	14:10	SW1	0	54	0	0	0	0	0	0	54	wing wall
۱۳/۱۵	LIN	13:31	SW1	0	0	0	0	0	0	0	0	0	willy wall
		13:33	SW2 SW3	0	0	0	17	0	0	0	0	17	
				_	-	0		0		0		25	
		13:34	SW4	0	10	U	15	U	0	U	0	25	



Т	emperature	s	Secchi:
	40.5		5.0
	40.6		4.0
	40.9		4.0
	41.1		4.0
	41.3		4.0
	41.4		4.5
	41.9		3.0
AVG:	41.1	AVG	4.1

The Dalles Dam Daily Readings and Averages for Temperatures, Secchi, Entrances, and Spill

= Out of criteria

	North Ladder East Ladder]
	North Entrance		East Entrance					West Entrance				South Entrance			
Date:	Differential	N1 Depth	Differential	E1 Depth	E2 Depth	E3 Depth	JP 6	Differential	W1 Depth	W2 Depth	W3 Depth	Differential	S1 Depth	S2 Depth	Spill KCFS
			1.6	0.9	12.0	11.9	13.8	1.6	9.9	9.4	6.9	1.6	12.5	12.4	
2/8/15															-
	_		1.6	0.8	11.8	11.8	12.0	1.5	10.0	9.5	7.0	1.5	12.1	12.1	
2/9/15			1.0	0.6	11.0	11.0	12.0	1.5	10.0	9.5	7.0	1.5	12.1	12.1	
	1		1.8	2.8	11.9	12.0	12.4	1.5	10.2	10.2	5.0	1.6	12.7	12.7	
2/10/15	North ladder out	orth laddar out													0
	of serv														n
2/11/15		iter	1.8	3.0	12.0	12.0	13.6	2.0	10.0	9.9	5.0	1.6	13.9	13.9	-
2/11/13		maintenance Feb 3, 2015 to Feb 26,													s
	3, 2015 to	-	1.6	2.9	11.9	11.9	13.6	1.8	10.0	9.9	5.0	1.0	13.8	13.7	e a
2/12/15	20.0													l	
			1.7	3.0	12.1	12.2	12.6	1.8	10.1	10.1	5.0	1.6	9.9	12.0	
2/13/15															
	4		1.8	3.0	11.6	11.5	12.5	1.5	10.0	10.1	5.2	1.5	9.8	11.8	
2/14/15			1.8	3.0	11.0	11.5	12.5	1.5	10.0	10.1	5.2	1.5	9.8	11.8	-
2, 1 1, 10															
AVG:			1.7	2.3	11.9	11.9	12.9	1.7	10.0	9.9	5.6	1.5	12.1	12.7	

Fishways are inspected once per day during the winter maintenance period.