The Dalles Dam Fishway Status Report

5/2/2021

Inspection Period: 04/25-5/1

THE DALLES DAM



The Dalles Project-Fisheries P.O. Box 564 The Dalles, OR 97058-9998 Phone: 541-506-3800

| The Dalles Dam | Inspections Criter | | Total Number of Inspections: | | | Temperature: 53.4 °F | | | | |
|---------------------------------|--------------------|--------------|------------------------------|----------------------------|------------|--------------------------------|--|--|--|--|
| The Dalles Dam | OOC | Limit | Comments: | AWS operating well. | | Weekly Ave. Secchi: 4.9 | | | | |
| NORTH FISHWAY | | | | | | | | | | |
| Exit differential | 0 | ≤ 0.5' | | | | | | | | |
| Count station differential | 0 | ≤ 0.3' | | | | | | | | |
| Weir crest depth | 0 | 1.0' ± 0.1' | | | | | | | | |
| Entrance differential | 0 | 1.0' - 2.0' | Weekly average | 10.0 | | | | | | |
| Entrance weir N1 | 0 | | Weekly average | 1.4 | | | | | | |
| Entrance weir N2 | 0 | Closed | | | | | | | | |
| PUD Intake differential | 0 | ≤ 0.5' | | | | | | | | |
| | | | EAST FIS | SHWAY | | | | | | |
| Exit differential | 0 | ≤ 0.5' | | | | | | | | |
| Removable weirs 154-157 | 0 | Per forebay | | | | | | | | |
| Weir 158-159 differential | 0 | 1.1' ± 0.1' | | | | | | | | |
| Count station differential | 0 | ≤ 0.3' | | | | | | | | |
| 153 Weir crest depth | 0 | 1.0' ± 0.1' | | | | | | | | |
| Junction pool weir JP6 | 0 | > 7.0' | | | | | | | | |
| East entrance differential | 0 | 1.0' - 2.0' | 1 fish unit operation | Week ave. 1.5 | | | | | | |
| Entrance weir E1 | 0 | No criteria | · | | | | | | | |
| Entrance weir E2 | 0 | depth (≥ 8') | | Week ave. 11.1 | | | | | | |
| Entrance weir E3 | 0 | depth (≥ 8') | | Week ave. 11.1 | | | | | | |
| Collection channel velocity | 0 | 1.5 - 4 fps | 2.07 fps 4/30 | Range MU20 1.39- MU | J16 2.48fp | OS . | | | | |
| Transportation channel velocity | 0 | 1.5 - 4 fps | 2.65 fps 4/30/2021 | <u> </u> | • | | | | | |
| North channel velocity | 0 | 1.5 - 4 fps | 2.44 fps, 5/1/2021 | | | | | | | |
| South channel velocity | 0 | 1.5 - 4 fps | 3.82 fps 4/30/21 | | | | | | | |
| West entrance differential | 0 | | Old SCADA | Week ave. 1.5 | | | | | | |
| Entrance weir W1 | 0 | depth (≥ 8') | | Week ave. 8.4 | | | | | | |
| Entrance weir W2 | 0 | depth (≥ 8') | | Week ave. 8.4 | | | | | | |
| Entrance weir W3 | 0 | No criteria | Closed | | | | | | | |
| South entrance differential | 0 | 1.0' - 2.0' | | Week ave. 1.2 | | | | | | |
| Entrance weir S1 | 0 | depth (≥ 8') | 1 fish unit operation | Week ave. 10.1 | | | | | | |
| Entrance weir S2 | 0 | | 1 fish unit operation | | | | | | | |
| | | | JUVENILE F | PASSAGE | | | | | | |
| Sluicegate operation | 0 | Units 1, 18 | Gates over MU1/1-2- | -3,MU8/1-3,MU18-2 ope | n | | | | | |
| Turbine trashrack drawdown | 0 | | | within drawdown criteria | | | | | | |
| Spill volume/pattern | 0 | 1 to 8 | Spilling 8 gates. | | | | | | | |
| Turbine Unit Priority | 0 | per FPP | <u> </u> | | | | | | | |
| Gatewells | 0 | | No mortality. Decrea | asing #s of salmon fry, ir | ncreasing | smolts in gatewells, 4/28/2021 | | | | |

OTHER ISSUES:

Current Unit Outages

FU2 OOS through 4/27/21

T10 (MU19 and 20) OOS 10/27/22 acetylene levels

MU22 out 3/1/2021 – 5/20/2021 for Top Plate Cover Upgrades

Maintenance

PUD intake rake returned to service. Temporary power supply repair completed. Exploring permanent options.

Five of 6 east fishway collection channel dewatering pumps removed for repair/rehab. Work to resume this summer.

Fishway automation replacement on hold. East exit, east and south entrances complete. West and north operating old system.

Calibrations 4/29/21 show entrance east gates E3 and S2 recording gates lower than actual opening. All in criteria >8'. Working on fix with TDE.

AWS backup system in operation with a single fish unit through next week. No intake debris accumulation or differential.

Spillway assessment (MRER); Spillgates 1-9 rehab date estimate 2034. Includes replacement of spillbay 9 trunnion pin repair

Predators

Gull numbers increasing with aggressive foraging below spillway in SW3 and 4. Cormorants nesting on BPA towers.

No opportunity for Green laser use for piscivorous bird hazing testing. Laser no longer effective moving cormorants off of BPA towers at dusk.

Pikeminnow dam angling resumes in May. All invasive bass/walleye by-catch release to continue per state requirement for past 5 years.

Processing tag data recovered. Avian predator investigation continues with purchase of game cams for east fishways.

Research/Construction/Contractors

Fish counters started Apr1. No issues.

AWS intake trashrack - EDR funded for FY21 to investigate solution for debris plugging issue. Team site visit Mar31.

PITAGS north and east fishladder data collection at count stations continues.

Fish unit rehab - Phase 1A on hold. Planning operation with AWS backup water supply during construction.

Fishway Operations

Ice Trash sluiceway opened 24/7. MU1/1-2-3, MU 8/1-3, MU18/2


East and north fishladders in full operation per Fish Passage Plan.

New automation working well within criteria.


Spillway open at 40% river flow


Approved by: Ron Twiner, Operation Project Manager, The Dalles Dam

New Avian Lines and laser deterrent zones









| | Secchi: | | ° F |
|------|---------|-------|------------|
| 4/25 | 5.0 | Sun | 52.0 |
| 4/26 | 4.0 | Mon | 52.4 |
| 4/27 | 5.0 | Tue | 52.8 |
| 4/28 | 5.0 | Wed | 53.3 |
| 4/29 | 5.0 | Thurs | 54.0 |
| 4/30 | 5.0 | Fri | 54.4 |
| 5/1 | 5.0 | Sat | 54.6 |
| | 4.9 | AVG | 53.4 |

Lower Columbia River Temperature Report for April 2021 (crohms.org)

The Dalles Dam Daily Readings and Averages for

Temperatures, Secchi, Entrances, and Spill

E1 and W3 do not have criteria opening. *S2, E3 value 1.5 '~ more than actual. out of criteria

| Date: | North Ladder | | East Ladder | | | | | | | | | | | |
|------------------|--------------|----------|---------------|----------|--------------|--------------|---------------|--------------|-----|-----|----------------|--------------|--------------|-------------|
| | | | East Entrance | | | | West Entrance | | | | South Entrance | | | |
| | Differential | N1 Depth | Differential | E1 Depth | E2 Depth | E3 Depth | JP 6 | Differential | W1 | W2 | W3 | Differential | S1 | S2 |
| | | | | | | | | | | | | | | |
| 4/25 | 1.4 | 9.9 | 1.4 | 8.2 | 11.2 | 11.2 | 12.3 | 1.5 | 8.3 | 8.3 | -1.2 | 1.2 | 9.7 | 9.7 |
| | 1.4 | 9.9 | 1.5 | 8.2 | 11.1 | 11.1 | 12.3 | 1.5 | 8.4 | 8.4 | -1.3 | 1.2 | 10.3 | 10.3 |
| | | | | | | | | | | | | | | |
| 4/26 | 1.4 | 10.0 | 1.4 | 8.4 | 11.0 | 11.0 | 12.5 | 1.4 | 8.2 | 8.2 | -1.3 | 1.2 | 9.7 | 9.6 |
| | 1.3 | 10.1 | 1.4 | 8.5 | 11.0 | 11.1 | 12.5 | 1.5 | 8.4 | 8.4 | -1.1 | 1.1 | 10.1 | 10.1 |
| 4/07 | | | | | | | | | | | | | | |
| 4/27 | 1.4 | 9.9 | 1.4 | 8.5 | 10.9 | 10.9 | 12.5 | 1.5 | 8.4 | 8.4 | -1.0 | 1.2 | 10.0 | 10.0 |
| | 1.4 | 10.0 | 1.5 | 8.5 | 10.9 | 11.0 | 12.6 | 1.5 | 8.4 | 8.3 | -1.0 | 1.2 | 10.1 | 10.0 |
| 4/28 | | 10.0 | | | 100 | 10.0 | | 1.6 | | | -1.1 | | | 10.1 |
| | 1.4 | 10.0 | 1.5 | 8.4 | 10.8 | 10.8 | 12.4 | 1.5 | 8.3 | 8.3 | -1.0 | 1.1 | 10.1 | 10.1 |
| | 1.3 | 10.0 | 1.5 | 8.3 | 10.7 | 10.8 | 12.4 | 1.6 | 8.2 | 8.2 | -1.2 | 1.2 | 10.2 | 10.2 |
| 4/29 | 1.3 | 9.9 | 1.7 | 7.7 | 10.2 | 10.2 | 11.7 | 1.4 | 8.4 | 8.4 | 1.0 | 1.2 | 10.2 | 10.2 |
| 4/29 | 1.3 | 10.0 | 1.7 1.5 | 8.3 | 10.2 10.7 | 10.2 10.8 | 11.7 12.4 | 1.4 1.7 | 8.4 | 8.4 | -1.8 -1.9 | 1.2 1.3 | 10.3 10.1 | 10.3 9.1 |
| | 1.3 | 10.0 | 1.5 | 8.3 | 10.7 | 10.8 | 12.4 | 1.7 | 8.6 | 8.6 | -1.9 -1.5 | 1.5 | 10.1 | 9.1 |
| 4/30 | 1.3 | 10.1 | 1.5 | 8.0 | 12.7 | 12.7 | 12.1 | 1.6 | 8.4 | 8.4 | -1.5 | 1.2 | 10.0 | 10.3 |
| | 1.4 | 10.1 | 1.5 | 8.0 | 12.7 | 12.7 | 12.1 | 1.6 | 8.3 | 8.3 | -1.5 | 1.2 | 10.1 | 10.4 |
| | 1.4 | 10.0 | 1.5 | 6.0 | 12.7 | 12.7 | 12.1 | 1.6 | 8.6 | 8.6 | -1.1 | 1.2 | 10.1 | 10.4 |
| 5/1 | 1.3 | 10.0 | 1.6 | 7.7 | 10.4 | 10.4 | 11.8 | 1.5 | 8.4 | 8.4 | -1.6 | 1.2 | 10.1 | 10.5 |
| - , - | 1.3 | 10.2 | 1.6 | 8.3 | 11.0 | 11.0 | 12.4 | 1.5 | 8.6 | 8.6 | -1.5 | 1.2 | 11.1 | 10.4 |
| AVG: | 1.4 | 10.0 | 1.5 | 8.2 | 11.1 | 11.1 | 12.3 | 1.5 | 8.4 | 8.4 | -1.3 | 1.2 | 10.1 | 10.1 |

Fishways are inspected twice daily. Overnight trend monitored via Old SCADA.



Sunday morning sport fishing upstream of the east ladder exit. Owl decoy doesn't work on them. We often observe them well within 50' of exit.