The Dalles Dam Fishway Status Report

11/12/2016

Inspection Period: 11/06/2016 - 11/12/2016

THE DALLES DAM



Fishways are inspected twice daily plus one SCADA inspection													
The Dalles Dam	Inspections	Criteria		ber of Inspections:	21	Temperatu	re:	56.4	°F				
The Dalles Dam	Out of Criteria	Limit		Fall like conditions on	project	Secchi:	4.6	feet					
			NORT	H FISHWAY									
Exit differential	0	≤ 0.5′											
Count station differential	0	≤ 0.3'											
Weir crest depth	0	1.0' ± 0.1'											
Entrance differential	0	1.0' - 2.0'	1.3										
Entrance weir N1	0	depth (≥ 8')	9.2										
Entrance weir N2	0	Closed											
PUD Intake differential	0	≤ 0.5′											
EAST FISHWAY													
Exit differential	0	≤ 0.5'											
Removable weirs 154-157	1	Per forebay	Weir in transiti	on									
Weir 158-159 differential	0	1.0' ± 0.1'											
Count station differential	0	≤ 0.3'	Picket leads ra	ked as needed.									
Weir crest depth	0	1.0' ± 0.1'											
Junction pool weir JP6	0	depth (≥ 7')	10.5										
East entrance differential	0	1.0' - 2.0'	1.5										
Entrance weir E1	0	No criteria	0.0										
Entrance weir E2	0	depth (≥ 8')	12.5										
Entrance weir E3	0	depth (≥ 8')	12.5										
Collection channel velocity	0	1.5 - 4 fps	3.28										
Transportation channel velocity	0	1.5 - 4 fps	2.66										
North channel velocity	0	1.5 - 4 fps	2.84										
South channel velocity	0	1.5 - 4 fps	3.48										
West entrance differential	0	1.0' - 2.0'	1.5										
Entrance weir W1	0	depth (≥ 8')	10.1										
Entrance weir W2	0	depth (≥ 8')	10.1										
Entrance weir W3	0	No criteria	Closed										
South entrance differential	0	1.0' - 2.0'	1.5										
Entrance weir S1	0	depth (≥ 8')	8.5										
Entrance weir S2	0	depth (≥ 8')	8.5										
			JUVENI	LE PASSAGE									
Sluicegate operation	0	Units 1, 8, 18											
Turbine trashrack drawdown	0												
spill													
off													
Turbine Unit Priority	4	per FPP	MU's 3, 15, an	d 16 OOS									
Turbine 1% Efficiency	0	per FPP											

Birds/Sea lions:

No sea lions observed. Primarily non-foraging cormorants on site.

Bird observation data collected once daily. Refer to Avian Zone map and bird count.

Two of 13 spillway avian lines broke closest to bridge. Awaiting USDA cost estimate.

Operations:

Calibration 11/11, some discrepancies found, TDE notified

Analyzing fish counts from Oct 13 powerhouse outage.

Current Outages;

T8 (MU15 & MU16) forced out due to transformer failure. Return unknown.

MU3 forced out of service through 8/4/2016 due to loss of governor sump oil level

MU21 out for exciter failure RTS unknown

Maintenance:

New east exit weir electrical panel FCQ7 installation ~50% complete. Work to continue with available FY17 funding.

Planning underway for winter dewater season, East ladder out Dec 1 through end Feb for AWS backup construction. North ladder out Jan 3 - 17.

Dewater pumps and bulkheads ready for fishladder dewatering.

Planned winter work; west entrance weir and lift beam rehab, east count station brush replace, vegetation removal and routine PMs.

Long Term repair maintenance plans; 154 -157 weir wheel replace, collection channel diffusers decommission, repair failed diffusers - all awaiting funding Fish related /non-fish funded items; Spillway crane rehab priority over spillgate 9, both awaiting funding.

All spillway items on Critical Infrastructure list and Unfunded Requirement list.

Studies/Construction:

Environmental acceptable grease testing on unit 1 continues. MOC coordinated through FPOM.

North fishladder rehab/rock wall stabilizing - Awaiting funding.

East fishladder emergency backup - Prefab continues on north staging area. Exploratory digging and utility relocate underway.

Railroad track removal - Start in water work period 2016/17. Crane rail replacement postponed to 2021.

Tailrace crane rehab - Work resumed. Completion Dec.

Fish unit breaker replace.- Work start fall 2017. Switch over Jan 2018.

Transformer replacement - Install start May 2018. Expect 4 months per transformer bank. Reviewing sequence for least risk to fish passage.

N Wasco Co PUD Memo of Agreement - Reviewing for final.

Fish unit rehab - Award planned for 2020. Completion 2022.

Fish unit breaker replacement - Start in water work period 2017/18


Lamprey minor mods - Rounded weir caps planned for all entrances 2018. Fab and install with project labor. Planning meeting Dec 12.

Research/Contractors:

Fish counting and dam angling done for season.

Approved by: Ron Twiner


Operation Project Manager The Dalles Dam





2016 Piscivorous Bird Counts

F=foraging, NF=non-foraging

Date	Observer	er AM/PM Z	Zone	G	ull	Corm	orant	Caspi	an tern	Gre	ebe	Pel	ican	Other		Total birds in	Notes
Date	Observer		Zone	F	NF	F	NF	F	NF	F	NF	F	NF	F	NF	zone	Notes
			FB	0	34	0	0	0	0	0	26	0	0	0	0	60	
			PH1	0	0	0	4	0	0	0	0	0	0	0	23	27	22 COME, 1 GBHE
			PH2	7	0	0	0	0	0	0	0	0	0	0	0	7	
1/6/16	JWR	PM	SW1	0	18	0	0	0	0	0	0	0	0	0	0	18	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	53	0	75	0	0	0	0	0	0	0	0	128	
			SW4	0	4	0	29	0	0	0	0	0	1	0	0	34	
			FB PH1	0	0	2	0	0	0	2	33	0	0	0	0	37	00145
			PH1 PH2	0	0	0	42 0	0	0	0	0	0	0	0	43 0	85 0	COME
1/7/16	JWR	AM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
1/1/10	SVVIC	Aivi	SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	1	0	56	0	0	0	0	0	0	0	0	57	
			SW4	0	0	0	4	0	0	0	0	0	0	0	0	4	
			FB	0	0	7	0	0	0	0	19	0	0	0	3	29	2 BAEA, GBHE
			PH1	0	1	10	31	0	0	0	0	0	0	9	25	76	33 COME, 1 GBHE
			PH2	0	0	3	0	0	0	0	0	0	0	0	0	3	00 002, 1 022
1/8/16	GJF	PM	SW1	0	5	2	0	0	0	0	0	0	0	0	0	7	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	3	0	16	0	0	0	0	0	0	0	0	19	
			SW4	0	0	3	15	0	0	0	0	0	0	0	1	19	GBHE
			FB	0	10	0	0	0	0	0	25	0	0	0	0	35	
			PH1	0	0	0	27	0	0	0	0	0	0	0	18	45	COME
			PH2	0	0	0	0	0	0	0	0	0	0	0	0	0	
1/9/16	JWR	AM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	0	0	37	0	0	0	0	0	0	0	0	37	
		PM	SW4	0	0	0	0	0	0	0	0	0	0	0	0	0	
			FB	0	165	0	0	0	0	0	0	0	0	0	0	165	
			PH1	0	0	0	23	0	0	0	0	0	0	0	60	83	COME
1/10/16	JWR		PH2 SW1	5	0 72	0	0	0	0	0	0	0	0	0	0	5	
1/10/10	JVVIX		SW1	0	0	1	0	0	0	0	0	0	0	0	0	72	
			SW3	0	27	6	46	0	0	0	0	0	0	0	0	79	
			SW4	0	1	0	5	0	0	0	0	0	0	0	0	6	
			FB	0	0	1	0	0	0	0	4	0	0	0	0	5	
			PH1	0	0	2	26	0	0	0	0	0	0	0	61	89	COME
		WR AM	PH2	4	0	0	0	0	0	0	0	0	0	0	0	4	
/11/16	JWR		SW1	0	44	0	0	0	0	0	0	0	0	0	1	45	GBHE
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	51	0	95	0	0	0	0	0	0	0	0	146	
			SW4	0	0	0	7	0	0	0	0	0	1	0	1	9	GBHE
			FB	94	1	4	0	0	0	0	12	0	0	0	1	112	GBHE
			PH1	0	3	6	34	0	0	0	0	0	0	31	16	90	COME
			PH2	13	0	2	0	0	0	0	0	0	0	0	0	15	
/12/16	GJF	PM	SW1	0	4	0	0	0	0	0	0	0	0	0	1	5	GBHE
			SW2	0	0	2	0	0	0	0	0	0	0	0	0	2	
			SW3	0	4	1	54	0	0	0	0	0	0	0	0	59	
			SW4	0	37	0	22	0	0	0	0	0	0	0	0	59	
	daily ave	erages		2.5	11.0	1.1	13.2	0.0	0.0	0.0	2.4	0.0	0.0	0.8	5.2	36.3	







	. =
Temperatures	
56.6	
56.5	
56.5	

56.5

56.4

56.2

56.4

Sun

Mon

Tue

Wed

Thurs

Fri

Sat

AVG

Secchi: 5.0

5.0

5.0

5.0

4.0

4.0

4.6

10/23 10/24

10/25

10/26

10/27

10/29


USGS: Nov - http://www.nwd-wc.usace.army.mil/tmt/documents/ops/temp/201611.lcol.html

The Dalles Dam Daily Readings and Averages for Temperatures, Secchi, Entrances, and Spill

= Out of criteria

	North I	Ladder	East Ladder													
	North E	North Entrance			East Entrance	ı			West E	ntrance		;	South Entrance	9		
Date:	Differential	N1 Depth	Differential	E1 Depth	E2 Depth	E3 Depth	JP 6	Differential	W1 Depth	W2 Depth	W3 Depth	Differential	S1 Depth	S2 Depth		
			1.2	0.1	12.5	12.5	9.4	1.1	10.4	10.4		1.4	8.6	8.6		
11/6	1.2	9.2	1.5	0.0	12.0	12.0	10.2	1.5	10.0	10.0		1.5	8.3	8.3		
	1.3	9.2	1.5	0.0	12.3	12.3	10.3	1.5	10.0	10.0		1.5	8.3	8.3		
			1.5	0.1	12.4	12.4	10.3	1.5	10.0	10.0		1.5	8.3	8.3		
11/7	1.3	9.2	1.5	0.0	12.7	12.7	11.0	1.5	10.1	10.1		1.5	8.5	8.5		
	1.4	9.3	1.4	0.0	12.7	12.7	11.2	1.7	9.9	9.9		1.5	8.6	8.6		
			1.2	0.2	13.1	13.2	10.3	1.4	10.2	10.2		1.3	8.8	8.8	S	
11/8	1.2	9.2	1.4	0.0	12.3	12.3	10.0	1.5	10.0	10.0		1.4	8.8	8.8	P	
	1.2	9.1	1.6	0.0	11.7	11.7	9.7	1.5	10.1	10.1		1.5	8.4	8.3	i	
			1.4	0.0	11.8	11.8	8.7	1.2	9.9	9.9		1.4	8.4	8.3	L	
11/9	1.3	9.2	1.6	0.0	12.2	12.2	10.1	1.5	10.1	10.1		1.4	8.6	8.6	L	
	1.5	9.2	1.3	0.0	12.8	12.8	10.7	1.5	10.1	10.1		1.5	8.5	8.5		
			1.3	0.0	12.5	12.5	9.7	1.4	10.1	10.1		1.4	8.5	8.5	O F	
11/10	1.4	9.1	1.7	0.0	12.2	12.3	11.3	1.6	10.1	10.1		1.6	8.6	8.5	F	
	1.3	9.2	1.7	0.0	12.2	12.3	10.7	1.6	10.1	10.1		1.6	8.5	8.4	'	
			2.0	0.0	12.2	12.3	10.6	1.6	10.3	10.3		1.4	8.6	8.6		
11/11	1.4	9.2	1.6	0.0	13.0	13.0	11.4	1.6	10.3	10.3		1.5	8.6	8.6		
	1.4	9.2	1.5	0.0	13.1	13.1	11.3	1.6	10.2	10.2		1.5	8.6	8.6		
			1.3	0.0	13.2	13.2	10.9	1.4	10.4	10.4		1.4	8.7	8.6		
11/12	1.5	9.1	1.5	0.0	13.0	12.9	10.9	1.5	10.2	10.2		1.5	8.5	8.5		
	1.4	9.1	1.4	0.0	13.0	13.0	11.2	1.6	10.3	10.3		1.5	8.5	8.4		
AVG:	1.3	9.2	1.5	0.0	12.5	12.5	10.5	1.5	10.1	10.1		1.5	8.5	8.5		

Fishways are inspected twice daily plus one SCADA inspection.



Rerouting water an sewer lines for EFL AWS 10' hole.