# The Dalles Dam Fishway Status Report

## 1/8/2017

Inspection Period: 01/07/2017 - 01/07/2017





		Fishwa	ays are inspected once daily during winter						
The Dalles Dam	Inspections	Criteria	Total Number of Inspections: 7 Temperature: 39.5 °F						
The Dalles Dam	Out of Criteria	Limit	Comments: Fall like conditions on project Secchi: 5.0 feet						
			NORTH FISHWAY						
Exit differential	0	≤ 0.5'							
Count station differential	0	≤ 0.3'							
Weir crest depth	0	1.0' ± 0.1'							
Entrance differential	0	1.0' - 2.0'	Out for winter maintenance						
Entrance weir N1	0	depth (≥ 8')							
Entrance weir N2	0	Closed							
PUD Intake differential	0	≤ 0.5′							
			EAST FISHWAY						
Exit differential		≤ 0.5'							
Removable weirs 154-157		Per forebay							
Weir 158-159 differential		1.0' ± 0.1'							
Count station differential		≤ 0.3'							
Weir crest depth		1.0' ± 0.1'							
Junction pool weir JP6		depth (≥ 7')							
East entrance differential		1.0' - 2.0'							
Entrance weir E1		No criteria							
Entrance weir E2		depth (≥ 8')							
Entrance weir E3		depth (≥ 8')	Out for winter maintenance and						
Collection channel velocity		1.5 - 4 fps							
Transportation channel velocity		1.5 - 4 fps	AWS backup construction						
North channel velocity		1.5 - 4 fps	71110 backap construction						
South channel velocity		1.5 - 4 fps							
West entrance differential		1.0' - 2.0'							
Entrance weir W1		depth (≥ 8')							
Entrance weir W2		depth (≥ 8')							
Entrance weir W3		No criteria							
South entrance differential		1.0' - 2.0'							
Entrance weir S1	S1 depth (≥ 8')								
Entrance weir S2									
			JUVENILE PASSAGE						
Sluicegate operation	NA	Units 1, 18	Closed. Reopens Mar1 for fish passage						
Turbine trashrack drawdown	NA								
spill	NA								
Turbine 1% Efficiency	NA	per FPP	Out of fish passage season						
Turbine Unit Priority	NA	per FPP	Out of fish passage season						



#### Birds/Sea lions:

No sea lions observed. High numbers of Cormorants. High Bald Eagle numbers in westrick park.

Bird observation data collected once daily. Refer to Avian Zone map and bird count.

Two of 13 spillway avian lines broke closest to bridge. Work plan and hazing contract routed for approvals.

#### **Operations:**

North fishladder dewatered Jan 4. Entrance below tailwater attempted Jan 5 but postponed due to low temperatures and ice coverage. (refer to pic tab)

#### Current Outages;

T8 (MU15 & MU16) forced out due to transformer failure. Return unknown.

MU21 out for exciter failure RTS unknown

#### Maintenance:

New east exit weir electrical panel FCQ7 installation to continue as funding allows.

East ladder dewatered Dec 1 through end Feb for AWS backup construction. North ladder dewatering Jan 4 - 17.

Winter work in progress; East exit weirs 154 and 159 coupler/seal replacement, ladder expansion joint repair, N1 weir rehab, W1 weir repair/wheel replace.

Long Term repair maintenance plans; 154 -157 rehab/weir wheel replace, collection channel diffusers decommission, repair failed diffusers.

Fish related /non-fish funded items; Spillway crane and spillgate 9, both awaiting funding.

All spillway items on Critical Infrastructure list and Unfunded Requirement list.

#### Research/Construction:

Unit 1 EAL environmental acceptable grease - Coordinated and approved through FPOM.

North fishladder rehab/rock wall stabilizing - Awaiting funding. Possible 2018/19.

East fishladder AWS emergency backup - Forebay diving underway. Scaffold and work platform in junction pool. Junction pool concrete east side removed. Jackhammering of hole resumed. Forebay slot cutting via dive for peirs underway.

Railroad track removal - Mobilizing for work start this winter. MOC under development for work over sluiceway next spring. Crane rail replacement 2021.

Tailrace crane rehab - Work resumed. Completion some day.

Fish unit breaker replace.- Work start fall 2017. Switch over Jan 2018.

Fish unit rehab - Award planned for 2020. Completion 2022.

Transformer replacement - Install start May 2018. Sequence being reviewed for least fish passage risk. MOC to be provided to FPOM.

N Wasco Co PUD Memo of Agreement - Reviewing final comments.


Lamprey minor mods - East tribal trap hoist improvements design underway. Rounded entrance weir caps design underway, planned fab '17, install '17/'18.

### Research/Contractors:

Kiewit on site for east fishladder AWS backup. Monitoring work progress. Refer to Pic tabs.

Approved by: Ron Twiner

Operation Project Manager The Dalles Dam




Red lines = avian zones


Yellow lines = current wires

Orange lines = down or missing wires

## 2016 Piscivorous Bird Counts


F=foraging, NF=non-foraging																	
Date	Observer	AM/PM	Zone -	Gull		Cormorant		Caspian tern		Grebe		Pelican		Other		Total birds	Notes
				F	NF	F	NF	F	NF	F	NF	F	NF	F	NF	in zone	
			FB	0	12	8	0	0	0	5	0	0	0	0	2	27	BAEA
			PH1	7	0	4	0	0	0	0	0	0	0	5	0	16	COME
1/1/17			PH2	5	0	0	0	0	0	0	0	0	0	0	39	44	BAEA
	GJF	PM	SW1	0	27	0	0	0	0	0	0	0	0	0	0	27	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	3	0	88	0	0	0	0	0	0	0	0	91	
			SW4	0	0	0	0	0	0	0	0	0	0	0	0	0	DAFA
			FB	0	74	11	2	0	0	0	6	0	0	0	3	96	BAEA
			PH1	3	0	0	0	0	0	0	0	0	0	7	0 47	14	COME BAEA
1/2/17	GJF	AM	PH2	2				0	0	0	0	0	0	0		49	BAEA
1/2/17	GJF	Alvi	SW1 SW2	0	19	2	0	0	0	0	0	0	0	0	0	21 5	
		-	SW2 SW3	0	2	0	0 154	0	0	0	0	0	0	0	5	161	BAEA
			SW4	0	0	0	2	0	0	0	0	0	0	0	0	2	DAEA
			FB	0	4	7	0	0	0	0	3	0	0	0	7	21	BAEA
			PH1	2	0	0	0	0	0	0	0	0	0	0	0	2	BALA
			PH2	2	0	0	0	0	0	0	0	0	0	0	51	53	BAEA
1/3/17	GJF	PM	SW1	0	2	0	0	0	0	0	0	0	0	0	0	2	BALA
170717	001		SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	0	0	133	0	0	0	0	0	0	0	0	133	
			SW4	0	0	0	0	0	0	0	0	0	0	0	0	0	
		+	FB	0	0	8	0	0	0	0	0	0	0	0	0	8	
			PH1	0	0	1	1	0	0	0	0	0	0	0	0	2	
			PH2	0	0	0	0	0	0	0	0	0	0	1	43	44	
1/4/17	JWR	AM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
	-		SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	3	0	63	0	0	0	0	0	0	0	2	68	1 BAEA, 1 GBHE
			SW4	0	0	0	0	0	0	0	0	0	0	0	1	1	BAEA
		PM -	FB	0	1	10	0	0	0	0	0	0	0	0	4	15	BAEA
			PH1	0	0	1	2	0	0	0	0	0	0	0	2	5	COME
1/5/17			PH2	0	0	0	0	0	0	0	0	0	0	0	59	59	56 BAEA, 3 GBHE
	JWR		SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	0	0	92	0	0	0	0	0	0	0	3	95	BAEA
			SW4	0	0	0	0	0	0	0	0	0	0	0	2	2	BAEA
			FB	0	0	6	0	0	0	0	0	0	0	0	2	8	BAEA
			PH1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			PH2	0	0	0	0	0	0	0	0	0	0	0	0	0	
1/6/17	JWR	AM	AM SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	0	0	114	0	0	0	0	0	0	0	0	114	
			SW4	0	0	0	1	0	0	0	0	0	0	0	0	1	
			FB	0	1	0	101	0	0	0	0	0	0	0	1	103	BAEA
			PH1	0	0	0	0	0	0	0	0	0	0	0	0	0	
1/7/17	JWR	D14	PH2	0	0	0	0	0	0	0	0	0	0	0	0	0	
		PM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	18	0	145	0	0	0	0	0	0	0	0	163	D454
			SW4	0	0	0	0	0	0	0	0	0	0	0	1	1	BAEA
daily averages			0.4	3.4	1.3	18.3	0.0	0.0	0.1	0.2	0.0	0.0	0.3	5.6	29.7		







Too much ice coverage to dewater north fishway entrance below tailwater. Postponed. Would require ice fishing tactics for fish salvage.



Concrete sections removed from junction pool wall