The Dalles Dam Fishway Status Report

2/4/2017

Inspection Period: 02/26/2017 - 03/04/2017

THE DALLES DAM



Fishways are inspected once daily during winter Inspections Criteria Total Number of Inspections: 7 Temperature: 38.7 °F												
The Dalles Dam	Inspections	Criteria	Total Numl	°F								
The Dalles Dalli	Out of Criteria	Limit		Snow conditions subsided	S	ecchi:	3.3	feet				
				H FISHWAY								
Exit differential	0	≤ 0.5'	1.3									
Count station differential	0	≤ 0.3'										
Weir crest depth	0	1.0' ± 0.1'										
Entrance differential	0	1.0' - 2.0'										
Entrance weir N1	0	depth (≥ 8')	9.1									
Entrance weir N2	0	Closed										
PUD Intake differential	0	≤ 0.5'										
			EAST	FISHWAY								
Exit differential		≤ 0.5']									
Removable weirs 154-157		Per forebay										
Weir 158-159 differential		1.0' ± 0.1']									
Count station differential		≤ 0.3']									
Weir crest depth		1.0' ± 0.1'										
Junction pool weir JP6		depth (≥ 7')										
East entrance differential		1.0' - 2.0'										
Entrance weir E1		No criteria	0		! (1	414/0			
Entrance weir E2		depth (≥ 8')) Out i	for winter m	naınt	enan	ce	ana .	AWS			
Entrance weir E3		depth (≥ 8')] , ,	,		_			D.T.O.			
Collection channel velocity		1.5 - 4 fps	back	kup constru	ICtiOi	n. Ex	nec	cted	RIS			
Transportation channel velocity		1.5 - 4 fps]			,	,, ,					
North channel velocity		1.5 - 4 fps			03/0	7						
South channel velocity		1.5 - 4 fps				, ,						
West entrance differential		1.0' - 2.0'										
Entrance weir W1		depth (≥ 8')										
Entrance weir W2		depth (≥ 8')										
Entrance weir W3		No criteria										
South entrance differential		1.0' - 2.0']									
Entrance weir S1		depth (≥ 8')]									
Entrance weir S2		depth (≥ 8')										
				E PASSAGE								
Sluicegate operation	2	Units 1, 18	Uni	t 18 return late Mar 1. Del	layed gate	adjustment	from un	it 19 to uni	t 18.			
Turbine trashrack drawdown	NA											
spill	NA		Spill for high riv	er flows								
Turbine 1% Efficiency	NA	per FPP	Out of fish pass	<u> </u>								
Turbine Unit Priority	NA	per FPP	Out of fish pass	sage season	-							

Birds/Sea lions:

No sea lions observed. All bird numbers low.

Bird observation data collected once daily. Refer to Avian Zone map and bird count.

Spillway avian lines repair planned. Awaiting USDA signatures for work plan. USDA prework site tour occurred Mar1.

Operations:

North Fishway in full operation. East fishway return delayed to Mar 7 due to AWS contract delays.

Sluiceway intermittent operation in conjunction with Feb involuntary spill per Fish Passage Plan. Open for fish passage Mar 1.

Current Outages;

T8 (MU15 & MU16) out due to transformer failure. Transformer replacement scheduled for spring 2018.

MU21 out for exciter failure, return Feb23

MU3 out for governor oil level failure, return Feb24

Awaiting tailrace crane completion to resume turbine maintenance schedule. ETR end of March.

Maintenance:

Additional temperature monitoring probe being deployed at east junction pool and south entrance prior to water up

Rubber seal installed to bottom of east count station crowder for lamprey exclusion.

New east exit weir electrical panel FCQ7 installation on hold awaiting funding. Approx 50% completed.

Maintenance status; East exit weirs 154 and 159 coupler/seal replacement complete, ladder expansion joint repair complete

N1 weir rehab and spare swap complete, W1 weir repair/wheel replace complete/install after fishway returns.

Other repair maintenance plans; 154 -157 rehab/weir wheel replace, diffuser valve overhaul (rehab or decommission).

Fish related /non-fish funded items; Spillway crane and spillgate 9, both awaiting funding.

All spillway items on Critical Infrastructure list and Unfunded Requirement list.

Research/Construction/Contractors:

Lamprey minor mods - Tribal trap hoist improvements and rounded entrance weir caps designs underway. Fab in-house '17. Install next winter. North fishladder rehab/rock wall stabilizing - Awaiting funding. Possible 2018/19.

East fishladder AWS emergency backup - Forebay diving saw cutting continues. Junction pool 7' pipe valve room start. Demob junction pool scaffold.

Jackhammering hole complete season 1. Excavation 10' valve room to occur in March per FPOM approval. EFL outage extension FPOM approved Railroad track removal - West powerhouse tailrace deck ~100' track removed. Intake deck start west end. Crane rail replace 2021.

Tailrace crane rehab - Work resumed. Completion March?


Fish unit breaker replace.- Work start fall 2017. Switch over Jan 2018.

Fish unit rehab - Weekly coordination meetings. Phase 1A report Jan 2018. Award 2020. Completion 2022. Investigating possible increase flow capacity.

Transformer replacement - Install start May 2018. Coordinated through FPOM.

Approved by: Ron Twiner

Operation Project Manager The Dalles Dam



Red lines = avian zones

Yellow lines = current wires


Orange lines = down or missing wires


2017 Bird Counts

F=foraging, NF=non-foraging

D-4-	01	444/7044	M Zone	G	ull	Cormorant		Caspia	an tern	Gre	ebe	Peli	ican	Ot	her	Total birds	Notes
Date	Observer	AM/PM		F	NF	F	NF	F	NF	F	NF	F	NF	F	NF	in zone	
			FB	0	1	0	0	0	0	0	0	0	0	0	0	1	
			PH1	0	0	0	2	0	0	0	0	0	0	0	0	2	
2/26		D14	PH2	0	0	1	0	0	0	0	0	0	0	0	4	5	GBHE
2/26		PM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2 SW3	0	0	0	0 20	0	0	0	0	0	0	0	0	1 20	
			SW4	0	0	0	0	0	0	0	0	0	0	0	0	0	
			FB	0	1	1	0	0	0	0	0	0	0	0	0	2	
			PH1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			PH2	0	0	0	0	0	0	0	0	0	0	0	1	1	GBHE
2/27		AM	SW1	0	2	0	0	0	0	0	0	0	0	0	1	3	GBHE
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	0	0	5	0	0	0	0	0	0	0	0	5	
			SW4	0	0	0	0	0	0	0	0	0	0	0	0	0	
			FB	0	0	0	0	0	0	0	0	0	0	0	0	0	COME
			PH1 PH2	0	0	0	0	0	0	0	0	0	0	0	3	5	COME
2/28		PM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	GBHE
2/20		1 101	SW2	0	0	1	0	0	0	0	0	0	0	0	0	1	
			SW3	0	0	0	14	0	0	0	0	0	0	0	0	14	
			SW4	0	0	0	0	0	0	0	0	0	0	0	0	0	
			FB	0	0	0	0	0	0	0	0	0	0	0	0	0	
			PH1	0	0	0	1	0	0	0	0	0	0	1	0	2	COME
		AM	PH2	0	0	0	0	0	0	0	0	0	0	0	0	0	
3/1			SW1	0	0	0	1	0	0	0	0	0	0	0	0	1	
			SW2	0	0	2	0	0	0	0	0	0	0	0	0	2	
			SW3	0	0	1	31	0	0	0	0	0	0	0	0	32	
			SW4 FB	0	0	0	0	0	0	0	0	0	0	0	0	0	
			PH1	0	0	0	0	0	0	0	0	0	0	0	0	0	
		PH	PH2	0	0	0	0	0	0	0	0	0	0	0	0	0	
3/2			SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
-,			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	0	0	37	0	0	0	0	0	0	0	0	37	
			SW4	0	0	0	0	0	0	0	0	0	0	0	0	0	
			FB	0	0	0	0	0	0	0	0	0	0	0	1	1	BAEA
			PH1	0	0	0	0	0	0	0	0	0	0	0	0	0	
2/2		AM	PH2	0	0	0	0	0	0	0	0	0	0	0	0	0	
3/3		AIVI	SW1 SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	0	0	36	0	0	0	0	0	0	0	0	36	
			SW4	0	0	0	0	0	0	0	0	0	0	0	0	0	
			FB	0	0	0	0	0	0	0	0	0	0	0	1	1	
			PH1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			PH2	0	0	0	0	0	0	0	0	0	0	0	0	0	
3/4		PM	SW1	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW2	0	0	0	0	0	0	0	0	0	0	0	0	0	
			SW3	0	1	0	33	0	0	0	0	0	0	0	0	34	
			SW4	0	0	0	0	0	0	0	0	0	0	0	0	0	
	Average-	-week		0.0	0.1	0.2	3.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.3	4.2	

а





			USGS:
	Secchi:		Temperatures
2/26	4.0	Sun	38.2
2/27	4.0	Mon	38.2
2/28	4.0	Tue	38.4
3/1	3.0	Wed	38.7
3/2	2.5	Thurs	38.9
3/3	2.5	Fri	39.2
3/4	3.0	Sat	39.4
	3.3	AVG	38.7

http://www.nwd-wc.usace.army.mil/tmt/documents/ops/temp/201701.lcol.html

The Dalles Dam Daily Readings and Averages for

Temperatures, Secchi, Entrances, and Spill

= Out of criteria

	North	Ladder						East l	_adder						I
	North E	intrance			East Entrance)			West E	ntrance		8	South Entrance	е	
Date:	Differential	N1 Depth	Differential	E1 Depth	E2 Depth	E3 Depth	JP 6	Differential	W1 Depth	W2 Depth	W3 Depth	Differential	S1 Depth	S2 Depth	
2/26	1.4	9.5													
2/27	1.4	9.6													
2/28	1.4	9.5													
3/1	1.4	9.6				Fas	t Ladd	er OOS	for Ma	aintena	ance				
	1.5	9.7					c = a.a.a	c. 000			acc				
3/2	1.5	9.7													
	1.3	10.0													
3/3	1.3	9.9													
	1.3	9.9													
3/4	1.4	9.9													
	4.4	0.7													
	1.4	9.7													



Footing poured for 7' valve room



Damaged diffuser grating from contractor work platform replaced