

**U.S. ARMY CORPS OF ENGINEERS  
WALLA WALLA DISTRICT  
FISH FACILITIES WEEKLY REPORT  
#34-2017**

**Project: McNary**

Biologist: Bobby Johnson and Denise Griffith

Dates: October 13 – 19, 2017

---

**Turbine Operation**

General Comments: The hard 1% peak efficiency constraint continues.

Yes   No   Turbine Unit Status

- All 14 turbine units available for service throughout the week (see Table 1 for outage details below).  
      All turbine units operated within 1% peak efficiency constraint. Constraint in effect:  Hard  Soft.

Table 1. Unit Outages at McNary Project.

Units	Outage Dates	Outage Length	Reason
3	Oct 10 to Dec 8	60 days	9-year overhaul.
5 & 6	Oct 17	46 minutes total	Extended-length submersible bar screens (ESBSs) camera inspections.

**Adult Fish Passage Facilities**

General Comments: McNary fisheries biologists performed measured inspections of the adult fishways on October 13, 15 and 17. Visual fish counts continue.

Fish Ladder Exits:

Criteria met?

Yes   No   Location, Criteria and Measurements

- Oregon Exit (Criteria – Head over weir 1.0' to 1.3')  
      Oregon Count Station Differential (Criteria – Differential 0.0' to 0.5')  
      Washington Exit (Criteria – Head over weir 1.0' to 1.3')  
      Washington Count Station Differential (Criteria – Differential 0.0' to 0.5')

Comments: The trash racks and picketed leads were cleaned as needed, including weekends, at both exits.

Debris loads at the Washington exit and along the shoreline were minimal. The Regulating weir set point was adjusted on October 15.

At the Oregon exit and along the shoreline, debris loads were minimal to very light. The encoder for tilting weir 339 has not been replaced. This weir rarely moves and will be adjusted manually.

The exit traveling screens debris trough continued to be cleaned as needed.

Fishway Entrances and Collection Channel:

<u>Yes</u>	<u>No</u>	<u>Location, Criteria and Measurements</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	North Oregon Entrance Head Differential (Criteria – 1.0' to 2.0')
<input checked="" type="checkbox"/>	<input type="checkbox"/>	NFEW2 Weir Depth (Criteria – $\geq 8.0'$ )
<input checked="" type="checkbox"/>	<input type="checkbox"/>	NFEW3 Weir Depth (Criteria – $\geq 8.0'$ )
<input type="checkbox"/>	<input checked="" type="checkbox"/>	South Oregon Entrance Head Differential (Criteria – 1.0' to 2.0'): 2.1' on October 13.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	SFEW1 Weir Depth (Criteria – $\geq 8.0'$ )
<input checked="" type="checkbox"/>	<input type="checkbox"/>	SFEW2 Weir Depth (Criteria – $\geq 8.0'$ )
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon Collection Channel Velocities (Criteria –1.5 to 4.0 fps): Averaged 1.9 fps.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Washington Entrance Head Differential (Criteria – 1.0' to 2.0')
<input checked="" type="checkbox"/>	<input type="checkbox"/>	WFE2 Weir Depth (Criteria – $\geq 8.0'$ )
<input checked="" type="checkbox"/>	<input type="checkbox"/>	WFE3 Weir Depth (Criteria – $\geq 8.0'$ )

Comments: The south entrance pool head differential was out of criterion on October 13. This appears to have occurred due to improved ladder flow conditions. The operators adjusted the fish pumps blade angles down about half a degree that day. On October 15, the biologist requested all operational Oregon ladder entrance weirs set points be lowered by approximately one tenth of an inch.

Auxiliary Water Supply System:

<u>Yes</u>	<u>No</u>	<u>In Service?</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Washington shore Wasco County PUD Turbine Unit.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Washington shore Wasco PUD Bypass. Service was not required.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon Ladder Fish Pump 1: Blade angle was approximately 23 degrees.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon Ladder Fish Pump 2: Blade angle was approximately 22 degrees.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon Ladder Fish Pump 3: Blade angle was approximately 23 degrees.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon North Powerhouse Pool supply from juvenile fishway.

Comments: There are no problems to report.

**Juvenile Fish Passage Facility**

General Comments: Fall primary bypass season continues. Light maintenance, preparations for the winter work list, cleaning and partial winterization has begun at the facility and in the collection channel.

Forebay Debris/Gatewell Debris/Oil:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Forebay debris load acceptable?
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Trash rack differentials measured? If so, were differentials acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Any debris seen in gatewells?
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Any oil seen in gatewells?

Comments: Forebay debris loads near the powerhouse were moderate to heavy. Debris loads at the spillway were minimal. New incoming debris loads were minimal. No trash racks were cleaned.

ESBSs/Vertical barrier screen (VBSs):

- | <u>Yes</u>                          | <u>No</u>                | <u>Item</u>  |
|-------------------------------------|--------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | ESBSs deployed in all slots?   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | ESBSs inspected this week? If so, were results acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A            |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | VBSs differentials checked this week? If so, were results acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |

Comments: The brush cycles for the screens in 1A, 1B, 3B, 7B, 8C, 12B, 13A slots, units 11 and 14 remained in timer mode. The ESBS brushes on the screens in 1B and 13A slots appear to be cycling more frequently than the brushes on the ESBSs in adjacent slots. On October 17, an electrician examined the brush control program and continues to look for an issue. ESBS camera inspections occurred on October 17. No problems were found. We were able to examine the screens even with the camera having limited pan and tilt functions.

VBS differential monitoring continued. No high differential measurements were recorded. Five screens total were cleaned on October 13 and 19. No mortalities were observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

- | <u>Yes</u>                          | <u>No</u>                | <u>Item</u>   |
|-------------------------------------|--------------------------|---|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Orifices operating satisfactory? 42 orifices were open. |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Dewatering and cleaning systems operating satisfactory? |

Comments: Orifices were adjusted as required for VBS cleaning. We continued to operate the transition screen cleaning brush manually to insure it completes a full cleaning cycle.

On October 19, from 0733 to 0747 hours, as part of the station service upgrades, the collection channel was without power. The outage resulted in no adverse effects.

Bypass Facility:

- | <u>Yes</u>               | <u>No</u>                           | <u>Item</u>   |
|--------------------------|-------------------------------------|---|
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | Sample gates on? Fall bypass season continues.                                    |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | Passive integrated transponder (PIT) tag system on? Fall bypass season continues. |

Comments: During the fall primary bypass season, PIT tag detection occurs in the full flow pipe. All systems remain out of service. Light maintenance, cleaning and partial winterization continues.

The fisheries staff is exploring alternatives to improve smolt delivery to the wet lab for gas bubble trauma (GBT) examinations.

**River Conditions**

General Comments: River conditions were provided by the control room and outlined in Table 2 below. The data period runs from 0000 to 2400 hours each day. Flows and spill are recorded in one-thousand cubic feet per second (kcfs). Temperatures are recorded in degrees F.

Table 2. River Conditions at McNary Dam.

Daily Average River Flow		Daily Average Spill		Water Temperature		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
94.4	73.3	0.0	0.0	60.0	58.0	6.0	5.8

Comments: There are no problems to report. Scheduled spillbay hoist maintenance continues.

## **Other**

Inline Cooling Water Strainers: Regional discussion and agreement have moved the next cooling water strainer examinations to December.

Invasive Species: The next mussel station examinations will occur in early November.

Avian Activity: Avian counts concluded on September 30. Casual observations continue while doing other inspections. Overall, gull and cormorant numbers appear to be fluctuating with the juvenile shad outmigration. A large number of gulls were roosting on project inside and outside of the counting zones in multiple locations. Gulls and cormorants were feeding at the bypass outfall. Gulls were also feeding in the powerhouse flow. The birds in the spillway zone are roosting on the navigation lock wing wall and other structures. Terns and pelicans were not observed.

In the forebay zone, an occasional gull, gull flock, cormorant, egret, grebe or blue heron was observed. A few gulls were occasionally observed on the rocks by the Washington shore boat dock.

Fish Salvage/Rescue: None occurred.

## **Research**

Item: No onsite research is occurring at this time.

**Project: Ice Harbor**

Biologist: Ken Fone

Dates: October 13 – October 19, 2017

---

**Turbine Operation**

Yes No Turbine Unit Status

- All 6 turbine units available for service throughout the week (see comments below for outage details).
- Available turbine units operated within 1% peak efficiency constraint. Constraint in effect:  Hard  Soft.

Comments: Unit 2 was taken out of service on April 25, 2016, at 0606 hours for the runner replacement. Unit 4 was removed from service at 1218 hours on March 6, 2017, when it tripped off due to a problem in the 115 kv section 2 bus. That problem was fixed. The unit 4 hub oil drain valve was replaced to address an oil leak. Annual maintenance is now being performed on the unit. Unit 6 was out of service from 0950 hours on September 5 to 1342 hours on October 18 for annual maintenance. Units 1, 3, and 5 were removed from service one at a time on October 17 for STS inspections.

Unit 3 was noted to be operating a few megawatts below the 1% peak operating efficiency range on the fishway inspections. This was due to the GDACS program needing to be updated with the narrower operating efficiency range of unit 3 since it became a fixed-blade unit.

**Adult Fish Passage Facilities**

Fish facility personnel inspected the adult fishways on October 16, 17, and 19.

Fish Ladders:

Yes No Location, Criteria and Measurements

- North Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')
- North Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.3')
- North Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')
- South Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')
- South Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.3')
- South Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')

Comments: None.

Fishway Entrances and Collection Channel:

Yes No Sill Location, Criteria and Measurements

- South Shore Entrance (SFE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- South Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- South Shore Channel Velocity (Criteria: 1.5 – 4.0 fps)
- North Powerhouse Entrance (NFE-2) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- North Powerhouse Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- North Shore Entrance (NSE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- North Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')

Comments: NSE-1 weir depth was out of criteria on October 16, with a depth of 7.2' while the weir gate was not on sill. This was partly due to the electronic readout of the north shore tailwater elevation being out of calibration. This has been reported to the electricians for calibration.

Auxiliary Water Supply (AWS) System:

Yes   No   In Service and Operating Satisfactory?

- South Shore AWS Pumps. Six of the eight south shore AWS pumps were in service.  
      North Shore AWS Pumps. Two of the three north shore AWS pumps were in service.

Comments: None.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

Yes   No   Item

- Forebay debris load acceptable? An average of 87 square yards of debris was observed.  
      Trash rack differentials measured this week? If so, were differentials acceptable?  Yes  No  N/A  
      Any debris seen in gatewells (i.e: over 10% coverage)? Surface coverage ranged from 0% to 30%.  
      Any oil seen in gatewells?

Comments: None.

STSS/VBSs:

Yes   No   Item

- STSS deployed in all slots and in service?  
      STSS in continuous-run mode (If not, then STSS are in cycle-run mode)?  
      STSS inspected this week? If so, were results acceptable?  Yes  No  N/A  
      VBSs differentials checked this week? If so, were results acceptable?  Yes  No  N/A

Comments: STSS are in cycle-run mode. Unit 2 STSS are not installed since the unit will not be returned to service this year. Unit 1, 3, and 5 STSS were inspected on October 17.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

Yes   No   Item

- Orifices operating satisfactory? How many are open and in service? 20.  
      Dewaterer and cleaning systems operating satisfactory?

Comments: None.

Juvenile Fish Facility: The fish facility is in bypass operation.

Fish Sampling: Sampling is done for the year.

Removable Spillway Weir (RSW): Voluntary spill for fish passage is done for the season.

**River Conditions**

River conditions during the week are outlined in Table 1 below.

Table 1. River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
24.0	15.4	0	0	60	59	7.5	6.7

\*Unit 1 scroll case temperature.

### Other

Inline Cooling Water Strainers: Turbine cooling water strainer inspections for lamprey are no longer required from July to November.

Invasive Species: No exotic species that are new to the area have been found.

Avian Activity: There were low numbers of piscivorous birds around the project, with most of them observed roosting on Eagle Island.

Research: No on-site research is occurring at this time.

**Project: Lower Monumental**

Biologists: Chuck Barnes and Raymond Addis

Dates: October 13 - 19, 2017

---

**Turbine Operation**

Yes No Turbine Unit Status

- All 6 turbine units available for service throughout the week (see comments below for outage details).  
  Available turbine units operated within 1% peak efficiency constraint.

Constraint in effect:  Hard  Soft. Hard constraint began at 0000 hour on April 1.

Comments: Unit 1 was removed from service on December 10, 2014 for Unit Rehabilitation with an estimated return to service date of May 31, 2018. Unit 5 was removed from service on January 17, 2017 due to a turbine oil leak with an estimated return to service of June 30, 2018. Unit 6 was removed from service at 1545 on October 4 due to an issue with the STS hanging over gatewell 6A. Estimated return to service for Unit 6 is October 24, 2017. Unit 4 was removed from service at 0701 and returned to service at 1617 on October 16 for a D/S waterway survey. Unit 3 was removed from service at 0845 on October 20 for a digital governor installation with an estimated return to service of December 7, 2017.

**Adult Fish Passage Facility**

The adult fishway was inspected by Corps and Anchor QEA biologists on October 14, 15 and 17.

Fish Ladders:

Yes No Location, Criteria and Measurements

- North Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')  
  North Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.4')  
  North Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')  
  South Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')  
  South Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.3')  
  South Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')

Comments: None.

Fishway Entrances and Collection Channel:

Yes No Sill Location, Criteria and Measurements

- North Shore Entrance (NSE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)  
   North Shore Entrance (NSE-2) Weir Depth (Criteria:  $\geq$  8.0' or on sill)  
   North Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')  
   South Powerhouse Entrance (SPE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)  
   South Powerhouse Entrance (SPE-2) Weir Depth (Criteria:  $\geq$  8.0' or on sill)  
   South Powerhouse Entrance Channel/Tailwater Differential (Criteria: 1.0' – 2.0')  
   South Shore Entrance (SSE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)  
   South Shore Entrance (SSE-2) Weir Depth (Criteria:  $\geq$  6.0' or on sill)  
   South Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')



Comments: South Powerhouse Entrance weirs (SPE-1 and SPE-2) were on sill during all inspections. While on sill readings for both were 6.9, 7.1 and 7.3 feet.  
South Shore Entrance (SSE-1) was on sill during the October 14 inspection with a reading of 7.8 feet.

Auxiliary Water Supply System:

<u>Yes</u>	<u>No</u>	<u>In Service and Operating Satisfactory?</u>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	AWS Fish Pump 1.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	AWS Fish Pump 2.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	AWS Fish Pump 3.

Comments: Pump 1 will be out of service throughout this season unless an emergency occurs.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Forebay debris load acceptable? An average of 8 square yards of debris observed in forebay.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Trash rack differentials measured this week? If so, were differentials acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Any debris seen in gatewells?
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Any oil seen in gatewells?

Comments: Gatewell ranged from 0 to 50% during inspections. Gatewell 3A had 50 % debris coverage during the October 15 inspections. Debris was dipped from the gatewells on October 16.

STSS/VBSs:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	STSS deployed in all slots and in service?
<input type="checkbox"/>	<input checked="" type="checkbox"/>	STSS in continuous-run mode (Note: if not, then STSS are in cycle-run mode)?
<input type="checkbox"/>	<input checked="" type="checkbox"/>	STSS inspected this week? If so, were results acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
<input type="checkbox"/>	<input checked="" type="checkbox"/>	VBSs differentials checked this week? If so, were results acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A

Comments: STS's were operating on cycle mode due to CH0 lengths being over the 120 mm criteria point.

Orifices, Collection Channel, Dewatering Structure, and Flume:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Orifices operating satisfactory? How many are open and in service? 18.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Dewaterer and cleaning systems operating satisfactory?

Comments: Orifice checks were conducted every six hours during this reporting period.

Collection Facility: Collection for transport ended at 0700 on October 1, at which time the facility was placed into primary bypass. The collection facility was dewatered on October 11.

Transport Summary: Transport season ended on October 1.

## River Conditions

General Comments.

Table 1. River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
21.3	16.9	0	0	59.0	58.0	5.6	5.4

\*Scrollcase temperatures.

Spill: The RSW spill was closed on August 18. Summer spill ended at 0000 on September 1.

### Other

Inline Cooling Water Strainers: Cooling water strainers were inspected on August 16. There were zero live fish. Mortalities included 14 Siberian prawns and 13 YOY American shad.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on October 1.

Avian Activity: Gulls and cormorants were the predominant piscivorous bird species observed during fish ladder inspections this week.

Table 2. Tailrace counts of foraging piscivorous birds at Lower Monumental Dam.

Date	Time	Gulls	Cormorants	Terns	Grebes	Pelicans

Tailrace counts ended on July 13.

Outfall pipe bird water cannons were shut down and dewatered on October 12.

Research: No onsite research is in progress at this time.

**Project: Little Goose**

Biologists: Scott St. John & Richard Weis

Dates: October 13-19, 2017

---

**Turbine Operation**

Yes No Turbine Unit Status

- All 6 turbine units available for service throughout the week (see Table 1 for outage details).
- Available turbine units operated within 1% peak efficiency constraint. Constraint in effect:  Hard  Soft.

Table 1. Little Goose Unit Outages

Unit	OOS Date	OOS Time	RTS Date	RTS Time	Outage Description
2	10-Oct	07:20	27-Oct	17:00	Unit Annual
4	16-Oct	14:11	20-Oct	16:05	Wicket Gate Packing Repair
5	14-Apr	14:11	28-Feb	17:00	Upper Guide Bearing Repair

Comments: None.

**Adult Fish Passage Facility**

The adult fishway was inspected by Corps biologists and Anchor QEA staff on October 15, 16, and 19.

Fish Ladder:

Yes No Location, Criteria and Measurements

- Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')
- Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.3')
- Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')
- Emergency Ladder Exit Cooling Water Pumps in Service
- Emergency Ladder Exit Cooling Water Pumps Operating Satisfactorily.

Comments: Emergency cooling pump permanent power is scheduled to be installed during the winter maintenance outage.

Fishway Entrances and Collection Channel:

Yes No Sill Location, Criteria and Measurements

- South Shore Entrance (SSE-1) Weir Depth (Criteria:  $\geq$  8.0')
- South Shore Entrance (SSE-2) Weir Depth (Criteria:  $\geq$  8.0')
- South Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- North Powerhouse Entrance (NPE-1) Weir Depth (Criteria:  $\geq$  7.0' or on sill)
- North Powerhouse Entrance (NPE-2) Weir Depth (Criteria:  $\geq$  7.0' or on sill)
- North Powerhouse Entrance Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- North Shore Entrance (NSE-1) Weir Depth (Criteria:  $\geq$  6.0' or on sill)
- North Shore Entrance (NSE-2) Weir Depth (Criteria:  $\geq$  6.0' or on sill)
- North Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- Collection Channel Surface Velocity (Criteria: 1.5 – 4.0 fps)

Comments: None.

Auxiliary Water Supply System:

<u>Yes</u>	<u>No</u>	<u>In Service and Operating Satisfactory?</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	AWS Fish Pump 1 (operating).
<input checked="" type="checkbox"/>	<input type="checkbox"/>	AWS Fish Pump 2 (operating).
<input checked="" type="checkbox"/>	<input type="checkbox"/>	AWS Fish Pump 3 (operating).

Comments: None.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Forebay debris load acceptable.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Trash rack differentials measured this week? If so, were differentials acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Any debris seen in gatewells (i.e: over 10% coverage)?
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Any oil seen in gatewells?

Comments: There is an estimated 5,000 square feet of floating woody debris in the immediate forebay. Trash rack differentials were measured on October 19 and were in criteria.

Spillway Weir: Temporary spillway weir was closed for the season on July 19 at 09:00.

ESBS/VBS:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	ESBSs deployed in all slots and in service?
<input type="checkbox"/>	<input checked="" type="checkbox"/>	ESBSs inspected this week? If so, were results acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
<input checked="" type="checkbox"/>	<input type="checkbox"/>	VBSs differentials checked this week? If so, were results acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A

Comments: VBS differentials were measured on October 19 and were in criteria.

Orifices, Collection Channel, Dewatering Structure, and Flume:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Orifices operating satisfactory? How many are open and in service? <u>19 open.</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Dewaterer and cleaning systems operating satisfactory? N/A

Comment: Orifices and primary dewatering structure are being back flushed every 8 hours.

Collection Facility: Juvenile Fish Facility is currently operating.

Transport Summary: The collection and transportation facility operated in criteria this report period. A total of 1,395 fish were collected and 1,594 were transported during this report period. Fish transported includes fish collected on October 12. The descaling and mortality rates were 2.5% and 0.8% respectively. This weekly report period saw 3 adult lamprey removed from the raceways or sample and released one mile above the Dam at Little Goose Landing.

## River Conditions

River conditions during the week are outlined in Table 2 below.

Table 2. River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
20.8	17.1	0	0	60.2	59.3	5.4	5.1

\*Ladder temperature.

Comment: Spill ended at midnight August 31.

## Other

Inline Cooling Water Strainers: Cooling water strainers will be inspected again starting in December.

Invasive Species: No invasive species have been observed on the mussel station.

Avian Activity: USDA bird hazing ended on June 25. See table 3 for USACE counts.

Table 3. Daily Piscivorous bird counts at Little Goose Dam.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
10-13	13:30	45	23	0	0
10-14	14:00	62	34	0	0
10-15	08:00	72	39	0	0
10-16	14:00	11	28	0	0
10-17	08:00	24	16	0	0
10-18	14:30	49	20	0	0
10-19	14:00	68	42	0	0

Gas Bubble Trauma: Final GBT sampling for the season was conducted on August 21.

Research: No research is currently being conducted at this time.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Oregon Department of Fish and Wildlife and Anchor, frozen and properly disposed of in a landfill. There were 161 prawns collected in the sample and euthanized during this report period. Prawn numbers are outlined in Table 4 below.

Table 4. Daily Siberian prawn sample.

Date	Sample	Collection
10-13	23	23
10-14	14	14
10-15	14	14
10-16	16	16
10-17	6	6
10-18	18	18
10-19	70	70
Total	161	161

**Project: Lower Granite**

Biologists: Elizabeth Holdren and Stephen Hampton

Dates: October 13-19, 2017

---

**Turbine Operation**

Yes No Turbine Unit Status

- All 6 turbine units available for service throughout the week (see comments below for outage details).
- Available turbine units operated within 1% peak efficiency constraint. Constraint in effect:  Hard  Soft.

Comments: Unit 1 remains out of service for blade/runner repair. Unit 2 currently has hydraulically locked blades that limit operation to the upper end of 1% peak efficiency constraint. Unit 3 remains out of service for annual maintenance. Unit priority was changed to unit 1, 3, 4, 5-6, then unit 2 last on/second to last off October 13 due to inadequate river flows to operate unit 2 and the RSW for the coordinated spill time of 0600-1800 hours. Unit 2 was changed to standby mode at 0110 hours and unit 4 was brought on line at 0102 hours October 13. Unit 5 was operated outside of unit priority operation to provide station service power from 1003-1052 hours October 16 during 500KV line relay replacement test.

**Adult Fish Passage Facility**

General comments: Adult fish facilities were inspected by Corps or Anchor QEA biologists October 14, 17, 18, and 19.

Fish Ladder:

Yes No Location, Criteria, and Measurements

- Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')
- Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.3')
- Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')
- Ladder Temperature Pumps in Service.
- Ladder Temperature Pumps Operating Satisfactorily.

Comments:

Fish Ladder Entrances and Collection Channel:

Yes No Sill Location, Criteria and Measurements

- South Shore Entrance (SSE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- South Shore Entrance (SSE-2) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- South Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- North Powerhouse Entrance (NPE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- North Powerhouse Entrance (NPE-2) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- North Powerhouse Entrance Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- North Shore Entrance (NSE-1) Weir Depth (Criteria:  $\geq$  7.0' or on sill)
- North Shore Entrance (NSE-2) Weir Depth (Criteria:  $\geq$  7.0' or on sill)
- North Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- Collection Channel Velocity (Criteria: 1.5 – 4.0 fps)

Comments: NSE-2 has been out of service since 2011 and remains set with a chain fall hoist in the closed position to improve channel/tailwater head differential. SSE 1 & 2 depth over weir was out of criteria October 14 with gate depth readings of 7.8' and 7.7 feet, respectively. NPE 1 & 2 were in sill criteria October 14 with gate depth reading of 7.5' and 7.6 feet. NPE 1 & 2 depth over weir was out of criteria October 19 with gate depth readings of 7.5' and 7.3 feet. The fish ladder control system continues to be unable to maintain both depth over the weir and channel/tailwater head differential at the north shore during spill at current tailwater elevation. NSE depth over the weir criteria is being sacrificed to achieve channel/tailwater head differentials. Electricians and operations continue to troubleshoot the fish ladder control system to address the issues during the winter maintenance outage.

Collection Channel Velocity: Collection channel velocities were in criteria on all inspections.

Auxiliary Water Supply System:

<u>Yes</u>	<u>No</u>	<u>In Service and Operating Satisfactory?</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	AWS Fish Pump 1 (operating).
<input type="checkbox"/>	<input checked="" type="checkbox"/>	AWS Fish Pump 2 (operating).
<input checked="" type="checkbox"/>	<input type="checkbox"/>	AWS Fish Pump 3 (operating).

Comments: AWS pump 2 is in standby mode. AWS pump 1 remains in fast operation. Fish pumps 1 and 3 were offline October 16 from 0911-0914 and 1043-1047 during 500KV line relay testing.

### **Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Forebay debris load acceptable? Debris was observed in the powerhouse forebay this week.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Trash rack differentials measured this week? If so, were differentials acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Debris in gatewells (i.e.: over 10% coverage)?
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Oil in gatewells?

Comments: Forebay debris in front of the powerhouse averaged about 70.0 square yards this week.

ESBSs/VBSs:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	ESBSs deployed in all slots and in service?
<input type="checkbox"/>	<input checked="" type="checkbox"/>	ESBSs inspected this week? If so, were results acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
<input type="checkbox"/>	<input checked="" type="checkbox"/>	VBSs differentials checked this week? If so, were results acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A

Comments: ESBS are dogged off in gatewell slots.

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Orifices operating satisfactory? There are 18 orifices operating.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Dewaterer and cleaning systems operating satisfactory?

Comments: Dewatered.

Collection Facility: Dewatered.

Transport Summary: No transport is occurring.

## River Conditions

General Comments.

Table 1: River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (F°)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
18.0	16.8	3.5	2.7	59.1	56.3	5.0	4.3

### Other

Adult Fish Trap Operations: The adult trap is in twenty-four hour operation seven days a week at a 20% sample rate. Fall Chinook are being collected for transport to Lyons Ferry and Nez Perce hatcheries.

Inline Cooling Water Strainers: N/A

Invasive Species: No signs of mussels were present during the October 16 inspection.

Avian Activity: Piscivorous bird continue to be counted in the forebay and tailrace (Table 2).

Table 2. Daily piscivorous bird counts at Lower Granite Dam.

Date	Time (hours)	Gulls	Cormorants	Caspian Terns	Pelicans
October 13	1300	13	10	0	0
October 14	1330	17	31	0	0
October 15	1014	12	41	0	0
October 16	1500	10	11	0	0
October 17	1430	5	14	0	0
October 18	1109	10	11	0	1
October 19	1600	4	1	0	0

Spill: Inflow is too low to maintain minimum generation with unit 2 operating and RSW spill as coordinated for early juvenile facility shut down as part of Phase 1a construction. Spill is being managed based on river flow with unit 4 in operation. If river flows below the minimum required to operate both unit 4 and the RSW operation will shift to deep spill through spillbay 2 with two stops open at about 3.5 kcfs. Water will be pooled when possible to provide spill for fish and minimum generation.

Gas Bubble Trauma (GBT) Monitoring: N/A.

Research: N/A.