

**U.S. ARMY CORPS OF ENGINEERS  
WALLA WALLA DISTRICT  
FISH FACILITIES WEEKLY REPORT  
#39-2017**

**Project: McNary**

Biologist: Bobby Johnson and Denise Griffith

Dates: November 17 – 23, 2017

---

**Turbine Operation**

General Comments: The soft 1% peak efficiency constraint continues.

Yes   No   Turbine Unit Status

     All 14 turbine units available for service throughout the week (see Table 1 for outage details below).

Table 1. Unit Outages at McNary Project.

Units	Outage Dates	Outage Length	Reason
3	Oct 10 to Dec 8	60 days	9-year overhaul.
1	Nov 18	24 minutes	Restart extended-length submersible bar screen (ESBS) brush cycle for screen in 1B slot.
2	Nov 19	23.1 hours	XJ breaker issue.
1	Nov 20	2.8 hours	ESBS in 1 B slot replaced.
All	Nov 21	3.0 hours total	Rotated through units for black start testing.
6	Nov 22	6.5 hours	Hub tapped.
4	Nov 22	10 minutes	Attempted ESBS camera inspections.

**Adult Fish Passage Facilities**

General Comments: McNary fisheries biologists performed measured inspections of the adult fishways on November 17, 19 and 21. The inspection on November 21 began 22 minutes after the fish pump 2 outage described below. Video review of adult passage will continue to February 28, 2018.

Fish Ladder Exits: Criteria met?

Yes   No   Location, Criteria and Measurements

- Oregon Exit (Criteria – Head over weir 1.0’ to 1.3’)
- Oregon Count Station Differential (Criteria – Differential 0.0’ to 0.5’)
- Washington Exit (Criteria – Head over weir 1.0’ to 1.3’)
- Washington Count Station Differential (Criteria – Differential 0.0’ to 0.5’)

Comments: The trash racks and picketed leads were cleaned as needed, including Saturdays, at both exits.

Debris loads at the Washington exit and along the shoreline were minimal.

At the Oregon exit and along the shoreline, debris loads were minimal to moderate. Tilting weir 339 remains in manual mode. On November 21, the regulating weir set point adjusted.

Fishway Entrances and Collection Channel:

<u>Yes</u>	<u>No</u>	<u>Location, Criteria and Measurements</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	North Oregon Entrance Head Differential (Criteria – 1.0' to 2.0')
<input checked="" type="checkbox"/>	<input type="checkbox"/>	NFEW2 Weir Depth (Criteria – $\geq 8.0'$ )
<input checked="" type="checkbox"/>	<input type="checkbox"/>	NFEW3 Weir Depth (Criteria – $\geq 8.0'$ )
<input checked="" type="checkbox"/>	<input type="checkbox"/>	South Oregon Entrance Head Differential (Criteria – 1.0' to 2.0')
<input checked="" type="checkbox"/>	<input type="checkbox"/>	SFEW1 Weir Depth (Criteria – $\geq 8.0'$ )
<input checked="" type="checkbox"/>	<input type="checkbox"/>	SFEW2 Weir Depth (Criteria – $\geq 8.0'$ )
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon Collection Channel Velocities (Criteria –1.5 to 4.0 fps): Averaged 1.8 fps.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Washington Entrance Head Differential (Criteria – 1.0' to 2.0')
<input checked="" type="checkbox"/>	<input type="checkbox"/>	WFE2 Weir Depth (Criteria – $\geq 8.0'$ )
<input checked="" type="checkbox"/>	<input type="checkbox"/>	WFE3 Weir Depth (Criteria – $\geq 8.0'$ )

Comments: There are no problems to report.

Auxiliary Water Supply System:

<u>Yes</u>	<u>No</u>	<u>In Service?</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Washington shore Wasco County PUD Turbine Unit.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Washington shore Wasco PUD Bypass. Service was not required.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon Ladder Fish Pump 1: Blade angle was approximately 23 to 24 degrees.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon Ladder Fish Pump 2: Blade angle was approximately 21 to 22 degrees.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon Ladder Fish Pump 3: Blade angle was approximately 20 degrees.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oregon North Powerhouse Pool supply from juvenile fishway.

Comments: On November 20, from 1203 to 1412 hours, both units 1 and 2 were out of service, thus neither unit was providing attraction flow for the Oregon ladder south powerhouse entrance. Also, that day, from 1433 to 1515 hours, each fish pump was removed from service independently for black star testing. Fish pump 1, 2 and 3 were out of service for 15, 9 and 14 minutes, respectively. Intermittent pool differential alarms occurred during three outages. During the black start testing on November 21, fish pump 2 was out of service from 0902 to 1053 hours. The two remaining fish pumps were operated at higher blade angles during this outage.

**Juvenile Fish Passage Facility**

General Comments: Fall primary bypass season continues. Light maintenance, preparations for the winter work list, cleaning and partial winterization continues at the facility and in the collection channel.

Forebay Debris/Gatewell Debris/Oil:

<u>Yes</u>	<u>No</u>	<u>Item</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Forebay debris load acceptable?
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Trash rack differentials measured? If so, were differentials acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Any debris seen in gatewells?
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Any oil seen in gatewells?

Comments: Forebay debris loads near the powerhouse were moderate to heavy as variable winds moved the debris to and from the Oregon shore line. Debris loads at the spillway were minimal. New incoming debris loads were minimal. No trash racks were cleaned. Woody debris was removed from the gatewell slots as needed this week.

ESBSs/Vertical barrier screen (VBSs):

Yes   No   Item

- ESBSs deployed in all slots?
- ESBSs inspected this week? If so, were results acceptable?    Yes    No    N/A
- VBSs differentials checked this week? If so, were results acceptable?    Yes    No    N/A

Comments: The brush cycles for the screens in slots 1A, 2A, 2B, 3B, 7B, 8C, 12B, units 11 and 14 remained in timer mode. This week, the ESBS brush cycle, which had been in timer mode, for the screen in 1B slot had to be restarted by the control room operator on November 17 and 18. The second time, the unit was removed from service, which allowed the cycle to resume. On November 20, the ESBS in 1B slot was replaced. The replacement screen brush cycle was set in automatic mode. The brush on the screen in 2A slot appears to be cycling less frequently than the brushes on the ESBSs in adjacent slots. We will continue to examine this issue. On November 18, the technician on duty had the control room operator start the brush cycles for the screens in unit 5. ESBS camera inspections did not occur this week, as the pan and tilt function failed before the inspections at unit 4 were begun on November 22. The electrical staff will examine the camera next week.

VBS differential monitoring continued. No high differential measurements were recorded. Six screens were cleaned on November 22. No mortalities were observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

Yes   No   Item

- Orifices operating satisfactory? 42 orifices were open.
- Dewatering and cleaning systems operating satisfactory?

Comments: Orifices were adjusted as required for VBS cleaning. Maintenance occurred on the orifice operators as needed. Moisture in the orifices air supply line was bled off daily. We continued to operate the transition screen cleaning brush manually to insure it completes a full cleaning cycle.

Bypass Facility:

Yes   No   Item

- Sample gates on? Fall bypass season continues.
- Passive integrated transponder (PIT) tag system on? Fall bypass season continues.

Comments: During the fall primary bypass season, PIT tag detection occurs in the full flow pipe. All systems remained out of service. Light maintenance, cleaning and partial winterization continues.

Preparations for the winter work list continue.

**River Conditions**

General Comments: River conditions were provided by the control room and outlined in Table 2 below. The data period runs from 0000 to 2400 hours each day.

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
121.0	95.9	0.0	0.0	51.0	50.0	6.0	6.0

Comments: There are no problems to report.

## **Other**

Inline Cooling Water Strainers: The next cooling water strainer examinations will occur on December 5.

Invasive Species: The next mussel station examinations will occur in early December.

Avian Activity: Casual avian observations continue while doing other inspections. Overall, gull and cormorant numbers appear to be fluctuating with the juvenile shad outmigration. A large number of gulls were roosting on project inside and outside of the counting zones in multiple locations. Low numbers of gulls and cormorants were feeding at the bypass outfall. Higher numbers of gulls were also feeding in the powerhouse flow. The gulls and cormorants in the spillway zone are roosting on the navigation lock wing wall and other structures.

In the forebay zone, an occasional gull, gull flock, blue heron or grebe was observed. Gulls and cormorants were occasionally observed on the rocks by the Washington shore boat dock.

Fish Salvage/Rescue: None occurred.

## **Research**

No onsite research is occurring at this time.

**Project: Ice Harbor**

Biologist: Ken Fone

Dates: November 17 – November 23, 2017

---

**Turbine Operation**

Yes No Turbine Unit Status

- All 6 turbine units available for service throughout the week (see comments below for outage details).  
  Available turbine units operated within 1% peak efficiency constraint. Constraint in effect:  Hard  Soft.

Comments: Unit 2 was taken out of service on April 25, 2016, at 0606 hours for the runner replacement

**Adult Fish Passage Facilities**

Fish facility personnel inspected the adult fishways on November 20, 21, and 22.

Fish Ladders:

Yes No Location, Criteria and Measurements

- North Fish Ladder Exit Differential (Criteria – Head  $\leq 0.5'$ )  
  North Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq 0.3'$ )  
  North Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')  
  South Fish Ladder Exit Differential (Criteria – Head  $\leq 0.5'$ )  
  South Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq 0.3'$ )  
  South Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')

Comments: The picketed leads are raised out of the water for the remainder of the season.

Fishway Entrances and Collection Channel:

Yes No Sill Location, Criteria and Measurements

- South Shore Entrance (SFE-1) Weir Depth (Criteria:  $\geq 8.0'$  or on sill)  
  South Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')  
  South Shore Channel Velocity (Criteria: 1.5 – 4.0 fps)  
   North Powerhouse Entrance (NFE-2) Weir Depth (Criteria:  $\geq 8.0'$  or on sill)  
  North Powerhouse Channel/Tailwater Differential (Criteria: 1.0' – 2.0')  
   North Shore Entrance (NSE-1) Weir Depth (Criteria:  $\geq 8.0'$  or on sill)  
  North Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')

Comments: None.

Auxiliary Water Supply (AWS) System:

Yes No In Service and Operating Satisfactory?

- South Shore AWS Pumps. Six of the eight south shore AWS pumps were in service.  
  North Shore AWS Pumps. Two of the three north shore AWS pumps were in service.

Comments: South shore AWS pump #4 was out of service from 1535 hours on November 7 to 0949 hours on November 20 to fix the oil pump.

### Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

- | <u>Yes</u>                          | <u>No</u>                           | <u>Item</u>   |
|-------------------------------------|-------------------------------------|---|
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Forebay debris load acceptable? An average of 100 square yards of debris was observed.  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Trash rack differentials measured this week? If so, were differentials acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | Any debris seen in gatewells (i.e: over 10% coverage)? Surface coverage ranged from 0% to 10%.  |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | Any oil seen in gatewells?  |

Comments: None.

STSS/VBSs:

- | <u>Yes</u>               | <u>No</u>                           | <u>Item</u>  |
|--------------------------|-------------------------------------|--|
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | STSS deployed in all slots and in service?   |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | STSS in continuous-run mode (If not, then STSS are in cycle-run mode)?   |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | STSS inspected this week? If so, were results acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A             |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | VBSs differentials checked this week? If so, were results acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A |

Comments: STSS are in cycle-run mode. Unit 2 STSS are not installed since the unit will not be returned to service this year.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

- | <u>Yes</u>                          | <u>No</u>                | <u>Item</u>  |
|-------------------------------------|--------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Orifices operating satisfactory? How many are open and in service? 20. |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Dewaterer and cleaning systems operating satisfactory?                 |

Comments: None.

Juvenile Fish Facility: The fish facility is in bypass operation.

Fish Sampling: Sampling is done for the year.

Removable Spillway Weir (RSW): Voluntary spill for fish passage is done for the season.

### River Conditions

River conditions during the week are outlined in Table 1 below.

Table 1. River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
33.3	12.3	0	0	52	51	7.1	6.8

\*Unit 1 scroll case temperature.

## **Other**

Inline Cooling Water Strainers: Turbine cooling water strainer inspections for lamprey are no longer required from July to November. Unit 6, 3, and 1 strainers were cleaned on November 20 and 22, because of juvenile shad plugging up the strainers. A total of approximately 4,500 dead juvenile shad were removed.

Invasive Species: No exotic species that are new to the area have been found.

Avian Activity: There were large numbers of piscivorous birds seen around the project, including gulls, pelicans, mergansers, cormorants, and grebes. Most of them were observed roosting on Eagle Island and/or foraging opportunistically downstream of the powerhouse and at the navigation lock discharge.

Research: No on-site research is occurring at this time.

**Project: Lower Monumental**

Biologists: Chuck Barnes and Raymond Addis

Dates: November 17 – November 23, 2017

---

**Turbine Operation**

Yes No Turbine Unit Status

- All 6 turbine units available for service throughout the week (see comments below for outage details).
- Available turbine units operated within 1% peak efficiency constraint.

Constraint in effect:  Hard  Soft. Soft constraint began at 0000 hours on November 1.

Comments: Unit 1 was removed from service on December 10, 2014 for Unit Rehabilitation with an estimated return to service date of May 31, 2018. Unit 5 was removed from service on January 17, 2017 due to a turbine oil leak with an estimated return to service at the end of February, 2018. Unit 3 was removed from service at 0845 on October 20 for a digital governor installation with an estimated return to service of December 7, 2017.

**Adult Fish Passage Facility**

The adult fishway was inspected by Corps biologists on November 20, 21 and 22.

Fish Ladders:

Yes No Location, Criteria and Measurements

- North Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')
- North Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.4')
- North Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')
- South Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')
- South Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.3')
- South Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')

Comments: None.

Fishway Entrances and Collection Channel:

Yes No Sill Location, Criteria and Measurements

- North Shore Entrance (NSE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- North Shore Entrance (NSE-2) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- North Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- South Powerhouse Entrance (SPE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- South Powerhouse Entrance (SPE-2) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- South Powerhouse Entrance Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- South Shore Entrance (SSE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- South Shore Entrance (SSE-2) Weir Depth (Criteria:  $\geq$  6.0' or on sill)
- South Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')

Comments: South Powerhouse Entrance weirs (SPE-1 and SPE-2) were on sill during all inspections. While on sill readings for both were 7.1, 7.4 and 7.4 feet.



Auxiliary Water Supply System:

- |                                     |                                     |   |
|-------------------------------------|-------------------------------------|---|
| <u>Yes</u>                          | <u>No</u>                           | <u>In Service and Operating Satisfactory?</u> |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | AWS Fish Pump 1.                              |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | AWS Fish Pump 2.                              |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | AWS Fish Pump 3.                              |

Comments: Pump 1 will be out of service throughout this season unless an emergency occurs.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

- |                                     |                                     |  |
|-------------------------------------|-------------------------------------|--|
| <u>Yes</u>                          | <u>No</u>                           | <u>Item</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Forebay debris load acceptable? An average of 670 square yards of debris observed in forebay.  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Trash rack differentials measured this week? If so, were differentials acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A. |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Any debris seen in gatewells?  |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | Any oil seen in gatewells?   |

Comments: Gatewell debris ranged from 0 to 20% during inspections.

STSs/VBSs:

- |                                     |                                     |  |
|-------------------------------------|-------------------------------------|--|
| <u>Yes</u>                          | <u>No</u>                           | <u>Item</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | STSs deployed in all slots and in service?   |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?   |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | STSs inspected this week? If so, were results acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A             |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | VBSs differentials checked this week? If so, were results acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A |

Comments: STS's were operating on cycle mode due to CH0 lengths being over the 120 mm criteria point.

Orifices, Collection Channel, Dewatering Structure, and Flume:

- |                                     |                          |  |
|-------------------------------------|--------------------------|--|
| <u>Yes</u>                          | <u>No</u>                | <u>Item</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Orifices operating satisfactory? How many are open and in service? 18. |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Dewaterer and cleaning systems operating satisfactory?                 |

Comments: None.

Collection Facility: Collection for transport ended at 0700 on October 1, at which time the facility was placed into primary bypass. The collection facility was dewatered on October 11.

Transport Summary: Transport season ended on October 1.

**River Conditions**

General Comments.

Table 1. River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
34.4	12.3	0	0	48.9	48.2	6.9	5.6

\*Scrollcase temperatures.

Spill: The RSW spill was closed on August 18. Summer spill ended at 0000 on September 1.

**Other**

Inline Cooling Water Strainers: Cooling water strainers were inspected on August 16

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on October 1.

Avian Activity: Gulls and cormorants were the predominant piscivorous bird species observed during fish ladder inspections this week. Tailrace counts ended on July 13.

Outfall pipe bird water cannons were shut down and dewatered on October 12.

Research: No onsite research is in progress at this time.

**Project: Little Goose**

Biologists: Scott St. John & Richard Weis

Dates: November 17-23, 2017

---

**Turbine Operation**

Yes No Turbine Unit Status

- All 6 turbine units available for service throughout the week (see Table 1 for outage details).  
  Available turbine units operated within 1% peak efficiency constraint. Constraint in effect:  Hard  Soft.

Table 1. Little Goose Unit Outages

Unit	OOS Date	OOS Time	RTS Date	RTS Time	Outage Description
5	14-Apr	14:11	31-July	17:00	Upper Guide Bearing Repair (ERTS July 31, 2018)

Comments: None.

**Adult Fish Passage Facility**

The adult fishway was inspected by Corps biologists and Anchor QEA staff on November 20, 21 and 22.

Fish Ladder:

Yes No Location, Criteria and Measurements

- Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')  
  Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.3')  
  Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')  
  Emergency Ladder Exit Cooling Water Pumps in Service  
  Emergency Ladder Exit Cooling Water Pumps Operating Satisfactorily.

Comments: Emergency cooling pump permanent power is scheduled to be installed during the winter maintenance outage.

Fishway Entrances and Collection Channel:

Yes No Sill Location, Criteria and Measurements

- South Shore Entrance (SSE-1) Weir Depth (Criteria:  $\geq$  8.0')  
   South Shore Entrance (SSE-2) Weir Depth (Criteria:  $\geq$  8.0')  
   South Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')  
   North Powerhouse Entrance (NPE-1) Weir Depth (Criteria:  $\geq$  7.0' or on sill)  
   North Powerhouse Entrance (NPE-2) Weir Depth (Criteria:  $\geq$  7.0' or on sill)  
   North Powerhouse Entrance Channel/Tailwater Differential (Criteria: 1.0' – 2.0')  
   North Shore Entrance (NSE-1) Weir Depth (Criteria:  $\geq$  6.0' or on sill)  
   North Shore Entrance (NSE-2) Weir Depth (Criteria:  $\geq$  6.0' or on sill)  
   North Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')  
   Collection Channel Surface Velocity (Criteria: 1.5 – 4.0 fps)

Comments: Rickly velocity measurement was conducted on October 23 and averaged 3.0 fps.

Auxiliary Water Supply System:

- | <u>Yes</u>                          | <u>No</u>                | <u>In Service and Operating Satisfactory?</u> |
|-------------------------------------|--------------------------|---|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | AWS Fish Pump 1 (operating).                  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | AWS Fish Pump 2 (operating).                  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | AWS Fish Pump 3 (operating).                  |

Comments: None.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

- | <u>Yes</u>                          | <u>No</u>                           | <u>Item</u>  |
|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Forebay debris load acceptable.  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Trash rack differentials measured this week? If so, were differentials acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A. |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | Any debris seen in gatewells (i.e: over 10% coverage)?   |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | Any oil seen in gatewells?   |

Comments: There is an estimated 4,500 square feet of floating woody debris in the immediate forebay. Trash rack differentials were measured on November 21 and were in criteria.

Spillway Weir: Temporary spillway weir was closed for the season on July 19 at 09:00.

ESBS/VBS:

- | <u>Yes</u>                          | <u>No</u>                           | <u>Item</u>  |
|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | ESBSs deployed in all slots and in service?  |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | ESBSs inspected this week? If so, were results acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A            |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | VBSs differentials checked this week? If so, were results acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |

Comments: VBS differentials were measured on November 21 and were in criteria.

Orifices, Collection Channel, Dewatering Structure, and Flume:

- | <u>Yes</u>                          | <u>No</u>                | <u>Item</u>  |
|-------------------------------------|--------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Orifices operating satisfactory? How many are open and in service? <u>19 open.</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | Dewaterer and cleaning systems operating satisfactory? N/A                         |

Comment: Orifices and primary dewatering structure are being back flushed every 8 hours.

Collection Facility: Juvenile Fish Facility switched to primary bypass on November 1 at 07:00.

Transport Summary: Collection for transport ended on November 02 with the last truck leaving LGS.

### River Conditions

River conditions during the week are outlined in Table 2 below.

Table 2. River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
34.6	12.4	0	0	49.0	48.6	5.8	5.7

\*Ladder temperature.

Comment: Spill ended at midnight August 31.

### Other

Inline Cooling Water Strainers: Cooling water strainers will be inspected again starting in December.

Invasive Species: No invasive species have been observed on the mussel station.

Avian Activity: USDA bird hazing ended on June 25 and USACE bird counts ended on October 31.

Gas Bubble Trauma: Final GBT sampling for the season was conducted on August 21.

Research: No research is currently being conducted at this time.

Siberian Prawn: Collection ended for the season on November 1.

**Project: Lower Granite**

Biologists: Elizabeth Holdren and Stephen Hampton

Dates: November 17 - November 23, 2017

---

**Turbine Operation**

Yes No Turbine Unit Status

- All 6 turbine units available for service throughout the week (see comments below for outage details).
- Available turbine units operated within 1% peak efficiency constraint. Constraint in effect:  Hard  Soft.

Comments: Unit 1 remains out of service for blade/runner repair. Unit 2 currently has hydraulically locked blades that limit operation to the upper end of 1% peak efficiency constraint. Unit 3 is currently in operation as the priority unit. Unit 2 was removed from service at 0825 hours October 31 for annual maintenance.

**Adult Fish Passage Facility**

General comments: Adult fish facilities were inspected by Corps biologists November 21 and 22.

Fish Ladder:

Yes No Location, Criteria, and Measurements

- Fish Ladder Exit Differential (Criteria – Head  $\leq$  0.5')
- Fish Ladder Picketed Lead Differential (Criteria – Head  $\leq$  0.3')
- Fish Ladder Depth over Weirs (Criteria – Head over weir 1.0' to 1.3')
- Ladder Temperature Pumps in Service.
- Ladder Temperature Pumps Operating Satisfactorily.

Comments: None.

Fish Ladder Entrances and Collection Channel:

Yes No Sill Location, Criteria and Measurements

- South Shore Entrance (SSE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- South Shore Entrance (SSE-2) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- South Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- North Powerhouse Entrance (NPE-1) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- North Powerhouse Entrance (NPE-2) Weir Depth (Criteria:  $\geq$  8.0' or on sill)
- North Powerhouse Entrance Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- North Shore Entrance (NSE-1) Weir Depth (Criteria:  $\geq$  7.0' or on sill)
- North Shore Entrance (NSE-2) Weir Depth (Criteria:  $\geq$  7.0' or on sill)
- North Shore Channel/Tailwater Differential (Criteria: 1.0' – 2.0')
- Collection Channel Velocity (Criteria: 1.5 – 4.0 fps)

Comments: None.

NPE-1 and NPE-2 were in sill criteria on November 22 with gate depth readings of 7.9 feet. NSE-2 has been out of service since 2011 and remains set with a chain fall hoist in the closed position to improve channel/tailwater head differential. The fish ladder control system continues to be unable to consistently maintain both depth over the weir and channel/tailwater head differential at the north shore during spill at current tailwater elevation. NSE depth over the weir criteria is being sacrificed to achieve channel/tailwater head differentials.

Collection Channel Velocity: Collection channel velocities were in criteria on all inspections.

Auxiliary Water Supply System:

Yes No In Service and Operating Satisfactory?

- AWS Fish Pump 1 (operating).
- AWS Fish Pump 2 (operating).
- AWS Fish Pump 3 (operating).

Comments: AWS pump 2 is in standby mode. AWS pump 1 is in fast operation. AWS pump 1 was OOS November 20 from 0826 hours to 1532 hours due to 5 kV line reconnect.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

Yes No Item

- Forebay debris load acceptable? Debris was observed in the powerhouse forebay this week.
- Trash rack differentials measured this week? If so, were differentials acceptable?  Yes  No  N/A.
- Debris in gatewells (i.e.: over 10% coverage)?
- Oil in gatewells?

Comments: Forebay debris in front of the powerhouse averaged about 12.5 yard<sup>2</sup> this week.

ESBSs/VBSs:

Yes No Item

- ESBSs deployed in all slots and in service?
- ESBSs inspected this week? If so, were results acceptable?  Yes  No  N/A
- VBSs differentials checked this week? If so, were results acceptable?  Yes  No  N/A

Comments: ESBS are dogged off in gatewell slots.

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes No Item

- Orifices operating satisfactory? There are 18 orifices operating.
- Dewaterer and cleaning systems operating satisfactory?

Comments: Dewatered.

Collection Facility: Dewatered.

Transport Summary: No transport is occurring.

**River Conditions**

General Comments.

Table 1: River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)	Daily Average Spill (kcfs)	Water Temperature (°F)*	Water Clarity (Secchi disk - feet)
---------------------------------	----------------------------	-------------------------	------------------------------------

High	Low	High	Low	High	Low	High	Low
32.3	15.6	3.5	3.4	46.1	46.1	4.9	4.4

\*Collection channel temperature readings were taken due to unit 1 and 2 being unavailable.

### **Other**

Adult Fish Trap Operations: The adult trap stopped trapping operations for the season, November 19 at 0900 hours.

Inline Cooling Water Strainers: Unit cooling water strainers were inspected November 20. Mortalities included 1 juvenile lamprey and 1 unidentified non-salmonid.

Invasive Species: No signs of mussels were present during the November 1 inspection.

Avian Activity: N/A

Spill: Spill is being managed based on river flow with unit 3 in operation. If river flows fall below the minimum required to operate both unit 3 and the RSW spill will shift to spillbay 2 open two stops (3.5 kcfs). When possible water will be pooled to provide spill for fish and minimum generation. Spill operations were shifted from the RSW to Spillbays 2 and 7 November 17 from 1038 hours to 1318 hours, November 20 from 0600 hours to 1648 hours, November 21 from 0800 hours to 1600 hours, and November 22 from 0558 hours to 1052 hours, to assist with BRZ work.

Gas Bubble Trauma (GBT) Monitoring: N/A.

Research: None at this time.