

**U.S. ARMY CORPS OF ENGINEERS  
WALLA WALLA DISTRICT  
FISH FACILITIES WEEKLY REPORT  
#31-2019**

**Project: McNary**

Biologist: Bobby Johnson and Denise Griffith

Dates: September 27 to October 3, 2019

---

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 14 turbine units available for service. (See table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

Unit(s)	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	05/23	0943	10/31	NA	Turbine blade packing.
13	06/10	0610	10/18	NA	Turbine bearing.
14	08/19	1221	01/01/20	NA	Oil replacement and turbine bearing.
12	08/26	0711	10/01	0909	Annual and oil leaks.
10 & 11	10/01	1000	10/01	1044	ESBS camera inspections, rotated through units.

Comments: All return to service dates are subject to change.

**Adult Fish Passage Facilities**

McNary fisheries biologists performed measured inspections of the adult fishways on September 27, 29 and October 1. Video review of night time lamprey passage concluded on September 30. Adult fish counting continued.

The Oregon ladder temperature probe located at diffuser 7 was out of service from September 4 to 26.

Fish Ladder Exits:

Yes	No	Location	Criteria	Comments
X		Oregon Exit	Head over weir 1.0' to 1.3'	
X		Oregon Count Station Differential	0.0' to 0.5'	
X		Washington Exit	Head over weir 1.0' to 1.3'	
X		Washington Count Station Differential	0.0' to 0.5'	

Comments: Debris loads were minimal to moderate near the Oregon exit and minimal to light near the Washington exit. Picketed leads were cleaned as required.

At the Washington ladder exit, multiple tilting weir alarms came in and were reset on October 1.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			North Oregon Entrance Head Differential	1.0' – 2.0'	
	X		NFEW2 Weir Depth	≥ 8.0'	7.9' on Sep 29
	X		NFEW3 Weir Depth	≥ 8.0'	7.9' on Sep 29
X			South Oregon Entrance Head Differential	1.0' – 2.0'	
X			SFEW1 Weir Depth	≥ 8.0'	
X			SFEW2 Weir Depth	≥ 8.0'	
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	Averaged 2.1 fps.
X			Washington Entrance Head Differential	1.0' – 2.0'	
X			WFE2 Weir Depth	≥ 8.0'	
X			WFE3 Weir Depth	≥ 8.0'	

Comments: The out of criteria points listed above were possibly due to calibration or set point drifts, control issues and/or low tailwater elevations.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			WA shore Wasco County PUD Turbine Unit
	X		WA shore Wasco PUD Bypass
		X	Oregon shore Fish Pump 1, OOS to December 31.
X			Oregon shore Fish Pump 2, Blade angle: 25 to 27°
X			Oregon shore Fish Pump 3, Blade angle: 27 to 28°
X			OR North Powerhouse Pool supply from juvenile fishway

Comments: There are no problems to report.

**Juvenile Fish Passage Facility**

The sampling season consisting of alternating days of primary and secondary bypass concluded on September 30, at 0700 hours. There were no interruptions in the schedule. Partial winterization and light maintenance began at the facility. The full flow flume adult flush line valve will remain open until the valve can be repaired during the winter maintenance season.

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Powerhouse forebay debris load acceptable?	Minimal to moderate.
X			Trash rack differentials measured this week?	Daily.
X			Trash rack differentials acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: New incoming debris was minimal. The spillway debris load would be described as minimal. Much of the debris moves between the powerhouse and the Oregon shoreline. The debris is a mix of aquatic vegetation and woody material. No trash racks were cleaned.

There are no problems to report.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs):

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: The brush cycles for the screens in units 6, 8, 10 and 13 remained in timer mode. Camera inspections in units 10 and 11 revealed no problems on October 1.

Daily VBS differential monitoring continued. No high differentials were recorded. Six screens were cleaned on October 3. No fish were observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

Yes	No	NA	Item	Number of orifices in service
X			Orifices operating satisfactory?	42
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: Orifices were operated as required for VBS cleaning. Orifice valve operators and area lighting were repaired as required. With colder weather, both side dewatering valves returned to normal operating temperatures.

Bypass Facility:

Yes	No	NA	Item
X			Sample gates on?
		X	PIT-tag sampling system on?

Comments: The sample gates were operated only when in secondary bypass and the PIT tag system remained out of service until winter maintenance began on September 30.

This week, 20 juvenile lamprey and 10 smolts were bypassed during secondary bypass. There were no smolts in the last sample on September 30. Juvenile shad remained the predominant fish examined.

TSW Operations: The TSW in spillbay 19 remained closed for the season. The TSW in bay 20 will be operated per the adult steelhead top spillway weir (TSW) passage efficiency study plan. Scheduled maintenance was performed on the bay 20 hoist this week.

**River Conditions**

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
98.5	71.8	2.1	0.0	66.0	64.0	6.0	6.0

Comments: The above data is from the control room. The spill recorded was due to the TSW passage study. Spillway hoist and crane maintenance began this week.

**Other**

Inline Cooling Water Strainers: The cooling water next strainer inspections will occur on December 3.

Avian Activity: Reporting avian observations concluded on September 30. The counts are reflected in Table 3 below.

Gull activity fluctuated in the powerhouse zone with birds feeding and roosting. At times, gulls were noted feeding in large numbers but not when the count was occurring. In the spill zone, gull and cormorant numbers again fluctuated. No pelicans or terns were noted. All birds were feeding or roosting. Feeding was especially high when the TSW was open. A large percentage of gulls and cormorants roosted on the top of the navigation lock and Washington ladder walls. Adult and juvenile birds were observed. Bird numbers appear to be fluctuating with their migration and the juvenile shad out migration.

Table 3. McNary Project’s Daily Tailwater Avian Counts.

Date	Zone	Gull	Cormorant	Tern	Pelican
Sep 27	Spill	400	55	0	0
	Powerhouse	30	0	0	0
	Outfall	13	5	0	0
Sep 28	Spill	66	50	0	0
	Powerhouse	41	0	0	0
	Outfall	14	30	0	0
Sep 29	Spill	59	44	0	0
	Powerhouse	16	0	0	0
	Outfall	13	49	0	0
Sep 30	Spill	242	37	0	0
	Powerhouse	45	0	0	0
	Outfall	10	48	0	0

In the bypass outfall zone, the gulls and cormorants were mostly roosting on the full flow pipe. However, at times, a fair number of these birds were noted feeding.

The laser for bypass outfall hazing remained in place and functional. The laser does seem to deter the birds in flight. However, birds roosting are more difficult to haze with the laser. It is suspected the laser is not covering the outfall zone completely. A second laser is on project and will be installed in October. Casual avian observations will continue so a comparison can be made between one versus two lasers.

The bird distress calls deployed along the navigation lock wing wall and at the end of the remaining outfall pipe walkway were removed this week. When juvenile shad are out migrating, these calls appear to be less effective, especially on gulls. When the lasers are installed and adjusted later this month, we may attempt to haze these areas.

In the forebay zone, an occasional gull flock was observed. The grebe distress will be removed next week. No grebes were observed on project. Fluctuating numbers of cormorants and gulls were noted roosting outside the zone along the Washington shore line. Large gull flocks have been staging around the project.

Invasive Species: The next mussel station examinations will occur in late October. This week, no Siberian prawns were removed from the sample and euthanized. The season final total was 11 prawns.

Fish Rescue/Salvage: No fish rescue occurred this week.

Research: The University of Idaho continued the adult lamprey passage study, which is near conclusion. The adult steelhead top spillway weir (TSW) passage efficiency study continued.

**Project: Ice Harbor**

Biologist: Ken Fone

Dates: September 27 – October 3, 2019

---

**Turbine Operation**

Yes	No	Turbine Unit Status		
	X	All 6 turbine units available for service (see table & comments below for details).	<b>Hard</b>	<b>Soft</b>
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Ice Harbor Unit Outages (OOS) and Return to Service (RTS):

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	5/3/19	0641	---	---	Turbine runner replacement and stator rewind
6	8/14/19	0743	---	---	Annual maintenance and overhaul
4	10/3/19	0830	---	---	TWO transformer bus duct modification

Comments: None.

**Adult Fish Passage Facility**

Ice Harbor fish facility staff inspected the adult fishways on October 1, 2, and 3.

Fish Ladders:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head $\leq$ 0.3'	
X		North Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head $\leq$ 0.3'	
X		South Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			South Shore Entrance (SFE-1) Weir Depth	$\geq$ 8.0' or on sill	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			South Shore Channel Velocity	1.5 – 4.0 fps	
X			North Powerhouse Entrance (NFE-1) Weir Depth	$\geq$ 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
X			North Shore Entrance (NEW-2) Weir Depth	$\geq$ 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: None.

Auxiliary Water Supply (AWS) System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
7 pumps	1 pump		Status of the 8 South Shore AWS Pumps
2 pumps	1 pump		Status of the 3 North Shore AWS Pumps

Comments: None.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Average of 12 square yards
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0-1%
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
	X		STSs deployed in all slots and in service?
	X		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	20
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Juvenile Fish Facility: The fish facility is being operated in primary bypass.

Fish Sampling: Sampling has ended for the year.

Removable Spillway Weir (RSW): Voluntary spill for fish passage has ended for the year.

## River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
29.3	20.6	0	0	67	63	7.6	7.6

\*Unit 1 scroll case temperature.

## Other

Inline Cooling Water Strainers: Monthly strainer inspections for lamprey ended in June and will start again in December.

Avian Activity: There were low numbers of gulls and pelicans observed around the project.

Invasive Species: No new exotic species have been found.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Anchor, frozen and properly disposed of in a landfill. Sampling is done for the year.

Fish Rescue/Salvage: None.

Research: Research conducted on fish interactions with the lamprey passage structure at the south shore fish ladder entrance (SFE2) ended on October 1. The lamprey passage structure was closed on October 2.

On September 24, PNNL began releasing sensor fish through unit 2 turbine for the turbine environment characterization study.

**Project: Lower Monumental**

Biologists: Chuck Barnes and Raymond Addis

Dates: September 27 – October 3, 2019

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 1	10/01/2019	07:22	10/01/2019	14:04	STS Inspection
Unit 2	7/15/2019	07:20	1/10/2020	ERTS	Annual Maintenance/Draft Tube Liner Repair
Unit 3	10/01/2019	14:05	10/01/2019	16:23	STS Inspection
Unit 4	10/03/2019	08:30	10/03/2019	10:05	STS Inspection
Unit 5	10/02/2019	08:45	10/02/2019	10:30	STS Inspection
Unit 5	10/03/2019	15:50	12/05/2019	ERTS	Governor Control
Unit 6	8/05/2019	12:20	11/01/2019	ERTS	6 Year maintenance

Comments: Units went into Hard Restraint at 0001 on April 1.

**Adult Fish Passage Facility**

The adult fishways were inspected by Corps and Anchor QEA biologists on September 27, 28, 29 and October 2.

Fish Ladder:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head $\leq$ 0.5'	
X		North Ladder Picketed Lead Differential	Head $\leq$ 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head $\leq$ 0.5'	
X		South Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments: One adult unclipped steelhead mortality was found on the North Ladder walkway near weir 528.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	$\geq$ 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	$\geq$ 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	$\geq$ 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	$\geq$ 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
		X	South Shore Entrance (SSE-1) Weir Depth	$\geq$ 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	$\geq$ 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	



Comments: South Powerhouse Entrance weir (SPE-1) was on sill during all inspections with readings of 6.0, 6.3, 6.0 and 5.5 feet respectively.

South Powerhouse Entrance weir (SPE-2) was on sill during all inspections with readings of 6.0, 6.3, 6.0 and 5.5 feet respectively.

South Shore Entrance weir (SSE-1) was on sill during all inspections with readings of 7.2, 7.2, 7.0 and 6.5 feet respectively.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	152 yd <sup>2</sup>
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0 – 8 %
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service?
	X		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
X			STSs inspected this week?
X			STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: STS's were operating in Cycle mode due to average sub-yearling Chinook and sockeye lengths being greater than 120 mm.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	17
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Collection Facility: Collection into raceways for transport began at 1500 on April 23. Loading fish into raceways for barge transport ended at 1500 on July 30. The facility went to 100% sample for truck transport at that time.

Collection for truck transport ended at 0700 on September 30 and the facility operation was changed to primary bypass. The facility was dewatered at 1200 on October 3 for cleaning and winter maintenance.

Transport Summary: Every-other day barging transport ended with the July 30 barge. Every-other day truck transport began with the August 1 truck. A total of 20 fish were collected with 20 fish being bypassed during this reporting period. Per 2019 Fish Passage Plan, the Lower Monumental trucking schedule is contingent upon fish numbers. Saturday, August 3 was the third consecutive day with less than 50 smolts collected; therefore trucking was ceased after the second trip. Bypassed fish numbers reflect the end of truck transport.

Spillway Weir: RSW went into service at 00:01:00 on April 3. The RSW was removed from service at 0630 on August 8 due to low river flows. Summer Spill ended at 00:00:00 on September 1.

### River Conditions

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
28.6	19.3	0.0	0.0	65.9	64.0	4.4	3.6

\*Scrollcase temperatures.

### Other

Inline Cooling Water Strainers: Cooling water strainers were not checked during this reporting period.

Avian Activity: Cormorants and gulls were the predominant piscivorous bird species observed during fish ladder inspections this week.

Date	Time	Gulls	Cormorants	Terns	Grebes	Pelicans
9/27/2019	13:40	1	7	0	2	0
9/28/2019	09:30	6	13	0	0	0
9/29/2019	13:40	0	9	0	0	0
10/02/2019	10:00	0	1	0	0	0

Comments: Bird hazing efforts by USDA personnel ended at the end of the working day on June 2. Daily bird hazing effectiveness tailrace observations ended with the June 30 observation.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on September 7.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by PSMFC and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Lower Monumental Dam for this reporting period are reported below.

Date	Sample (euthanized)	Collection*
9/27/2019	1	1
9/28/2019	0	0
9/29/2019	0	0
9/30/2019	0	0
Totals	1	1

\*Collection and sample numbers are the same as the facility when sampling at 100%

Fish Rescue/Salvage: No Fish Rescue/Salvage took place this reporting period.

Research: No Research took place during this reporting period.

**Project: Little Goose**

Biologists: Scott St. John and Richard Weis

Dates: September 27 – October 03, 2019

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

**Little Goose Unit Outages (OOS) and Return to Service (RTS)**

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	04/21/17	00:54	03/31/21	17:00	Spider and Upper Guide Bearing Repair
3	09/09/19	07:29	10/03/19	15:15	Unit Annual

Comments: None.

**Adult Fish Passage Facility**

Little Goose fish facility, Anchor QEA and/or Oregon Department of Fish and Wildlife staff inspected the adult fishway on September 29 and October 03.

Fish Ladder:

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head $\leq$ 0.5'	
X			Fish Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pump in Service		
		X	Fish Ladder Exit Cooling Water Pump Operating Satisfactorily		

Comments: Cooling water pump were shut off for the season on September 23.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurement
X			South Shore Entrance (SSE-1) Weir Depth	$\geq$ 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	$\geq$ 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	$\geq$ 7.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	$\geq$ 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
	X		North Shore Entrance (NSE-1) Weir Depth	$\geq$ 6.0' or on sill	5.5
	X		North Shore Entrance (NSE-2) Weir Depth	$\geq$ 6.0' or on sill	5.5
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: The adult fishway continues to operate in manual mode. Project staff have struggled to maintain entrance criteria during spill. The equipment used to measure NSE weir depth was found out of service on the August 11 inspection. NSE weir depth was found out of criteria on the October 3 inspection. Subsurface water velocity was measured near NPE on September 21 using a Rickly velocity meter and averaged 2.5 feet per second.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	
	X		Trash rack differentials measured this week?	
		X	Trash rack differentials acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Trash rack differential for Units 1 and 2 was measured on September 19 and was in criteria. There is approximately 2,000 square feet of floating woody debris inside the trash shear boom in the immediate forebay.

ESBS/VBS:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
	X		VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: ESBS/VBS underwater camera inspections were conducted on Unit 3 during Unit annual maintenance. VBS differential for Unit 1 and 2 was measured on September 19 and was in criteria.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	19
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Collection Facility: The juvenile bypass system is currently operating in criteria. Daily collection for condition sampling began on April 23 at 07:00. The last every other day barge departed on July 30 and every other day truck transport commenced on August 01.

Transport Summary: The collection and transportation facility operated within criteria this report period. A total of 277 fish were collected, of which 212 transported via truck. The descaling and mortality rates were 0.7% and 4.4% respectively. There were 0 adult lamprey removed from the separator, raceways, and sample and released one mile above the Dam at Little Goose Landing.

Spillway Weir: The adjustable spillway weir (ASW) was closed on July 23 at 15:17 per the guidance outlined in the Columbia Basin Teletype (CBT). The ASW will remain closed for the season.

### River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
26.9	19.6	0	0	65.1	63.4	6.0	6.0

\*Ladder temperature.

### Other

Inline Cooling Water Strainers: Cooling water strainers were last inspected on July 3 with no lamprey being observed. Inspections will resume in December per the Fish Passage Plan.

Avian Activity: Daily Piscivorous bird counts at Little Goose Dam started April 01.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
9-27	0730	31	12	0	0
9-28	0730	17	12	0	0
9-29	1330	8	18	0	0
9-30	1215	15	16	0	0
10-1	1240	7	11	0	0
10-2	1313	44	14	0	0
10-3	1200	66	23	0	0

Invasive Species: No zebra or Quagga mussels were observed.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Oregon Department of Fish and Wildlife and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Little Goose Dam for this reporting period are reported below.

Date	Sample	Collection*
9-27	122	122
9-28	157	157
9-29	136	136
9-30	130	130
10-1	168	168
10-2	200	200
10-3	64	64
Totals	977	977

\*Collection and sample numbers are the same as the facility when sampling at 100%

Gas Bubble Trauma (GBT): The last gas bubble monitoring occurred on July 15.

Fish Rescue/Salvage: A fish salvage was conducted in gatewell 3A on September 10 to support a VBS fastener upgrade. No fish were observed during the operation.

Research: N/A

**Project: Lower Granite**

Biologists: Elizabeth Holdren and Steve Lee

Dates: September 27 to October 3, 2019

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

## Lower Granite Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	09/30	0700			Annual Maintenance
4	09/30	0954	10/02	1453	Failed motor operated cooling valve

Comments: None.

**Adult Fish Passage Facility**

Lower Granite Corps biologist's and Anchor Environmental biologist's inspected the adult fish ladder September 27, 28, 30, and October 2.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head $\leq$ 0.5'	
X			Fish Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
		X	Fish Ladder Cooling Water Pumps in Service		
		X	Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments: Fish ladder temperature control pumps were removed from service at 1700 hours September 25 in response to FPP adult ladder operation criteria.

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
	X		South Shore Entrance (SSE-1) Weir Depth	$\geq$ 8.0'	7.8'
	X		South Shore Entrance (SSE-2) Weir Depth	$\geq$ 8.0'	7.8'
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
	X		North Powerhouse Entrance (NPE-1) Weir Depth	$\geq$ 8.0' or on sill	6.7
	X		North Powerhouse Entrance (NPE-2) Weir Depth	$\geq$ 8.0' or on sill	6.6
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
	X		North Shore Entrance (NSE-1) Weir Depth	$\geq$ 7.0' or on sill	6.9
			North Shore Entrance (NSE-2) Weir Depth	$\geq$ 7.0' or on sill	Closed
X			North Shore Channel/Tailwater Differential	1.0' – 2.0'	
	X		Collection Channel Surface Velocity	1.5 – 4.0 fps	1.4

Comments: Since May 4 the fish ladder control system screen and local reading for the south shore channel/tailwater and depth over the SSEs have been inconsistent. SSE gates remain in local operation until Operation and District engineering can resolve the control system issues. All weir gate depths were out of criteria on the October 2

inspection. NSE-1 motor control brake failed October 3. NSE-1 was set at sill depth of 628.0 feet. SSE-1 and SSE-2 were lowered manually to meet gate depth criteria in response to the out of criteria reading October 4.

NPE channel velocity sensor readings have consistently read below 1.5 fps for several weeks. Surface velocity is being verified using tape measure and stopwatch and found to be in criteria. Surface velocities and/or NSE velocities will be used until the fish ladder control system NPE velocity issues are resolved. Velocities have been reading below 1.5 fps at both north powerhouse and north shore sensors. Biologists, operators, and District engineers are working to resolve fish ladder velocity issues and control system issues.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
X			AWS Fish Pump 1
	X		AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: AWS pump 1 remains in fast mode to improve collection channel velocity and channel/tailwater differentials.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
	X		Any debris seen in gatewells (% coverage)	
X			Any oil seen in gatewells?	

Comments: An unidentified film was noted in gatewell slots 4C and 6A September 29. Absorbent materials were immediately deployed to remove the substances. The source was unidentifiable.

ESBSs/VBSs:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
		X	ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: The collection channel is operating with twelve 14” orifices and six 10” orifices open to maintain optimal flume flow at current forebay elevation. The north makeup water valve remains in local control due to an

automatic control motor hardware failure. Intermittent issues with local and remote operation of orifices for back flushing continue to be observed. Problems are reported to operations when they are identified.

Hours Collection Facility: The facility is in collection for transport mode at a 100% sample rate.

Transport Summary: Every-other-day truck transport continues.

Spillway Weir: No spill is occurring at this time.

### River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
26.5	22.5	0	0	64.0	62.0	5.0	5.0

\*Cooling water intake temperature.

### Other

Inline Cooling Water Strainers: Cooling water strainers were not inspected during this reporting period.

Invasive Species: There were 386 Siberian prawns collected in the sample this week. Of these, 335 were live collected and euthanized and 51 were mortalities when sampled. No signs of Zebra/Quagga mussels were found on submerged substrates.

Avian Activity: Bird wires were removed from the spillway tailrace area August 29 for crane barge access to spillway 1 for PIT tag detection array install. Biologist daily piscivorous bird counts at Lower Granite Dam are listed below.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
09/27	0840	6	22	0	0
09/28	1144	0	12	0	0
09/29	1215	12	17	0	0
09/30	0950	22	24	0	0
10/01	1245	22	29	0	0
10/02	1133	26	30	0	0
10/03	1230	22	27	0	0

Gas Bubble Trauma (GBT) Monitoring: GBT monitoring has ended for the year.

Adult Fish Trap Operations: Adult trap operation remains a 20 % sample rate, 24 hours per day, 7 days per week for NPTH and LFH brood stock collection for transport. Collection of B-run steelhead brood stock for IDFG and collection of Coho brood stock for NPT began October 2.

Fish Rescue/Salvage: No fish salvage/rescue operations occurred during this reporting period.



## Research:

### USGS Juvenile Fall Chinook Salmon Growth and Origin:

USGS began collection of previously tagged subyearling Chinook utilizing LWG juvenile collection facility SbyC system October 1 and will continue through October 31. Previously PIT tagged fish are diverted to the SbyC tanks, weighed, measured, scanned for PIT tag code, recovered from anesthetic, and released back to the river. The objective of this project is to estimate the growth of PIT-tagged subyearling Chinook salmon from the Clearwater River to Lower Granite Dam.

### National Marine Fisheries Service (NMFS) PIT tagging of Adult Wild Chinook and Adult Steelhead for ISEMP-Related Dispersal Monitoring:

The goal of this project is to PIT tag up to 4000 unclipped adult Chinook and 4000 unclipped adult steelhead collected in the adult trap daily sample for dispersal monitoring.

### National Marine Fisheries Service (NMFS) Ancillary Adult Passage Monitoring:

Fish that were PIT as juveniles at LWG are monitored as returning adults through the river and LWG facility. For each returning adult the following is estimated; 1) passage time between sets of detection PIT tag coils, 2) whether the fish was handled at the adult trap, 3) duration the fish was held at the adult trap, 4) overall passage time from ladder entrance to exit, 5) whether the turnpool gate was open or closed during passage. This will be the last year of this evaluation.

### Sampling of Steelhead, Chinook salmon, and Sockeye salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating steelhead, spring/summer Chinook salmon, and sockeye salmon are collected from the adult trap beginning April 4 through December 15. The goal is to collect 5-20% of adult steelhead, spring/summer Chinook salmon, and sockeye salmon ascending the ladder April 4-December 15. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. All natural origin adult steelhead and spring/summer Chinook salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some steelhead and spring/summer Chinook salmon may be radio-tagged or spaghetti-tagged. This information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs.

### PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be incidentally collected as part of the normal adult trap daily sample as well as the recaptured previously PIT tagged using adult SbyC system. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder.