

**U.S. ARMY CORPS OF ENGINEERS  
WALLA WALLA DISTRICT  
FISH FACILITIES WEEKLY REPORT  
#21-2020**

**Project: McNary**

Biologist: Bobby Johnson and Denise Griffith

Dates: July 17 to 23, 2020

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 14 turbine units available for service. (See table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

Unit(s)	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	5/23/19	0943	7/31/20	NA	Turbine blade packing.
9	7/20	0630	7/23	1700	Annual maintenance.

Comments: The hard one percent peak efficiency constraint continued. The biologist requested the saw tooth unit priority pattern for temperature abatement on July 22, at 0725 hours as water temperature in the sample tanks reached 68 degrees Fahrenheit.

**Adult Fish Passage Facilities**

McNary fisheries biologists performed measured inspections of the adult fishways on July 17, 19 and 22. Adult fish counting and video review of night time lamprey passage continued.

Fish Ladder Exits:

Yes	No	Location	Criteria	Comments
	X	Oregon Exit	Head over weir 1.0' to 1.3'	0.9' on July 22
X		Oregon Count Station Differential	0.0' to 0.5'	
X		Washington Exit	Head over weir 1.0' to 1.3'	
X		Washington Count Station Differential	0.0' to 0.5'	

Comments: Debris loads were very light to light near the Oregon exit and minimal near the Washington exit. Aquatic vegetation continued to be an issue. The general maintenance staff cleaned the picketed leads frequently, including the weekend. The Oregon exit traveling screens debris trough was cleaned as required.

At the Oregon exit, the out of criterion point above was resolved with a set point adjustment. Also, traveling screen alarms were reset on July 22.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			North Oregon Entrance Head Differential	1.0' – 2.0'	
X			NFEW2 Weir Depth	≥ 8.0'	
X			NFEW3 Weir Depth	≥ 8.0'	
X			South Oregon Entrance Head Differential	1.0' – 2.0'	
X			SFEW1 Weir Depth	≥ 8.0'	
X			SFEW2 Weir Depth	≥ 8.0'	
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	Averaged 1.9 fps.
X			Washington Entrance Head Differential	1.0' – 2.0'	
X			WFE2 Weir Depth	≥ 8.0'	
X			WFE3 Weir Depth	≥ 8.0'	

Comments: There are no problems to report.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			WA shore Wasco County PUD Turbine Unit
	Yes		WA shore Wasco PUD Bypass
		Yes	Oregon shore Fish Pump 1, OOS to September 12.
Yes			Oregon Ladder Fish Pump 2, Blade angle: 25°.
Yes			Oregon Ladder Fish Pump 3, Blade angle: 24 to 26°.
Yes			OR North Powerhouse Pool supply from juvenile fishway

Comments: There are no problems to report.

**Juvenile Fish Passage Facility**

The sampling season, consisting of alternating days of primary and secondary bypass, continued. There were no interruptions in the schedule.

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Very light to moderate.
X			Trash rack differentials measured this week?	Daily.
X			Trash rack differentials acceptable?	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Debris loads were light to moderate along the powerhouse and moderate beside the spillway. Incoming debris loads were minimal to very light and consisted mostly of aquatic vegetation. The debris continued to dissipate as it moved back and forth from the powerhouse to the Oregon shoreline with wind direction changes. Debris removal has not yet been required.

No trash rack cleaning occurred this week.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs):

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: ESBS's remained deployed in all units, except for unit 5, which is out of service. ESBS camera inspections occurred in unit 9 while the unit was out of service on July 20. No problems were found.

Daily VBS differential monitoring continued. No high differentials were measured. A total of ten screens were cleaned on July 20, 21 and 23. No fish were observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

Yes	No	NA	Item	Number of orifices in service
X			Orifices operating satisfactory?	42
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: Orifices were adjusted for VBS cleaning as required. Orifice operators were repaired as needed.

Bypass Facility:

Yes	No	NA	Item
X			Sample gates on?
		X	PIT-tag sampling system on?

Comments: The sample gates were only operated on secondary bypass days. The PIT-tag system remained out of service as there are no studies requiring its use.

This week, 100 juvenile lamprey and 34,152 smolts were bypassed during secondary bypass. Subyearling Chinook remained the primary species in the samples.

Two subyearling Chinook mortalities were removed from under the primary bypass gate this week, bring the total to six subyearlings for the season. This issue will be examined during the next winter outage.

TSW Operations: The TSW's remained out of service. Standard gates remain in bays 19 and 20.

**River Conditions**

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
223.9	189.8	127.6	108.5	68.3	65.7	6.0	6.0

Comments: The above data was supplied by the smolt monitoring staff except water clarity, which came from the control room. The summer spill program continued, with 57 percent of the flow being spilled.

Spillbay 15's gate remained lowered onto seal awaiting arrival of parts to repair the bearing mount for the hoist's north drum pillow block.

Crane 6, which was attached to the spillgate in bay 20, failed on July 20. Initially, the bay was open at 2 feet and was part of the spill pattern. The spillway gate could not be adjusted due to an electrical failure in Crane 6. Because of safety and other concerns, the gate was closed on seal on July 21. Crane 6 was moved to the south end of the spillway for future repairs. Locating and procuring parts for Crane 6 will require time so no return to service date has been set.

Spill for bays 15 and 20 was distributed throughout the other bays.

Crane 7 is attached to the spillgate in bay 2. Due to the failure of Crane 6, in order to preserve the functionality of Crane 7, which is critical to emergency action plan, Crane 7 was removed from GDACS auto response control on July 23. Current spill pattern changes occur too frequently in auto response, causing wear and tear on old equipment that is not designed to operate so frequently. Per the district hydraulic engineer, the gate in bay 2 was set at four stops open for the remainder of the spill season.

All water temperature monitoring probes are now in place except for 5B gatewell slot due to an ESBS being stored. Daily monitoring and reporting throughout the juvenile passage facility continued. The smolt monitoring staff will publish weekly results in a separate report. The weekly report will include any issues with the probes. The new weather station was installed on July 23 and will be programmed early next week.

### Other

Inline Cooling Water Strainers: The next cooling water strainer examinations will occur on August 4.

Avian Activity: Avian counts continued. These counts are reflected in Table 3 below.

Table 3. McNary Project's Daily Avian Count.

Date	Zone	Gull	Cormorant	Tern	Pelican
July 17	Spill	0	0	3	21
	Powerhouse	0	0	0	4
	Outfall	1	0	0	11
July 18	Spill	1	0	1	32
	Powerhouse	0	0	0	3
	Outfall	2	0	0	8
July 19	Spill	0	0	1	13
	Powerhouse	0	0	0	3
	Outfall	1	0	0	2
July 20	Spill	3	0	1	6
	Powerhouse	0	0	0	0
	Outfall	3	1	0	0
July 21	Spill	0	1	0	20
	Powerhouse	0	0	0	2
	Outfall	2	1	0	0
July 22	Spill	3	0	2	27
	Powerhouse	0	0	0	1
	Outfall	7	4	0	2
July 23	Spill	12	2	3	22
	Powerhouse	0	0	0	0
	Outfall	5	0	0	3

Only pelicans were observed in the powerhouse zone at the Oregon ladder floating orifice gates during the day.

In the spillway zone, gull numbers were very low. The gulls were feeding and roosting. Cormorants were present only observed when roosting. Tern numbers remained fairly low with birds feeding. Pelican numbers were stable with most of them feeding. An occasional osprey was noted roosting. The breaks in the spill pattern with bays 15 and 20 closed did not appear to attract birds.

At the juvenile bypass outfall, gulls, pelicans and cormorants were noted attempting to feed. Also, gulls and cormorants were roosting on the bypass pipe.

In the forebay zone, zero to 16 grebes and zero to nine juvenile gulls were observed, along with an occasional pelican, cormorant or osprey. Also, pelicans, gulls and cormorants were noted on the roosting rocks along the Washington shoreline in low numbers. Finally, a flock of adult gulls was observed outside the counting zone.

No pelicans were observed inside the Oregon ladder exit. A few pelicans were observed just outside the exit at times.

No grebes were observed in the gatewell slots or in the juvenile collection channel.

The lasers on the navigation lock wing wall and on the juvenile bypass outfall walkway were returned to service as part of an evaluation study on July 20. The lasers appeared to reduce feeding but had little effect on roosting. Though functional, we believe the outfall laser needs to be replaced.

The bird distress calls deployed along on the navigation lock wing wall appeared to be successful. No decision has been made on where to install the second large distress call. The forebay grebe distress call remained deployed and appeared somewhat effective. However, we feel more volume is required.

USDA Wildlife Services' last eight hour shift will concluded on July 25. Hazing continued from shore in the tailwater area and forebay zone.

Invasive Species: The next mussel station examinations will occur on July 29. No Siberian prawns were observed in this week's samples. None have been observed so far this season.

Fish Rescue/Salvage: None occurred this week.

Research: The gas bubble trauma (GBT) examinations occurred on July 17 and 21. No smolts were observed with signs of GBT. Examinations will continue twice a week.

**Project: Ice Harbor**

Tim DeKoster (Fisheries Tech)

Dates: July 17, 2020 – July 23, 2020

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Ice Harbor Unit Outages (OOS) and Return to Service (RTS).

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	5/3/19	0641	---	---	Turbine runner replacement and stator rewind
4	7/6/20	0740	---	---	Annual maintenance

Comments: None.

**Adult Fish Passage Facility**

Ice Harbor Fish Facility staff inspected the adult fishways on July 20<sup>th</sup>, 21<sup>st</sup>, and 22<sup>nd</sup>.

Fish Ladders:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head $\leq$ 0.3'	
X		North Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head $\leq$ 0.3'	
X		South Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
		X	South Shore Entrance (SFE-1) Weir Depth	$\geq$ 8.0' or on sill	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			South Shore Channel Velocity	1.5 – 4.0 fps	
		X	North Powerhouse Entrance (NFE-2) Weir Depth	$\geq$ 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Shore Entrance (NEW-1) Weir Depth	$\geq$ 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: None.

Auxiliary Water Supply (AWS) System :

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
6 pumps	2 pumps		Status of the 8 South Shore AWS Pumps
2 pumps	1 pump		Status of the 3 North Shore AWS Pumps

Comments: None.

### Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Average of 2.67 square yards
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0-6%
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service for available units?
X			STSs in continuous-run mode? (Note: if not, then STSs are in cycle-run mode).
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: The STSs were switched to continuous-run mode on May 18<sup>th</sup>, due to the presence of subyearling Chinook in the Ice Harbor fish sample with an average fork length of less than 120 mm.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	20
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Juvenile Fish Facility: The Juvenile Fish Facility is being operated in primary bypass mode, except when collecting fish for sampling.

Fish Sampling: Fish sampling is done for the year at Ice Harbor Project. The last day fish sampling was conducted was on July 16<sup>th</sup>.

Removable Spillway Weir (RSW): Voluntary spill for fish passage is occurring.

### River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
47.6	41.1	17.9	12.3	67	66	8.0	6.0

\*Unit 1 scroll case temperature.

Comments: None.

### Other

Inline Cooling Water Strainers: Monthly strainer inspections for lamprey ended in June and will resume in December.

Avian Activity: There were low numbers of piscivorous birds seen around the project (see table below).

Daily maximum piscivorous bird counts at Ice Harbor Dam.

<b>Date</b>	<b>Gulls</b>	<b>Cormorants</b>	<b>Caspian Terns</b>	<b>Grebes</b>	<b>Pelicans</b>
July 17	---	---	---	---	---
July 18	---	---	---	---	---
July 19	---	---	---	---	---
July 20	5	0	0	0	27
July 21	12	6	0	0	10
July 22	36	3	0	0	11
July 23	17	5	0	0	10

Invasive Species: No new exotic species have been discovered.

Fish Rescue/Salvage: Unwatering activities that involved fish rescue did not occur this week.

Research: No on-site research is occurring at this time.

If you have any questions please contact the Ice Harbor Fish Facility Biologist Ken Fone for more information and updates.



**Project: Lower Monumental**

Biologists: Chuck Barnes and Raymond Addis

Dates: July 17 - 23, 2020

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

**Lower Monumental Unit Outages (OOS) and Return to Service (RTS)**

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 2	7/15/2019	0720	8/28/2020	ERTS	Annual, Draft Tube Liner
Unit 3	7/06/2020	0706	8/06/2020	ERTS	Annual Maintenance

Comments: None.

**Adult Fish Passage Facility**

The adult fishways were inspected by Corps and EAS/Anchor QEA biologists on July 17, 18, 19 and 22.

Fish Ladder:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head $\leq$ 0.5'	
X		North Ladder Picketed Lead Differential	Head $\leq$ 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head $\leq$ 0.5'	
X		South Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments:

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	$\geq$ 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	$\geq$ 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	$\geq$ 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	$\geq$ 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
		X	South Shore Entrance (SSE-1) Weir Depth	$\geq$ 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	$\geq$ 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	

**Comments:**

South Powerhouse Entrance (SPE-1) Weir was on sill during all inspections with readings of 6.3, 6.0, 5.7 and 6.2 feet respectively.

South Powerhouse Entrance (SPE-2) Weir was on sill during all inspections with readings of 6.3, 6.0, 5.7 and 6.2 feet respectively.

South Shore Entrance (SSE-1) Weir was on sill during all inspections with readings of 6.4, 6.6, 6.1 and 6.8 feet respectively.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments: None.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	180 yds <sup>2</sup>
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0 – 10%
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service?
	X		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: STS's were operating in cycle mode due to average sub-yearling Chinook and sockeye lengths being greater than 120 mm.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Collection Facility: The Juvenile collection facility was watered up at 10:00 on March 26.

Collection into raceways for transport ended at 1500 on June 21. The facility went into secondary bypass with daily condition sampling at that time. A total of 15,684 fish were collected with total of 15,674 bypassed back to the river.

Transport Summary: Alternate day barge transport ended June 21.

Spillway Weir: RSW went into service at 0001 on April 3.

### River Conditions

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
45.2	38.1	17.0	17.0	68.0	66.3	6.3	3.4

\*Scrollcase temperatures.

### Other

Inline Cooling Water Strainers: Cooling water strainers were inspected on July 6. No live fish were recovered. Mortalities included 7 salmonid smolts and 9 juvenile lamprey.

Avian Activity: Highest counts of foraging piscivorous birds in tailrace (SWT1+PH1+PH2) at Lower Monumental Dam.

Date	Time	Gulls	Cormorants	Terns	Grebes	Pelicans
7/17/2020	1400	9	0	0	0	3
7/18/2020	1000	13	0	0	0	1
7/19/2020	1400	0	0	0	0	0
7/22/2020	0900	6	0	0	0	0

\* Table shows tailrace observation conducted during Adult Fish Ladder inspections

Comments: Bird hazing efforts by USDA personnel ended June 2, 2020.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on July 5.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by PSMFC and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Lower Monumental Dam for this reporting period are reported below.

Date	Sample (euthanized)	Collection*
7/17/2020	0	0
7/18/2020	4	80
7/19/2020	0	0
7/20/2020	12	240
7/21/2020	3	30
7/22/2020	6	60
7/23/2020	7	70
Total	32	480

\*Collection and sample numbers are the same as the facility when sampling at 100%

Fish Rescue/Salvage: No Fish Rescue/Salvage took place during this reporting period.

Research: No research is occurring at this time.

**Project: Little Goose**

Biologists: Scott St. John and Richard Weis

Dates: July 17-23, 2020

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

**Little Goose Unit Outages (OOS) and Return to Service (RTS)**

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	04/14/17	14:11	03/31/21	17:00	Spider and upper guide bearing repair.
6	07/06/20	07:25	07/30/20	17:00	Unit annual maintenance

Comments: None.

**Adult Fish Passage Facility**

Little Goose fish facility staff inspected the adult fishway on July 19, 21 and 23.

**Fish Ladder:**

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head $\leq$ 0.5'	
X			Fish Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X			Fish Ladder Cooling Water Pumps in Service		
X			Fish Ladder Exit Cooling Water Pumps Operating Satisfactorily		

Comments: Adult ladder cooling pump was started on June 22 at 1035.

**Fishway Entrances and Collection Channel:**

Yes	No	Sill	Location	Criteria	Measurements
X			South Shore Entrance (SSE-1) Weir Depth	$\geq$ 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	$\geq$ 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	$\geq$ 7.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	$\geq$ 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	$\geq$ 6.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	$\geq$ 6.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: The adult fishway continues to operate in manual mode. Project staff have struggled to maintain entrance criteria at the NSE. The fish control system still has a faulty I/O module for the NSE weirs and is currently being repaired. Subsurface water velocity was measured on July 3 and averaged 2.4 feet per second.

**Auxiliary Water Supply System:**

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None.

### Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
	X		Any debris seen in gatewells (% coverage)	
X			Any oil seen in gatewells?	4A

Comments: There is approximately 60 square feet of floating woody debris currently inside the trash shear boom in the forebay. Drawdowns were performed on July 23 on units 1 and 2 and were in criteria. Oil sheen detected on July 18 in gatewell 4A, determined to be from EAL cable lube dripping from the gantry crane. Crane was immediately moved, absorbent pads were deployed, and sheen completely dissipated by July 22.

ESBS/VBS:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?
	X		VBSs inspected this week?

Comments: VBS differentials were last performed on July 23 on units 1, and 2 and were in criteria.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	19
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: The airline for the backflush system on orifice 1C1 was found broken and will need repaired once the juvenile channel is dewatered for winter maintenance (MFR 20 LGS 12). During prior ESBS/VBS inspections, an issue with the orifice liner in 6C2 was observed and will need repaired during winter maintenance (MFR 20 LGS 14).

Collection Facility: Collection for condition sampling began on April 1. The facility continues to collect for daily sample and was placed in secondary bypass on June 21. Collection for truck transport is scheduled to begin on August 1 with the first truck departing on August 3.

Transport Summary: Everyday barge transport began on April 24 and ended on May 18. Every other day barging started with the first barge leaving on May 20. Last barge of the season left LGS on June 21. The JFF is collecting for condition sample every day and is in secondary by-pass. The collection and transportation facility operated within criteria this report period. A total of 15,086 fish were collected. Of those, 15,070 were bypassed back to the

river. The descaling and mortality rates were 1.1% and 0.16%, respectively. There was 1 adult lamprey removed from the separator this report period and released upstream of the powerhouse.

Spillway Weir: Summer spill operations began on June 21 with the ASW crest height set in the high position.

### River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
46.5	38.1	13.9	11.3	68.8	67.1	6.0	4.9

\*Ladder temperature.

### Other

Inline Cooling Water Strainers: Inline cooling strainers were inspected and results submitted to district operations every other week for FPOM distribution through mid-June per Fish Passage Plan (FPP) requirements.

Avian Activity: Daily piscivorous bird counts at Little Goose Dam began on April 1.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
7-17	1500	15	14	0	0
7-18	0730	14	2	0	0
7-19	0730	20	8	0	1
7-20	0800	23	4	0	0
7-21	1300	16	6	0	0
7-22	1000	61	0	0	0
7-23	0730	151	2	0	1

Invasive Species: No invasive species have been observed on the mussel station.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Oregon Department of Fish and Wildlife and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Little Goose Dam for this reporting period are reported below.

Date	Sample	Collection*
7-17	291	1,455
7-18	253	1,265
7-19	189	756
7-20	188	752
7-21	208	832
7-22	171	1,368
7-23	66	1,320
Totals	1366	7,748

Gas Bubble Trauma (GBT): GBT monitoring was performed on July 19. Of the 5 fish examined, one showed signs of GBT.

Fish Rescue/Salvage: None.

Research: The Nez Perce Tribe (NPT) ended steelhead kelt collection on June 25.

**Project: Lower Granite**

Biologists: Elizabeth Holdren and David Miller

Dates: July 17-23, 2020

---

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Lower Granite Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	June 20	0751	July 23	1538	Annual Maintenance

Comments: None.

**Adult Fish Passage Facility**

Lower Granite and EAS/Anchor QEA staff inspected the adult fishway July 17, 18, 20, and 22.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head $\leq$ 0.5'	
X			Fish Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
	X		Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	1.4
X			Fish Ladder Cooling Water Pumps in Service		
X			Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments: Adult fish ladder temperature control system remains in operation.

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			South Shore Entrance (SSE-1) Weir Depth	$\geq$ 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	$\geq$ 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	$\geq$ 8.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	$\geq$ 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	$\geq$ 7.0' or on sill	
			North Shore Entrance (NSE-2) Weir Depth	$\geq$ 7.0' or on sill	Closed
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: FOGs 1 and 10 are in operation. Impacts of spill operation on ladder out of criteria readings have declined with summer spill.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
No		OOS guide bearing	AWS Fish Pump 3

Comments: AWS pump 3 remains in standby until LWG mechanical is able to perform standard testing that requires all AWS pumps be removed from service for 4 hours while stoplogs are swapped.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil: Forebay debris has not created any fish passage issues this season. Some woody debris observed in the forebay this season is likely due to the failure in the upriver two sections of the forebay debris boom. Though this has not created a problem, repairs are recommended to prevent further damage to the boom and potential for additional debris in the powerhouse forebay and on unit trashracks.

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Gatewell differentials were measured on July 19.

ESBSs/VBSs:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
		X	ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18-24
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: Juvenile collection channel water level and flow is being adjusted using 10” orifices depending on forebay elevations. The 14” orifice in gatewell slot 4C was removed from service June 10 to prevent fish injury due to a damaged flange. The 10” orifice remains in operation and with no issues.

Collection Facility: The sample rate is being adjusted daily based on fish passage numbers. The facility is in secondary bypass mode. Collection for transport is scheduled to begin at 0700 hours August 1.

Transport Summary: Truck transport is scheduled to begin with the first truck departing LWG August 3.

Spillway Weir: Summer spill continues.



## River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
46.2	41.7	18.8	18.6	65.5	64.0	5.0	5.0

\*Cooling water intake temperature.

## Other

Inline Cooling Water Strainers: Unit cooling strainer inspections were conducted on June 25.

Invasive Species: No zebra/quagga mussels were detected on the trap substrate. There was 547 Siberian prawn collected in the sample and euthanized for disposal.

Avian Activity: Biologist daily piscivorous bird counts at Lower Granite Dam.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
July 17	1410	5	12	0	0
July 18	1010	1	5	0	0
July 19	0831	0	5	0	0
July 20	0835	3	7	0	0
July 21	1043	1	5	0	0
July 22	1105	8	7	0	0
July 23	1223	8	10	0	0

Adult Fish Trap Operations: Adult trap operations resumed at 0700 hours July 2 with an overall sample rate of 20%. LWG Project Biologist are providing oversight and operating the adult facility with IDFG handling the adult fish sample.

Fish Rescue/Salvage: The adult fish trap was flushed due to shad mortalities plugging the drain screen. During trap flushing one unclipped Chinook mortality was observed. It is likely the trap will continue to need to be dewatered for flushing at least once a week. Currently flushing is scheduled for Wednesday's and Sunday's.

Research:

National Marine Fisheries Service (NMFS) Ancillary Adult Passage Monitoring:

Fish that were PIT as juveniles at LWG are monitored as returning adults through the river and LWG facility. For each returning adult the following is estimated; 1) passage time between sets of detection PIT tag coils, 2) whether the fish was handled at the adult trap, 3) duration the fish was held at the adult trap, 4) overall passage time from ladder entrance to exit, 5) whether the turnpool gate was open or closed during passage. This will be the last year of this evaluation.

Sampling of Steelhead, Chinook salmon, and Sockeye salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating steelhead, spring/summer Chinook salmon, and sockeye salmon are collected from the adult trap beginning April 4 through December 15. The goal is to collect 5-20% of adult steelhead, spring/summer Chinook salmon, and sockeye salmon ascending the ladder April 4-December 15. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. All

natural origin adult steelhead and spring/summer Chinook salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some steelhead and spring/summer Chinook salmon may be radio-tagged or spaghetti-tagged. This information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs.

PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be collected as part of the normal adult trap daily sample and using the adult SbyC system to recapture previously PIT tagged fish. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder.