

**U.S. ARMY CORPS OF ENGINEERS
WALLA WALLA DISTRICT
FISH FACILITIES WEEKLY REPORT
#31-2020**

Project: McNary

Biologist: Bobby Johnson and Denise Griffith

Dates: September 25 to October 1, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 14 turbine units available for service. (See table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

Unit(s)	OOS		RTS		Outage Description
	Date	Time	Date	Time	
9	9/14	0700	10/2	1305	Annual and other maintenance.
3	9/21	0700	10/1	1722	New top plate pump installation.
10	9/28	0700	10/1	1613	Annual maintenance.
7 & 8	9/29	1000	9/29	1100	ESBS camera inspections.

Comments: The hard one percent peak efficiency constraint continued.

Adult Fish Passage Facilities

McNary fisheries biologists performed measured inspections of the adult fishways on September 25, 27 and 29. Adult fish counting continued. Video review of nighttime lamprey passage concluded on September 30.

District personnel performed maintenance on the Washington ladder water temperature monitoring system on September 25.

Fish Ladder Exits:

Yes	No	Location	Criteria	Comments
X		Oregon Exit	Head over weir 1.0' to 1.3'	
X		Oregon Count Station Differential	0.0' to 0.5'	
X		Washington Exit	Head over weir 1.0' to 1.3'	
X		Washington Count Station Differential	0.0' to 0.5'	

Comments: Debris loads were very light to light near the Oregon exit and minimal to light near the Washington exit. Aquatic vegetation continued to be an issue. The general maintenance staff cleaned the picketed leads frequently, including the on weekend.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			North Oregon Entrance Head Differential	1.0' – 2.0'	
X			NFEW2 Weir Depth	≥ 8.0'	
	X		NFEW3 Weir Depth	≥ 8.0'	7.9' on Sep 25.
X			South Oregon Entrance Head Differential	1.0' – 2.0'	
X			SFEW1 Weir Depth	≥ 8.0'	
X			SFEW2 Weir Depth	≥ 8.0'	
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	Averaged 1.7 fps.
X			Washington Entrance Head Differential	1.0' – 2.0'	
X			WFE2 Weir Depth	≥ 8.0'	
X			WFE3 Weir Depth	≥ 8.0'	

Comments: The out of criterion point noted above was possibly due calibration drift.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			WA shore Wasco County PUD Turbine Unit
	Yes		WA shore Wasco PUD Bypass
		Yes	Oregon shore Fish Pump 1, OOS to November 19.
Yes			Oregon Ladder Fish Pump 2, Blade angle: 24°.
Yes			Oregon Ladder Fish Pump 3, Blade angle: 24°.
Yes			OR North Powerhouse Pool supply from juvenile fishway

Comments: Repairs to fish pump 1 continued.

Juvenile Fish Passage Facility

The sampling season, consisting of alternating days of primary and secondary bypass, concluded on September 30 at 0700 hours. There were no interruptions in the schedule. With the fall primary bypass season starting, partial winterization and light maintenance of the juvenile passage system will begin. The technician who covered swing shift was furloughed on September 30. For the remainder of the season, there will be no fisheries staff member on duty from 1600 to 0000 hours.

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Very light to light.
X			Trash rack differentials measured?	Daily.
X			Trash rack differentials acceptable?	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Debris loads were very light to light near the powerhouse and minimal beside the spillway. Incoming debris loads were very light and consisted mostly of aquatic vegetation. The woody debris and aquatic vegetation continued to move back and forth from the powerhouse to the Oregon shoreline.

No trash rack cleaning or forebay debris removal occurred.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs):

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: ESBS's remained deployed in all units. ESBS camera inspections in units 7 and 8 revealed no problems on September 29.

Daily VBS differential monitoring continued. No high differentials were measured. A total of eight screens were cleaned on September 27 and October 1. No fish mortalities were observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

Yes	No	NA	Item	Number of orifices in service
X			Did orifices operate satisfactory?	42
X			Were the dewaterer and cleaning systems operated satisfactory?	

Comments: Due to continued concern for the two side dewatering valves, orifices cycling remained once a day. Orifices were adjusted for VBS cleaning as required.

The transition screen cleaning brush remained out of service. The air burst system's zone 5 kept the transition screen clean.

The north side dewatering valve, one of two valves that regulate the channel water elevation, had its control response time reduce on September 28. The electrical staff monitored the side dewatering valves all week and concluded that all the adjustments that could be made have been done. Future access to the control program is our next step. The north valve appeared to run less frequently with cooler motor temperatures after the adjustment. However, the valve still appeared to be hanging up at times, which resulted in a "popping" noise. This remains a concern. We began monitoring both valves' motor temperatures on September 29. We were informed that the valve actuators' trip off temperature was 150 degrees F. The highest motor temperature we recorded was 110 degrees F.

Latching down the covers on the flume section of the bypass pipe continued.

Bypass Facility:

Yes	No	NA	Item
X			Sample gates on?
		X	PIT-tag sampling system on?

Comments: The sample gates were only operated on secondary bypass days with the gates turned off on September 30 at 0700 hours for the season. The PIT-tag system remained out of service.

This week, 16 juvenile lamprey and 32 smolts were bypassed during secondary bypass. Juvenile shad were the predominate species examined in the sample.

Area lighting received scheduled maintenance this week. Also, a tool rack was installed behind the separator observation building.

Top Spillway Weir (TSW) Operations: The TSW in bay 19 remained out of service. The TSW in bay 20 is being used for the adult steelhead TSW passage efficiency study and as required by the new Biological Opinion. The TSW will be opened per the study plan.

River Conditions

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
119.8	73.1	1.3	0.0	65.6	64.3	6.0	6.0

Comments: The above data was supplied by the smolt monitoring staff except water clarity, which came from the control room. The spill recorded above was for the TSW study.

Other

Inline Cooling Water Strainers: The next cooling water strainer inspections will occur on December 1.

Avian Activity: Avian counts concluded on September 30. These counts are reflected in Table 3 below.

Table 3. McNary Project's Daily Avian Count.

Date	Zone	Gull	Cormorant	Tern	Pelican
Sept 25	Spill	178	5	0	0
	Powerhouse	9	0	0	0
	Outfall	3	30	0	0
Sept 26	Spill	147	48	0	0
	Powerhouse	30	0	0	0
	Outfall	17	47	0	0
Sept 27	Spill	28	33	0	0
	Powerhouse	10	0	0	0
	Outfall	1	33	0	0
Sept 28	Spill	65	49	0	0
	Powerhouse	164	0	0	0
	Outfall	0	0	0	0
Sept 29	Spill	130	9	0	0
	Powerhouse	42	0	0	0
	Outfall	8	35	0	0
Sept 30	Spill	20	11	0	0
	Powerhouse	1	2	0	0
	Outfall	0	37	0	0

No terns and pelicans were observed on project.

At times, gulls were observed feeding in the powerhouse zone along with some roosting. The gull feeding activity occurred very quickly. An occasional cormorant was also noted feeding.

In the spillway zone, gull and cormorants were observed. The birds were roosting around the spill basin with some feeding activity, especially during TSW use. Again, feeding activity was very short. An occasional grebe was also observed.

At the juvenile bypass outfall, gulls and cormorants were noted feeding in increasing numbers after the lasers were turned off and then removed. However, roosting on the bypass pipe was still the primary use of the area.

In the forebay zone, an occasional gull, grebe or osprey was observed. A few gulls and cormorants were noted on the roosting rocks along the Washington shoreline. Finally, a flock of gulls was observed outside the counting zone, at times.

Both lasers were removed for the winter on September 28. The bird distribution seen in Table 3 above for that date was recorded when the fisheries staff was on the outfall pipe walkway.

The bird distress calls deployed along on the navigation lock wing wall and the second large distress call deployed on the juvenile facility barge loading dock appeared to be somewhat effective.

There is no active hazing program currently.

A future LRAD test has not yet been scheduled.

Invasive Species: The next mussel station examinations will occur in late October. One Siberian prawn was observed in this week's samples and was euthanized. The yearly total was three prawns.

Fish Rescue/Salvage: None occurred this week.

Research: Pacific Northwest National Laboratory (PNNL) continued with the adult steelhead TSW passage efficiency study.

Project: Ice Harbor

Biologist: Ken Fone

Dates: September 25, 2020 – October 1, 2020

Turbine Operation

Yes	No	Turbine Unit Status		
	X	All 6 turbine units available for service (see table & comments below for details).	Hard	Soft
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Ice Harbor Unit Outages (OOS) and Return to Service (RTS).

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	5/3/19	0641	---	---	Turbine runner replacement and stator rewind
5	9/21/20	0900	---	---	Annual maintenance and overhaul
6	9/25/20	1345	9/25/20	1526	Governor oil pump #2 did not start – replaced blown fuse

Comments: None.

Adult Fish Passage Facility

Ice Harbor Fish Facility staff inspected the adult fishways on September 28, 29, and October 1.

Fish Ladders:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.3'	
X		North Ladder Picketed Lead Differential	Head \leq 0.3'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.3'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			South Shore Entrance (SFE-1) Weir Depth	\geq 8.0' or on sill	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			South Shore Channel Velocity	1.5 – 4.0 fps	
X			North Powerhouse Entrance (NFE-2) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
X			North Shore Entrance (NEW-1) Weir Depth	\geq 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: The lamprey entrance structure at the south shore entrance #2 (SFE-2) was closed on October 1, per Ice Harbor Section 2.4.2.5.iv of the Fish Passage Plan.

Auxiliary Water Supply System (AWS) :

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
6 pumps	2 pumps		Status of the 8 South Shore AWS Pumps
2 pumps	1 pump		Status of the 3 North Shore AWS Pumps

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Average of 35 square yards
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0-10%
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service for available units?
	X		STSs in continuous-run mode? (Note: if not, then STSs are in cycle-run mode).
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	20
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Juvenile Fish Facility: The Juvenile Fish Facility is operating in primary bypass mode.

Fish Sampling: Fish sampling is done for the year at Ice Harbor Project.

Removable Spillway Weir (RSW): The RSW will be periodically opened for downstream passage of adult steelhead that may have strayed into the Snake River. For the benefit of steelhead, the RSW is scheduled to be operated from 0500 hours to 0900 hours on Sundays, Wednesdays, and Fridays, from October 1 to November 15.

River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
27.3	18.4	0	0	65	64	7.7	7.2

*Unit 1 scroll case temperature.

Comments: None.

Other

Inline Cooling Water Strainers: Monthly strainer inspections for lamprey will resume in December.

Avian Activity: There were low numbers of piscivorous birds seen around the project. Most of the birds were observed in the vicinity of Eagle Island.

Invasive Species: No new exotic species have been observed.

Fish Rescue/Salvage: Unwatering activities that involved fish rescue did not occur this week.

Research: No on-site research is occurring at this time.

Project: Lower Monumental

Biologists: Chuck Barnes and Raymond Addis

Dates: September 25 – October 1, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 2	7/15/2019	0720	4/01/2021	ERTS	Annual, Draft Tube Liner
Unit 4	8/10/2020	0730	10/01/2020	0930	Annual, Blade Seals, Headcover Pump
Unit 6	9/28/2020	0725	10/16/2020	ERTS	Annual

Comments: None.

Adult Fish Passage Facility

The adult fishways were inspected by Corps and EAS/Anchor QEA biologists on September 25, 26, 27,30 and October 1.

Fish Ladder:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.5'	
X		North Ladder Picketed Lead Differential	Head \leq 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.5'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments: None.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	\geq 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	\geq 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	\geq 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	\geq 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X		X	South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments:

South Powerhouse Entrance (SPE-1) Weir was on sill during all inspections with readings of 7.4, 7.2, 7.4, 7.1 and 5.9 feet respectively.

South Powerhouse Entrance (SPE-2) Weir was on sill during all inspections with readings of 7.4, 7.2, 7.4, 7.1 and 5.9 feet respectively.

South Shore Entrance (SSE-1) Weir was on sill during the September 30 and October 1 inspections with readings of 8.5 and 7.0 feet respectively.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	224 yds ²
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0 – 5%
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service?
	X		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: STS's were operating in cycle mode due to average sub-yearling Chinook and sockeye lengths being greater than 120 mm.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Collection Facility: The Juvenile collection facility was watered up at 10:00 on March 26.

Everyday collection for sample condition ended at 0700 on October 1. The facility went into primary bypass at that time. A total of 76 fish were collected during this reporting period with a total of 76 bypassed back to the river.

Transport Summary: Alternate day barge transport ended June 21.

Spillway Weir: Summer spill ended on August 31 at 23:59:59.

River Conditions

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
27.3	17.0	1.3	0	65.0	63.5	5.3	3.8

*Scrollcase temperatures.

Other

Inline Cooling Water Strainers: Cooling water strainers were inspected on August 10. No live fish or mortalities were recovered.

Avian Activity: Highest counts of foraging piscivorous birds in tailrace (SWT1+PH1+PH2) at Lower Monumental Dam.

Date	Time	Gulls	Cormorants	Terns	Grebes	Pelicans
9/25/2020	1530	2	6	0	0	0
9/26/2020	0900	0	0	0	0	0
9/27/2020	1315	0	8	0	0	0
9/30/2020	0900	17	6	0	0	0
10/01/2020	0930	10	0	0	0	0

* Table shows tailrace observation conducted during Adult Fish Ladder inspections

Comments: Bird hazing efforts by USDA personnel ended June 2, 2020.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on September 4.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by PSMFC and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Lower Monumental Dam for this reporting period are reported below.

Date	Sample (euthanized)	Collection*
9/25/2020	19	38
9/26/2020	11	22
9/27/2020	5	10
9/28/2020	6	12
9/29/2020	10	20
9/30/2020	4	8
10/01/2020	49	98
Total	104	208

*Collection and sample numbers are the same as the facility when sampling at 100%

Fish Rescue/Salvage: A Fish Rescue/Salvage took place on September 30 for the Unit 6 scroll case. No fish were recovered.

Research: No research is occurring currently.

Project: Little Goose

Biologists: Scott St. John and Richard Weis

Dates: September 25-October 01, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Little Goose Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	04/14/17	14:11	03/31/21	17:00	Spider and upper guide bearing repair.
3	09/21/20	03:20	10/30/20	17:00	Unit Annual

Comments: None.

Adult Fish Passage Facility

Little Goose fish facility staff inspected the adult fishway on September 27, 29 and October 01.

Fish Ladder:

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pump in Service		
		X	Fish Ladder Exit Cooling Water Pumps Operating Satisfactorily		

Comments: Adult ladder cooling pump were shut down for the season on September 16.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	\geq 7.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	\geq 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	\geq 6.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	\geq 6.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: The adult fishway continues to operate in manual mode. Project staff struggled to maintain entrance criteria at the NSE during Spring spill. The fish control system for the NSE weirs was replaced and is functioning satisfactorily. Sub surface channel velocity was performed on September 05 and averaged 1.9 fps.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	
	X		Gatewell drawdown measured this week?	
		X	Gatewell drawdown acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: There is approximately 5,000 square feet of floating woody debris currently inside the trash shear boom in the forebay. Drawdowns were performed on September 24 on Unit 1 and were in criteria.

ESBS/VBS:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
	X		VBSs differentials checked this week?
		X	VBSs differentials acceptable?
	X		VBSs inspected this week?

Comments: VBS differentials were performed on September 24 on Unit 1 and were in criteria. ESBS/VBS camera inspections were performed on Unit 3 on September 24 and screens were in satisfactory condition.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: The airline for the backflush system on orifice 1C1 was found broken and will need repaired once the juvenile channel is dewatered for winter maintenance (MFR 20 LGS 12). During prior ESBS/VBS inspections, an issue with the orifice liner in 6C2 was observed (MFR 20 LGS 14) and will need repaired during winter maintenance.

Collection Facility: Collection for condition sampling began on April 1. The facility continues to collect for daily sample and was placed in secondary bypass on June 21. Collection for every other day truck transport began on August 01 with the first truck leaving LGS on August 03.

Transport Summary: The JFF began collecting for truck transport on August 01. The collection and transportation facility operated within criteria this report period. A total of 496 fish were collected. Of the fish collected, 8 were sample or facility mortalities, 0 were bypassed and 399 were transported by truck to release site near Bonneville Dam. The descaling and mortality rates were 1.4% and 1.83%, respectively. There were 0 adult lamprey removed from the separator this report period.

Spillway Weir: Summer spill operations began on June 21. The ASW was closed for the season on August 07. Spill for adult steelhead overshoots commenced on October 01. ASW spill operations will continue to be conducted in accordance to the most recent Columbia Basin Teletype.

River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
27.6	15.5	1.3	0	64.4	63.7	6.0	5.5

*Ladder temperature.

Other

Inline Cooling Water Strainers: Inline cooling strainers were inspected and results submitted to district operations every other week for FPOM distribution through mid-June per Fish Passage Plan (FPP) requirements.

Avian Activity: Daily piscivorous bird counts at Little Goose Dam began on April 1.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
9-25	1200	17	20	0	0
9-26	0800	30	10	0	0
9-27	1230	15	20	0	0
9-28	0800	19	5	0	0
9-29	1035	17	16	0	0
9-30	0830	23	6	0	0
10-01	0800	40	18	0	0

Invasive Species: No invasive species have been observed on the mussel station.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Oregon Department of Fish and Wildlife and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Little Goose Dam for this reporting period are reported below.

Date	Sample	Collection*
9-25	214	214
9-26	89	89
9-27	347	347
9-28	242	242
9-29	277	277
9-30	240	240
10-01	210	210
Totals	1,619	1,619

Gas Bubble Trauma (GBT): GBT monitoring has finished for the season.

Fish Rescue/Salvage: None

Research: The Nez Perce Tribe (NPT) ended steelhead kelt collection on June 25.

Project: Lower Granite

Biologists: Elizabeth Holdren and David Miller

Dates: September 25-October 1, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Lower Granite Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
4	Aug 24	0700	Sept 30	0740	Annual Maintenance
1	Sept 28	0719	Sept 28	0941	Replace Nexus Meter

Comments: None.

Adult Fish Passage Facility

Lower Granite and EAS/Anchor QEA staff inspected the adult fishway September 25, 26, 28, 29 and 30.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pumps in Service		
		X	Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments: Adult fish ladder temperature control system was removed from service at 1305 hours on September 18.

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	\geq 8.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
	X		North Shore Entrance (NSE-1) Weir Depth	\geq 7.0' or on sill	6.7, 6.9, 6.7, 6.8
			North Shore Entrance (NSE-2) Weir Depth	\geq 7.0' or on sill	Closed
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
	X		Collection Channel Surface Velocity	1.5 – 4.0 fps	1.2, 1.1, 1.3, 1.4

Comments: FOGs 1 and 10 are in operation. The issue with the control system reading being in sync with local readings requires the electrical crew investigation of programming and calibration.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
No		OOS guide bearing	AWS Fish Pump 3

Comments: AWS pump 3 remains in standby until LWG mechanical is able to perform standard testing will require all AWS pumps be removed from service for 4 hours while stoplogs are swapped.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil: Forebay debris has not created any fish passage issues this season. Some woody debris observed in the forebay this season is likely due to the failure in the upriver two sections of the forebay debris boom. Though this has not created a problem, repairs are recommended to prevent further damage to the boom and potential for additional debris in the powerhouse forebay and on unit trashracks.

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Gatewell differentials were measured on September 27.

ESBSs/VBSs:

Yes	No	NA	Item
	X		ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18-24
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: Juvenile collection channel water level and flow is being adjusted using 10” orifices depending on forebay elevations. The 14” orifice in gatewell slot 4C was removed from service June 10 to prevent fish injury due to a damaged flange. The mechanical staff repaired the damaged flange in slot 4C to the 14” orifice during the unit outage.

Collection Facility: The sample rate is being adjusted daily based on fish passage numbers. Collection for truck transport began at 0700 hours August 1.

Transport Summary: Truck transport for the week of September 25-October 1 totaled 430 fish transported in three trips.

Spillway Weir: The RSW is scheduled to operate from 0500-0900 hours Sundays, Tuesdays, and Thursdays October 1 through November 15 to facilitate overshoot steelhead downstream passage.

River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
26.7	19.0	1.2	0.0	63.5	62.0	5.0	5.0

*Cooling water intake temperature.

Other

Inline Cooling Water Strainers: N/A

Invasive Species: No zebra/quagga muscles were detected on the trap substrate. There were 2,065 Siberian prawns collected in the sample and euthanized for disposal.

Avian Activity: Biologist daily piscivorous bird counts at Lower Granite Dam.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
Sept 25	1006	6	23	0	0
Sept 26	1105	6	25	0	0
Sept 27	0947	13	28	0	0
Sept 28	1123	14	37	0	0
Sept 29	0935	17	40	0	0
Sept 30	1030	13	33	0	0
Oct 1	1000	4	31	0	0

Adult Fish Trap Operations: Adult trap sample rate was 18%. Collection of Coho broodstock for NPT started on October 1. A total of 60 Coho were collected.

Fish Rescue/Salvage: N/A

Research:

USGS Juvenile Fall Chinook Salmon Growth and Origin

USGS collection of previously tagged subyearling Chinook utilizing LWG juvenile collection facility SbyC system began September 8 and will continue through October 31. Previously PIT tagged fish are diverted to the SbyC tanks, weighed, measured, GSI sampled, scanned for PIT tag code, recovered from anesthetic, and released back to the river. The objective of this project is to estimate the growth of PIT-tagged subyearling Chinook salmon from the Clearwater River to Lower Granite Dam.

National Marine Fisheries Service (NMFS) Ancillary Adult Passage Monitoring:

Fish that were PIT as juveniles at LWG are monitored as returning adults through the river and LWG facility. For each returning adult the following is estimated; 1) passage time between sets of detection PIT tag coils, 2) whether the fish was handled at the adult trap, 3) duration the fish was held at the adult trap, 4) overall passage time from ladder entrance to exit, 5) whether the turnpool gate was open or closed during passage. This will be the last year of this evaluation.

Sampling of Steelhead, Chinook salmon, and Sockeye salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating steelhead, spring/summer Chinook salmon, and sockeye salmon are collected from the adult trap beginning April 4 through December 15. The goal is to collect 5-20% of adult steelhead, spring/summer Chinook salmon, and sockeye salmon ascending the ladder April 4-December 15. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. All natural origin adult steelhead and spring/summer Chinook salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some steelhead and spring/summer Chinook salmon may be radio-tagged or spaghetti-tagged. This information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs.

PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be collected as part of the normal adult trap daily sample and using the adult SbyC system to recapture previously PIT tagged fish. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder.