

**U.S. ARMY CORPS OF ENGINEERS
WALLA WALLA DISTRICT
FISH FACILITIES WEEKLY REPORT
#32-2020**

Project: McNary

Biologist: Bobby Johnson and Denise Griffith

Dates: October 2- 8, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 14 turbine units available for service. (See table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

Unit(s)	OOS		RTS		Outage Description
	Date	Time	Date	Time	
4	10/05	0700	10/13	NA	New top plate pump installation.
9	09/14	0700	10/02	1305	Annual and other maintenance.
12	10/05	0700	10/23	NA	Annual and other maintenance.
13 & 14	10/06	1000	10/06	1100	ESBS camera inspections.

Comments: The hard one percent peak efficiency constraint continued.

Adult Fish Passage Facilities

McNary fisheries biologists performed measured inspections of the adult fishways on October 2, 4 and 6. Adult fish counting continued.

Fish Ladder Exits

Yes	No	Location	Criteria	Comments
	X	Oregon Exit	Head over weir 1.0' to 1.3'	0.9' on Oct 4.
X		Oregon Count Station Differential	0.0' to 0.5'	
X		Washington Exit	Head over weir 1.0' to 1.3'	
X		Washington Count Station Differential	0.0' to 0.5'	

Comments: Debris loads were light near the Oregon exit and very light to light near the Washington exit. Aquatic vegetation continued to be an issue. The general maintenance staff cleaned the picketed leads frequently, including on the weekend.

At the Oregon exit, the out of criterion point mentioned above was resolved with a set point adjustment.

At the Washington exit, a picketed lead and a regulating weir alarm was reset after the leads were cleaned on October 4.

Fishway Entrances and Collection Channel

Yes	No	Sill	Location	Criteria	Comments
X			North Oregon Entrance Head Differential	1.0' – 2.0'	
X			NFEW2 Weir Depth	≥ 8.0'	
X			NFEW3 Weir Depth	≥ 8.0'	
X			South Oregon Entrance Head Differential	1.0' – 2.0'	
X			SFEW1 Weir Depth	≥ 8.0'	
X			SFEW2 Weir Depth	≥ 8.0'	
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	Averaged 1.5 fps.
X			Washington Entrance Head Differential	1.0' – 2.0'	
X			WFE2 Weir Depth	≥ 8.0'	
X			WFE3 Weir Depth	≥ 8.0'	

Comments: There are no problems to report.

Auxiliary Water Supply System

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			WA shore Wasco County PUD Turbine Unit
	Yes		WA shore Wasco PUD Bypass
		Yes	Oregon shore Fish Pump 1, OOS to November 19.
Yes			Oregon Ladder Fish Pump 2, Blade angle: 24°.
Yes			Oregon Ladder Fish Pump 3, Blade angle: 24 to 26°.
Yes			OR North Powerhouse Pool supply from juvenile fishway

Comments: Repairs to fish pump 1 continued.

Juvenile Fish Passage Facility

The juvenile system remains in primary bypass for the fall season. Partial winterization, cleaning, light maintenance and preparations for winter began at the facility. There will be no fisheries staff member on duty from 0000 to 0800 hours for the remainder of the season starting October 11.

Forebay Debris/Gatewell Debris/Oil

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Minimal to moderate.
X			Were trash rack differentials measured?	Daily.
X			Trash rack differentials acceptable?	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Debris loads were minimal to moderate near the powerhouse and minimal beside the spillway. Incoming debris loads were minimal. The woody debris and aquatic vegetation continued to move back and forth from the powerhouse to the Oregon shoreline.

No trash rack cleaning or forebay debris removal occurred.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs)

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: ESBS's remained deployed in all units. ESBS camera inspections in units 12, 13 and 14 reveal no problems on October 6. Unit 12 was already out of service.

Daily VBS differential monitoring continued. No high differentials were measured. Four VBS's were cleaned on October 8. No fish were observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe

Yes	No	NA	Item	Number of orifices in service
X			Did orifices operate satisfactory?	42
X			Were the dewaterer and cleaning systems operated satisfactory?	

Comments: Due to continued concern for the two side dewatering valves, orifices cycling remained once a day. Orifices were adjusted for VBS cleaning as required.

The transition screen cleaning brush remained out of service. The air burst system's zone 5 kept the transition screen clean.

The fisheries staff continued to monitor the north and south side dewatering valves with both valves' motor temperatures being recorded. The highest motor temperature we recorded was 110 degrees F. We were able to note that the two valves alternate between being the warmest valve. Both appear to be working independently. Future access to the control program is our next step. The north valve still appeared to hang up at times, which causes a "popping" noise with the valve shaking at times. This remains as a concern.

Latching down the covers on the flume section of the bypass pipe continued.

Bypass Facility

Yes	No	NA	Item
		X	Sample gates on?
		X	PIT-tag sampling system on?

Comments: During fall primary bypass season, all systems remain out of service. Light maintenance continues. Partial winterization was completed.

The sampling system was cleaned on October 2.

Top Spillway Weir (TSW) Operations: The TSW in bay 19 remained out of service. The TSW in bay 20 is being used for the adult steelhead TSW passage efficiency study and as required by the new Biological Opinion. The TSW will be opened per the study plan.

River Conditions

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
113.6	91.6	1.8	0.0	65.0	65.0	6.0	6.0

Comments: The above data comes from the control room. The data day is 0000 to 0000 hours. Spillgate hoist maintenance, which began last week, continues. The spill recorded above was for the TSW study and hoist testing.

Other

Inline Cooling Water Strainers: The next cooling water strainer inspections will occur on December 1.

Avian Activity: Casual avian observations began on October 1.

No terns were observed on project.

Gull activity fluctuated in the powerhouse zone with birds feeding and roosting. At times, gulls were noted feeding in large numbers. Occasionally, a cormorant was noted.

In the spillway zone, gull and cormorants were observed. The birds were roosting around the spill basin with some feeding activity, especially during TSW use. Again, feeding activity was very short. Two pelicans were observed once.

At the juvenile bypass outfall, gulls and cormorants were noted. Roosting on the bypass pipe was still the primary use of the area. However, with the navigation lock laser removed, more birds appear to be feeding at the outfall.

In the forebay zone, occasional gulls were observed feeding or flying along with a grebe or great blue heron noted. A few gulls were noted on the roosting rocks along the Washington shoreline. At times, a flock of gulls was observed outside the counting zones, generally near the Oregon boat launch or project helicopter pad.

The lasers remained out of service and there is no active hazing program.

The bird distress calls deployed along on the navigation lock wing wall and the second large distress call deployed on the juvenile facility barge loading dock appeared to be somewhat effective.

A future LRAD test has not yet been scheduled.

Invasive Species: The next mussel station examinations will occur in late October.

Fish Rescue/Salvage: None occurred this week.

Research: Pacific Northwest National Laboratory (PNNL) continued with the adult steelhead TSW passage efficiency study. Both the USFWS and CRITFC picked up juvenile lamprey mortalities collected during the season on October 5.

Project: Ice Harbor

Biologist: Ken Fone

Dates: October 2, 2020 – October 8, 2020

Turbine Operation

Yes	No	Turbine Unit Status		
	X	All 6 turbine units available for service (see table & comments below for details).	Hard	Soft
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Ice Harbor Unit Outages (OOS) and Return to Service (RTS).

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	5/3/19	0641	---	---	Turbine runner replacement and stator rewind
5	9/21/20	0900	---	---	Annual maintenance and overhaul

Comments: None.

Adult Fish Passage Facility

Ice Harbor Fish Facility staff inspected the adult fishways on October 5, 6, 7.

Fish Ladders:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.3'	
X		North Ladder Picketed Lead Differential	Head \leq 0.3'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.3'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
		X	South Shore Entrance (SFE-1) Weir Depth	\geq 8.0' or on sill	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			South Shore Channel Velocity	1.5 – 4.0 fps	
		X	North Powerhouse Entrance (NFE-2) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Shore Entrance (NEW-1) Weir Depth	\geq 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: None.

Auxiliary Water Supply System (AWS):

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
6 pumps	2 pumps		Status of the 8 South Shore AWS Pumps
2 pumps	1 pump		Status of the 3 North Shore AWS Pumps

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Average of 77 square yards
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0-10%
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service for available units?
	X		STSs in continuous-run mode? (Note: if not, then STSs are in cycle-run mode).
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	20
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: The light for orifice 5AN was found to be burned out on October 5. Orifice 5AS was opened in place of 5AN until the light was replaced later that day.

Juvenile Fish Facility: The Juvenile Fish Facility is operating in primary bypass mode. The raw water lines in the sampling facility were drained for winterization on October 8.

Fish Sampling: Fish sampling is done for the year at Ice Harbor Project.

Removable Spillway Weir (RSW): The RSW is periodically opened for downstream passage of adult steelhead that may have strayed into the Snake River. For the benefit of steelhead, the RSW is scheduled to be operated from 0500 hours to 0900 hours on Sundays, Wednesdays, and Fridays, from October 1 to November 15.

River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
23.7	12.8	1.5	0	64	64	8.2	8.2

*Unit 1 scroll case temperature.

Comments: None.

Other

Inline Cooling Water Strainers: Monthly strainer inspections for lamprey will resume in December.

Avian Activity: There were low numbers of piscivorous birds seen around the project. Most of the birds were observed in the vicinity of Eagle Island.

Invasive Species: No new exotic species have been observed.

Fish Rescue/Salvage: Unwatering activities that involved fish rescue did not occur this week.

Research: No on-site research is occurring at this time.

Project: Lower Monumental

Biologists: Chuck Barnes and Raymond Addis

Dates: October 2 - 8, 2020

Turbine Operation

Yes	No	Turbine Unit Status		
	X	All 6 turbine units available for service (see table & comments below for details).	Hard	Soft
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 1	10/07/2020	0656	10/07/2020	1015	STS Inspection/Brush Cleaning
Unit 1	10/07/2020	1250			Governor Control Issues
Unit 2	7/15/2019	0720	4/01/2021	ERTS	Annual, Draft Tube Liner
Unit 3	10/06/2020	1050	10/06/2020	1312	STS Inspection
Unit 4	10/06/2020	0900	10/06/2020	1040	STS Inspection
Unit 5	10/07/2020	1230	10/07/2020	1430	STS Inspection
Unit 6	9/28/2020	0725	10/16/2020	ERTS	Annual

Comments: None

Adult Fish Passage Facility

The adult fishways were inspected by Corps and EAS/Anchor QEA biologists on October 2, 5, 6 and 7.

Fish Ladder:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.5'	
X		North Ladder Picketed Lead Differential	Head \leq 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.5'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments: None

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	≥ 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	≥ 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	≥ 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	≥ 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
		X	South Shore Entrance (SSE-1) Weir Depth	≥ 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	≥ 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments:

South Powerhouse Entrance (SPE-1) Weir was on sill during all inspections with readings of 6.5, 7.2, 7.2 and 7.0 feet respectively.

South Powerhouse Entrance (SPE-2) Weir was on sill during all inspections with readings of 6.5, 7.2, 7.2 and 7.0 feet respectively.

South Shore Entrance (SSE-1) Weir was on sill during all inspections with readings of 7.3, 8.0, 8.4 and 8.0 feet respectively.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments: None

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	1075 yds ²
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0 – 17%
	X		Any oil seen in gatewells?	

Comments: None

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service?
	X		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
X			STSs inspected this week?
X			STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: STS's were operating in cycle mode due to average sub-yearling Chinook and sockeye lengths being greater than 120 mm. STS's were inspected on October 6 and 7. All were in good working order. VBS for gatewell 6B was inspected October 6 and was in good working order.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	17
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: None

Collection Facility: The Juvenile collection facility was watered up at 10:00 on March 26. Everyday collection for condition sampling ended at 0700 on October 1. The facility went into primary bypass at that time. The collection facility was dewatered at 1230 on October 5.

Transport Summary: Alternate day barge transport ended June 21.

Spillway Weir: Summer spill ended on August 31 at 23:59:59. Off-season spill through the RSW is occurring 3 days/week on non-consecutive days for 4 hours/day from October 1 through November 15 per the 2020 CRS BiOp began October 1.

River Conditions

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
22.8	14.2	1.3	0	63.7	63.0	4.7	4.3

*Scrollcase temperatures.

Other

Inline Cooling Water Strainers: Cooling water strainers was last inspected on August 10. No live fish or mortalities were recovered. Cooling water strainers inspections will resume in December.

Avian Activity: Highest counts of foraging piscivorous birds in tailrace (SWT1+PH1+PH2) at Lower Monumental Dam.

Date	Time	Gulls	Cormorants	Terns	Grebes	Pelicans
10/02/2020	1515	0	6	0	0	0
10/05/2020	1000	5	18	0	0	0
10/06/2020	1130	20	44	0	0	0
10/07/2020	1500	4	14	0	0	0

* Table shows tailrace observation conducted during Adult Fish Ladder inspections

Comments: Bird hazing efforts by USDA personnel ended June 2, 2020.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on September 4.

Fish Rescue/Salvage: No Fish Rescue/Salvage took place during this reporting period.

Research: No research is occurring currently.

Project: Little Goose

Biologists: Scott St. John and Richard Weis

Dates: October 02-08, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Little Goose Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	04/14/17	14:11	03/31/21	17:00	Spider and upper guide bearing repair.
3	09/21/20	03:20	10/30/20	17:00	Unit Annual

Comments: None.

Adult Fish Passage Facility

Little Goose fish facility staff inspected the adult fishway on October 4, 5 and 8.

Fish Ladder:

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pump in Service		
		X	Fish Ladder Exit Cooling Water Pumps Operating Satisfactorily		

Comments: Adult ladder cooling pump was shut down for the season on September 16.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	\geq 7.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	\geq 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	\geq 6.0' or on sill	
	X		North Shore Entrance (NSE-2) Weir Depth	\geq 6.0' or on sill	5.9
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: The adult fishway continues to operate in manual mode. Project staff struggled to maintain entrance criteria at the NSE during Spring spill. The fish control system for the NSE weirs was replaced and is functioning satisfactorily. Sub surface channel velocity was performed on October 04 and averaged 2.5 fps. Weir depth at NSE-2 was found out of criteria during the October 5 inspection.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	
	X		Gatewell drawdown measured this week?	
		X	Gatewell drawdown acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: There is approximately 5,000 square feet of floating woody debris currently inside the trash shear boom in the forebay. Drawdowns were not conducted this report period due to plant conditions. Drawdowns were last performed on September 24 on Unit 1 and were in criteria.

ESBS/VBS:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
	X		VBSs differentials checked this week?
		X	VBSs differentials acceptable?
	X		VBSs inspected this week?

Comments: VBS differentials were not conducted this report period due to plant conditions. VBS differentials were last performed on September 24 on Unit 1 and were in criteria. ESBS/VBS camera inspections were performed on Unit 3 on September 24 and screens were in satisfactory condition.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: The airline for the backflush system on orifice 1C1 was found broken and will need repaired once the juvenile channel is dewatered for winter maintenance (MFR 20 LGS 12). During prior ESBS/VBS inspections, an issue with the orifice liner in 6C2 was observed (MFR 20 LGS 14) and will need repaired during winter maintenance.

Collection Facility: Collection for condition sampling began on April 1. The facility continues to collect for daily sample and was placed in secondary bypass on June 21. Collection for every other day truck transport began on August 01 with the first truck leaving LGS on August 03. The B-side PIT gate failed at 08:30 on October 8. The gate was repaired and returned to service at 10:20. The B-side separator exit was closed during the repair.

Transport Summary: The JFF began collecting for truck transport on August 01. The collection and transportation facility operated within criteria this report period. A total of 1,736 fish were collected. Of the fish collected, 16 were sample or facility mortalities, 0 were by-passed and 1,809 were transported by truck to release site near Bonneville Dam. The total fish transported included fish collected on October 1. The descaling and mortality rates

were 2.7% and 2.66%, respectively. There were 0 adult lamprey removed from the separator this report period and released approximately 1-mile upstream of the powerhouse.

Spillway Weir: Summer spill operations began on June 21. The ASW was closed for the season on August 07. Spill for adult steelhead overshoots commenced on October 01. ASW spill operations will continue to be conducted in accordance to the most recent Columbia Basin Teletype.

River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
21.3	14.0	1.2	0	64.4	63.9	6.0	6.0

*Ladder temperature.

Other

Inline Cooling Water Strainers: Inline cooling strainers were inspected and results submitted to district operations every other week for FPOM distribution through mid-June per Fish Passage Plan (FPP) requirements.

Avian Activity: Daily piscivorous bird counts at Little Goose Dam began on April 1.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
10-02	1045	19	13	0	0
10-03	0935	7	10	0	0
10-04	1050	17	6	0	0
10-05	1000	16	16	0	0
10-06	1020	20	16	0	0
10-07	1000	8	14	0	0
10-08	0835	8	2	0	0

Invasive Species: No invasive species have been observed on the mussel station.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Oregon Department of Fish and Wildlife and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Little Goose Dam for this reporting period are reported below.

Date	Sample	Collection*
10-02	143	143
10-03	323	323
10-04	530	530
10-05	325	325
10-06	592	592
10-07	544	544
10-08	120	120
Totals	2,577	2,577

Gas Bubble Trauma (GBT): GBT monitoring has finished for the season.

Fish Rescue/Salvage: None

Research: The Nez Perce Tribe (NPT) ended steelhead kelt collection on June 25.

Project: Lower Granite

Biologists: Elizabeth Holdren and David Miller

Dates: October 2-8, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
X		All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Comments: No units were out of service (OOS) this reporting period.

Adult Fish Passage Facility

Lower Granite and EAS/Anchor QEA staff inspected the adult fishway October 2, 3, 5, and 7.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pumps in Service		
		X	Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments: None

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	\geq 8.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
	X		North Shore Entrance (NSE-1) Weir Depth	\geq 7.0' or on sill	6.7, 6.9, 6.9, 6.7
			North Shore Entrance (NSE-2) Weir Depth	\geq 7.0' or on sill	Closed
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
	X		Collection Channel Surface Velocity	1.5 – 4.0 fps	1.3, 1.1, 1.1

Comments: FOGs 1 and 10 are in operation. The issue with the control system reading being in sync with local readings requires the electrical crew investigation of programming and calibration.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
No		OOS guide bearing	AWS Fish Pump 3

Comments: AWS pump 3 remains in standby until LWG mechanical is able to perform standard testing will require all AWS pumps be removed from service for 4 hours while stoplogs are swapped.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil: Debris load has picked up this week and is being managed with additional facility rounds. Some woody debris observed in the forebay this season is likely due to the failure in the upriver two sections of the forebay debris boom. Repairs are recommended to prevent further damage to the boom and potential for additional debris in the powerhouse forebay and on unit trashracks.

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
X			Any debris seen in gatewells (% coverage)	Ranged from 1-3%
	X		Any oil seen in gatewells?	

Comments: Gatewell differentials were measured October 4. Debris was removed from gatewells with a hand dip basket.

ESBSs/VBSs:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: None

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18-24
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: Juvenile collection channel water level and flow is being adjusted using 10" orifices depending on forebay elevations.

Collection Facility: The sample rate is being adjusted daily based on fish passage numbers. Collection for truck transport began at 0700 hours August 1.

Transport Summary: Truck transport for the week of October 2-8 totaled 2,429 fish transported in four trips.

Spillway Weir: The RSW is operating to facilitate adult steelhead passage from 0500-0900 hours Sundays, Tuesdays, and Thursdays October 1 through November 15. RSW PIT tag detections October 1-8 included 12 adult steelhead, 27 adult Chinook, and 19 juvenile Chinook. Of the 12 adult steelhead detected over the RSW, 8 were PIT tagged and recently released from the LWG adult trap. The juvenile bypass PIT tag system detected 3 adult Chinook, 3 adult steelhead, and 42 juvenile Chinook during this same period.

River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
23.8	18.9	1.2	0.0	63.0	62.0	5.0	5.0

*Cooling water intake temperature.

Other

Inline Cooling Water Strainers: N/A

Invasive Species: No zebra/quagga muscles were detected on the trap substrate. There were 2,065 Siberian prawns collected in the sample and euthanized for disposal.

Avian Activity: Biologist daily piscivorous bird counts at Lower Granite Dam.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
Oct 2	1349	7	36	0	0
Oct 3	0930	10	22	0	0
Oct 4	0800	27	36	0	0
Oct 5	1315	16	43	0	0
Oct 6	0810	15	56	0	0
Oct 7	1349	16	37	0	0
Oct 8	0950	18	43	0	0

Adult Fish Trap Operations: Adult trap sample rate was 18%. Collection of Coho broodstock for NPT started on October 1. During the report week 250 of the Coho collected at the adult trap were transported.

Fish Rescue/Salvage: N/A

Research:

USGS Juvenile Fall Chinook Salmon Growth and Origin

USGS collection of previously tagged subyearling Chinook utilizing LWG juvenile collection facility SbyC system began September 8 and will continue through October 31. Previously PIT tagged fish are diverted to the SbyC tanks, weighed, measured, GSI sampled, scanned for PIT tag code, recovered from anesthetic, and released back to the river. The objective of this project is to estimate the growth of PIT-tagged subyearling Chinook salmon from the Clearwater River to Lower Granite Dam.

National Marine Fisheries Service (NMFS) Ancillary Adult Passage Monitoring:

Fish that were PIT as juveniles at LWG are monitored as returning adults through the river and LWG facility. For each returning adult the following is estimated; 1) passage time between sets of detection PIT tag coils, 2) whether the fish was handled at the adult trap, 3) duration the fish was held at the adult trap, 4) overall passage time from ladder entrance to exit, 5) whether the turnpool gate was open or closed during passage. This will be the last year of this evaluation.

Sampling of Steelhead, Chinook salmon, and Sockeye salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating steelhead, spring/summer Chinook salmon, and sockeye salmon are collected from the adult trap beginning April 4 through December 15. The goal is to collect 5-20% of adult steelhead, spring/summer Chinook salmon, and sockeye salmon ascending the ladder April 4-December 15. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. All natural origin adult steelhead and spring/summer Chinook salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some steelhead and spring/summer Chinook salmon may be radio-tagged or spaghetti-tagged. This information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs.

PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be collected as part of the normal adult trap daily sample and using the adult SbyC system to recapture previously PIT tagged fish. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder.