

**U.S. ARMY CORPS OF ENGINEERS
WALLA WALLA DISTRICT
FISH FACILITIES WEEKLY REPORT
#36-2020**

Project: McNary

Biologist: Bobby Johnson and Denise Griffith

Dates: October 30 - November 5, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 14 turbine units available for service. (See table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	X

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

Unit(s)	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	10/26	0700	11/9	N/A	Thrust bearing system maintenance/upgrades.
7	10/29	0700	11/5	1021	New top plate pump installation.
6	11/3	1100	11/3	1321	Hub tap.
1 & 2	11/3	1000	11/3	1100	ESBS camera inspections.
8	11/5	1134	11/10	N/A	New top plate pump installation.

Comments: The soft one percent peak efficiency constraint began November 1 at 0001 hours.

Adult Fish Passage Facilities

McNary fisheries biologists performed measured inspections of the adult fishways on October 30, November 1 and 3. Adult fish counting concluded on October 31. The general maintenance staff raised the picketed leads on November 2 at 0700 hours.

Fish Ladder Exits

Yes	No	Location	Criteria	Comments
X		Oregon Exit	Head over weir 1.0' to 1.3'	
X		Oregon Count Station Differential	0.0' to 0.5'	
X		Washington Exit	Head over weir 1.0' to 1.3'	
X		Washington Count Station Differential	0.0' to 0.5'	

Comments: Debris loads were minimal to light near the Oregon and Washington exits. Aquatic vegetation continued to be an issue. The general maintenance staff cleaned the picketed leads frequently, including on Saturday.

At the Washington exit, tilting weir 337 tripped an alarm and reset was on October 30.

At the Oregon exit, the traveling screen trough was cleaned as needed.

Fishway Entrances and Collection Channel

Yes	No	Sill	Location	Criteria	Comments
X			North Oregon Entrance Head Differential	1.0' – 2.0'	
X			NFEW2 Weir Depth	≥ 8.0'	
X			NFEW3 Weir Depth	≥ 8.0'	
X			South Oregon Entrance Head Differential	1.0' – 2.0'	
X			SFEW1 Weir Depth	≥ 8.0'	
X			SFEW2 Weir Depth	≥ 8.0'	
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	Averaged 1.7 fps.
X			Washington Entrance Head Differential	1.0' – 2.0'	
X			WFE2 Weir Depth	≥ 8.0'	
X			WFE3 Weir Depth	≥ 8.0'	

Comments: NFEW3 was found in manual mode on November 1 and was immediately returned to automatic mode by the control room. Looking at the data, it appears NFEW3 was in manual mode briefly and remained in criterion.

Auxiliary Water Supply System

Operating Satisfactory	Standby	Out of Service (OOS)	Auxiliary Water Supply System (AWS)
Yes			WA shore Wasco County PUD Turbine Unit
	Yes		WA shore Wasco PUD Bypass
		Yes	Oregon shore Fish Pump 1, OOS to mid-Dec.
Yes			Oregon Ladder Fish Pump 2, Blade angle: 24°.
Yes			Oregon Ladder Fish Pump 3, Blade angle: 24° or 26°.
Yes			OR North Powerhouse Pool supply from juvenile fishway

Comments: Repairs to fish pump 1 continued. The returned to service date has been revised to sometime in mid-December.

Juvenile Fish Passage Facility

The juvenile system remains in primary bypass for the fall season. Cleaning, light maintenance and preparations for winter continued at the facility. Staffing remained on day shift only.

Plans and discussions for the separator rehabilitation continued with powerhouse staff. The main focus will be the separator floor and upwell screens side supports. Rebuild materials have begun to be purchased.

Forebay Debris/Gatewell Debris/Oil

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Minimal to light.
X			Were trash rack differentials measured?	Daily.
X			Trash rack differentials acceptable?	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Debris loads were minimal to light near the powerhouse and minimal beside the spillway. Incoming debris loads were minimal. The woody debris and aquatic vegetation continued to move back and forth from the powerhouse to the Oregon shoreline.

No trash rack cleaning or forebay debris removal occurred.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs)

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: ESBS's remained deployed in all units. ESBS camera inspections in units 1 and 2 revealed no problems on November 3.

Daily VBS differential monitoring continued. No high differentials were measured. Two VBS's were cleaned on November 5. No fish mortalities were observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe

Yes	No	NA	Item	Number of orifices in service
X			Did orifices operate satisfactory?	42
X			Were the dewaterer and cleaning systems operated satisfactory?	

Comments: Due to continued concern for the two side dewatering valves, orifices cycling remained once a day. Orifices were adjusted for VBS cleaning as required. Orifice valve operators were repaired as needed.

The transition screen cleaning brush remained out of service. The air burst system's zone 5 kept the transition screen clean.

The fisheries staff continued to monitor the north and south side dewatering valves' motor temperatures. The north valve still appeared to hang up at times, which causes a "popping" noise with the valve shaking occasionally. This remains as a concern. Future access to the control program is our next step.

Bypass Facility

Yes	No	NA	Item
		X	Sample gates on?
		X	PIT-tag sampling system on?

Comments: During fall primary bypass season, all systems remain out of service. Light maintenance continues.

As noted above in the Juvenile Fish Passage Facility section, the separator remains dewatered.

Top Spillway Weir (TSW) Operations: The TSW in bay 19 remained out of service. The TSW in bay 20 is being used for the adult steelhead TSW passage efficiency study and as required by the new Biological Opinion. The TSW will be opened per the study plan.

River Conditions

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
129.2	89.4	1.5	0.0	55.0	52.0	6.0	6.0

Comments: The above data comes from the control room. The data day is 0000 to 0000 hours. The spill recorded above was for the TSW study. Repairs to crane 6 began this week. The crane is scheduled to return to service in mid-January. Crane 7 is also scheduled to receive a new gearbox.

Other

Inline Cooling Water Strainers: The next cooling water strainer inspections will occur on December 1.

Avian Activity: Casual avian observations continued.

No terns or pelicans were observed on project. Gull and cormorant numbers were estimated to be the highest seen this year early in the week.

Frequently, gull and cormorant activity was heavy in the powerhouse zone where the birds were noted feeding in large numbers.

In the spillway zone, gulls and cormorants were observed in large numbers at times. The birds were roosting around the spill basin and feeding during TSW use.

At the juvenile bypass outfall, gulls and cormorants were noted. Cormorant numbers were again high. Roosting on the bypass pipe was still the primary use of the area with feeding occurring occasionally.

In the forebay zone, occasionally gulls were observed flying by or a large number of gulls would be noted roosting on the water. Several grebes and a few cormorants were observed foraging. One loon was noted. At times, gull flocks were observed outside the counting zones.

Currently, there are no hazing efforts occurring.

Invasive Species: The next mussel stations examination will occur at the end of November.

Fish Rescue/Salvage: None occurred this week.

Research: Pacific Northwest National Laboratory (PNNL) continued with the adult steelhead TSW passage efficiency study.

Project: Ice Harbor

Biologist: Ken Fone; Fisheries Technician: Timothy DeKoster

Dates: October 30, 2020 – November 5, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Ice Harbor Unit Outages (OOS) and Return to Service (RTS).

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	5/3/19	0641	---	---	Turbine runner replacement and stator rewind
5	9/21/20	0900	---	---	Annual maintenance and overhaul
2	11/2/20	0702	--	---	Replace 2A head gate cylinder

Comments: None.

Adult Fish Passage Facility

Ice Harbor Fish Facility staff inspected the adult fishways on November 2, 3, and 4.

Fish Ladders:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.3'	
X		North Ladder Picketed Lead Differential	Head \leq 0.3'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.3'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
		X	South Shore Entrance (SFE-1) Weir Depth	\geq 8.0' or on sill	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			South Shore Channel Velocity	1.5 – 4.0 fps	
		X	North Powerhouse Entrance (NFE-2) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Shore Entrance (NEW-1) Weir Depth	\geq 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: The adult fish counting season ended on October 31, 2020. The picketed leads were raised on November 2, 2020.

Auxiliary Water Supply System (AWS):

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
5 pumps	3 pumps		Status of the 8 South Shore AWS Pumps
2 pumps	1 pump		Status of the 3 North Shore AWS Pumps

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Average of 21 square yards
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0-5%
X			Any oil seen in gatewells?	

Comments: On October 31, the powerhouse operator noticed oil leaking out of the gearbox of the STS stored in gatewell 2C. The gearbox seal had ruptured due to the temperature change from the water to the air. The pressure in the gearbox was mistakenly not equalized with the pressure in the air after the STS was raised out of the water from slot 2A for repairs. Approximately ¾ cup of oil had dripped into gatewell 2C. Oil absorbent booms were installed in the slot to soak up the oil. The appropriate state and federal agencies were notified of the oil spill.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service for available units?
	X		STSs in continuous-run mode? (Note: if not, then STSs are in cycle-run mode).
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	20
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: The hydrocannon water pipe leak was repaired on November 4. Two leaky couplings were replaced with new couplings. The hydrocannon pump was recently pulled out of the water to prevent freezing of water in the outlet from the pump. Since the juvenile fish bypass is scheduled to be unwatered in mid-November, the pump will not be reinstalled this season unless there are piscivorous birds observed foraging at the outfall pipe.

Juvenile Fish Facility: The Juvenile Fish Facility is operating in primary bypass mode.

Fish Sampling: Fish sampling is done for the year at Ice Harbor Project.

Removable Spillway Weir (RSW): The RSW is periodically opened for downstream passage of adult steelhead that may have strayed into the Snake River. For the benefit of steelhead, the RSW is scheduled to be operated from 0500 hours to 0900 hours on Sundays, Wednesdays, and Fridays, from October 1 to November 15.

River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
22.5	16.6	1.5	0	58	56	7.6	6.4

*Unit 1 scroll case temperature.

Comments: None.

Other

Inline Cooling Water Strainers: November 3rd and 5th the unit 1 and 6 inline cooling strainers were inspected and cleaned of debris and American Shad, *Alosa sapidissima* (See table below). Monthly strainer inspections for lamprey will resume in December.

Date	Unit 1	Unit 6
11/3	2,500 American Shad	1,700 American Shad
11/5	145 American Shad	74 American Shad

Avian Activity: There were high numbers of piscivorous birds seen around the project, including gulls, mergansers, and pelicans. Many of the birds were observed foraging or resting along the shore, downstream of the powerhouse.

Invasive Species: No new exotic species have been observed.

Fish Rescue/Salvage: Unwatering activities that involved fish rescue did not occur this week.

Research: No on-site research is occurring at this time.

Project: Lower Monumental

Biologists: Chuck Barnes and Raymond Addis

Dates: October 30 – November 5, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 2	7/15/2019	0720	4/01/2021	ERTS	Annual, Draft Tube Liner
Unit 5	10/19/2020	0707	11/13/2020	ERTS	Annual Maintenance
Unit 1	11/4/2020	0720	11/4/2020	0905	STS Inspections
Unit 3	11/3/2020	0930	11/3/2020	1050	STS Inspections
Unit 4	11/3/2020	0720	11/3/2020	0920	STS Inspections
Unit 6	11/4/2020	0910	11/4/2020	1045	STS Inspections

Comments: None.

Adult Fish Passage Facility

The adult fishways were inspected by Corps biologists on November 3, 4, and 5.

Fish Ladder:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.5'	
X		North Ladder Picketed Lead Differential	Head \leq 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.5'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments: None.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	\geq 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	\geq 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	\geq 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	\geq 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X		X	South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments:

South Powerhouse Entrance (SPE-1) Weir was on sill during all inspections with readings of 6.8, 6.6 and 7.2 feet respectively.

South Powerhouse Entrance (SPE-2) Weir was on sill during all inspections with readings of 6.8, 6.6 and 7.2 feet respectively.

South Shore Entrance (SSE-1) Weir was on sill during all inspections with readings of 7.6, 7.5 and 8.6 feet respectively.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	5 yds ²
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0 – 30%
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service?
	X		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
X			STSs inspected this week?
X			STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: STS's were operating in cycle mode due to average sub-yearling Chinook and sockeye lengths being greater than 120 mm.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Collection Facility: The Juvenile collection facility was watered up at 10:00 on March 26.

Everyday collection for sample condition ended at 0700 on October 1 and the facility was placed into primary bypass at that time. The collection facility was dewatered at 1230 on October 5.

Transport Summary: Alternate day barge transport ended June 21.

Spillway Weir: Summer spill ended on August 31 at 23:59:59. Off season spill for downstream passage of steelhead overshoots is occurring from October 1 through November 15.

River Conditions

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
21.3	17.8	1.4	0	55.0	54.5	6.0	4.0

*Scrollcase temperatures.

Other

Inline Cooling Water Strainers: Cooling water strainers were inspected on August 10. No live fish or mortalities were recovered.

Avian Activity: Bird hazing efforts by USDA personnel ended June 2, 2020. Tailrace bird observations conducted during fish ladder inspections ended for the season September 30, 2020.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on October 19.

Fish Rescue/Salvage: No Fish Rescue/Salvage took place during this reporting period.

Research: No research is occurring currently.

Project: Little Goose

Biologists: Scott St. John and Richard Weis

Dates: October 30-November 5, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Little Goose Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	04/14/17	14:11	03/31/21	17:00	Spider and upper guide bearing repair.
3	09/21/20	03:20	11/03/20	11:00	Unit Annual
2	10/26/20	03:08	11/30/20	17:00	Unit Annual

Comments: None.

Adult Fish Passage Facility

Little Goose fish facility staff inspected the adult fishway on November 1 and 5.

Fish Ladder:

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pump in Service		
		X	Fish Ladder Exit Cooling Water Pumps Operating Satisfactorily		

Comments: Adult ladder cooling pump was shut down for the season on September 16.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
	X		South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	7.9
	X		South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	7.9
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	\geq 7.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	\geq 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
	X		North Shore Entrance (NSE-1) Weir Depth	\geq 6.0' or on sill	5.7
	X		North Shore Entrance (NSE-2) Weir Depth	\geq 6.0' or on sill	5.8
X			North Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: The adult fishway continues to operate in manual mode. Project staff struggled to maintain entrance criteria at the NSE during Spring spill. The fish control system for the NSE weirs was replaced and is functioning satisfactorily. Sub surface channel velocity was performed on November 2 and averaged 2.2 fps. Weir depth at NSE-1, NSE-2, SSE-1 and SSE-2 were found out of criteria during the November 1 inspection.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	
	X		Gatewell drawdown measured this week?	
		X	Gatewell drawdown acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: There is approximately 700 square feet of floating woody debris currently inside the trash shear boom in the forebay. Drawdowns were performed on October 22 on Units 1 and 2 and were in criteria.

ESBS/VBS:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
	X		VBSs differentials checked this week?
		X	VBSs differentials acceptable?
	X		VBSs inspected this week?

Comments: All ESBS screens are in slots and deployed for all available and in-service Units. VBS differentials were performed on October 22 on Units 1 and 2 and were in criteria. ESBS/VBS camera inspections were performed on Unit 3 on September 24 and screens were in satisfactory condition.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: The airline for the backflush system on orifice 1C1 was found broken and will need repaired once the juvenile channel is dewatered for winter maintenance (MFR 20 LGS 12). During prior ESBS/VBS inspections, an issue with the orifice liner in 6C2 was observed (MFR 20 LGS 14) and will need repaired during winter maintenance. The limitorque motor that operates the weirs for water elevation at the primary dewatering structure is out of service. Weirs are currently being adjust manually until repairs are made.

Collection Facility: The collection facility was placed in primary bypass on November 1. The facility was dewatered for winter maintenance on November 4.

Transport Summary: The JFF began collecting for truck transport on August 01 with the last truck of the season departing on November 1. The collection and transportation facility operated within criteria this report period. A total of 244 fish were collected. Of the fish collected, 20 were sample or facility mortalities, 0 were by-passed and 418 were transported by truck to release site near Bonneville Dam. Total fish transported includes fish collected on

October 29. The descaling and mortality rates were 1.9% and 7.6%, respectively. There were 0 adult lamprey removed from the separator this report period and released approximately 1-mile upstream of the powerhouse.

Spillway Weir: Summer spill operations began on June 21. The ASW was closed for the season on August 07. Spill for adult steelhead overshoots commenced on October 01. ASW spill operations will continue to be conducted in accordance to the most recent Columbia Basin Teletype.

River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
22.7	17.2	1.2	0.0	55.4	54.5	6.0	6.0

*Ladder temperature.

Other

Inline Cooling Water Strainers: Inline cooling strainers were inspected and results submitted to district operations every other week for FPOM distribution through mid-June per Fish Passage Plan (FPP) requirements.

Avian Activity: Daily piscivorous bird counts at Little Goose Dam began on April 1 and ended on October 31.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
10-30	0830	155	57	0	0
10-31	1215	180	7	0	0

Invasive Species: No invasive species have been observed on the mussel station.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Oregon Department of Fish and Wildlife and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Little Goose Dam for this reporting period are reported below.

Date	Sample	Collection*
10-30	61	61
10-31	197	197
11-01	47	47
Total	305	305

Gas Bubble Trauma (GBT): GBT monitoring has finished for the season.

Fish Rescue/Salvage: None.

Research: Pacific Northwest National Laboratory (PNNL) collected 1,264 juvenile American shad at Little Goose JFF on October 29. PNNL is developing a revolutionary acoustic transmitter that can be used to study the behavior and survival of sensitive species such as juvenile American shad to inform hydropower mitigation and species management. The ability to implant acoustic transmitters and track the movements of species and life stages of fish that have never been studied before at this level of detail would greatly advance our understanding of fish migration timing and behaviors, habitat use, fishway use and performance, and survival rates at hydropower facilities – resulting in more informed management decisions regarding new and existing hydroelectric facilities and better designs of new hydropower systems that minimize or avoid environmental impacts. In the long term this acoustic transmitter for shad may also lead to reduced cost and time of hydropower permitting and fewer environmental impacts.

Project: Lower Granite

Biologists: Elizabeth Holdren and David Miller

Dates: October 30-Nov 5, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Lower Granite Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	Oct 19	0659			Annual maintenance

Comments: None.

Adult Fish Passage Facility

Lower Granite and EAS/Anchor QEA staff inspected the adult fishway October 30, 31, and November 2, 3, 4, and 5.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pumps in Service		
		X	Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments: None.

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			North Powerhouse Entrance (NPE-1) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance (NPE-2) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
	X		North Shore Entrance (NSE-1) Weir Depth	\geq 7.0' or on sill	6.8, 6.8
			North Shore Entrance (NSE-2) Weir Depth	\geq 7.0' or on sill	Closed
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
	X		Collection Channel Surface Velocity	1.5 – 4.0 fps	1.3, 1.2, 1.4, 1.2, 1.2, 1.3

Comments: FOGs 1 and 10 are in operation. The control system sensor for NSE-1 continues to have issues recognizing and responding to tailwater elevation changes. Operations cycled the gate on November 2 and the control sensor system has been responding appropriately during calm tailrace conditions. Turbulent conditions during RSW spill continue to cause criteria issues at NSE-1.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
No			AWS Fish Pump 3

Comments: AWS pump 3 is operational in standby mode with lower guide bearing work delayed until the winter outage due to COVID.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil: Debris load has picked up this week and is being managed with additional facility rounds. Some woody debris observed in the forebay this season is likely due to the failure in the upriver two sections of the forebay debris boom. Repairs are recommended to prevent further damage to the boom and potential for additional debris in the powerhouse forebay and on unit trashracks.

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
X			Any debris seen in gatewells (% coverage)	Ranged from 1-3%
	X		Any oil seen in gatewells?	

Comments: Gatewell differentials were measured November 2. Debris is removed from gatewells with a hand dip basket.

ESBSs/VBSs:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18-24
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: Juvenile collection channel water level and flow is being adjusted using 10" orifices depending on forebay elevations. Facility was changed to primary bypass mode at 0900 hours November 1.

Collection Facility: Collection for condition sampling and truck transported ended with the facility operations switched to secondary bypass mode at 0700 hours November 1. Operation was changed to primary bypass at 0900 hours November 1. The juvenile fish facility was dewatered and winterized on November 2. LWG total facility collection for the 2020 season was 1,495,940 salmonids. Of these, 329,111 were bypassed, 1,165,554 were transported, and 1,275 (0.09%) were collection mortalities.

Transport Summary: Truck transport October 30 and November 1 totaled 1,055 fish. Collection for transport ended at 0700 hours November 1. The total salmonids transported during the 2020 season was 1,144,545 (98.2%) barged and 21,009 (1.8%) trucked.

Spillway Weir: The RSW is operating to facilitate adult steelhead passage from 0500-0900 hours Sundays, Tuesdays, and Thursdays October 1 through November 15.

River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
23.4	18.1	1.2	0.0	52.0	49.0	5.0	5.0

*Cooling water intake temperature.

Other

Inline Cooling Water Strainers: N/A

Invasive Species: No zebra/quagga mussels were detected on the trap substrate. There were 15 Siberian prawns collected in the sample and euthanized for disposal.

Avian Activity: Biologist daily piscivorous bird counts at Lower Granite Dam.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
Oct 30	1129	3	7	0	0
Oct 31	1055	4	10	0	0

Adult Fish Trap Operations: The adult fish trap continues to be operated at a 18% sample rate for IDFG steelhead sample collection.

Fish Rescue/Salvage: N/A

Research:

USGS Juvenile Fall Chinook Salmon Growth and Origin

USGS collection of previously tagged subyearling Chinook utilizing LWG juvenile collection facility SbyC system began September 8 and was scheduled to continue through October 31. Previously PIT tagged fish are diverted to the SbyC tanks, weighed, measured, GSI sampled, scanned for PIT tag code, recovered from anesthetic, and released back to the river. The objective of this project is to estimate the growth of PIT-tagged subyearling Chinook salmon from the Clearwater River to Lower Granite Dam. Collection and sampling for this study concluded October 30.

National Marine Fisheries Service (NMFS) Ancillary Adult Passage Monitoring:

Fish that were PIT as juveniles at LWG are monitored as returning adults through the river and LWG facility. For each returning adult the following is estimated; 1) passage time between sets of detection PIT tag coils, 2) whether the fish was handled at the adult trap, 3) duration the fish was held at the adult trap, 4) overall passage time from ladder entrance to exit, 5) whether the turnpool gate was open or closed during passage. This will be the last year of this evaluation.

Sampling of Steelhead, Chinook salmon, and Sockeye salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating steelhead, spring/summer Chinook salmon, and sockeye salmon are collected from the adult trap beginning April 4 through December 15. The goal is to collect 5-20% of adult steelhead, spring/summer Chinook salmon, and sockeye salmon ascending the ladder April 4-December 15. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. All natural origin adult steelhead and spring/summer Chinook salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some steelhead and spring/summer Chinook salmon may be radio-tagged or spaghetti-tagged. This information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs.

PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be collected as part of the normal adult trap daily sample and using the adult SbyC system to recapture previously PIT tagged fish. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder.