

**U.S. ARMY CORPS OF ENGINEERS
WALLA WALLA DISTRICT
FISH FACILITIES WEEKLY REPORT
#37-2020**

Project: McNary

Biologist: Bobby Johnson and Denise Griffith

Dates: November 6 - 12, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 14 turbine units available for service. (See table & comments below for details).		
	X	Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

Unit(s)	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	10/26	0700	11/9	1403	Thrust bearing system maintenance/upgrades.
8	11/5	1134	11/10	1731	New top plate pump installation.
13 & 14	11/10	1000	11/10	1100	ESBS camera inspections.
9	11/12	0641	11/18	N/A	New top plate pump installation.

Comments: The soft one percent peak efficiency constraint continues. At times, the units ran outside the constraint at BPA's request.

Adult Fish Passage Facilities

McNary fisheries biologists performed measured inspections of the adult fishways on November 6, 8 and 10.

Fish Ladder Exits

Yes	No	Location	Criteria	Comments
X		Oregon Exit	Head over weir 1.0' to 1.3'	
X		Oregon Count Station Differential	0.0' to 0.5'	
X		Washington Exit	Head over weir 1.0' to 1.3'	
X		Washington Count Station Differential	0.0' to 0.5'	

Comments: Debris loads were minimal to light near the Oregon exit and minimal at Washington exit.

At the Oregon exit, the traveling screen trough was cleaned as needed. The head over weir measured 1.4 feet on November 9. The biologist asked for the weirs' set points to be adjusted.

Fishway Entrances and Collection Channel

Yes	No	Sill	Location	Criteria	Comments
X			North Oregon Entrance Head Differential	1.0' – 2.0'	
X			NFEW2 Weir Depth	≥ 8.0'	
X			NFEW3 Weir Depth	≥ 8.0'	
X			South Oregon Entrance Head Differential	1.0' – 2.0'	
X			SFEW1 Weir Depth	≥ 8.0'	
X			SFEW2 Weir Depth	≥ 8.0'	
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	Averaged 1.8 fps.
X			Washington Entrance Head Differential	1.0' – 2.0'	
X			WFE2 Weir Depth	≥ 8.0'	
X			WFE3 Weir Depth	≥ 8.0'	

Comments: There is nothing to report.

Auxiliary Water Supply System

Operating Satisfactory	Standby	Out of Service (OOS)	Auxiliary Water Supply System (AWS)
Yes			WA shore Wasco County PUD Turbine Unit
	Yes		WA shore Wasco PUD Bypass
		Yes	Oregon shore Fish Pump 1, OOS to Feb 1, 2021.
Yes			Oregon Ladder Fish Pump 2, Blade angle: 24°.
Yes			Oregon Ladder Fish Pump 3, Blade angle: 24°.
Yes			OR North Powerhouse Pool supply from juvenile fishway

Comments: Repairs to fish pump 1 continued. The returned to service date has been revised again. The mechanical staff could be done by mid-December. However, with the holiday season soon after, the electrical work may not be completed until February 2021. The juvenile fishway will no longer be supplying water to the Oregon ladder north powerhouse pool starting November 16. This will be discussed below.

Juvenile Fish Passage Facility

The juvenile system will remain in primary bypass for the fall season until November 16, at which time the system will be switched to emergency bypass. The switch to this mode of bypass will allow major repairs in the juvenile channel and facility to begin a month earlier, which should ensure the system is ready for early start up in March.

Separator rehabilitation continued. The focus will be the separator floor and upwell screens side supports.

Forebay Debris/Gatewell Debris/Oil

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Minimal to moderate.
X			Were trash rack differentials measured?	Daily.
X			Trash rack differentials acceptable?	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Debris loads were minimal to moderate near the powerhouse and minimal beside the spillway. A few storms brought in new vegetation and woody debris, which continued to move back and forth from the powerhouse to the Oregon shoreline.

No trash rack cleaning or forebay debris removal occurred.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs)

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: ESBS's remained deployed in all units. ESBS camera inspections in units 13 and 14 revealed no problems on November 10.

Daily VBS differential monitoring continued. One high differential was measured in 9B slot on November 9. This screen with nine more VBS's were cleaned on November 7 and 9. One juvenile lamprey mortality was observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe

Yes	No	NA	Item	Number of orifices in service
X			Did orifices operate satisfactory?	42
X			Were the dewaterer and cleaning systems operated satisfactory?	

Comments: Due to continued concern for the two side dewatering valves, orifices cycling remained once a day. Orifices were adjusted for VBS cleaning as required.

A high-water alarm came in and was reset during the ESBS camera inspections on November 10. Orifice protocols were reviewed as orifices are exchanged during camera inspections.

The transition screen cleaning brush remained out of service. The air burst system's zone 5 kept the transition screen clean.

The fisheries staff continued to monitor the north and south side dewatering valves' motor temperatures. The north valve still appeared to hang up at times, which causes a "popping" noise with the valve shaking occasionally. This remains as a concern. Future access to the control program is our next step.

Bypass Facility

Yes	No	NA	Item
		X	Sample gates on?
		X	PIT-tag sampling system on?

Comments: During fall primary bypass season, all systems remain out of service. Light maintenance continues.

As noted above in the Juvenile Fish Passage Facility section, the separator remains dewatered.

Top Spillway Weir (TSW) Operations: The TSW in bay 19 remained out of service. The TSW in bay 20 is being used for the adult steelhead TSW passage efficiency study and as required by the new Biological Opinion. The TSW will be opened per the study plan. This TSW will be closed when these requirements conclude on November 15. New spillway leaves, which will facilitate TSW install and removal, will be installed in bays 19 and 20 on November 18.

River Conditions

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
147.9	113.6	1.6	0.0	54.0	52.0	6.0	6.0

Comments: The above data comes from the control room. The data day is 0000 to 0000 hours. The spill recorded above was for the TSW study. Repairs to crane 6 continue. The crane is scheduled to return to service in mid-January 2021. Crane 7 is also scheduled to receive a new gearbox.

Other

Inline Cooling Water Strainers: The next cooling water strainer inspections will occur on December 1.

Avian Activity: Casual avian observations continued.

No terns or pelicans were observed on project.

Frequently, gull and cormorant activity was heavy in the powerhouse zone where the birds were noted feeding in large yet decreasing numbers.

In the spillway zone, gulls and cormorants were observed in large numbers at times. The birds were roosting around the spill basin and feeding during TSW use.

At the juvenile bypass outfall, gulls and cormorants were noted. Cormorant numbers remained high. Roosting on the bypass pipe was still the primary use of the area with feeding occurring occasionally.

In the forebay zone, occasionally gulls were observed flying by or a gull flock would be noted roosting on the water. Several grebes were observed foraging. At times, gull flocks and a few cormorants were observed outside the counting zones. One bald eagle was also noted.

Currently, there are no hazing efforts occurring.

Invasive Species: The next mussel stations examination will occur at the end of November.

Fish Rescue/Salvage: None occurred this week.

Research: Pacific Northwest National Laboratory (PNNL) continued with the adult steelhead TSW passage efficiency study, which concludes on November 15.

Project: Ice Harbor

Biologist: Ken Fone

Dates: November 6, 2020 – November 12, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Ice Harbor Unit Outages (OOS) and Return to Service (RTS).

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	5/3/19	0641	---	---	Turbine runner replacement and stator rewind
5	9/21/20	0900	---	---	Annual maintenance and overhaul
2	11/2/20	0702	11/12/20	0916	Replace 2A head gate cylinder

Comments: None.

Adult Fish Passage Facility

Ice Harbor Fish Facility staff inspected the adult fishways on November 9, 10, and 12.

Fish Ladders:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.3'	
X		North Ladder Picketed Lead Differential	Head \leq 0.3'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.3'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
		X	South Shore Entrance (SFE-1) Weir Depth	\geq 8.0' or on sill	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			South Shore Channel Velocity	1.5 – 4.0 fps	
		X	North Powerhouse Entrance (NFE-2) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Shore Entrance (NEW-1) Weir Depth	\geq 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: None.

Auxiliary Water Supply System (AWS):

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
5 pumps	3 pumps		Status of the 8 South Shore AWS Pumps
2 pumps	1 pump		Status of the 3 North Shore AWS Pumps

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Average of 10 square yards
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0-5%
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service for available units?
	X		STSs in continuous-run mode? (Note: if not, then STSs are in cycle-run mode).
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	20
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Juvenile Fish Facility: The Juvenile Fish Facility is operating in primary bypass mode.

Fish Sampling: Fish sampling is done for the year at Ice Harbor Project.

Removable Spillway Weir (RSW): The RSW is periodically opened for downstream passage of adult steelhead that may have strayed into the Snake River. For the benefit of steelhead, the RSW is scheduled to be operated from 0500 hours to 0900 hours on Sundays, Wednesdays, and Fridays, from October 1 to November 15.

River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
22.6	16.6	1.6	0	54	53	8.5	7.5

*Unit 1 scroll case temperature.

Comments: None.

Other

Inline Cooling Water Strainers: On November 12, unit 1, 2, 4, and 6 strainers were unclogged of debris and American shad. A total of approximately 3,200 shad mortalities were removed from the strainers.

Avian Activity: There were high numbers of piscivorous birds seen around the project, including gulls, mergansers, and pelicans. Many of the birds were observed foraging or resting along the shore, downstream of the powerhouse.

Invasive Species: No new exotic species have been observed.

Fish Rescue/Salvage: Unwatering activities that involved fish rescue did not occur this week.

Research: No on-site research is occurring at this time.

Project: Lower Monumental

Biologists: Chuck Barnes and Raymond Addis

Dates: November 6 – November 12, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 2	7/15/2019	0720	4/01/2021	ERTS	Annual, Draft Tube Liner
Unit 5	10/19/2020	0707	11/10/2020	1415	Annual Maintenance

Comments: None.

Adult Fish Passage Facility

The adult fishways were inspected by Corps biologists on November 9 and 10.

Fish Ladder:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.5'	
X		North Ladder Picketed Lead Differential	Head \leq 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.5'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments: None.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	\geq 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	\geq 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	\geq 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	\geq 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X		X	South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments:

South Powerhouse Entrance (SPE-1) Weir was on sill during all inspections with readings of 7.9 and 6.8 feet respectively.

South Powerhouse Entrance (SPE-2) Weir was on sill during all inspections with readings of 7.9 and 6.8 feet respectively.

South Shore Entrance (SSE-1) Weir was on sill during the November 10 inspection with a reading of 7.7 feet.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	0 yds ²
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0 – 18%
	X		Any oil seen in gatewells?	

Comments: None.

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service?
	X		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: STS's were operating in cycle mode due to average sub-yearling Chinook and sockeye lengths being greater than 120 mm.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	17-18
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Collection Facility: The Juvenile collection facility was watered up at 10:00 on March 26.

Everyday collection for sample condition ended at 0700 on October 1 and the facility was placed into primary bypass at that time. The collection facility was dewatered at 1230 on October 5.

Transport Summary: Alternate day barge transport ended June 21.

Spillway Weir: Summer spill ended on August 31 at 23:59:59. Off-season spill to facilitate downstream passage for overshoot steelhead is occurring as described in the Columbia River System BiOp.

River Conditions

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
24.0	15.4	1.4	0	52.5	51.5	5.2	5.0

*Scrollcase temperatures.

Other

Inline Cooling Water Strainers: Cooling water strainers were inspected on August 10. No live fish or mortalities were recovered.

Avian Activity: Bird hazing efforts by USDA personnel ended June 2, 2020. Tailrace bird observations conducted during fish ladder inspections ended for the season September 30, 2020.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on October 19.

Fish Rescue/Salvage: No Fish Rescue/Salvage took place during this reporting period.

Research: No research is occurring currently.

Project: Little Goose

Biologists: Scott St. John and Richard Weis

Dates: November 6-12, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Little Goose Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	04/14/17	14:11	03/31/21	17:00	Spider and upper guide bearing repair.
2	10/26/20	03:08	11/30/20	17:00	Unit Annual

Comments: None.

Adult Fish Passage Facility

Little Goose fish facility staff inspected the adult fishway on November 8, 9, 10 and 12.

Fish Ladder:

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pump in Service		
		X	Fish Ladder Exit Cooling Water Pumps Operating Satisfactorily		

Comments: Adult ladder cooling pump was shut down for the season on September 16.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	\geq 7.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	\geq 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	\geq 6.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	\geq 6.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: The adult fishway continues to operate in manual mode.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: There is approximately 5 square feet of floating woody debris currently inside the trash shear boom in the forebay. Drawdowns were performed on November 9 on Units 1, 3 and 4 and were in criteria.

ESBS/VBS:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?
X			VBSs inspected this week?

Comments: All ESBS screens are in slots and deployed for all available and in-service Units. VBS differentials were performed on November 9 on Units 1, 3 and 4 and were in criteria. ESBS/VBS camera inspections were performed on Unit 2 on November 10 and screens were in satisfactory condition.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: The airline for the backflush system on orifice 1C1 was found broken and will need repaired once the juvenile channel is dewatered for winter maintenance (MFR 20 LGS 12). During prior ESBS/VBS inspections, an issue with the orifice liner in 6C2 was observed (MFR 20 LGS 14) and will need repaired during winter maintenance. The limitorque motor that operates the weirs for water elevation at the primary dewatering structure is out of service. Weirs are currently being adjust manually until repairs are made.

Collection Facility: The collection facility was placed in primary bypass on November 1. The facility was dewatered for winter maintenance on November 4.

Transport Summary: Daily collection and transport ended on November 1 at 07:00.

Spillway Weir: Spill for adult steelhead overshoots commenced on October 01. ASW spill operations will continue to be conducted in accordance to the most recent Columbia Basin Teletype.

River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
24.3	15.4	1.2	0.0	53.3	50.5	6.0	5.2

*Ladder temperature.

Other

Inline Cooling Water Strainers: Inline cooling strainers were inspected and results submitted to district operations every other week for FPOM distribution through mid-June per Fish Passage Plan (FPP) requirements.

Avian Activity: Daily piscivorous bird counts at Little Goose Dam began on April 1 and ended on October 31.

Invasive Species: No invasive species have been observed on the mussel station.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized, frozen and properly disposed of in a landfill. Daily collection ended on November 1; therefore no prawns were collected and euthanized.

Gas Bubble Trauma (GBT): GBT monitoring has finished for the season.

Fish Rescue/Salvage: None.

Research: None.

Project: Lower Granite

Biologists: Elizabeth Holdren and David Miller

Dates: Nov 6-12, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Lower Granite Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	Oct 19	0659			Annual maintenance

Comments: None.

Adult Fish Passage Facility

Lower Granite Biologist inspected the adult fishway October November 7, 9, 11, and 12.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pumps in Service		
		X	Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments: None.

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
	X		South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	7.9
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			North Powerhouse Entrance (NPE-1) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance (NPE-2) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	\geq 7.0' or on sill	
			North Shore Entrance (NSE-2) Weir Depth	\geq 7.0' or on sill	Closed
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
	X		Collection Channel Surface Velocity	1.5 – 4.0 fps	1.2, 1.2, 1.2

Comments: FOGs 1 and 10 are in operation. The control system sensor for NSE-1 continues to have issues recognizing and responding to tailwater elevation changes. Turbulent conditions during RSW spill continue to cause criteria issues at NSE-1.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
No			AWS Fish Pump 3

Comments: AWS pump 3 is operational in standby mode with lower guide bearing work delayed until the winter outage due to COVID.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil: oody debris observed in the forebay this season is likely due to the failure in the upriver two sections of the forebay debris boom. Repairs of the forebay debris boom are recommended to prevent further damage and limit debris in the powerhouse forebay and on unit trashracks.

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
X			Any debris seen in gatewells (% coverage)	Ranged from 1-3%
	X		Any oil seen in gatewells?	

Comments: Gatewell differentials were measured November 9. Debris is removed from gatewells with a hand dip basket.

ESBSs/VBSs:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18-24
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: Juvenile collection channel water level and flow is being adjusted using 10" orifices depending on forebay elevations. The facility is in primary bypass operation.

Collection Facility: Dewatered for winter maintenance.

Transport Summary: Transport operations have ended for the year.

Spillway Weir: The RSW is operating to facilitate adult steelhead passage from 0500-0900 hours Sundays, Tuesdays, and Thursdays October 1 through November 15.

River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
24.2	16.7	1.2	0.0	48.0	47.0	5.0	5.0

*Cooling water intake temperature.

Other

Inline Cooling Water Strainers: N/A

Invasive Species: No zebra/quagga muscles were detected on the trap substrate.

Avian Activity: Biologist daily piscivorous bird counts at Lower Granite Dam have ended for the year.

Adult Fish Trap Operations: Adult fish trap operations ended with the last sample worked up November 12. The trap will be dewatered November 15.

Fish Rescue/Salvage: N/A

Research:

National Marine Fisheries Service (NMFS) Ancillary Adult Passage Monitoring:

Fish that were PIT as juveniles at LWG are monitored as returning adults through the river and LWG facility. For each returning adult the following is estimated; 1) passage time between sets of detection PIT tag coils, 2) whether the fish was handled at the adult trap, 3) duration the fish was held at the adult trap, 4) overall passage time from ladder entrance to exit, 5) whether the turnpool gate was open or closed during passage. This will be the last year of this evaluation. Collection for this evaluation ended November 12.

Sampling of Steelhead, Chinook salmon, and Sockeye salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating steelhead, spring/summer Chinook salmon, and sockeye salmon are collected from the adult trap beginning April 4 through December 15. The goal is to collect 5-20% of adult steelhead, spring/summer Chinook salmon, and sockeye salmon ascending the ladder April 4-December 15. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. All natural origin adult steelhead and spring/summer Chinook salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some steelhead and spring/summer Chinook salmon may be radio-tagged or spaghetti-tagged. This information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs. Collection for this study ended November 12.

PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be collected as part of the normal adult trap daily sample and using the adult SbyC system to recapture previously PIT tagged fish. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder. Collection for this study ended November 12.