

**U.S. ARMY CORPS OF ENGINEERS
WALLA WALLA DISTRICT
FISH FACILITIES WEEKLY REPORT
#44-2020**

Project: McNary

Biologist: Bobby Johnson and Denise Griffith

Dates: December 25 – 31, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 14 turbine units available for service. (See table & comments below for details).		
	X	Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

Unit(s)	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	12/7	0643	01/14	N/A	Thrust bearing system maintenance/upgrades.
2	12/27	0530	12/29	0826	ETBOC pump failure.

Comments: The soft one percent peak efficiency constraint continues. At times the units ran outside the constraint at BPA's request. All return to service dates are subject to change. There is nothing more to report.

Adult Fish Passage Facilities

McNary fisheries biologists performed measured inspections of the adult fishways on December 27, 28 and 29. Preparations for the Washington ladder winter outage in January began this week. Dewatering the ladder will start on January 4. The Oregon ladder outage will occur in February.

Fish Ladder Exits

Yes	No	Location	Criteria	Comments
X		Oregon Exit	Head over weir 1.0' to 1.3'	
X		Oregon Count Station Differential	0.0' to 0.5'	
X		Washington Exit	Head over weir 1.0' to 1.3'	
X		Washington Count Station Differential	0.0' to 0.5'	

Comments: Debris loads were minimal to very light near the Oregon and Washington exits. There is nothing more to report.

Fishway Entrances and Collection Channel

Yes	No	Sill	Location	Criteria	Comments
X			North Oregon Entrance Head Differential	1.0' – 2.0'	
X			NFEW2 Weir Depth	≥ 8.0'	
X			NFEW3 Weir Depth	≥ 8.0'	
X			South Oregon Entrance Head Differential	1.0' – 2.0'	
	X		SFEW1 Weir Depth	≥ 8.0'	7.9' on Dec 28.
X			SFEW2 Weir Depth	≥ 8.0'	
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	Averaged 1.6 fps.
X			Washington Entrance Head Differential	1.0' – 2.0'	
X			WFE2 Weir Depth	≥ 8.0'	
X			WFE3 Weir Depth	≥ 8.0'	

Comments: The out of criterion point listed above for the Oregon ladder south entrance weir SFEW1 was possibly due to a calibration drift. The biologist requested both south weirs' set points be adjusted down one tenth of an inch on December 29. There is nothing more to report.

Auxiliary Water Supply System

Operating Satisfactory	Standby	Out of Service (OOS)	Auxiliary Water Supply System (AWS)
Yes			WA shore Wasco County PUD Turbine Unit
	Yes		WA shore Wasco PUD Bypass
Yes			Oregon Ladder Fish Pump 1, Blade angle: 22°.
Yes			Oregon Ladder Fish Pump 2, Blade angle: 22°.
Yes			Oregon Ladder Fish Pump 3, Blade angle: 22°.
		Yes	OR North Powerhouse Pool supply from juvenile fishway

Comments: The biologist noted an alarm sounding in the fish pump house, but the operators stated there was no problems to report on December 27. The juvenile system flow will return to service in late February. There is nothing more to report.

Juvenile Fish Passage Facility

The juvenile system remains out of service for the winter maintenance season. Emergency bypass will resume for the TSW overshoot study in February 2021. Primary bypass will begin in preparation for early start up in late February 2021.

Forebay Debris/Gatewell Debris/Oil

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Minimal to light.
X			Were trash rack differentials measured?	Three times.
X			Trash rack differentials acceptable?	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Debris loads were minimal to light near the powerhouse and minimal to very light beside the spillway. New debris loads were minimal to very light. The debris consisted mostly of aquatic vegetation and woody material. No trash rack cleaning or forebay debris removal occurred. Four test trash racks will be cleaned before January 16. Trash rack differentials and gatewell slots will continue to be checked during the winter maintenance season. There are no other problems to report.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs)

Yes	No	NA	Item
		X	ESBSs deployed in all slots and in service?
		X	ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: ESBS maintenance continued. Camera inspections will resume in late March 2021. VBS differential monitoring will resume when ESBS are installed for the TSW fallback study in February. There is nothing more to report.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe

Yes	No	NA	Item	Number of orifices in service
X		X	Did orifices operate satisfactory?	42
		X	Were the dewaterer and cleaning systems operated satisfactory?	

Comments: Full winter maintenance season continued in the channel. Modifying the electrical conduit to the three screen cleaning brushes' limit switches has almost been completed. Also, the mechanics began maintenance on the brushes. Work on the control system program continued. Dewatering valve maintenance with the focus being the north side dewatering valve began this week. The fisheries staff also cleaned the water elevation sensor still well. There are no problems to report.

Bypass Facility

Yes	No	NA	Item
		X	Sample gates on?
		X	PIT-tag sampling system on?

Comments: All bypass facility systems remain out of service. The separator and sample system rehabilitation continued along with gasket replacement on the full flow flume primary/secondary bypass gate. The welding phase of the separator rehabilitation is scheduled to begin January 4, 2021.

Top Spillway Weir (TSW) Operations: The TSW's in bays 19 and 20 remained out of service.

River Conditions

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
145.3	119.0	0.0	0.0	44.0	41.0	6.0	6.0

Comments: The above data comes from the control room. The data day is 0000 to 0000 hours. Repairs to crane 6 continued. The crane is scheduled to return to service in mid-January 2021. Crane 7 is also scheduled to receive a new gearbox.

Other

Inline Cooling Water Strainers: The next cooling water strainer inspections will occur on January 5.

Avian Activity: Casual avian observations continued.

Currently, there are no hazing efforts occurring. No terns were observed on project. However, two bald eagles appeared to be roosting and foraging in the area.

Gull and cormorant feeding activity remained light with very few birds in the powerhouse zone. A fair number of pelicans were also observed roosting on the water.

In the spillway zone, gulls and cormorants were observed in fairly low numbers, with the birds roosting around the spill basin or on the water.

At the juvenile bypass outfall, gulls and cormorants were noted. Gull numbers remained low and cormorant numbers fluctuated. Roosting on the bypass pipe was still the primary use of the area with feeding occurring occasionally.

In the forebay zone, gulls, cormorants, grebes and pelicans were noted in small numbers roosting on the water or flying by at times. In addition, gull flocks, a few cormorants and a fair number of pelicans were observed roosting outside the zone. Gull numbers also appear to be fluctuating.

Invasive Species: As systems are being dewatered this winter, they will be examined for invasive species.

Fish Rescue/Salvage: There is nothing to report.

Research: There is nothing to report.

Project: Ice Harbor

Biologist: Ken Fone

Fisheries Technician: Timothy DeKoster

Dates: December 25, 2020 – December 31, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	x	All 6 turbine units available for service (see table below for details).		
x		Available turbines operated within 1% peak efficiency? Constraint in effect.		x

Ice Harbor Unit Outages (OOS) and Return to Service (RTS).

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	5/3/19	0641	---	---	Turbine runner replacement and stator rewind
5	9/21/20	0900	12/10/20	1210	Annual maintenance and overhaul
2	11/30/20	0702	---	---	Annual maintenance

Comments: None.

Adult Fish Passage FacilityIce Harbor Fish Facility staff inspected the adult fishways on December 28th, 29th, and 30th.Fish Ladders:

Yes	No	Location	Criteria	Measurements
x		North Ladder Exit Differential	Head \leq 0.3'	
x		North Ladder Picketed Lead Differential	Head \leq 0.3'	
x		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
x		South Ladder Exit Differential	Head \leq 0.3'	
x		South Ladder Picketed Lead Differential	Head \leq 0.3'	
x		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
x			South Shore Entrance (SFE-1) Weir Depth	\geq 8.0' or on sill	
x			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
x			South Shore Channel Velocity	1.5 – 4.0 fps	
x			North Powerhouse Entrance (NFE-2) Weir Depth	\geq 8.0' or on sill	
x			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
x			North Shore Entrance (NEW-1) Weir Depth	\geq 8.0' or on sill	
x			North Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: None.

Auxiliary Water Supply System (AWS):

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
5 pumps	3 pumps		Status of the 8 South Shore AWS Pumps
2 pumps	1 pump		Status of the 3 North Shore AWS Pumps

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
x			Forebay debris load acceptable? (amount)	Average of 28.3 square yards
x			Gatewell drawdown measured this week?	
x			Gatewell drawdown acceptable	
x			Any debris seen in gatewells (% coverage)	Stored STSs obstruct full view into gatewells
	x		Any oil seen in gatewells?	

Comments: None.

Submersible Traveling Screens/Vertical Barrier Screens (STSs/VBSs):

Yes	No	NA	Item
	x		STSs deployed in all slots and in service for available units?
		x	STSs in continuous-run mode? (Note: if not, then STSs are in cycle-run mode).
		x	STSs inspected this week?
		x	STSs inspection results acceptable?
		x	VBSs differentials checked this week?
		x	VBSs differentials acceptable?

Comments: STSs are removed for winter maintenance.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
		x	Orifices operating satisfactory?	0
		x	Dewaterer and cleaning systems operating satisfactory?	

Comments: The juvenile fish bypass is unwatered for winter maintenance.

Juvenile Fish Facility: The juvenile fish facility is unwatered for winter maintenance.

Fish Sampling: Fish sampling is done for the year at Ice Harbor Project.

Removable Spillway Weir (RSW): Voluntary spill for fish is done for the year.

River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
---	---	0	0	43	42	10.1	8.9

*Unit 1 scroll case temperature.

Comments: Currently there is no daily average river flow (kcfs) data available, and we will update the report when it becomes available.

Other

Inline Cooling Water Strainers: Seasonal inspections of strainers for lamprey started up again in December and will be completed later in June.

Avian Activity: There were moderate to low numbers of piscivorous birds seen around the project, including gulls, mergansers, and pelicans.

Invasive Species: No new exotic species have been observed.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by fisheries management personnel, frozen and properly disposed in a landfill.

Fish Rescue/Salvage: None.

Research: No on-site research is occurring currently.

Project: Lower Monumental

Biologists: Chuck Barnes and Raymond Addis

Dates: December 25-31, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 1	12/7/2020	0700	1/11/2021	ERTS	Annual Maintenance
Unit 2	7/15/2019	0720	4/01/2021	ERTS	Annual, Draft Tube Liner

Comments:

Adult Fish Passage Facility

The adult fishways were inspected by Corps biologists on December 29 and 30.

Fish Ladder:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.5'	
X		North Ladder Picketed Lead Differential	Head \leq 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.5'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments:

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	$>$ 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	$>$ 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	$>$ 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	$>$ 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments:

South Powerhouse Entrance (SPE-1) Weir was on sill during both inspections with readings of 6.7 and 6.6 feet respectively.

South Powerhouse Entrance (SPE-2) Weir was on sill during both inspections with readings of 6.7 and 6.6 feet respectively.

South Shore Entrance (SSE-1) Weir was on sill during both inspections with readings of 7.4 and 7.7 feet respectively.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments:

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	75 yds ²
		X	Gatewell drawdown measured this week?	
		X	Gatewell drawdown acceptable	
		X	Any debris seen in gatewells (% coverage)	STS's dogged off blocking gatewells
		X	Any oil seen in gatewells?	

Comments:

STSs/VBSs:

Yes	No	NA	Item
	X		STSs deployed in all slots and in service?
		X	STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
		X	STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments:

STS's for Units 1 and 2 were removed on December 7. Both units are out of service for the remainder of the juvenile fish passage season. STS's for Units 3-6 were removed for the season on December 16 and 17.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
		X	Orifices operating satisfactory?	0
		X	Dewaterer and cleaning systems operating satisfactory?	

Comments: Orifices were closed and juvenile channel and primary bypass were dewatered for winter maintenance on December 16.

Collection Facility: The collection facility is dewatered for winter maintenance.

Transport Summary: The 2020 transport season has ended.

Spillway Weir: Summer spill ended on August 31 at 23:59:59.

River Conditions

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
27.9	25.1	0	0	41.4*	41.1	5.5	5.5

* Water temperature came from South Shore collection channel on all inspections, due to Scrollcase temperatures not being available.

Other

Inline Cooling Water Strainers: Cooling water strainers were inspected on December 1. No live fish were recovered. Several juvenile American shad mortalities were present in strainers but could not be counted due to decomposition.

Avian Activity: Highest counts of foraging piscivorous birds in tailrace (SWT1+PH1+PH2) at Lower Monumental Dam.

Date	Time	Gulls	Cormorants	Terns	Grebes	Pelicans

* Table shows tailrace observation conducted during Adult Fish Ladder inspections*

Comments: Bird hazing efforts by USDA personnel ended June 2, 2020.

Tailrace bird observations conducted during fish ladder inspections ended for the season September 30, 2020.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on December 1.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by PSMFC and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Lower Monumental Dam for this reporting period are reported below.

Date	Sample (euthanized)	Collection*
Total		

*Collection and sample numbers are the same as the facility when sampling at 100%

Fish Rescue/Salvage: N/A

Research: No research is occurring currently.

Project: Little Goose

Biologists: Scott St. John

Dates: December 25-31, 2020

Turbine Operation

Yes	No	Turbine Unit Status		
	X	All 6 turbine units available for service (see table & comments below for details).	Hard	Soft
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Little Goose Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	04/14/17	14:11	03/31/21	17:00	Spider and upper guide bearing repair.
1	11/30/20	08:00	01/29/21	17:00	Unit Annual

Comments: None.

Adult Fish Passage Facility

Little Goose fish facility staff inspected the adult fishway on December 28, 29 and 30.

Fish Ladder:

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pump in Service		
		X	Fish Ladder Exit Cooling Water Pumps Operating Satisfactorily		

Comments: Adult ladder cooling pump was shut down for the season on September 16.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	\geq 7.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	\geq 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	\geq 6.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	\geq 6.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
	X		Collection Channel Surface Velocity	1.5 – 4.0 fps	1.4

Comments: The adult fishway continues to operate in manual mode. The surface velocity near the NSE was found out of criteria on the December 30 inspection.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	
	X		Gatewell drawdown measured this week?	
		X	Gatewell drawdown acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: There is approximately 4,000 square feet of floating woody debris currently inside the trash shear boom in the forebay. Drawdowns were last performed on December 3 on Units 3, 4 and 6 and were in criteria.

ESBS/VBS:

Yes	No	NA	Item
	X		ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
	X		VBSs differentials checked this week?
		X	VBSs differentials acceptable?
	X		VBSs inspected this week?

Comments: All ESBS screens were removed for winter maintenance on December 16 and 17. Screens were visually inspected and in satisfactory conditions. VBS differentials were last performed on December 3 on Units 3, 4 and 6 and were in criteria. ESBS/VBS camera inspections were last performed on Unit 1 on December 3 and screens were in satisfactory condition.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
		X	Orifices operating satisfactory?	0
		X	Dewaterer and cleaning systems operating satisfactory?	

Comments: The juvenile bypass system was dewatered for winter maintenance on December 21. The airline for the backflush system on orifice 1C1 was found broken and will need repaired once the juvenile channel is dewatered for winter maintenance (MFR 20 LGS 12). During prior ESBS/VBS inspections, an issue with the orifice liner in 6C2 was observed (MFR 20 LGS 14) and will need repaired during winter maintenance. The limitorque motor that operates the weirs for water elevation at the primary dewatering structure is out of service.

Collection Facility: The juvenile bypass system was dewatered for winter maintenance on December 21.

Transport Summary: Daily collection and transport ended on November 1 at 07:00.

Spillway Weir: Spill for adult steelhead overshoots ended on November 15.

River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
28.1	22.6	0.0	0.0	41.0	40.5	6.0	6.0

*Ladder temperature.

Other

Inline Cooling Water Strainers: Inline cooling strainers were inspected, and results submitted to district operations every other week for FPOM distribution through mid-June per Fish Passage Plan (FPP) requirements. Strainer inspections commenced again on December 28 and results submitted.

Avian Activity: Daily piscivorous bird counts at Little Goose Dam began on April 1 and ended on October 31.

Invasive Species: No invasive species have been observed on the mussel station.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized, frozen and properly disposed of in a landfill. Daily collection ended on November 1; therefore, no prawns were collected and euthanized.

Gas Bubble Trauma (GBT): GBT monitoring has finished for the season.

Fish Rescue/Salvage: None.

Research: None.

Project: Lower Granite

Biologists: Elizabeth Holdren and David Miller

Dates: Dec 25-31, 2020

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.		X

Lower Granite Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	

Comments:

Adult Fish Passage Facility

Lower Granite Biologist inspected the adult fishway December 28, 29, and 30.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pumps in Service		
		X	Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments:

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X			North Powerhouse Entrance (NPE-1) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance (NPE-2) Weir Depth	\geq 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	\geq 7.0' or on sill	
			North Shore Entrance (NSE-2) Weir Depth	\geq 7.0' or on sill	Closed
	X		North Shore Channel/Tailwater Differential	1.0' – 2.0'	0.9
	X		Collection Channel Surface Velocity	1.5 – 4.0 fps	1.3, 1.0, 1.1

Comments: FOGs 1 and 10 are in operation. The control system sensors continue to have issues recognizing and responding to tailwater elevation changes. The electrical crew continues to work on programming and calibration issues with the control system.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
No			AWS Fish Pump 3

Comments: AWS pump 3 is operational in standby mode with lower guide bearing work delayed until the winter outage due to COVID. All AWS will be turned off at 0001 hours on January 1, 2021 for the adult fishway winter maintenance outage.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil: The failure in the upriver two sections of the forebay debris boom may be resulting in increased powerhouse debris. Repairs of the forebay debris boom are recommended to prevent further damage and limit debris in the powerhouse forebay and on unit trashracks.

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
X			Any debris seen in gatewells (% coverage)	Ranged from 1-3%
	X		Any oil seen in gatewells?	

Comments: Debris is removed from gatewells with a hand dip basket.

ESBSs/VBSs:

Yes	No	NA	Item
	X		ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
	X		VBSs differentials checked this week?
	X		VBSs differentials acceptable?

Comments:

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
	X		Orifices operating satisfactory?	18-24
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: Dewatered for winter maintenance.

Collection Facility: Dewatered for winter maintenance.

Transport Summary: No transport.

Spillway Weir: No spill.

River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcs)		Daily Average Spill (kcs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
26.9	23.2	0.0	0.0	39.0	38.0	4.8	4.7

*Cooling water intake temperature.

Other

Inline Cooling Water Strainers: Cooling Water Strainers were inspected December 29.

Invasive Species: No zebra/quagga mussels were detected on the trap substrate.

Avian Activity: N/A

Adult Fish Trap Operations: N/A

Fish Rescue/Salvage: N/A

Research: N/A