

**U.S. ARMY CORPS OF ENGINEERS
WALLA WALLA DISTRICT
FISH FACILITIES WEEKLY REPORT
#32-2021**

Project: McNary

Biologist: Bobby Johnson and Denise Griffith

Dates: October 1-7, 2021

Turbine Operation

Yes	No	Turbine Unit Status
	X	All 14 turbine units available for service? (See table & comments below for details.)

*All available turbine units are operated in accordance with App. C of the Fish Passage Plan.

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

Unit(s)	OOS		RTS		Outage Description
	Date	Time	Date	Time	
4	8/2	1018	10/ 28	N/A	Nine-year overhaul
5 thru 8	10/4	0730	11/9	N/A	Lines 3 & 4 outages for BPA relays
9, 11 & 12	10/5	1000	10/5	1130	ESBS camera inspections

Comments: The one percent peak efficiency constraint and unit priority are being followed per the 2021 Fish Passage Plan (FPP). RTS dates are subject to change.

Adult Fish Passage Facilities

The fisheries biologist and a technician performed a measured inspection of the adult fishways on October 1, 3, and 7. Fish counting continues.

Fish Ladder Exits:

Yes	No	Location	Criteria	Measurements
X		Oregon Exit	Head over weir 1.0' to 1.3'	1.1'
X		Oregon Count Station Differential	0.0' to 0.5'	0.2' to 0.3'
X		Washington Exit	Head over weir 1.0' to 1.3'	1.1' to 1.2'
X		Washington Count Station Differential	0.0' to 0.5'	0.1' to 0.3'

Comments: Debris loads near the Oregon exit were very light to light and debris loads near the Washington shore exit were minimal to very light. Picketed leads at both exits were cleaned as needed, including the weekend.

There are no other problems to report.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Oregon Entrance Head Differential	1.0' – 2.0'	1.2' to 1.4'
X			NFEW2 Weir Depth	≥ 8.0'	8.0' to 8.1'
X			NFEW3 Weir Depth	≥ 8.0'	8.1' to 8.2'
X			South Oregon Entrance Head Differential	1.0' – 2.0'	1.4' to 1.5'
X			SFEW1 Weir Depth	≥ 8.0'	8.0' to 8.1'
X			SFEW2 Weir Depth	≥ 8.0'	8.1' to 8.2'
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	Averaged 1.5 fps
X			Washington Entrance Head Differential	1.0' – 2.0'	1.3' to 1.4'
X			WFE2 Weir Depth	≥ 8.0'	10.0' to 10.3'
X			WFE3 Weir Depth	≥ 8.0'	10.1' to 10.2'

Comments: There are no problems to report.

Fabrication of the six remaining FOG's is on hold until fish pump 3 repairs are completed.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Fish Pump Blade Angle	Auxiliary Water Supply System (AWS)
Yes				WA shore Wasco County PUD Turbine Unit
	Yes			WA shore Wasco PUD Bypass
Yes			24° to 25°	Oregon Ladder Fish Pump 1
Yes			23°	Oregon Ladder Fish Pump 2
		Yes		Oregon Ladder Fish Pump 3, RTS date is October 29
Yes				OR North Powerhouse Pool supply from juvenile fishway

Comments: Fish pump 3 remained out of service. The estimated return to service date is October 29. There are no other problems to report.

Juvenile Fish Passage Facility

Fall primary bypass season continues. Light maintenance and winterization have begun at the juvenile facility.

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Light to moderate
X			Gatewell drawdown measured this week?	Daily
X			Gatewell drawdown acceptable?	
	X		Any debris seen in gatewells? (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Current debris loads were light to moderate near the powerhouse and minimal beside the spillway. Incoming debris was minimal. Most of the debris appeared to be moving back and forth from the powerhouse to the Oregon shoreline.

No trash racks were cleaned this week.

There are no problems to report.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs):

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: All screens are in place. Camera inspections in units 9, 11 and 12 revealed no issues.

Daily VBS differential monitoring revealed no differentials out of criteria. No screens were cleaned this week.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

Yes	No	NA	Item	Number of orifices in service
X			Did orifices operate satisfactory?	42
X			Dewatering and cleaning systems operating satisfactory?	

Comments: With low debris loads and a temporary air supply line, orifice cycling remains at once a day except as outlined below. Water in the air line continues to be an issue, which will be monitored. Orifice operators and area lighting were repaired as needed.

The air supply was lost again on October 1 at about 0900 hours. The roving operator found two supply valves closed, which they opened and restored the air supply by 1130 hours. A caution order card was installed on all four air valves leading to and included in the temporary supply line on October 3 at about 1400 hours. Hopefully, this eliminates the issue of someone closing these valves.

An air leak in a branch of the temporary supply line was noted on October 1 at about 1700 hours. Cycling the orifices was suspended on October 3 at about 0900 hours, when the biologist was finally informed of the air leak. The leaking air branch issue was resolved on October 4 at about 1400 hours and orifice cycling resumed.

The air supply was again found off on October 5 from about 0900 to 1300 hours. This time, the “check” valve in the line was found closed and the roving operator had to resolve the issue as before. The mechanical staff removed the check valve on October 7 at about 1400 hours. Hopefully, the above measures will resolve all issues with the temporary supply line until the permanent line is restored.

The contractor who is reinforcing the intake deck crane’s east rail will continue to be monitored.

Bypass Facility:

Yes	No	NA	Item
X			Sample gates on?
		X	PIT-tag sampling system on?

Comments: All bypass facility systems are down for above water winter maintenance and partial winterization.

Preparations to remove a debris blockage from the separator winterization drains began this week. There are no other problems to report.

Top Spillway Weir (TSW) Operations:

A standard spill gate is in spill bay 19. The TSW, which is attached to a hoist in bay 20, became operational for the fall adult fallback season per the FPP on October 1 and openings are occurring per the schedule released by RCC.

River Conditions

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
91.7	73.3	1.7	0.0	65.0	63.3.7	6.0	6.0

Comments: The above data is provided by the control room. The data day runs from 0000 to 0000 hours.

Though crane 6 is in service, remote operation has yet to be restored. The load limit indicator continues to be an issue. Crane 7 is out of service and work on the main hoist gearbox continued. The crane's motor starter still needs to be replaced. A contract will be required. The current target date for replacement will be in late October or early November. Also, the crane's load limit indicator continues to be an issue.

Other

Inline Cooling Water Strainers: The next cooling water strainer inspections will occur on December 7.

Avian Activity: Avian counts concluded with the sampling season on September 30. During fall primary bypass season, only casual avian observations are made.

In the spillway zone, gulls and cormorants were noted. The birds were mostly roosting around the basin in numbers that appeared to fluctuate with the out migration of juvenile shad. However, when the TSW was open, gulls feed heavily.

In the powerhouse zone, gulls were noted occasionally feeding or roosting. Again, numbers fluctuated.

In the bypass outfall zone, gulls and cormorants were noted in numbers that fluctuated. All the birds were roosting on the pipe and feeding at the outfall at times.

In the forebay zone, six grebes were noted once. Outside the zone, a few cormorants were observed along with a large gull flock that roosted along the shorelines or on the water.

Two large bird distress calls remain installed on the navigation lock wing wall but will be removed soon for the winter. No other hazing occurred. The lasers on the outfall pipe and navigation lock wing remained off and will also be removed. The use of the LRAD will resume next spring.

Invasive Species: The next mussel station examinations will occur in late October.

Siberian Prawn: There is nothing to report.

Fish Rescue/Salvage: Unit 7 was dewatered for maintenance this week. No fish were found in the scroll case on October 5. Three channel catfish (12 inches to seven pounds) and two sturgeon (2.5 and 3.5 feet) were removed from the draft tube and returned to the river on October 6.

Research: There in nothing to report.

Project: Ice Harbor
 Fisheries Biologist: Ken Fone

Turbine Operation

Yes	No	Turbine Unit Status
	x	All 6 turbine units available for service (see table & comments below for details).

*All available turbine units are operated in accordance with App. C of the Fish Passage Plan.

Ice Harbor Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	5/3/19	0641	---	---	Turbine runner replacement and stator rewind
5	10/5/21	0930	10/5/21	1835	Replace burned out brake solenoid

Comments: None.

Adult Fish Passage Facility

Ice Harbor Fish Facility staff inspected the adult fishways on October 5, 6, and 7.

Fish Ladders:

Yes	No	Location	Criteria	Measurements
x		North Ladder Exit Differential	Head \leq 0.3'	
x		North Ladder Picketed Lead Differential	Head \leq 0.3'	
x		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
x		South Ladder Exit Differential	Head \leq 0.3'	
x		South Ladder Picketed Lead Differential	Head \leq 0.3'	
x		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
x			South Shore Entrance (SFE-1) Weir Depth	\geq 8.0' or on sill	
x			South Shore Channel/Tailwater Differential	1.0' – 2.0'	2.6', 2.6', 2.3'
x			South Shore Channel Velocity	1.5 – 4.0 fps	
x			North Powerhouse Entrance (NFE-2) Weir Depth	\geq 8.0' or on sill	
x			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
x			North Shore Entrance (NEW-1) Weir Depth	\geq 8.0' or on sill	
x			North Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: The lamprey passage structure at the south shore entrance #2 was closed for the season on October 4.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply (AWS) System
5 pumps	3 pumps		Status of the 8 south shore AWS pumps
2 pumps	1 pump		Status of the 3 north shore AWS pumps

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
x			Forebay debris load acceptable? (amount)	Average of 2 square yards
x			Gatewell drawdown measured this week?	
x			Gatewell drawdown acceptable	
x			Any debris seen in gatewells (% coverage)	0-1%
	x		Any oil seen in gatewells?	

Comments: None.

Submersible Traveling Screens (STSs) / Vertical Barrier Screens (VBSs):

Yes	No	NA	Item
x			STSs deployed in all slots that are in service?
	x		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
	x		STSs/VBSs inspected this week?
		x	STS/VBS inspection results acceptable?
		x	VBS differentials checked this week?
		x	VBS differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
x			Orifices operating satisfactory?	20
	x		Dewaterer and cleaning systems operating satisfactory?	

Comments: Orifices are being backflushed once per day. There were no debris obstructions observed at the orifices, as indicated by reduced flow through the orifices.

The replacement actuator for the water regulating weirs in the collection channel is being operated in manual control. An analog controller input was added to the actuator and needs to be programmed to function automatically. Currently, the water level in the collection channel is being visually monitored once per day. The actuator is operated electronically in "local" control to manually adjust the weirs as needed.

The mechanical screen cleaner was taken out of service on October 4 due to the drive cable coming off the sheaves and the cable starting to fray. The drive pulley had also become deeply grooved from the friction of the cable against the pulley. The drive pulley was removed, and a new pulley is being machined. The water regulating weirs had to be lowered during the week to maintain the proper level as debris accumulated on the inclined floor screen.

Juvenile Fish Facility: The Juvenile Fish Facility is operating in primary bypass mode. The raw water supply lines in the Fish Facility were drained and winterized on October 6.

Fish Sampling: Sampling at Ice Harbor Dam has concluded for the season.

Removable Spillway Weir (RSW): The RSW is periodically opened for downstream passage of adult steelhead that may have strayed into the Snake River. The RSW is scheduled to be operated from 0500 hours to 0900 hours on Sundays, Wednesdays, and Fridays, from October 1 to November 15.

River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
19.8	15.6	1.7	0.0	64	63	8.8	5.5

*Unit 1 scroll case temperature.

Other

Inline Cooling Water Strainers: Inspection of turbine cooling water strainers for lamprey will resume in December.

Avian Activity: There were moderate numbers of gulls and pelicans that were resting or foraging at Eagle Island and along the south shore downstream of the dam

Invasive Species: No exotic species that are new to the area have been found.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by the fish sampling contractor, frozen and properly disposed of in a landfill.

Fish Rescue/Salvage: Unwatering activities that involved fish rescue did not occur this week.

Research: No on-site research is currently going on.

Project: Lower Monumental

Biologists: Raymond Addis and Paul Bertschinger

Turbine Operation

Yes	No	Turbine Unit Status
	X	All 6 turbine units available for service (see table & comments below for details).

* All available turbine units are operated in accordance with App. C of the Fish Passage Plan.

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 1	10/6/2021	1000	10/6/2021	1120	STS Inspection
Unit 2	07/15/2019	0720	12/16/2021	ERTS	Annual, Draft Tube Liner
Unit 3	10/6/2021	0740	10/6/2021	0905	STS Inspection
Unit 4	10/5/2021	1220	10/5/2021	1430	STS Inspection
Unit 5	10/5/2021	0955	10/5/2021	1155	STS Inspection
Unit 6	10/5/2021	0810	10/5/2021	0930	STS Inspection

Comments: None

Adult Fish Passage Facility

The adult fishways were inspected by Corps and EAS biologists on October 1, 3 and 5.

Fish Ladder:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.5'	
X		North Ladder Picketed Lead Differential	Head \leq 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.5'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments: None.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	\geq 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	\geq 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	\geq 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	\geq 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X		X	South Shore Entrance (SSE-1) Weir Depth	\geq 8.0' or on sill	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: The south powerhouse entrance weir (SPE-1) was on sill during all inspections with readings of 7.5, 7.4 and 7.4 feet respectively. The south powerhouse entrance weir (SPE-2) was on sill during all inspections with readings of 7.5, 7.4 and 7.4 feet respectively. The south shore entrance weir (SSE-1) was on sill during the October 3 inspection with readings of 7.8 feet.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments: None

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	32 yds ²
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0 - 3%
	X		Any oil seen in gatewells?	

Comments: None

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed and in service in operating and available units?
	X		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
	X		VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: STS's were operating on cycle mode during the reporting period due to average sub-yearling Chinook salmon and sockeye salmon lengths being greater than 120 mm.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: None

Collection Facility: Collection for condition sampling ended at 0700 on October 1. The facility was placed into Primary Bypass at that time and dewatered on October 2. A total of 4 fish were collected with 4 fish bypassed back to the river during this reporting period.

Transport Summary: Transport at Lower Monumental ended June 20.

Spillway Weir: Fall spill began at 0001 on October 1.

River Conditions

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
18.4	15.3	1.5	0.0	64.5	63.5	7.0	6.4

*Scrollcase temperatures.

Other

Inline Cooling Water Strainers: Cooling water strainer inspections will resume in December.

Avian Activity: Highest counts of foraging piscivorous birds in tailrace (SWT1+PH1+PH2) at Lower Monumental Dam are reported in the table below.

Date	Time	Gulls	Cormorants	Terns	Grebes	Pelicans
10/1/2021	1330	0	8	0	0	0
10/3/2021	1015	0	8	0	0	0
10/5/2021	1030	0	6	0	0	0

Comments: Bird hazing efforts by USDA personnel ended June 2.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on September 19.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by PSMFC and EAS, frozen and properly disposed of in a landfill. Total Siberian prawn counts at Lower Monumental Dam for this reporting period are reported in the table below.

Date	Sample (euthanized)	Collection*
10/01/2021	74	148
Total	74	148

*Collection and sample numbers are the same as the facility when sampling at 100%

Fish Rescue/Salvage: No fish rescue or salvage occurred.

Research: No research is occurring currently.

Project: Little Goose

Biologists: Chuck Barnes and Deborah Snyder

Turbine Operation

Yes	No	Turbine Unit Status
	X	All 6 turbine units available for service (see table & comments below for details).

*All available turbine units are operated in accordance with App. C of the Fish Passage Plan.

Little Goose Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	04/14/17	14:11	12/31/2022	17:00	Spider and upper guide bearing repair.
6	03/18/21	14:17	N/A	17:00	T2 C phase ground fault
4	09/20/21	08:00	10/15/2021	17:00	Annual Maintenance

Comments: Little Goose experienced a T2 transformer ground on March 18 at 14:17. T2 transformer and Units 5 and 6 will be out of service until repairs/replacement can be performed.

Adult Fish Passage Facility

Little Goose fish facility, Environmental Assessment Services (EAS) and Oregon Department of Fish and Wildlife (ODFW) staff inspected the adult fishway on October 2, October 3, and October 7.

Fish Ladder:

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X			Fish Ladder Cooling Water Pumps in Service		
	X		Fish Ladder Exit Cooling Water Pumps Operating Satisfactorily		

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
X		X	North Powerhouse Entrance (NPE-1) Weir Depth	\geq 7.0' or on sill	
X		X	North Powerhouse Entrance (NPE-2) Weir Depth	\geq 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	\geq 6.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	\geq 6.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: The adult fishway continues to operate in manual mode. The fish control system still has a faulty hydranger for the NSE1 weir and is currently awaiting repair. Subsequent NSE fish control system channel and tailwater readings were encountered and remedied with physical staff gauge and water level depth indicator measurements.

Ladder exit cooling pumps were placed into service at 2052 hrs on 12 June when 0.5m forebay temperatures exceeded 64°F. At 16:00 on September 19 the 0.5m forebay temperature met the qualifying criteria to shut down the ladder exit cooling pump for the season.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: Fish pumps 1 and 2 were returned to service on February 23. Fish pump 3 returned to service April 7.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	100ft ² on 10/07; 1900ft ² on 10/04
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	6C: 1% 10/03
	X		Any oil seen in gatewells?	

Comments: There is currently fluctuating minimal to moderate floating woody debris inside the trash shear boom. Gatewell drawdowns for Unit 1 were conducted on October 7 and were in criteria.

ESBS/VBS:

Yes	No	NA	Item
	X		ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
	X		ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?
	X		VBSs inspected this week?

Comments: ESBS's were installed in Units 2, 3 and 4 on March 22 and 23. VBS differentials for Unit 1 were conducted on October 7 and were in criteria. ESBS/VBS camera inspections for all units took place June 8-10. Unit 4 was inspected again on October 7. Unit 6 has 1 remaining ESBS currently raised and stored within the Unit 5-B slot position. Unit 6 bulkheads are in place; both Units 5 and 6 are out of service.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	19
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: The juvenile bypass system was watered up on March 22 and began daily collection for transportation on April 23.

Collection Facility: Collection for condition monitoring in conjunction with secondary bypass commenced on April 1 with the first sample being conducted on April 2. Every other day collection and sampling occurred through April 22. Daily collection for transportation began on April 23 with the first daily barge departing on April 24. The collection and transport facility operated within criteria this report period. A total of 408 fish were collected, 355 were transported via truck, 0 were bypassed, and there were 7 sample or facility mortalities. The descaling and mortality rates were 0.0% and 1.79%, respectively. No adult lamprey were removed from the separator during this report period.

Transport Summary: Daily fish transportation via barge began on April 24. Every other day barge transportation began May 18 and ended June 21. Collection for transport resumed at 0700 hrs July 5 and every other day truck transportation began July 6.

Spillway Weir: Spring spill operations began on April 3 with the ASW in high crest. ASW day surface spill emergency procedure began July 3 at 0900 hours and ceased July 9 at 1600 hours. Off-season surface spill for adult steelhead downstream passage as outlined in the 2020 NOAA Fisheries CRS Biological Opinion took place between 0500 and 0900 hours on October 1, October 3, October 5, and October 7.

River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcs)		Daily Average Spill (kcs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
18.6	15.1	1.2	0.0	64.8	64.0	6.0	5.2

*Ladder temperature.

Other

Inline Cooling Water Strainers: Inspections will resume in December.

Avian Activity: Daily piscivorous bird counts at Little Goose Dam began on April 1. USDA hazing activities began on March 29 and ended June 19.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
10-01	0930	25	14	0	0
10-02	0630	25	23	0	0
10-03	0845	15	18	0	0
10-04	1000	0	9	0	0
10-05	0830	20	6	0	0
10-06	1015	8	2	0	0
10-07	1100	8	2	0	0

Invasive Species: No invasive species have been observed on the mussel station.

Siberian Prawn: Juvenile fish collection began on April 1. Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Oregon Department of Fish and Wildlife and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Little Goose Dam for this reporting period are reported below.

Date	Sample	Collection*
10-01	63	63
10-02	54	54
10-03	140	140
10-04	102	102
10-05	228	228
10-06	255	255
10-07	528	528
Totals	1370	1370

Gas Bubble Trauma (GBT): GBT monitoring for the 2021 season concluded July 26.

Fish Rescue/Salvage: No fish rescue / salvage activities were performed this period.

Research: The Nez Perce Tribe (NPT) began adult steelhead kelt collection on May 3 and ended June 30.

Project: Lower Granite

Biologists: Elizabeth Holdren and David Miller

Turbine Operation

Yes	No	Turbine Unit Status
	X	All 6 turbine units available for service (see table & comments below for details).

*All available turbine units are operated in accordance with App. C of the Fish Passage Plan.

Lower Granite Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
3	10/04	0704			Annual Maintenance and Bearing Indication Work
1	10/04	1120	10/04	1152	Swap the direct current feed to bus 2

Comments: None.

Adult Fish Passage Facility

Lower Granite Biologists and Anchor QEA staff inspected the adult fishway October 2, 4, and 6.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head < 0.5'	
X			Fish Ladder Picketed Lead Differential	Head < 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
	X		Fish Ladder Cooling Water Pumps in Service		
		X	Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments: None.

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			South Shore Entrance (SSE-1) Weir Depth	≥ 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	≥ 8.0'	
	X		South Shore Channel/Tailwater Differential	1.0' – 2.0'	0.9'
X			North Powerhouse Entrance (NPE-1) Weir Depth	≥ 8.0' or on sill	
X			North Powerhouse Entrance (NPE-2) Weir Depth	≥ 8.0' or on sill	
	X		North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	0.9'
X			North Shore Entrance (NSE-1) Weir Depth	≥ 7.0' or on sill	6.8'
X			North Shore Entrance (NSE-2) Weir Depth	≥ 7.0' or on sill	6.8'
	X		North Shore Channel/Tailwater Differential	1.0'–2.0'	0.7', 0.9', 0.8'
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: Ladder collection channel operation and configuration are being evaluated to resolve ongoing issues. FOGs 1, 4, 7, and 10 are in operation. North shore and north powerhouse channel/tailrace head differential's ability to maintain criteria range is dependent of tailrace conditions. Lower Granite electrical crew continue to work on the ladder control system issues.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
	Yes		AWS Fish Pump 3

Comments: AWS pumps were out of service October 4 from 1120 hours to 1123 hours to swap the direct current feed to bus 1. AWS pump 1 was returned to service in fast mode to address the channel/tailwater differentials being out of criteria during the previous reporting week.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Weekly average 25.4 yds ²
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: None.

ESBSs/VBSs:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Collection Facility: The facility is in collection mode for condition sample and juvenile truck transport.

Transport Summary: A total of 66 smolts were transported this reporting period. There have been 119,309 smolts transported by truck since July 2.

Spillway Weir: A total of 250,440 PIT tagged smolts have been detected over the RSW this season compared to a total of 23,582 smolts detected in the juvenile system. A total of 709 adult PIT tagged steelhead, 69 Chinook, and 2 Sockeye have been detected at the RSW this season compared to 95 adult steelhead and 37 Chinook detected at the juvenile facility.

River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
18.5	16.1	1.8	0	62.5	62.0	5.0	5.0

*Cooling water intake temperature.

Other

Inline Cooling Water Strainers: N/A

Invasive Species: No zebra/quagga mussels were detected on the trap substrate. There were 2,536 Siberian prawns collected in sample and euthanized this week.

Avian Activity:

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
Oct 1	1730	0	17	0	0
Oct 2	1131	9	25	0	0
Oct 3	1609	4	14	0	0
Oct 4	1100	17	29	0	0
Oct 5	1350	22	25	0	0
Oct 6	1140	13	25	0	0
Oct 7	1115	20	31	0	0

Gas Bubble Trauma (GBT) Monitoring: N/A

Adult Fish Trap Operations: Trapping 7 days per week at 18% and collection of fall Chinook salmon broodstock for transport to NPT and WDFW hatcheries began August 18.

Fish Rescue/Salvage: N/A

Research:

National Marine Fisheries Service (NMFS) PIT tagging of Adult Wild Chinook salmon and Adult Steelhead for ISEMP-Related Dispersal Monitoring:

The goal of this project is to PIT tag up to 4000 unclipped adult Chinook salmon and 4000 unclipped adult steelhead collected in the adult trap daily sample for dispersal monitoring.

Sampling of Steelhead, Chinook salmon, and Sockeye salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating steelhead, spring/summer Chinook salmon, and sockeye salmon are collected from the adult trap beginning April 4 through December 15. The goal is to collect 5-20% of adult steelhead, spring/summer Chinook salmon, and sockeye salmon ascending the ladder April 4-December 15. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. Natural origin adult steelhead and spring/summer Chinook salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some steelhead and spring/summer Chinook salmon may be radio-tagged or spaghetti-tagged. This

information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs.

PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be collected as part of the normal adult trap daily sample and using the adult SbyC system to recapture previously PIT tagged fish. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder.

USGS Juvenile Fall Chinook Salmon Growth and Origin

USGS began collection of previously tagged subyearling Chinook salmon utilizing LWG juvenile collection facility SbyC system began September 8 and will continue through October 31. Previously PIT tagged fish are diverted to the SbyC tanks, weighed, measured, GSI sampled, scanned for PIT tag code, recovered from anesthetic, and released back to the river. The objective of this project is to estimate the growth of PIT-tagged subyearling Chinook salmon from the Clearwater River to Lower Granite Dam.