

**U.S. ARMY CORPS OF ENGINEERS
WALLA WALLA DISTRICT
FISH FACILITIES WEEKLY REPORT
#29-2022**

Project: McNary

Biologist: Bobby Johnson and Paul Bertschinger

Dates: September 16-22, 2022

Turbine Operation

| Yes | No | Turbine Unit Status |
|-----|----|---|
| | X | All 14 turbine units available for service? (See table & comments below for details.) |

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

| Unit(s) | OOS | | RTS | | Outage Description |
|---------|------|------|------|----------------|------------------------------|
| | Date | Time | Date | Time | |
| 8 | 6/6 | 1002 | 9/16 | 0413 | Transformer gaskets (T4) |
| 7 | 8/4 | 0635 | 9/16 | 0431 | Transformer gaskets (T4) |
| 9 & 10 | 9/12 | 0625 | 9/22 | 1401 & 1822 | Transformer maintenance (T5) |
| 6 | 9/20 | 1000 | 9/20 | 1030 | ESBS inspections |

Comments: The one percent peak efficiency constraint and unit priority are being followed per the 2022 Fish Passage Plan (FPP). RTS dates are subject to change.

Adult Fish Passage Facilities

The McNary fisheries staff performed measured inspections of the adult fishways on September 16, 18 and 20. In person fish counting continued. Video review of nighttime lamprey passage will conclude on September 30.

Fish Ladder Exits:

| Yes | No | Location | Criteria | Measurements |
|-----|----|---------------------------------------|-----------------------------|--------------|
| X | | Oregon Exit | Head over weir 1.0' to 1.3' | 1.0' |
| X | | Oregon Count Station Differential | 0.0' to 0.5' | 0.2' to 0.4' |
| X | | Washington Exit | Head over weir 1.0' to 1.3' | 1.1' to 1.2' |
| X | | Washington Count Station Differential | 0.0' to 0.5' | 0.2' to 0.3' |

Comments: Debris loads were light to moderate near the Oregon exit and minimal near the Washington exit. Most of the debris was residual and circulated from the powerhouse to the Oregon shore depending on the wind direction. The general maintenance staff cleaned both exits' picketed leads as needed including the weekend.

At the Oregon shore exit, high picketed lead differentials overnight were resolved the morning of September 16, when the leads were cleaned, and the exit weirs' set points were adjusted. This occurred before the inspection.

At the Washington shore exit, high picketed lead differentials were resolved when the leads were cleaned on September 17. Also, a regulating weir alarm came in and was reset on September 19.

Fishway Entrances and Collection Channel:

| Yes | No | Sill | Location | Criteria | Measurements |
|-----|----|------|---|----------------|-------------------|
| X | | | North Oregon Entrance Head Differential | 1.0' - 2.0' | 1.1' to 1.3' |
| | X | | NFEW2 Weir Depth | ≥ 8.0' | 7.9' to 8.1' |
| X | | | NFEW3 Weir Depth | ≥ 8.0' | 8.1' to 8.3' |
| X | | | South Oregon Entrance Head Differential | 1.0' - 2.0' | 1.2' to 1.4' |
| | X | | SFEW1 Weir Depth | ≥ 8.0' | 7.9' to 8.1' |
| X | | | SFEW2 Weir Depth | ≥ 8.0' | 8.0' to 8.1' |
| X | | | Oregon Collection Channel Velocities | 1.5 to 4.0 fps | Averaged 1.7 fps. |
| X | | | Washington Entrance Head Differential | 1.0' - 2.0' | 1.4' to 1.5' |
| X | | | WFE2 Weir Depth | ≥ 8.0' | 10.0' to 10.3' |
| X | | | WFE3 Weir Depth | ≥ 8.0' | 9.2' to 9.6' |

Comments: The above Oregon ladder out of criteria points were possibly due to set point drifts on September 20. WFE3 still requires calibration, and this will occur in the near future. Currently, the weirs depth is being estimated and appears to be in criterion.

There are four floating orifice gate (FOG) slots that still require future gate replacement. Slots W37 and W41 remain closed. Ten of 12 slots are open. Eight gates are new or rehabilitated. Two gates are old.

Auxiliary Water Supply System:

| Operating Satisfactory | Standby | Out of Service | Fish Pump Blade Angle | Auxiliary Water Supply System (AWS) |
|------------------------|---------|----------------|-----------------------|---|
| Yes | | | | WA shore Wasco County PUD Turbine Unit |
| | Yes | | | WA shore Wasco PUD Bypass |
| Yes | | | 22° | Oregon Ladder Fish Pump 1 |
| | | Yes | | Oregon Ladder Fish Pump 2 RTS date is Dec. 19, 2022 |
| Yes | | | 22° | Oregon Ladder Fish Pump 3 |
| Yes | | | | OR North Powerhouse Pool supply from juvenile fishway |

Comments: Fish pump 2 remains out of service. Repairs are waiting on funding. The return to service date is has been updated to December 19, 2022.

Juvenile Fish Passage Facility

Every other day sample collection continued with no interruptions in the schedule.

Forebay Debris/Gatewell Debris/Oil:

| Yes | No | NA | Item | Comments |
|-----|----|----|--|------------------------|
| X | | | Forebay debris load acceptable? (amount) | Very light to moderate |
| X | | | Gatewell drawdown measured this week? | Daily |
| X | | | Gatewell drawdown acceptable? | |
| | X | | Any debris seen in gatewells? (% coverage) | |
| | X | | Any oil seen in gatewells? | |

Comments: Debris loads were very light to moderate near the powerhouse. Wind direction changes moved the residual debris across the forebay from the powerhouse to the Oregon shore and back. Debris loads beside the spillway were minimal. New debris loads were minimal. Much of the debris was woody material and aquatic vegetation.

No trash racks were cleaned this week.

There are no problems to report.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs):

| Yes | No | NA | Item |
|-----|----|----|---|
| X | | | ESBSs deployed in all slots and in service? |
| X | | | ESBSs inspected this week? |
| X | | | ESBSs inspection results acceptable? |
| X | | | VBSs differentials checked this week? |
| X | | | VBSs differentials acceptable? |

Comments: ESBS's are installed in all units. ESBS camera inspections revealed no issues in units 6, 9 and 10 on September 20. Units 9 and 10 were out of service. Unit 1's ESBS control panel view continued to be intermittent. When needed, brush motor amp readings were requested from the control room.

Daily VBS differential monitoring revealed no high differentials. One VBS was cleaned on September 22. No fish were observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

| Yes | No | NA | Item | Number of orifices in service |
|-----|----|----|---|-------------------------------|
| X | | | Did orifices operate satisfactorily? | 42 |
| X | | | Dewatering and cleaning systems operating satisfactorily? | |

Comments: There was a small amount of moisture in the temporary air supply line this week as air temperatures decreased. We continued to bleed off the line on every shift. Orifices were adjusted for VBS cleaning.

The rectangular screen cleaning brush's east retraction cable developed an overlap on the cable spool, which was noted September 17. A mechanic examined the brush on September 22. Currently, the brush is operating satisfactorily.

The electrical staff examined the brush cycle sequence to determine how best to resolve the issue of one brush overloading tripping all three brushes offline on September 21.

The side screen cleaning brush's drive chain was tightened on September 22.

Bypass Facility:

| Yes | No | NA | Item |
|-----|----|----|-----------------------------|
| X | | | Sample gates on? |
| | | X | PIT-tag sampling system on? |

Comments: All bypass facility systems functioned well. The sample gates were only on during secondary bypass. The PIT-tag system gates remained off as there is no need for that system.

This week, 40 juvenile lamprey and 130 smolts, all sub-yearling Chinook, were bypassed during secondary bypass. Juvenile shad continued to be the predominant species. The smolt monitoring staff reports fish data in a separate report.

The facility PIT room air conditioning continued to trip offline and be reset. The new unit is installed with only electrical work to be completed. Two water faucets were repaired in the wet lab this week.

Top Spillway Weir (TSW) Operations: Spillbay 19 currently has a standard spillgate installed. The TSW is installed in bay 20 and is being opened per the fall season adult fallback schedule.

River Conditions

Table 2. River Conditions at McNary Dam.

| Daily Average River Flow (kcfs) | | Daily Average Spill (kcfs) | | Water Temperature (°F) | | Water Clarity (Secchi disk - feet) | |
|---------------------------------|------|----------------------------|-----|------------------------|------|------------------------------------|-----|
| High | Low | High | Low | High | Low | High | Low |
| 96.5 | 77.5 | 1.0 | 0.0 | 68.3 | 67.0 | 6.0 | 5.5 |

Comments: The above data is provided by the smolt monitoring staff except water clarity, which comes from the control room. The data day runs from 0700 to 0700 hours. The above spill is due to TSW use and testing in bay 1.

Crane 7 returned to service on September 22 and was used for testing in bay 1. Electrical work will resume on crane 6 next week. With limited crane use and hoist issues previously discussed, a crane is required in order to move the gates in bays 2, 6, and 16. The hoist for bay 6 is still out of service until December at the earliest.

Other

Inline Cooling Water Strainers: The next cooling water strainer inspections will occur on December 6.

Avian Activity: Recording avian counts continued. These counts are reflected in Table 3 below.

Table 3. McNary Project's Daily Avian Count.

| Date | Zone | Gull | Cormorant | Tern | Pelican | Grebe |
|--------------|------------|------|-----------|------|---------|-------|
| September 16 | Spill | 273 | 13 | 0 | 0 | 0 |
| | Powerhouse | 22 | 0 | 0 | 2 | 0 |
| | Outfall | 27 | 30 | 0 | 0 | 0 |
| | Forebay | 3 | 0 | 0 | 0 | 0 |
| September 17 | Spill | 321 | 16 | 0 | 0 | 0 |
| | Powerhouse | 18 | 0 | 0 | 0 | 0 |
| | Outfall | 16 | 7 | 0 | 0 | 0 |
| | Forebay | 3 | 0 | 0 | 0 | 0 |
| September 18 | Spill | 703 | 33 | 0 | 0 | 0 |
| | Powerhouse | 11 | 0 | 0 | 0 | 0 |
| | Outfall | 5 | 64 | 0 | 0 | 0 |
| | Forebay | 2 | 0 | 0 | 0 | 0 |
| September 19 | Spill | 165 | 21 | 0 | 0 | 0 |
| | Powerhouse | 96 | 1 | 0 | 0 | 0 |
| | Outfall | 6 | 37 | 0 | 0 | 0 |
| | Forebay | 0 | 0 | 0 | 0 | 0 |
| September 20 | Spill | 108 | 1 | 0 | 0 | 0 |
| | Powerhouse | 17 | 0 | 0 | 0 | 0 |
| | Outfall | 3 | 75 | 0 | 0 | 0 |
| | Forebay | 0 | 0 | 0 | 0 | 0 |
| September 21 | Spill | 293 | 20 | 0 | 0 | 0 |
| | Powerhouse | 37 | 0 | 0 | 0 | 0 |
| | Outfall | 3 | 47 | 0 | 0 | 0 |
| | Forebay | 0 | 0 | 0 | 0 | 0 |
| September 22 | Spill | 191 | 40 | 0 | 0 | 0 |
| | Powerhouse | 14 | 0 | 0 | 0 | 0 |
| | Outfall | 12 | 20 | 0 | 0 | 0 |
| | Forebay | 2 | 0 | 0 | 0 | 0 |

For the outfall, the LRAD has been in place. Over time, the response from the roosting birds has decreased. However, more sounds need to be tested. Ordering parts for the laser had to be delayed until the next fiscal year.

The navigation lock wing wall laser, which is aimed at the outfall, remains in service along with the two large bird distress calls. There was no other hazing.

In the spillway zone, gulls and cormorants were roosting unless the TSW was open, which encouraged feeding. Gull and cormorant numbers were high. Many of these birds may be migrating through the area.

In the powerhouse zone, gull numbers decreased with the birds roosting and feeding. An occasional pelican, osprey or cormorant was observed. The gulls were also noted feeding downstream of the release of juvenile shad from the sample.

In the bypass outfall zone, gull numbers decreased, and cormorant numbers increased. Most of the birds were roosting but feeding was also noted.

In the forebay zone, a few gulls were noted roosting along with an occasional great blue heron. Outside the zone, large gull flocks, a few ospreys, and cormorants were noted.

No pelicans were observed in the ladders and no grebes entered the gate well slots this week.

Invasive Species: The next mussel station examinations will occur on September 25.

Siberian Prawn: No Siberian prawns were removed from the sample this week. None have been seen this year.

Fish Rescue/Salvage: No fish rescue occurred this week.

Research: For a CRITFC study, there were tissue samples removed from four juvenile lamprey collected at the facility this week. For the season, a total of 703 juvenile lampreys have been sampled. All fish were returned to the river unharmed.

The Oregon Department of Fish and Wildlife continued their TSW adult fallback study.

Project: Ice Harbor

Biologist: Ken Fone

Dates: September 16 - September 22, 2022

Turbine Operation

| Yes | No | Turbine Unit Status |
|-----|----|---|
| | x | All 6 turbine units available for service (see table & comments below for details). |
| x | | All available turbine units are operated in accordance with Appendix C of the Fish Passage Plan |

Ice Harbor Unit Outages (OOS) and Return to Service (RTS)

| Unit | OOS | | RTS | | Outage Description |
|------|---------|------|---------|------|--|
| | Date | Time | Date | Time | |
| 3 | 5/3/19 | 0641 | --- | --- | Turbine runner replacement and stator rewind |
| 2 | 9/21/22 | 1526 | 9/22/22 | 1200 | Oil leak from wicket gate servo |

Comments: Units 6, 5, 4, 2, and 1 were taken out of service one at a time for STS inspections and/or to tap the hub on September 19, 20, and 21.

Adult Fish Passage Facility

Ice Harbor staff inspected the adult fishways on September 17, 19, and 21.

Fish Ladders:

| Yes | No | Location | Criteria | Measurements |
|-----|----|---|-----------------------------|--------------|
| x | | North Ladder Exit Differential | Head \leq 0.3' | |
| x | | North Ladder Picketed Lead Differential | Head \leq 0.3' | |
| x | | North Ladder Depth over Weirs | Head over weir 1.0' to 1.3' | |
| x | | South Ladder Exit Differential | Head \leq 0.3' | |
| | x | South Ladder Picketed Lead Differential | Head \leq 0.3' | 0.4' |
| x | | South Ladder Depth over Weirs | Head over weir 1.0' to 1.3' | |

Fishway Entrances and Collection Channel:

| Yes | No | Sill | Location | Criteria | Measurements |
|-----|----|------|--|------------------------|--------------|
| | x | | South Shore Entrance (SFE-1) Weir Depth | \geq 8.0' or on sill | 6.7' |
| | x | | South Shore Channel/Tailwater Differential | 1.0' - 2.0' | 2.3', 2.1' |
| x | | | South Shore Channel Velocity | 1.5 - 4.0 fps | |
| | | x | North Powerhouse Entrance (NFE-2) Weir Depth | \geq 8.0' or on sill | |
| x | | | North Powerhouse Entrance Channel/Tailwater Differential | 1.0' - 2.0' | |
| | | x | North Shore Entrance (NEW-1) Weir Depth | \geq 8.0' or on sill | |
| x | | | North Shore Channel/Tailwater Differential | 1.0' - 2.0' | |

Comments: The south fish ladder picketed lead differential was out of criteria on September 21 due to the buildup of filamentous algae on the leads. The picketed leads were cleaned immediately after the reading was taken and need to be cleaned every 24 hours to keep the differential in criteria.

The south shore entrance weir depth was out of criteria on September 19 when the weir was positioned slightly off of sill to stop the lifting beam from banging around in the guide slot. The weir was lowered back to sill on September 21, and the lifting beam was observed to be relatively still in the guide slot.

The south shore entrance channel/tailwater differential was above criteria on September 17 and 19. This was caused by lower tailwater levels. Five south shore auxiliary water supply pumps have been operating, which are the minimum number of pumps needed to maintain at least 1' of channel/tailwater differential as well as the depth over the stationary weirs that are just above tailwater level.

Auxiliary Water Supply (AWS) System:

| Operating Satisfactory | Standby | Out of Service | Auxiliary Water Supply System (AWS) |
|------------------------|-----------|----------------|---------------------------------------|
| 5 pumps | 2-3 pumps | 0-1 pump | Status of the 8 south shore AWS pumps |
| 2 pumps | 1 pump | | Status of the 3 north shore AWS pumps |

Comments: South shore AWS pump #5 was taken out of service at 1240 hours on September 20 to replace the lower seal.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

| Yes | No | NA | Item | Comments |
|-----|----|----|---|----------------------------|
| x | | | Forebay debris load acceptable? (amount) | Average of 13 square yards |
| x | | | Gatewell drawdown measured this week? | |
| x | | | Gatewell drawdown acceptable | |
| x | | | Any debris seen in gatewells (% coverage) | 0-5% coverage |
| | x | | Any oil seen in gatewells? | |

Comments: None.

Submersible Traveling Screens (STSs) / Vertical Barrier Screens (VBSs):

| Yes | No | NA | Item |
|-----|----|----|--|
| x | | | STSs deployed in all slots that are in service? |
| | x | | STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)? |
| x | | | STSs inspected this week? |
| x | | | STSs inspection results acceptable? |
| | | x | VBSs differentials checked this week? |
| | | x | VBSs differentials acceptable? |

Comments: Unit 6, 4, 2, and 1 STSs were inspected on September 19, 20, and 21. There were no significant problems found.

Orifices, Collection Channel, Dewatering Structure, and Flume:

| Yes | No | NA | Item | Number open and in service |
|-----|----|----|--|----------------------------|
| x | | | Orifices operating satisfactory? | 20 |
| | x | | Dewaterer and cleaning systems operating satisfactory? | |

Comments: The actuator for the water regulating weirs in the collection channel is in local control due to a problem with the automatic control function. The weirs are being operated at the actuator to adjust the water level as needed until the problem can be fixed.

Orifice 2BN light was found to be burned out on September 14. Orifice 2BS was opened in place of orifice 2BN until September 20. The light was replaced on September 19.

Juvenile Fish Facility: The fish facility is operating in primary bypass mode.

Fish Sampling: Juvenile fish sampling is done for the season.

Removable Spillway Weir (RSW): The RSW is periodically opened from September 1 to November 15 for the downstream passage of adult steelhead that may have strayed into the Snake River. The RSW is scheduled to be operated from 0500 hours to 0900 hours on Sundays, Wednesdays, and Fridays for that purpose.

River Conditions

River conditions at Ice Harbor Dam.

| Daily Average River Flow (kcfs) | | Daily Average Spill (kcfs) | | Water Temperature* (°F) | | Water Clarity (Secchi disk - feet) | |
|---------------------------------|------|----------------------------|-----|-------------------------|-----|------------------------------------|-----|
| High | Low | High | Low | High | Low | High | Low |
| 24.0 | 13.9 | 1.7 | 0 | 68 | 66 | 8.3 | 7.5 |

*Unit 1 scroll case temperature.

Other

Inline Cooling Water Strainers: Unit cooling water strainer inspections for fish are done for the season until December.

Avian Activity: There were low numbers of piscivorous birds observed around the project. Most of the birds were observed foraging near the upstream tip of Eagle Island.

Invasive Species: No exotic species that are new to the area have been found.

Fish Rescue/Salvage: None.

Research: No on-site research is occurring at this time.

Project: Lower Monumental

Biologists: Denise Griffith and Raymond Addis

Dates: September 16 - 22, 2022

Turbine Operation

| Yes | No | Turbine Unit Status | Hard | Soft |
|-----|----|---|------|------|
| | X | All 6 turbine units available for service (see table & comments below for details). | | |
| X | | Available turbines operated within 1% peak efficiency? Constraint in effect. | X | |

Comments: All available turbine units are operated in accordance with App. C of the Fish Passage Plan

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

| Unit | OOS | | RTS | | Outage Description |
|--------|-----------|------|------|------|--------------------|
| | Date | Time | Date | Time | |
| Unit 5 | 8/22/2022 | 0645 | TBD | | T2 repairs |
| Unit 6 | 8/22/2022 | 0645 | TBD | | Annual/T2 repairs |

Comments: Estimated return to service for Units 5 and 6 has yet to be determined, but the target is December 15, 2022.

Adult Fish Passage Facility

The adult fishways were inspected by Army Corps and EAS biologists September 16, 17, 18, 19 and 22.

Fish Ladder:

| Yes | No | Location | Criteria | Measurements |
|-----|----|---|-----------------------------|--------------|
| X | | North Ladder Exit Differential | Head \leq 0.5' | |
| X | | North Ladder Picketed Lead Differential | Head \leq 0.4' | |
| X | | North Ladder Depth over Weirs | Head over weir 1.0' to 1.3' | |
| X | | South Ladder Exit Differential | Head \leq 0.5' | |
| X | | South Ladder Picketed Lead Differential | Head \leq 0.3' | |
| X | | South Ladder Depth over Weirs | Head over weir 1.0' to 1.3' | |

Comments: None.

Fishway Entrances and Collection Channel:

| Yes | No | Sill | Location | Criteria | Measurements |
|-----|----|------|--|------------------------|--------------|
| X | | | North Shore Entrance (NSE-1) Weir Depth | \geq 8.0' or on sill | |
| X | | | North Shore Entrance (NSE-2) Weir Depth | \geq 8.0' or on sill | |
| X | | | North Shore Channel/Tailwater Differential | 1.0' - 2.0' | |
| | | X | South Powerhouse Entrance (SPE-1) Weir Depth | \geq 8.0' or on sill | |
| | | X | South Powerhouse Entrance (SPE-2) Weir Depth | \geq 8.0' or on sill | |
| X | | | South Powerhouse Entrance Channel/Tailwater Differential | 1.0' - 2.0' | |
| X | | X | South Shore Entrance (SSE-1) Weir Depth | \geq 8.0' | |
| X | | | South Shore Entrance (SSE-2) Weir Depth | \geq 6.0' | |
| X | | | South Shore Channel/Tailwater Differential | 1.0' - 2.0' | |

Comments: The south powerhouse entrance weir (SPE-1) was on sill during all inspections with 6.5, 6.9, 6.8, 7.0 and 7.4 feet, respectively. The south powerhouse entrance weir (SPE-2) was on sill during all inspections with 6.5, 6.9, 6.8, 7.0 and 7.4 feet, respectively. The south shore entrance weir (SSE-1) was on sill during the September 17, 18 and 19 inspections with readings 7.3, 7.8 and 7.9 feet, respectively. South powerhouse tailwater staff gauge's, SG9N, frame was found loose on the April 13 inspections. If the gauge remains unreadable, readings will be taken

from the digital readings. The project has ordered new staff gauges and they will be installed during the winter maintenance period.

Auxiliary Water Supply System:

| Operating Satisfactory | Standby | Out of Service | Auxiliary Water Supply System (AWS) |
|------------------------|---------|----------------|-------------------------------------|
| Yes | | | AWS Fish Pump 1 |
| Yes | | | AWS Fish Pump 2 |
| Yes | | | AWS Fish Pump 3 |

Comments: None.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

| Yes | No | NA | Item | Comments |
|-----|----|----|---|---------------------|
| X | | | Forebay debris load acceptable? (amount) | 37 yds ² |
| X | | | Gatewell drawdown measured this week? | |
| X | | | Gatewell drawdown acceptable | |
| X | | | Any debris seen in gatewells (% coverage) | 0 – 5% |
| | X | | Any oil seen in gatewells? | |

Comments: A slight sheen was observed on September 21 at 0945 in the tailrace around Unit 5 and Unit 6. The sheen was believed to be approximately a cup of turbine oil. The oil was reported through proper authorities. No negative impacts were observed related to fish.

STSs/VBSs:

| Yes | No | NA | Item |
|-----|----|----|--|
| X | | | STSs deployed in all slots and in service? |
| | X | | STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)? |
| X | X | | STSs inspected this week? |
| X | | | STSs inspection results acceptable? |
| | X | | VBSs differentials checked this week? |
| | X | | VBSs differentials acceptable? |

Comments: The STSs were running in Cycle-Run mode throughout this reporting period due to average sub-yearling Chinook and sockeye lengths being greater than 120 mm.

Orifices, Collection Channel, Dewatering Structure, and Flume:

| Yes | No | NA | Item | Number open and in service |
|-----|----|----|--|----------------------------|
| X | | | Orifices operating satisfactory? | 18 |
| X | | | Dewaterer and cleaning systems operating satisfactory? | |

Comments: None.

Collection Facility: Every-third day condition sampling continued with samples collected on September 15–16, September 18-19 and September 21-22. A total of 16 fish were collected with 15 fish bypassed back to the river during this reporting period.

Power outage from 1005 to 1130 of September 21. No negative effects to the JFF were observed other than an issue with the outfall bird cannon stated below in the avian activity section of this report.

Small debris was removed from the fencing area around the outfall pump on September 21. Approximately 20 large logs were removed from the fencing area on September 22.

The Smith-Root counter box was replaced for the “A” side count tunnels by powerhouse electricians on September 22. The counter box was borrowed from Little Goose project in order to test the box for accuracy before this fish season was over. The box appeared to be working, however, the sensitivity is still not accurate. Further testing will be required.

Transport Summary: At this time, there is no transporting of juvenile salmonids occurring.

Spillway: Fall spill for steelhead began at 00:00:00 on September 1. Spillgate 5 went out of service on September 13 and returned to service on September 22 for spillgate trunnion modifications. Spillgate 6 went out of service on September 21 with an estimated return of service of September 29 for spillgate trunnion modifications.

River Conditions

River conditions at Lower Monumental Dam.

| Daily Average River Flow (kcfs) | | Daily Average Spill (kcfs) | | Water Temperature (°F)* | | Water Clarity (Secchi disk - feet) | |
|---------------------------------|------|----------------------------|-----|-------------------------|------|------------------------------------|-----|
| High | Low | High | Low | High | Low | High | Low |
| 22.9 | 15.0 | 1.5 | 0.0 | 67.5 | 66.0 | 7.0 | 5.4 |

*Scrollcase temperatures.

Other

Cooling Water Strainers: Cooling water strainers inspections will occur again in December. Monitoring is performed from December to June.

Avian Activity: Highest daily counts of piscivorous birds in all zones combined at Lower Monumental Dam are reported in the table below.

| Date | Time | Gulls | Cormorants | Terns | Grebes | Pelicans |
|-----------|------|-------|------------|-------|--------|----------|
| 9/16/2022 | 840 | 64 | 42 | 0 | 0 | 0 |
| 9/17/2022 | 810 | 37 | 55 | 0 | 0 | 0 |
| 9/18/2022 | 1030 | 75 | 31 | 0 | 0 | 1 |
| 9/19/2022 | 1120 | 44 | 68 | 0 | 0 | 0 |
| 9/20/2022 | 900 | 42 | 64 | 0 | 0 | 0 |
| 9/21/2022 | 1015 | 80 | 36 | 0 | 0 | 0 |
| 9/22/2022 | 915 | 62 | 40 | 0 | 0 | 0 |

Comments: Piscivorous bird observations are occurring daily. The outfall bird cannon functioned efficiently this week, except during the power outage on September 21. During the outage the sprinklers were OOS. Once the power was returned to service at 1130, the smaller of the two cannons stopped functioning. Approximately an hour later it began operating again. There may have been a small amount of debris in the line that broke free after some time.

Invasive Species: The mussel traps are scheduled to be inspected in October.

Fish Rescue/Salvage: No fish rescue/salvage took place during this reporting period.

Research: No research is occurring currently.

Project: Little Goose Dam

Biologists: Chuck Barnes and Deb Snyder

Dates: September 16 – September 22, 2022

Turbine Operation

| Yes | No | Turbine Unit Status | Hard | Soft |
|-----|----|---|------|------|
| | x | All 6 turbine units available for service (see table & comments below for details). | | |
| x | | Available turbines operated within 1% peak efficiency? Constraint in effect. | x | |

Little Goose Unit Outages (OOS) and Return to Service (RTS)

| Unit | OOS | | RTS | | Outage Description |
|------|-----------|-------|------------|------|---|
| | Date | Time | Date | Time | |
| 5 | 4/14/2017 | 14:11 | 12/31/2022 | ERTS | Spider and upper guide bearing repair. |
| 6 | 4/18/2022 | 5:10 | 12/31/2022 | ERTS | Rooftop/BUS work replacement; 6-year overhaul |

Comments: Previously reported Unit 6 RTS date of 4/21/2022 pertained to station service only, the anticipated RTS for regular service is 12/31/2022.

Adult Fish Passage Facility

EAS Bio, ODFW, and USACE staff inspected the adult Fishway on September 17, September 19, September 21, and September 22.

Fish Ladder:

| Yes | No | NA | Location | Criteria | Measurements |
|-----|----|----|---|-----------------------------|--------------|
| X | | | Fish Ladder Exit Differential | Head \leq 0.5' | |
| X | | | Fish Ladder Picketed Lead Differential | Head \leq 0.3' | |
| X | | | Fish Ladder Depth over Weirs | Head over weir 1.0' to 1.3' | |
| X | | | Fish Ladder Cooling Water Pumps in Service | | |
| X | | | Fish Ladder Exit Cooling Water Pumps Operating Satisfactorily | | |

Fishway Entrances and Collection Channel:

| Yes | No | Sill | Location | Criteria | Measurements |
|-----|----|------|--|------------------------|--------------|
| X | | | South Shore Entrance (SSE-1) Weir Depth | \geq 8.0' | |
| X | | | South Shore Entrance (SSE-2) Weir Depth | \geq 8.0' | |
| X | | | South Shore Channel/Tailwater Differential | 1.0' – 2.0' | |
| | | X | North Powerhouse Entrance (NPE-1) Weir Depth | \geq 7.0' or on sill | |
| | | X | North Powerhouse Entrance (NPE-2) Weir Depth | \geq 7.0' or on sill | |
| X | | | North Powerhouse Entrance Channel/Tailwater Differential | 1.0' – 2.0' | |
| X | X | | North Shore Entrance (NSE-1) Weir Depth | \geq 6.0' or on sill | 5.8 on 9/19 |
| X | X | | North Shore Entrance (NSE-2) Weir Depth | \geq 6.0' or on sill | 5.8 on 9/19 |
| X | | | North Shore Channel/Tailwater Differential | 1.0' – 2.0' | |
| X | | | Collection Channel Surface Velocity | 1.5 – 4.0 fps | |

Comments: The adult fishway was returned to service on February 8 with AWS pumps returning to service on February 24. The NSE channel/tailwater differential and NSE weir depths were manually measured, adjusted, and monitored into criteria from February 24 through March 1. The fishway Fish System Control (FSC) was recommissioned on May 5 with NSE weir reading anomalies. NSE weirs 1 and 2 are being monitored with manual measurements as both weir targets enabling the FSC system to accurately read and automatically adjust weir heights were compromised during emergency flood control measures in June, repairs are pending. The Fish Ladder Exit

Cooling Water Pump was replaced, installed, and readied for service on April 23. Criteria requiring the activation of the Fish Ladder Exit Cooling Pump was met during the night hours of June 26, and the system was started at 0800 hours on June 27. The Collection Channel Surface Velocity is measured at NPE.

Auxiliary Water Supply System:

| Operating Satisfactory | Standby | Out of Service | Auxiliary Water Supply System (AWS) |
|------------------------|---------|----------------|-------------------------------------|
| X | | | AWS Fish Pump 1 |
| X | | | AWS Fish Pump 2 |
| X | | | AWS Fish Pump 3 |

Comments: Fish pumps 1, 2, and 3 were returned to service February 24.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

| Yes | No | NA | Item | Comment |
|-----|----|----|---|--|
| X | | | Forebay debris load acceptable? (amount) | High 525 ft ² - Low 0 ft ² |
| X | | | Gatewell drawdown measured this week? | |
| X | | | Gatewell drawdown acceptable | |
| X | | | Any debris seen in gatewells (% coverage) | 4A - <1% 9/21, 9/22 |
| | X | | Any oil seen in gatewells? | |

Comments: The forebay had minimal floating debris inside the trash shear boom with the highest measurement occurring on September 21. Gatewell 6B remained dewatered for maintenance purposes.

ESBS/VBS:

| Yes | No | NA | Item |
|-----|----|----|---|
| | X | | ESBSs deployed in all slots and in service? |
| | X | | ESBSs inspected this week? |
| | | X | ESBSs inspection results acceptable? |
| X | | | VBSs differentials checked this week? |
| X | | | VBSs differentials acceptable? |
| | X | | VBSs inspected this week? |

Comments: Installation of ESBS's began March 21 with most units completed on March 22. Unit 6 ESBS and VBS undergoing work during scheduled maintenance period. 1 ESBS pulled and stored above gatewell 5C.

Orifices, Collection Channel, Dewatering Structure, and Flume:

| Yes | No | NA | Item | Number open and in service |
|-----|----|----|--|----------------------------|
| X | | | Orifices operating satisfactory? | 19 |
| X | | | Dewaterer and cleaning systems operating satisfactory? | |

Comments: The juvenile bypass system was watered up March 23.

Collection Facility: The juvenile collection facility completed water up activities on March 29. Every other day collection for condition monitoring in conjunction with secondary bypass commenced on April 1 with the first sample being conducted on April 2. Everyday collection began April 23 coinciding with every other day barge transportation. A total of 620 fish were collected, 0 were bypassed, 702 were transported by truck, and there were

24 sample or facility mortalities. The descaling and mortality rates were 3.2% and 4.50%, respectively. Six adult lamprey were removed from the collection facility; both the collection and transport facility operated within criteria this report period.

Transport Summary: Collection for fish transportation began April 23 with the first barge departure on April 24. Every other day barging transitioned to everyday barging on May 16 due to an increase in fish numbers. Every other day barging resumed on May 24. Barge transportation for the season ended with the final barge departure of June 19. Collection for truck transport operations began on August 1, with the first truck departure on August 3.

Spillway Weir: Little Goose began operation of the adjustable spillway weir (ASW) on March 2 to facilitate passage of adult steelhead overshoots. Operation occurred three days each week on non-consecutive days for four hours in the morning on Tuesday, Thursday and Sunday each week, through March 31. Spring spill operations began as scheduled on April 3 with the ASW in high crest. The ASW was positioned in low crest on May 28. Summer spill operations began as scheduled on June 21, and the ASW was repositioned into high crest on June 28. The ASW was closed for the spill season at 10:00 on August 1. Summer spill concluded for the season at 2357 hours on August 31. Surface spill to facilitate downstream passage of pre-spawn adult steelhead as natal stream overshoots commenced at 0500 hours on September 1. The ASW was positioned at an elevation of 639 feet and is scheduled to spill from 0500 hours through 0900 hours every Tuesday, Thursday, and Sunday through the month of October, with an anticipated slight schedule change to occur early November.

River Conditions

River conditions at Little Goose Dam.

| Daily Average River Flow (kcfs) | | Daily Average Spill (kcfs) | | Water Temperature* (°F) | | Water Clarity (Secchi disk - feet) | |
|---------------------------------|------|----------------------------|-----|-------------------------|------|------------------------------------|-----|
| High | Low | High | Low | High | Low | High | Low |
| 22.0 | 14.2 | 1.3 | 0.0 | 67.5 | 65.7 | 6.0 | 4.0 |

*Ladder temperature.

Other

Inline Cooling Water Strainers: Inline cooling strainer inspections commenced on December 9, 2021. Inspections will continue in accordance with the Fish Passage Plan (FPP) and results will be submitted to the District.

Avian Activity: Daily piscivorous bird counts at Little Goose Dam began April 1 with hazing beginning on March 29.

| Date | Time | Gulls | Cormorants | Caspian Terns | Pelicans |
|------|-------|-------|------------|---------------|----------|
| 9-16 | 8:00 | 9 | 3 | 0 | 0 |
| 9-17 | 9:15 | 17 | 14 | 0 | 0 |
| 9-18 | 8:30 | 6 | 4 | 0 | 0 |
| 9-19 | 10:40 | 0 | 0 | 0 | 0 |
| 9-20 | 8:00 | 3 | 4 | 0 | 0 |
| 9-21 | 10:30 | 7 | 0 | 0 | 0 |
| 9-22 | 9:30 | 9 | 15 | 0 | 0 |

Invasive Species: No invasive species have been observed on the mussel station.

Siberian Prawn: Juvenile fish collection began on April 1. Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Oregon Department of Fish and Wildlife and EAS Bio personnel, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Little Goose Dam for this reporting period are listed below.

| Date | Sample | Collection* |
|-------------|---------------|--------------------|
| 9-16 | 316 | 316 |
| 9-17 | 345 | 345 |
| 9-18 | 265 | 265 |
| 9-19 | 311 | 311 |
| 9-20 | 139 | 139 |
| 9-21 | 176 | 176 |
| 9-22 | 463 | 463 |
| Totals | 2015 | 2015 |

*Collection and sample numbers are equal when sample rates change to 100%

Gas Bubble Trauma (GBT): The last available GBT monitoring report occurred August 24 depicting an examination of 7 fish without signs of GBT.

Fish Rescue/Salvage: No fish rescue – salvage activities transpired during this report period.

Research: The Nez Perce Tribe (NPT) began a dult steelhead kelt collection efforts on April 1 and concluded June 29.

Project: Lower Granite

Biologists: Elizabeth Holdren and David Miller

Dates: September 16-22, 2022

Turbine Operation

| Yes | No | Turbine Unit Status | Hard | Soft |
|-----|----|---|------|------|
| | X | All 6 turbine units available for service (see table & comments below for details). | | |
| X | | Available turbines operated within 1% peak efficiency? Constraint in effect. | X | |

Lower Granite Unit Outages (OOS) and Return to Service (RTS)

| Unit | OOS | | RTS | | Outage Description |
|-------|-------|------|-------|------|--------------------------------------|
| | Date | Time | Date | Time | |
| 5 | 08/22 | 0746 | | | Annual Maintenance/Overhaul |
| 4 & 6 | 09/22 | 0930 | 09/22 | 1115 | ROV inspection of stoplog in slot 5A |

Comments:

Adult Fish Passage Facility

Lower Granite Biologists and Anchor QEA staff inspected the adult fishway on September 16, 17, 19, and 21.

Fish Ladder:

| Yes | No | NA | Location | Criteria | Comments |
|-----|----|----|--|-----------------------------|----------|
| X | | | Fish Ladder Exit Differential | Head \leq 0.5' | |
| X | | | Fish Ladder Picketed Lead Differential | Head \leq 0.3' | |
| X | | | Fish Ladder Depth over Weirs | Head over weir 1.0' to 1.3' | |
| X | | | Fish Ladder Cooling Water Pumps in Service | | |
| X | | | Fish Ladder Cooling Water Pumps Operating Satisfactorily | | |

Comments: Fish ladder cooling water pumps were removed from operation at 0845 hours September 22. Ladder temperature data can be found at <https://www.nwd-wc.usace.army.mil/dd/common/dataquery/www/>.**Fish Ladder Entrances and Collection Channel:**

| Yes | No | Sill | Location | Criteria | Comments |
|-----|----|------|--|------------------------|----------|
| X | | | South Shore Entrance (SSE-1) Weir Depth | \geq 8.0' | |
| X | | | South Shore Entrance (SSE-2) Weir Depth | \geq 8.0' | |
| X | | | South Shore Channel/Tailwater Differential | 1.0' – 2.0' | |
| X | | | North Powerhouse Entrance (NPE-1) Weir Depth | \geq 8.0' or on sill | |
| X | | | North Powerhouse Entrance (NPE-2) Weir Depth | \geq 8.0' or on sill | |
| X | | | North Powerhouse Entrance Channel/Tailwater Differential | 1.0' – 2.0' | |
| X | | | North Shore Entrance (NSE-1) Weir Depth | \geq 7.0' or on sill | 6.8' |
| X | | | North Shore Entrance (NSE-2) Weir Depth | \geq 7.0' or on sill | 6.8' |
| | X | | North Shore Channel/Tailwater Differential | 1.0' – 2.0' | 0.8' |
| X | | | Collection Channel Surface Velocity | 1.5 – 4.0 fps | |

Comments: The fish ladder control system continues to be evaluated to resolve ongoing issues. FOGs 1, 4, 7, and 10 are in operation. Although both NSEs and all four FOGs are in operation, the north shore has not consistently met channel/tailwater head differential criteria. This may be related to the operations of all four FOGs.

Auxiliary Water Supply System:

| Operating Satisfactorily | Standby | Out of Service | Auxiliary Water Supply (AWS) |
|--------------------------|---------|----------------|------------------------------|
| | X | | AWS Fish Pump 1 |
| Yes | | | AWS Fish Pump 2 |
| Yes | | | AWS Fish Pump 3 |

Comments:

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

| Yes | No | NA | Item | Comments |
|-----|----|----|--|-----------------------|
| X | | | Forebay debris load acceptable? (amount) | 18.3 yds ² |
| X | | | Trash rack differentials measured this week? | |
| X | | | Trash rack differentials acceptable | |
| | X | | Any debris seen in gatewells (% coverage) | |
| | X | | Any oil seen in gatewells? | |

Comments:

ESBSs/VBSs:

| Yes | No | NA | Item |
|-----|----|----|---|
| X | | | ESBSs deployed in all slots and in service? |
| | X | | ESBSs inspected this week? |
| | | X | ESBSs inspection results acceptable? |
| X | | | VBSs differentials checked this week? |
| X | | | VBSs differentials acceptable? |

Comments:

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

| Yes | No | NA | Item | Number open and in service |
|-----|----|----|---|----------------------------|
| X | | | Orifices operating satisfactory? | |
| X | | | Dewatering and cleaning systems operating satisfactory? | |

Comments:

Collection Facility: There were 1,461 fish collected this week.

Transport Summary: Truck transport continues even days. There were 1,607 fish transported this week.

Spillway Weir: Summer spill ended at 0000 hours September 1 and spill for overshoot steelhead began at 0500 hours September 1. Overshoot spill will continue Tuesdays, Thursdays, and Sundays between 0500 and 1100 hours until November 15. There were 17 adult PIT tagged steelhead fallbacks at LWG this report week with 12 detected at the RSW and 5 detected in the JBS full flow array.

There were 106,459 juvenile and 189 PIT tagged adult Chinook Salmon, 72,882 juvenile and 572 adult PIT tagged Steelhead, 10,826 juvenile and 4 adult Sockeye Salmon, and 4,064 juvenile Coho Salmon detected over the RSW spillway since March 1. There have been 39,411 juvenile and 25 adult Chinook Salmon, 28,754 juvenile and 132 adult Steelhead, 2,124 juvenile and 1 adult Sockeye Salmon, and 951 juvenile Coho Salmon detected at the JBS full flow PIT tag detection array since March 14 (DART).

River Conditions

River conditions at Lower Granite Dam.

| Daily Average River Flow (kcfs) | | Daily Average Spill (kcfs) | | Water Temperature* (°F) | | Water Clarity (Secchi disk - feet) | |
|---------------------------------|------|----------------------------|-----|-------------------------|------|------------------------------------|-----|
| High | Low | High | Low | High | Low | High | Low |
| 21.4 | 18.0 | 10.4 | 0.0 | 64.8 | 62.5 | 5.0 | 5.0 |

*Cooling water intake temperature.

Other

Inline Cooling Water Strainers: NA

Invasive Species: No zebra/quagga mussels were detected on the trap substrate. There were 13,791 Siberian prawn in the condition sample this report week.

Avian Activity: Biologist daily piscivorous bird counts and hazing continues at Lower Granite Dam.

| Date | Time | Gulls | Cormorants | Caspian Terns | Pelicans |
|---------|------|-------|------------|---------------|----------|
| Sept 16 | 1250 | 1 | 38 | 0 | 0 |
| Sept 17 | 1100 | 0 | 36 | 0 | 0 |
| Sept 18 | 1205 | 23 | 16 | 0 | 0 |
| Sept 19 | 0850 | 23 | 19 | 0 | 0 |
| Sept 20 | 0850 | 8 | 36 | 0 | 0 |
| Sept 21 | 1238 | 11 | 36 | 0 | 0 |
| Sept 22 | 1525 | 4 | 21 | 0 | 0 |

Gas Bubble Trauma (GBT) Monitoring: NA

Adult Fish Trap Operations: LWG Adult trap is in 24/7 collection broodstock operation. NPT is transporting Mondays and Tuesdays and WDFW is transporting Tuesday through Saturday.

Fish Rescue/Salvage: N/A

Research:

National Marine Fisheries Service (NMFS) PIT tagging of Adult Wild Chinook Salmon and Adult Steelhead for ISEMP-Related Dispersal Monitoring:

The goal of this project is to PIT tag up to 4000 unclipped adult Chinook Salmon and 4000 unclipped adult Steelhead collected in the adult trap daily sample for dispersal monitoring.

Sampling of Steelhead, Chinook Salmon, and Sockeye Salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating Steelhead, spring/summer Chinook Salmon, and Sockeye Salmon are collected from the adult trap beginning April 4 through December 15. The goal is to collect 5-20% of adult Steelhead, spring/summer Chinook Salmon, and Sockeye Salmon ascending the ladder. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. All natural origin adult Steelhead and spring/summer Chinook Salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye Salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some Steelhead and spring/summer Chinook Salmon may be radio-tagged or spaghetti-tagged. This information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs.

PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be collected as part of the normal adult trap daily sample and using the adult SbyC system to recapture previously PIT tagged fish. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder.

Columbia River Inter-Tribal Fisheries Commission (CRITFC) Pacific Lamprey Genetic Study:

CRITFC has requested that the SMP collect non-lethal tissue samples from up to 1,000 juvenile and 2,230 larval Pacific lamprey, not to exceed 20 juvenile or 10 larvae daily, during the routine smolt monitor condition sampling from March through October. The purpose of this study is to fill two objectives; 1) Determine relative proportion of translocation offspring among the total abundance of larval and juvenile lamprey passing the juvenile bypass systems at BON, JDA, MCN, and LWG. 2) Describe life history characteristics of larval and juvenile lamprey emigrating from the Columbia and Snake River basins. The genetic information collected will be used to evaluate the tribal Pacific lamprey programs efficacy and assist with guiding future management. There have been 653 macrophthalmia (juvenile) and 1588 ammocoete (larval) lamprey samples collected this season.

Idaho Power Hells Canyon Sturgeon Recruitment:

LWG Corps bio techs continue collecting passage and estimated lengths for White Sturgeon prior to removing them from the separator in support of Idaho Power Sturgeon program. A PIT tagged sturgeon was released from the juvenile separator August 8.