

CENWW-ODL

August 16, 2023

MEMORANDUM FOR THE RECORD: 23 LWG 10 AWS Pump 3 Removal from Service

SUBJECT: AWS 3 Removal from service due to oil leaking from the input shaft.

LWG AWS pump 3 was removed from service due to an oil leak from the input shaft. All AWS pumps were offline from 1209-1257 hours August 16. Bulkheads were swapped and AWS pump 2 was returned to service with AWS pump 1. AWS pump 3 will remain out of service until the problem is resolved and will remain in standby.

- A. Species – N/A
- B. Origin – N/A
- C. Length – N/A
- D. Marks and tags – N/A
- E. Marks and Injuries found on carcass – N/A
- F. Cause and Time of Death – N/A
- G. Future and Preventative Measures – AWS pump 3 was removed from service to prevent future damage.

Sincerely,

David Miller
Supervisory Fisheries Biologist
Lower Granite Project and Dworshak Dam
Walla Walla District
Ph. (509) 843-2264