

FPP Change Form

Change Request Number: 11BON005

Date: 8/10/10

Proposed by: BON Fisheries

Location of Change: BON section 6.5.2

Proposed Change: Current language:

6.5.2. From 1 December through 30 April, turbines which have been idle/out of service for more than 12 hours will be started by slow rolling the unit after manually tipping turbine blades from flat to steep and back to flat.

Proposed language:

6.5.2 From 1 December through 30 June, turbines which have been idle/out of service ~~for more than 12 hours~~ will be started by slow rolling the unit after manually tipping turbine blades from flat to steep and back to flat. The slow roll procedure should target 5 minutes in duration from the time of cracking the wicket gates to the time the unit reaches rated speed.

Reason for Change: Extend the slow roll procedure by one month based on sturgeon mortalities occurring outside of the previous timeframe. Also adds a target ramp up time to allow for more standardization and a reasonable timeframe for bringing a unit back on line

Comments from others: Kruger suggested any outage rather than waiting for 12 hours or more.

Record of Final Action: approved as changed, at August 2010 FPOM.