

MEMORANDUM FOR THE RECORD

SUBJECT: 22BON022 MFR PH2 Fish Unit 2 Outage

On 28 June at 1142 Bonneville Powerhouse 2's Fish Unit 2 (F2) was forced out of service (OOS) due to a suspected hub seal leak. In response, the WA Shore Fishway was placed into Single Fish Unit Ops as defined in FPP Table BON-12 and will remain so until further notice. Single Fish Unit Ops at current tailwater elevation (~28') placed the South "B" Diffusers B3-8 in manual and in the closed position while the PH2 North Upstream Entrance was closed as well. These adjustments allow for the fishway entrances to maintain proper differentials (1.0'-2.0').

BON Project Fisheries and Operations will continue to monitor fishway conditions closely during this operation.

- A. Species – N/A
- B. Origin – N/A
- C. Length – N/A
- D. Marks and tags – N/A
- E. Marks and Injuries found on carcass – N/A
- F. Cause and Time of Death – N/A
- G. Future and Preventative Measures – We will continue to monitor fishway conditions closely while in Single Fish Unit Ops.

Sincerely,
Bonneville Project Fisheries