

**MEMORANDUM FOR THE RECORD**

**SUBJECT: 20JDA01 MFR – Oil leak in SFL collection channel**

At 1415 on 17 March, project fisheries on its second daily inspection found a garbage truck parked near the North powerhouse fish entrance weirs with a blown hydraulic line. The truck had turned around at the end of the powerhouse just as the line broke and released an unknown amount of fluid (likely <2 gal) on the tailrace deck on top of the collection channel of the South fishway. The driver had a spill kit and immediately positioned absorbent material and litter. A small amount of oil likely fell into the fishway through the grating. Project fisheries notified the environmental compliance coordinator and the oil spill team and the spill was promptly cleaned up. No visible sheen of oil was observed in either the collection channel or tailrace.



Sincerely,  
JD Project Fisheries