CENWP-ODJ 11/8/2023

## MEMORANDUM FOR THE RECORD

SUBJECT: 23JDA39 Oil Sheen in Gatewell 12A.

On 06 November 2023, at approximately 1400, JDM personnel noticed a rainbow sheen in bulkhead gate slot 12A. JDM personnel called the Control Desk and Oil Accountability Program (OAP) personnel investigated. OAP personnel deployed absorbents in slot to absorb sheen. Amount of oil was determined to be approximately two tablespoons of oil based on sheen size. Source of sheen currently being investigated by JDM personnel.

07 November 2023 Update: JDM personnel determined that sheen was caused by rainwater filling catch pan below thirty-ton crane that was moved over slot 12A. Amount loss remains the same at approximately two tablespoons. Product loss now considered mixture of hydraulic oil and motor oil residue.

- A. Species NA
- B. Origin NA
- C. Length NA
- D. Marks and tags NA
- E. Marks and Injuries found on carcass –NA
- F. Cause and Time of Death NA
- G. Future and Preventative Measures- Daily gatewell inspections, and monitor crane catch pan after heavy rain.

Sincerely,

JDA Project Fisheries