

MEMORANDUM FOR THE RECORD - 23 IHR 06

SUBJECT: Spillway Outage to Repair Fishway Debris Boom

On June 18, an operator found that the north fish ladder exit debris boom was detached from its anchor point at one end. Later that same week, the boom became detached on the other end. Because of the proximity of the fishway exit to the spillway, a full spillway outage was required to repair the log boom. The spillway was out of service from 0704 to 0958 hrs on 28 June for this repair.

Chris Peery
USACE, Walla Walla District
Fishery Biologist
509-527-7124