

CENWW-ODL

May 25, 2023

MEMORANDUM FOR THE RECORD: 23 LWG 07 Adult Trap Hoist Removed from Service

SUBJECT: Adult trap hoist removed from service due to a failed solenoid for the brake system.

LWG adult trap hoist was removed from service at 1115 hours May 23, due to a failed solenoid for the hoist's brake system. No fish were present in the trap and the sample was turned off at that time. A replacement solenoid is being ordered. The brake system was inspected, and it was determined that the operation of the trap could resume while the part is being ordered with no immediate risk to damage to the machinery. The hoist was returned to service at 1310 hours May 23, and normal trapping operation resumed.

- A. Species – N/A
- B. Origin – N/A
- C. Length – N/A
- D. Marks and tags – N/A
- E. Marks and Injuries found on carcass – N/A
- F. Cause and Time of Death – N/A
- G. Future and Preventative Measures – A short delay in trap operation will be needed to install the replacement solenoid.

Sincerely,

David Miller
Supervisory Fisheries Biologist
Lower Granite Project and Dworshak Dam
Walla Walla District
Ph. (509) 843-2264