### **CENWP-ODB**

## MEMORANDUM FOR Biologist, Operations Division (CENWP-OD)

**SUBJECT:** Bonneville Project, Fishway and Fish Activities for <u>Week 48</u> of 2021, which covers the period from <u>21</u> to 27 November 2021.

## 1. OPERATION SUMMARY:

a. Daily average river flows ranged from 126.3 to 151.3 kcfs. Daily average powerhouse forebay elevation ranged from 73.1' to 74.1' msl. Daily average project tailwater ranged from 11.8' to 13.5' msl. Secchi disk measurements ranged from 5.0 to 7.0+'. Daily average water temperature ranged from 49 to 50°F.

b. Daily average spill remained at 1.0 kcfs.

c. <u>Unit Operation</u>. **PH2** remains the priority powerhouse. Main unit drawdowns are measured every Monday and more frequently as needed.

Unit	OOS	RTS	Reason	Duration
3	0006 on 07 Sept		P.O., Annual Overhaul/PT Install	
4	0006 on 07 Sept		P.O., Annual Overhaul/PT Install	
6	1604 on 09 Nov		F.O., Oil in Tail Logs; Investigation in Progress	

• Table 1. Main Unit Outages

d. <u>Fish Units</u>. Second Powerhouse fish units provide attraction flow for the Washington Shore (WS) fish ladder.

<u>Fish Unit Outages</u>. Fish Units are periodically placed into reserve service (RS) to float trash when debris differentials become excessive and trash raking is not possible.

• Table 2. Fish Unit Outages.

Unit	OOS/RS	RTS	Reason	Duration
F1	0727 on 21 Nov	1503 on 23 Nov	F.O., Water in Turbine Bearing	2 days, 7 hours, 36 mins
F2	2014 on 21 Nov	2239 on 21 Nov	R.S., Float Trash	2 hours, 25 mins

• Table 3. Fish Unit Drawdowns, in Feet.

Date	F1	F2
11/21		3.8'
11/22		0.6'
11/23	0.2'	0.1'
11/24	0.3'	1.1'
11/25	0.2'	1.2'
11/26	0.2'	1.8'
11/27	0.4'	2.3'

# 2. MAINTENANCE ACTIVITIES:

a. <u>Auxiliary Water System Closures</u>:

- FV 1-1 was closed for cleaning from 1050 to 1100 on 22 November.
- FV 6-9 was closed for cleaning from 0750 to 0808 on 24 November.
- FV 3-7 and 3-9 were placed in manual for cleaning from 1102 to 1210 on 24 November.
- FV 1-1 was closed for cleaning from 1258 to 1324 on 24 November.
- FV 3-7 (Bradford Island) was placed in manual and pinched down to reduce flow in the BI AWS to

prevent blown diffuser grating and further damage to FG 3-3. FG 3-4, FG 3-5, and FG 3-6 are all OOS due to mechanical failure. These settings for the A-Branch AWS and diffusers will likely remain until the problems can be addressed during the 2021-2022 winter maintenance period. Please see 21BON014 MFR A-Branch FV 3-7 and FG 3-4,5,6 OOC for further explanation on the <u>FPOM BON</u> Coordination page.

- b. <u>STS/VBS Inspections</u>. Nothing to report.
- c. <u>Dewatering and Fish Salvages</u>. Nothing to report.

## 3. RESEARCH:

- a. <u>Four Peaks Environmental Fish counting contract</u>: Daytime visual counting (0500 to 2100 PDT) began on 01 April. Night video (2100 to 0500 PDT) counting began 15 May. Fish counts can be viewed <u>here</u>.
- b. <u>USFWS Lamprey Metamorphosis Study</u>: Juvenile lamprey researchers are onsite, and the work is underway.
- c. <u>Pacific States Marine Fisheries Commission Smolt Monitoring:</u> Smolt monitoring operations concluded for the season at the Bonneville SMF at 0700 on Sunday, 31 October. The system was put into bypass mode at that time. Full flow PIT tag interrogation will remain active until the 2-mile pipe is dewatered, in mid-December.
- d. <u>State Agency Pinniped Trapping</u>: Sea lion trapping has concluded for the year.

## 4. FISHWAYS:

- a. Project biologists inspected 21 to 24 and 26 to 27 November.
- b. Fish Passage Plan observations.

 •	Table 4.	FPP	P Items Out of Criteria.			
				т	•	ED

Date	Location	FPP Violation	Cause	Response			
PH1							
		S. End Gate S. End Gate					
		Inoperable and	Inoperable, 1a and				
		Chain Gates 1a & 1b Closed for					
11/21-27	PH1 ITS	1b Closed	Safety Reasons	W.O.			
		Units Running out	U6 F.O., U9 Ran in				
11/23-24	PH1	of Priority Order	Its Place	W.O.			
Bradford Island							
			FG 3-4				
			Mechanically				
		FG 3-4 Partially	Bound Partially				
11/21-27	A-Branch	Open	Open/Closed	W.O.			
		Weir Staff Gauge	eir Staff Gauge				
11/26-27	A-Branch	Diff.>1.1'	Unknown	N.A.			
			Currently in				
11/21-23	BI Exit	FV 3-7 Low	Manual	Caution Order			
	Cascades Island						
	FG 6-18 Closed,						
11/21-24	Cascades Island	Should be Open	Unknown	Mechanics Notified			
		Washington Shore					
		PH2 Ent/TW Diff					
11/21-23	PH2	<1.0	Single Fish Ops	W.O.			

- 5 avian lines were cut from the B2CC avian line array on 02 September. Avian lines are installed by 10
  April every year and normally remain up as a form of avian abatement through the start of winter when
  they may be taken down if winter maintenance activities require. These 5 lines were damaged and
  hanging extremely low to the water, creating a hazard for a survey vessel entering BON BRZ for a
  hydrosurvey on 03 Sept. These avian arrays are slated to be re-installed during the 1<sup>st</sup> or 2<sup>nd</sup> week of
  March 2022.
- FV 3-7 (Bradford Island) was placed in manual and pinched down to reduce flow in the BI AWS to prevent blown diffuser grating and further damage to FG 3-3. These settings for the A-Branch AWS and diffusers will likely remain until the problems can be addressed during the 2021-2022 winter maintenance period.
- FG 3-4 (A-Branch) was found mechanically bound and unable to move from the "almost closed" position in December of 2020. This diffuser will likely remain in this position until the 2021-2022 winter maintenance period.
- FG 3-5 (A-Branch) was not operating correctly on 07 June 2021 and was banging heavlily underwater due to an assumed broken fish gate. To prevent futher damage to the fishway and equipment, a clearance has been issued for FG 3-5 to be closed and taken out of service until the winter maintenance period.
- FG 3-6 (A-Branch) was found mechanically bound in the closed position on 07 June 2021. This diffuser will likely remain in this position until the 2021-2022 winter maintenance period.

#### c. Adult Fishways.

- (1) The AFF remains in service.
- (2) Sensor calibration occurred on 24 November.
- (3) SLEDs are installed at all locations.
- (4) Bradford Island, Cascades Island, and Washington Shore Fishways are in service.

#### d. Juvenile Fishways.

- (1) The ITS remains in service (auto-chain gates 3B, 6C, & 10B only).
- (2) The hydro-cannon remains out of service.
- (3) The B2CC was closed for the season 01 September when spill season ended.
- (4) The DSM remains in service.
- (5) STSs remain in service.
- e. Lamprey Fishways.
  - (1) BI, CI, and WA Shore LPS's remain out of service.
  - (2) The Bradford Island Wetted Wall (BIWW) remains out of service.
  - (3) The PH2 Lamprey Flume Structure (LFS) remains out of service.
  - (4) The AFF lamprey trap and CI lamprey trap remain out of service.
- f. <u>Avian Monitoring</u>. Avian counts are recorded 01 April 31 October.

(1) On 02 September, 5 avian lines were cut from the B2CC avian line array. Avian lines are installed by 10 April every year and normally remain up as a form of avian abatement through the start of winter when they may be taken down if winter maintenance activities require. These 5 lines were damaged and hanging extremely low to the water, creating a hazard for a survey vessel entering BON BRZ for a hydrosurvey on 03 Sept. These avain arrays are slated to be re-installed during the 1st or 2nd week of March 2022.

## 5. WATER QUALITY MONITORING:

- a. <u>Fishway Temperatures</u>. Temperature logs began on 28 February and concluded on 09 October.
- b. <u>Zebra Mussel Monitoring</u>. No signs of colonization were observed this reporting week.

### 6. CONSTRUCTION: Nothing to report.

## 7. HAZMAT, SPILLS AND CLEANUP: Nothing to report.

### 8. TELETYPES CURRENTLY IN EFFECT:

- A teletype sent out on 01 September with revisions to fall/winter spill priority list and fall/winter spill caps provided the order that projects spill for lack of load conditions. This order is to be used until further notice. Please see teletype BON R 090121 1544 for details.
- A teletype was sent out on 27 October outlining BON tailwater operations for chum spawning. Effective 01 November at 0600 HRS, and until further notice, the Bonneville Dam must maintain tailwater in the following order of operating ranges as project outflow increases:
  - 1. During all hours, operate project outflow to provide a tailwater elevation in the range of 11.3 to 13.0 feet.
  - 2. Then, if necessary to increase project outflow, the tailwater may be operated up to 16.5 feet during the nighttime hours (1700-0600) with highest elevations concentrated around 2400 HRS.
  - 3. Then, if necessary to increase project outflow, the tailwater may be operated up to 18.5 feet during nighttime hours (1700-0600)
  - 4. Then, if increasing river flow precludes the ability to manage the tailwater within the step above, operate to provide a tailwater in the range of 13.0 to 16.5 feet during daytime hours (0600-1700) and up to the maximum within project 24-HR ramp rate limits during nighttime hours (1700-0600).

The goal of this operation is to improve spawning conditions at the Ives/Pierce Island Complex for chum salmon. Please see teletype BON R 102721 1011 for further details.

- A teletype distributed on 18 November stated a Bonneville forebay restriction. The document requests that BPA operate the Bonneville forebay below a maximum of 74.0 feet, soft constraint during the following dates and times:
  - 1. 29 Nov 03 Dec, 0600-1800 HRS
  - 2. 06 Dec 10 Dec, 0600-1800 HRS
  - 3. 13 Dec 17 Dec, 0600-1800 HRS
  - 4. 20 Dec 22 Dec, 0600-1800 HRS

This forebay operation supports marine construction in the Bonneville Pool near the mouth of Rock Creek in the Columbia River, river mile 150. Please see teletype BON R 111821 1135 for more details.

MICHAEL ADAMS, P.E. Operations Project Manager Bonneville Project