The Dalles Dam Fishway Status Report

10/5/2020

Inspection Period: 9/27-10/03

THE DALLES DAM



The Dalles Project-Fisheries P.O. Box 564 The Dalles, OR 97058-9998 Phone: 541-506-3800

The Dalles Dam	Inspections OOC	Criteria Limit	Total Number of Inspections: 21 Comments: fishways functional	Temperature: Weekly Average Secchi	65.4 :	°F 5.4
			NORTH FISHWAY			
Exit differential	0	≤ 0.5′				
Count station differential	0	≤ 0.3'				
Weir crest depth	0	1.0' ± 0.1'				
Entrance differential	0	1.0' - 2.0'	1.3			
Entrance weir N1	0	depth (≥ 8')	9.0			
Entrance weir N2	0	Closed				
PUD Intake differential	5	≤ 0.5′	Damage to north FB index makes data unreliable.			
			EAST FISHWAY			
Exit differential	0	≤ 0.5'				
Removable weirs 154-157	0	Per forebay				
Weir 158-159 differential	0	1.1' ± 0.1'				
Count station differential	0	≤ 0.3'				
153 Weir crest depth	0	1.3' ± 0.1'				
Junction pool weir JP6	0	> 7.0'	Average for week = 9.1			
East entrance differential	0	1.0' - 2.0'	Average for week = 1.5			
Entrance weir E1	0	No criteria	Average for week = No criteria			
Entrance weir E2	0	depth (≥ 8')	Average for week = 11.5			
Entrance weir E3	0		Average for week = 11.5			
Collection channel velocity	0	1.5 - 4 fps	3.04 fps, 9/23/2020 Range: 3.74 fps MU 1 to 2.48	fps MU-2		
Transportation channel velocity	0	1.5 - 4 fps	2.53 fps, 9/28/2020	•		
North channel velocity	0	1.5 - 4 fps	2.56 fps, 9/28/2020			
South channel velocity	0	1.5 - 4 fps	3.48 fps, 9/28/2020			
West entrance differential	0	1.0' - 2.0'	Average for week = 1.5			
Entrance weir W1	0	depth (≥ 8')	Average for week = 9.9			
Entrance weir W2	0	depth (≥ 8')	Average for week = 9.9			
Entrance weir W3	0	No criteria				
South entrance differential	0	1.0' - 2.0'	Average for week = 1.5		,	
Entrance weir S1	0	depth (≥ 8')	Average for week = 8.5			
Entrance weir S2	0	depth (≥ 8')	Average for week = 8.5			
			JUVENILE PASSAGE			
Sluicegate operation	0	Units 1, 7, 18	MU8 OOS			
Turbine trashrack drawdown	0		9/23/2020 checked, all in criteria.			
Spill volume/pattern	0	1 to 8	Spill closed 9/1/2020.			
Turbine Unit Priority	1		All available MUs running; OOC due to forced outage			
Gatewells	0	Weekly	9/28/2020 fish check, some adult shad MU-22-2 mor			

OTHER ISSUES:

Unit Outages

- Line 1, MU1,2, FU1&2 limited to 188MVA for T1 replacement; 1/28/2021
- T10 (MU19 & 20) FOOS through 10/28/2021 due to acetylene levels
- MU8 OOS 0630 1/21/2020 1700 10/1/2020 for Overhaul
- T7 OOS 0001 6/22/2020 1700 10/1/2020 T7 GSU Replacement & Gnd. Switch Repairs
- MU22 FOOS through 1700 11/19/2020 due to excessive vibration.
- MU21 OOS 8/3/2020 11/19/2020 for Annual & Headcover Upgrade
- TO-1 OOS 0630 10/5/2020 1700 10/15/2020 for Doble Testing
- T5 OOS 0630 10/5/2020 1200 10/13/2020 for T5 GSU install re-work

Maintenance

PUD intake rake out of service due to power track damage. Exploring repair options. Expecting budget challenge. Raking with mobile crane as needed. Calibration check on 9/28, all in criteria. Damage to north FB staff gage giving potential accuracy problems.

Five of 6 east fishway collection channel dewatering pumps removed for repair/rehab. On hold due to budget constraints. Resume in Oct.

East fishway automation replacement no progress. PLC box assembly completed. Installation of east entrance planned completion in Sept.

Spillway assessment (MRER); No FY20 funding. Spillgate 9 trunnion pin included.

Predators

USDA hazing concluded 7/31. Refer to avian graph tab for bird numbers.

Green laser use for piscivorous bird hazing testing on hold. Potential safety concerns being addressed.

Cormorants foraging forebay near east ladder exit and entrance. Several herons foraging east fishladder. Fishway inspectors continuing ladder walks.

Invasive aquatic weeds subsiding at count station pickets. Zebra mussel samples collected 8/31.

Pikeminnow dam angling concluded w/980 removed. All invasive bass/walleye by-catch release continues per states gamefish requirements.

Research/Construction/Contractors

PSMFC concluded juvenile sampling at PUD 7/31

Four Peaks fish counting ongoing through 10/31.

CRITFC lamprey trapping concluded 9/3.526 total lamrey captures YTD

PITAGS north and east fishladder data collection at count stations continues.

Fish unit breaker replacement isntalled and in operation. Calculation issue needed for completion.


Fish unit rehab - Phase 1A. Planning operation scenario with AWS backup water supply during construction. Effort underway to finish report this year.

Fishway Operations

North and east fish ladders in full operation.

Approved by: Mike Colesar, Operation Project Manager, The Dalles Dam


Avian Lines and laser deterrent zones




Red lines = avian zones

Yellow lines = current wires

Orange lines = down or missing wires





	Secchi:		°F
9/27	5.0	Sun	65.3
9/28	5.0	Mon	65.1
9/29	5.0	Tue	65.4
9/30	5.0	Wed	65.5
10/1	6.0	Thurs	65.5
10/2	6.0	Fri	65.5
10/3	6.0	Sat	65.5
	5.4	AVG	65.4


USGS September USGS October

> The Dalles Dam Daily Readings and Averages for Temperatures, Secchi, Entrances, and Spill

SCADA INSPECTION out of criteria

Date:	North Ladder		East Ladder											
			East Entrance				West Entrance				South Entrance			
	Differential	N1 Depth	Differential	E1 Depth	E2 Depth	E3 Depth	JP 6	Differential	W1	W2	W3	Differential	S1	S2
9/27			1.3	7.4	11.3	11.3	8.1	1.3	10.0	10.0	-4.9	1.4	8.4	8.4
	1.2	9.5	1.4	7.5	11.5	11.5	8.5	1.3	10.1	10.1	-4.6	1.3	8.5	8.5
	1.2	9.7	1.4	4.0	11.5	11.5	8.5	1.5	10.0	10.0	-4.7	1.4	8.5	8.5
9/28			1.5	4.1	11.6	11.6	9.0	1.4	10.1	10.1	-4.2	1.4	8.6	8.5
	1.1	9.3	1.4	2.9	11.5	11.6	8.7	1.4	10.0	10.0	-4.6	1.4	8.6	8.6
	1.3	9.0	1.6	3.0	11.5	11.5	9.3	1.5	10.0	10.0	-4.3	1.4	8.6	8.5
9/29			1.3	4.6	11.5	11.5	8.4	1.3	10.1	10.1	-4.8	1.4	8.5	8.5
	1.3	8.9	1.3	4.4	11.5	11.5	8.6	1.7	9.0	9.0	-4.7	1.5	8.4	8.4
	1.3	8.9	1.4	3.6	11.6	11.6	9.0	1.5	9.7	9.7	-4.5	1.5	8.5	8.5
9/30			1.6	3.5	11.5	11.5	9.7	1.6	9.6	9.6	-3.9	1.6	8.6	8.6
	1.3	9.0	1.6	5.8	11.5	11.5	9.8	1.7	9.8	9.8	-3.8	1.5	8.6	8.6
	1.2	9.2	1.6	5.5	11.5	11.5	10.0	1.4	10.3	10.3	-3.7	1.5	8.5	8.5
10/1			1.3	5.5	11.5	11.5	8.5	1.2	10.4	10.4	-4.7	1.4	8.6	8.6
	1.3	9.0	1.3	3.0	11.5	11.5	8.4	1.5	9.6	9.6	-4.9	1.5	8.4	8.4
	2.3	7.8	1.6	3.0	11.5	11.5	8.8	1.5	9.7	9.7	-4.4	1.4	8.6	8.6
			1.6	3.0	11.7	11.6	8.9	1.4	9.9	9.9	-4.1	1.4	8.9	8.8
10/2	1.1	9.0	1.3	3.0	11.5	11.5	8.4	1.5	9.6	9.6	-4.9	1.5	8.4	8.4
	1.4	9.0	1.8	3.1	11.5	11.5	9.6	1.6	9.7	9.7	-3.6	1.5	8.5	8.5
10/3			1.9	3.5	11.4	11.5	9.6	1.5	9.7	9.7	-3.4	1.5	8.6	8.6
	1.3	9.2	1.9	3.0	11.5	11.5	10.2	1.7	9.8	9.8	-3.2	1.6	8.4	8.4
	1.4	9.1	2.0	3.0	11.5	11.5	11.0	1.8	9.8	9.8	-2.8	1.6	8.6	8.6
AVG:	1.3	9.0	1.5	4.1	11.5	11.5	9.1	1.5	9.9	9.9	-4.2	1.5	8.5	8.5

Fishways are inspected once daily plus one SCADA inspection.



PIT recovery efforts below dam 10/2/2020. No tags were found. Plenty of magnetic grit.