| The | Dalles Dan | Status Report THE DALLES DAM | | | | | | | | | | | |
|---|--------------------|--|---|--|--|--|--|--|--|--|--|--|--|
| | | The Dalles Project-Fisheries P.O. Box 564 US Army Corps The Dalles, OR 97058-9998 | | | | | | | | | | | |
| | Inspection | of Engineers The Dalies, OK 57050 5550 | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| The Dalles Dam | Inspections OOC | Criteria Limit | Total Number of Inspections:7Temperature:37.6°FComments:Eagle numbers increasing.Weekly Ave. Secchi:5.4 | | | | | | | | | | |
| NORTH FISHWAY | | | | | | | | | | | | | |
| Evit differential | 0 | | | | | | | | | | | | |
| Exit differential Count station differential | 0 | ≤ 0.5' ≤ 0.3' | Large amounts of floating milfoil kept out by boom and raking gratings. Video counting is ongoi | | | | | | | | | | |
| Weir crest depth | 0 | | North ladder is rock solid automation. | | | | | | | | | | |
| Entrance weir N1 | - | | | | | | | | | | | | |
| Entrance Differential | 0 | | <u> </u> | | | | | | | | | | |
| N2 | 0 | 1.0' - 2.0' Closed | Avg. for week 1.3 | | | | | | | | | | |
| PUD Intake differential | 0 | | PUD and hand raking keeping up with floating stems of aquatic weeds mostly. | | | | | | | | | | |
| | | • | | | | | | | | | | | |
| EA | ST FISH | WAY -U | JNDERGOING WINTER MAINTAINENCE | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | JUVENILE BYPASS | | | | | | | | | | |
| Sluicegate operation | 0 | closed | Endgate closed 12/16/22. Intakes 1-8-16-18 open. | | | | | | | | | | |
| Turbine trashrack drawdown | 0 | <1.5', biwkly | | | | | | | | | | | |
| Spill volume/pattern | 0 | 1 to 22 | NO SPILL. | | | | | | | | | | |
| Turbine Unit Priority | 0 | per FPP | | | | | | | | | | | |
| Gatewells | 0 | Weekly | Very little debris in gatewells, with debris accumulating in ITS as endgate is closed. | | | | | | | | | | |

Current Outages

MU19 & MU20 FOOS 10/07/2018 – 10/27/2023 T10 ACETYLENE MU12 OOS 04/12/2021 – 9/22/2023 ANNUAL MU18 OOS 08/29/2022 -1/26/2023, COOLER F1 OOS 11/26/2022 - 01/26/2023, 2 YEAR F2 OOS 12/01/2022 - 01/04/2023, ANNUAL MU21 OOS 12/12/2022 – 01/05/2023, GENERATOR FALL PROTECTION

Maintenance

ROV inspection of fish unit intake trashrack Jan18 to assess aquatic vegetation buildup. Planning to use fish unit intake trashrack rake in anticipation for future debris buildup concerns. To be in service be March 1. EFL exit weir 155 repair in progress. Weirs 154 and 155 cut lamprey orifices per PDT recommendation. Plan to pull north entrance trashrack end of Jan for inspection. Calibrations: North entrance maintaining criteria. 1/5/2023 Spillway assessment; Spillgates 1- 9 rehab 2034. Includes spillbay 9 trunnion pin repair. Spillway crane first priority Planning spill gates 9 and 10 cable and gearbox swap. Replacing bulkhead seals needed. Completion estimate end march. Fish unit rehab Phase 1A awaiting funding. AWS intake trashrack debris management - PDT reviewing alternatives.

Predators

Bald Eagles dominating other predatory birds from westrick park. Western/glaucus wing gulls NOT spending overnight on project Hybrid gulls dispersing daily, unable to feed due to eagles. Cormorants foraging around project.

Using green laser to move gulls and cormorants from common resting areas.

Comments provided for Environmental Assessment for approval this spring.

Construction/Contractors

USGS ladder-river temperatures-F°

4 peaks counting 4/1-10/31. Video countinued through December.


Fish Accords Lamprey Passage plan ongoing at 90% due 09/01 DDR junction pool LPS. Investigating mods for entrance and exit weirs. PTAGIS fishladder data collection at count stations continues


Operations

Ice Trash sluiceway endgate closed. Sluicegates 1,8,16,18 open to forebay. North fishways in full service. East fishway dewatered for winter maintenance.


Approved by: Ron Twiner, Operation Project Manager, The Dalles Dam

Bird Count Zones, Avian Lines and Laser Deterrent Sites







Note the blue bar indicates the number of eagles on project. The more eagles, the less gulls.



| | | Secchi: 6.0 6.0 5.0 5.0 4.5 6.0 | Sun Mon Tue Wed Thurs Fri Sat | USGS°F 37.9 37.7 37.6 37.5 37.4 37.5 37.4 37.5 37.6 | | | | Report | ing v | veek d | data | | | | |
|---------|--------------|---|---|--|---------------|----------|---------------|-----------------|-----------|----------|---------|----------------|-----------|----------|---|
| | | 5.42 | AVG | 37.6 | ĺ | | | | | | | | | | |
| Date: | North | ladder | East Ladder | | | | | | | | | | | | |
| | | | | | East Entrance | | West Entrance | | | | | South Entrance | | | |
| | Differential | N1 Depth | Differential | E1 Depth | E2 Depth | E3 Depth | JP 6 | Differential | W1 | W2 | W3 | Differential | S1 | S2 | 4 |
| 1/1 | 1.2 | 10.1 | 4 | | | | | | | | | | | | |
| 1/1 | 1.3 | 10.1 | 1 | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| 1/2 1.2 | 1.2 | 10.2 | | | | | | | | | | | | | |
| | 1.2 | 10.2 | - | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| 1/3 | 1.3 | 10.3 | | | | | | | | | | | | | |
| | 1.0 | 1010 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| 1/4 | 1.3 | 10.1 | 1 | | | | FAST | LADDER [|)FW/AT | FRFD | | | | | |
| 10 | | | 1 | | | | 2, 101 | | | | | | | | |
| | | | 1 | | | | | | | | | | | | |
| 1/5 1.2 | 1.2 | 10.1 | 1 | | | | | | | | | | | | |
| | | |] | | | | | | | | | | | | |
| | | |] | | | | | | | | | | | | |
| 1/6 | 1.3 | 9.7 |] | | | | | | | | | | | | |
| | | | J | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| 1/7 | 1.3 | 10.4 | | | | | | | | | | | | | 1 |
| | | | | | | | | | | | | | | | |
| | | 40.4 | #DIV/0! | //DI)//01 | #DIV/0! | #DIV/0! | #DIV/0! | #DIV/0! | //DIV//OI | 11001101 | #DIV/0! | #DIV/0! | #DIV/0! | #DIV//01 | |
| AVG: | 1.3 | 10.1 | #DIV/0! | #DIV/0! | #DIV/0! | | | d once daily 12 | #DIV/0! | #DIV/0! | #DIV/0! | #DIV/0! | found out | #DIV/0! | |



Repaired 155 weir installation. Lamprey orifices cut in bottom corners.



Eagles roosting north of SW1 near ladder entrance. Lone Pine village in the background.