

**U.S. ARMY CORPS OF ENGINEERS  
WALLA WALLA DISTRICT  
FISH FACILITIES WEEKLY REPORT  
#22-2019**

**Project: McNary**

Biologist: Bobby Johnson and Denise Griffith

Dates: July 26 to August 1, 2019

---

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 14 turbine units available for service. (See table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS).

Unit(s)	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	05/23	0943	08/15	NA	Turbine blade packing.
13	06/10	0610	TBD	NA	Turbine bearing.
7	07/29	0728	08/01	1611	Annual maintenance.

Comments: There are no problems to report.

**Adult Fish Passage Facilities**

McNary fisheries biologists performed measured inspections of the adult fishways on July 26, 28 and 30. Adult fish counting and video review of night time lamprey passage continued.

On July 29, at 1846 hours, the Oregon shore fish counter evacuated the count station due to an adverse reaction to spider spray. No data was lost as the counter reviewed the video tape the next day. The project biologist insured no future spraying would occur near the count stations.

Fish Ladder Exits:

Yes	No	Location	Criteria	Comments
X		Oregon Exit	Head over weir 1.0' to 1.3'	
X		Oregon Count Station Differential	0.0' to 0.5'	
X		Washington Exit	Head over weir 1.0' to 1.3'	
X		Washington Count Station Differential	0.0' to 0.5'	

Comments: Debris loads were light to moderate near the Oregon exit and minimal to light Washington exit. Picketed leads were cleaned as required, including on Saturday.

At the Washington exit, one regulating weir alarm came in and was reset on July 28.

There are no other problems to report.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			North Oregon Entrance Head Differential	1.0' – 2.0'	
X			NFEW2 Weir Depth	≥ 8.0'	
X			NFEW3 Weir Depth	≥ 8.0'	
X			South Oregon Entrance Head Differential	1.0' – 2.0'	
X			SFEW1 Weir Depth	≥ 8.0'	
	X		SFEW2 Weir Depth	≥ 8.0'	7.9' on July 26
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	Averaged 1.9 fps.
X			Washington Entrance Head Differential	1.0' – 2.0'	
X			WFE2 Weir Depth	≥ 8.0'	
X			WFE3 Weir Depth	≥ 8.0'	

Comments: The out of criterion point listed above may have been due to calibration drifts and/or low tailwater.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			WA shore Wasco County PUD Turbine Unit
	Yes		WA shore Wasco PUD Bypass
		Yes	Oregon shore Fish Pump 1, OOS to October 31.
Yes			Oregon shore Fish Pump 2, Blade angle: 23 to 24°
Yes			Oregon shore Fish Pump 3, Blade angle: 25 to 26°
Yes			OR North Powerhouse Pool supply from juvenile fishway

Comments: There are no problems to report.

**Juvenile Fish Passage Facility**

The sampling season consisting of alternating days of primary and secondary bypass continued. The schedule was not interrupted this week.

The full flow flume adult flush line valve continued to hesitate when opening. However, operating the valve manually and in local mode has increase the valve reliably. The issue will continue to be monitored.

Daily water temperature monitoring and reporting throughout the juvenile passage facility continued. The smolt monitoring staff, Anchor, QEA, published weekly results in a separate report, which includes any issues with the probes.

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Powerhouse forebay debris load acceptable?	Minimal to light.
X			Trash rack differentials measured this week?	Daily.
X			Trash rack differentials acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: New incoming debris was minimal. Aquatic vegetation has increased. The spillway debris load would be described as very light. Depending on weather, the debris moved back and forth from the powerhouse to the Oregon shore line. There are no plans to clean trash racks. There are no problems to report.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs):

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: The brush cycles for the screens in units 6, 8, 10 and 13 remained in timer mode. The camera inspections in units 5 and 13 revealed no problems on July 30.

Daily VBS differential monitoring continued. No high differentials were recorded. Due to freshwater sponge growth on the screens becoming substantial, the VBSs in 9B and 9C slots were cleaned on July 29. No fish were observed. Sponge has now been removed from all VBSs.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

Yes	No	NA	Item	Number of orifices in service
X			Orifices operating satisfactory?	42
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: There were 42 orifices in use. Orifices were operated as required for VBS cleaning. Orifice valve operators were repaired as required. On July 30, a low water alarm came in during orifice cycling. Protocols were reviewed.

There are no other problems to report. The channel system will continue to be monitored closely.

Bypass Facility:

Yes	No	NA	Item
X			Sample gates on?
		X	PIT-tag sampling system on?

Comments: The sample gates were operated only when in secondary bypass. The PIT tag system will remain out of service as there are no studies requiring its use. The issues with the full flow flume adult flush line are mentioned above.

This week, 76 juvenile lamprey and 4,772 smolts were bypassed during secondary bypass. Algae removal, flow adjustment and maintenance are ongoing. There are no problems to report.

TSW Operations: The two TSWs remained closed for the season.

**River Conditions**

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
169.8	129.3	96.7	73.9	70.3	69.2	6.0	6.0

Comments: The above data is supplied by Anchor, QEA except water clarity, which is provided by the control room. The summer spill program continued with 57 percent of the flow being spilled.

## Other

Inline Cooling Water Strainers: The next cooling water strainer examinations will occur on August 6, which should be the last inspections until December 3.

Avian Activity: Avian observations continued. The counts are reflected in Table 3 below.

Table 3. McNary Project's Daily Tailwater Avian Counts.

Date	Zone	Gull	Cormorant	Tern	Pelican
July 26	Spill	1	1	7	10
	Powerhouse	0	0	0	0
	Outfall	1	0	0	3
July 27	Spill	12	0	21	37
	Powerhouse	0	0	0	0
	Outfall	3	0	0	4
July 28	Spill	2	0	12	23
	Powerhouse	0	0	0	0
	Outfall	4	0	0	2
July 29	Spill	0	0	1	12
	Powerhouse	0	0	0	0
	Outfall	1	1	1	3
July 30	Spill	5	0	0	4
	Powerhouse	0	0	0	0
	Outfall	10	3	0	3
July 31	Spill	4	1	2	5
	Powerhouse	0	0	0	0
	Outfall	3	5	2	1
August 1	Spill	0	1	2	2
	Powerhouse	0	0	0	0
	Outfall	3	0	0	1

There was very little activity in the powerhouse zone. In the spill zone, gull, tern and pelican numbers decreased. All birds appeared to be feeding or roosting. The cormorants in the spill zone were roosting.

In the bypass outfall zone, the gulls along with an occasional osprey were roosting on the full flow pipe. At times, a few gulls, cormorants or terns were attempting to feed. Also, a small number of pelicans were noted feeding regularly at the outfall.

The laser for bypass outfall hazing remained in place and functional. The laser does seem to deter the gulls and terns, birds in flight. However, birds setting on the water, the pelicans and cormorants, are more difficult to haze with the laser. Therefore, we are considering a second laser from another angle. Also, we are looking into another form of noise deterrent.

The bird distress calls remained deployed along the navigation lock wing wall. Roosting on the wall has occurred but has been very limited. A large bird distress call is also deployed at the end of the remaining outfall pipe walkway. Due to its late installation, it appears to be less effective. The calls are being monitored weekly. USDA Wildlife Services concluded hazing on July 27.

In the forebay zone, grebes numbering from 0 to 20 birds. The grebe distress call appears to have promise but a call with higher volume is required. Occasionally, an osprey, pelican or a small group of juvenile gulls was observed. Also, small numbers of pelicans, cormorants and gulls were noted roosting outside the zone along the Washington shore line. Finally, small gull flocks have been staging around the project.

No pelicans were observed were inside the ladders and no grebes were observed elsewhere on project.

Invasive Species: The next mussel station examinations will occur in late August. So far this season, one Siberian prawn was removed from the sample and euthanized.

Fish Rescue/Salvage: No fish rescue occurred this week.

Research: The University of Idaho continued the adult lamprey passage study. Gas bubble trauma (GBT) examinations occurred once this week due to low fish numbers. No smolts were observed with signs of GBT and no mortalities were recorded.

**Project: Ice Harbor**

Biologist: Ken Fone

Dates: July 19 – July 25, 2019

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	x	All 6 turbine units available for service (see table & comments below for details).		
x		Available turbines operated within 1% peak efficiency? Constraint in effect.	x	

**Ice Harbor Unit Outages (OOS) and Return to Service (RTS):**

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
4	9/20/18	1619	---	---	Replace blade packing to fix oil leak
3	5/3/19	0641	---	---	Turbine runner replacement and stator rewind

Comments: Turbine units 1 and 2 were offline to conduct doble testing starting July 22, 2019 at 09:15 (unit 1) and 9:22 (unit 2). Both units were returned to service July 25, 2019 at 07:50 (unit 1) and 10:40 (unit 2).

**Adult Fish Passage Facility**

Ice Harbor fish facility staff inspected the adult fishways on July 22<sup>nd</sup>, July 24<sup>th</sup>, and July 25<sup>th</sup>. The newly installed lamprey entrance on the South Adult Fish Ladder (SFE2) was opened July 17<sup>th</sup> at 16:45 to allow for lamprey passage.

**Fish Ladders:**

Yes	No	Location	Criteria	Measurements
x		North Ladder Exit Differential	Head $\leq$ 0.3'	
x		North Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
x		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
x		South Ladder Exit Differential	Head $\leq$ 0.3'	
x		South Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
x		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

**Fishway Entrances and Collection Channel:**

Yes	No	Sill	Location	Criteria	Measurements
		x	South Shore Entrance (SFE-1) Weir Depth	$\geq$ 8.0' or on sill	
x			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
x			South Shore Channel Velocity	1.5 – 4.0 fps	
		x	North Powerhouse Entrance (NFE-1) Weir Depth	$\geq$ 8.0' or on sill	
x			North Powerhouse Entrance Channel/Tailwater Differential	1.0' – 2.0'	
		x	North Shore Entrance (NEW-1) Weir Depth	$\geq$ 8.0' or on sill	
x			North Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: None.

**Auxiliary Water Supply (AWS) System:**

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
7 pumps	1 pump		Status of the 8 South Shore AWS Pumps
2 pumps	1 pump		Status of the 3 North Shore AWS Pumps

Comments: None.

### Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
x			Forebay debris load acceptable? (amount)	10-15 square yards
	x		Gatewell drawdown measured this week?	
		x	Gatewell drawdown acceptable	
x			Any debris seen in gatewells (% coverage)	0-5%
x			Any oil seen in gatewells?	2A and 2C

Comments: Oil sheen was reported in gatewells 2A and 2C, and the oil response spill team dropped oil booms down in the gatewells to mitigate any oil seepage.

STSs/VBSs:

Yes	No	NA	Item
	x		STSs deployed in all slots and in service?
	x		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
	x		STSs inspected this week?
		x	STSs inspection results acceptable?
		x	VBSs differentials checked this week?
		x	VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
x			Orifices operating satisfactory?	20
x			Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Juvenile Fish Facility: The fish facility is being operated in primary bypass, except when collecting fish for sampling.

Fish Sampling: Sampling has ended for the year.

Removable Spillway Weir (RSW): Voluntary spill for fish passage is occurring.

### River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
38.80	31.60	11.7	10.0	69	68	8.0	6.7

\*Unit 1 scroll case temperature.

## Other

Inline Cooling Water Strainers: Monthly strainer inspections for lamprey ended in June and will start in December.

Avian Activity: There were moderate numbers of piscivorous birds counted around the project (see the table below). The birds were observed roosting on Eagle Island and foraging in the tailrace.

Daily maximum piscivorous bird counts at Ice Harbor Dam.

Date	Gulls	Cormorants	Caspian Terns	Grebes	Pelicans
July 19	---	---	---	---	---
July 20	---	---	---	---	---
July 21	---	---	---	---	---
July 22	26	7	0	---	99
July 23	18	4	0	---	42
July 24	6	4	2	---	41
July 25	42	0	5	---	13

Invasive Species: No new exotic species have been found.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Anchor, frozen and properly disposed of in a landfill. Sampling is done for the year.

Fish Rescue/Salvage: None.

Research: Blue Leaf is conducting research on the newly installed lamprey entrances on the South Adult Fish Ladder (SFE2). They will monitor via camera lamprey movement and salmonid fish interactions with the newly installed entrances.



**Project: Lower Monumental**

Biologists: Chuck Barnes and Raymond Addis

Dates: July 26 – August 1, 2019

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 1	7/25/2019	05:31	8/03/2019	ERTS	Doble Testing
Unit 2	7/15/2019	07:20	1/11/2020	ERTS	Annual Maintenance/Draft Tube Liner Repair
Unit 3	7/25/2019	05:31	8/03/2019	ERTS	Doble Testing
Unit 4	7/08/2019	07:20	8/09/2019	ERTS	Annual Maintenance
Unit 5	Daily	~05:30	Daily	~16:00 – 17:00	Doble Testing
Unit 6	Daily	~05:30	Daily	~16:00 – 17:00	Doble Testing

Comments: Units went into Hard Restraint at 0001 on April 1.

Unit 5 was taken out of service and placed on “speed no load” to supply station service power during working hours for Doble testing and returned to service each night of the reporting period.

Unit 6 was taken out of service during working hours for Doble testing and returned to service each night of the reporting period.

**Adult Fish Passage Facility**

The adult fishways were inspected by Corps and Anchor QEA biologists on July 26, 27, 28 and 31.

Fish Ladder:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head $\leq$ 0.5'	
X		North Ladder Picketed Lead Differential	Head $\leq$ 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head $\leq$ 0.5'	
X		South Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments:

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	≥ 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	≥ 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	≥ 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	≥ 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
		X	South Shore Entrance (SSE-1) Weir Depth	≥ 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	≥ 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: South Powerhouse Entrance weir (SPE-1) was on sill during all inspections with readings of 5.2, 5.0, 5.1 and 5.4 feet respectively.

South Powerhouse Entrance weir (SPE-2) was on sill during all inspections with readings of 5.2, 5.0, 5.1 and 5.4 feet respectively.

South Shore Entrance weir (SSE-1) was on sill during all inspections with readings of 6.0, 5.4, 5.7 and 5.7 feet respectively.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
Yes			AWS Fish Pump 1
Yes			AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments:

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	1 yd <sup>2</sup>
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0 – 25 %
	X		Any oil seen in gatewells?	

Comments:

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service?
X			STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
	X		STSs inspected this week?
		X	STSs inspection results acceptable?
		X	VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: STS's were operating in Continuous-Run mode until 1230 on July 11 when they were changed to Cycle mode due to average sub-yearling Chinook and sockeye lengths being greater than 120 mm.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: PDW mechanical screen brush failed to complete its cycle on June 29. This failure appears to show at approximately the same time every year and may be temperature related. Separator operators have been manually running the mechanical screen brush four times per day to ensure debris is not collecting on the screen.

Collection Facility: Collection into raceways for transport began at 1500 on April 23.

Loading fish into raceways for barge transport ended at 1500 on July 30. The facility went to 100% sample for truck transport at that time.

Transport Summary: Every-other day barging transport ended with the July 30 barge. Every-other day truck transport began with the August 1 truck. A total of 648 fish were collected with 696 fish being transported during this reporting period.

Spillway Weir: RSW went into service at 00:01:00 on April 3. Summer Spill began at 00:00:00 on June 21.

**River Conditions**

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
41.5	35.6	17.0	16.5	68.5	68.0	6.0	3.7

\*Scrollcase temperatures.

**Other**

Inline Cooling Water Strainers: Cooling water strainers were inspected on June 11. Live fish included 2 juvenile lamprey. Mortalities included 10 juvenile lamprey and 9 juvenile salmon.

Avian Activity: Tailrace counts of foraging piscivorous birds at Lower Monumental Dam.

Gulls and pelicans were the predominant piscivorous bird species observed during fish ladder inspections this week.

Date	Time	Gulls	Cormorants	Terns	Grebes	Pelicans
7/26/2019	13:30	1	0	0	0	2
7/27/2019	13:00	1	0	0	0	4
7/28/2019	12:00	10	0	0	0	3
7/31/2019	11:00	10	0	0	0	2

\* Table shows tailrace observation conducted during Adult Fish Ladder inspections

Comments: Bird hazing efforts by USDA personnel ended at the end of the working day on June 2. Daily bird hazing effectiveness tailrace observations ended with the June 30 observation.

Invasive Species: No zebra or quagga mussels were observed during monitoring station inspections on July 6.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by PSMFC and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Lower Monumental Dam for this reporting period are reported below.

<b>Date</b>	<b>Sample (euthanized)</b>	<b>Collection*</b>
7/26/2019	44	88
7/27/2019	35	70
7/28/2019	49	98
7/29/2019	19	38
7/30/2019	47	94
7/31/2019	44	44
8/01/2019	32	32
Totals	270	464

\*Collection and sample numbers are the same as the facility when sampling at 100%

Fish Rescue/Salvage: No Fish Rescue/Salvage took place during this reporting period.

Research: PNNL's Fish Guidance Efficiency, Head Gate Study equipment was removed from the trash racks July 29-31.

**Project: Little Goose**

Biologists: Scott St. John and Richard Weis

Dates: July 26 – August 01, 2019

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

**Little Goose Unit Outages (OOS) and Return to Service (RTS)**

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	04/21/17	00:54	03/31/21	17:00	Spider and Upper Guide Bearing Repair
6	07/08/19	08:40	08/01/19	16:52	Annual Maintenance

Comments:

**Adult Fish Passage Facility**

Little Goose fish facility, Anchor QEA and/or Oregon Department of Fish and Wildlife staff inspected the adult fishway on July 28, 30 and August 01.

**Fish Ladder:**

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head $\leq$ 0.5'	
X			Fish Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X			Fish Ladder Cooling Water Pump in Service		
X			Fish Ladder Exit Cooling Water Pump Operating Satisfactorily		

Comments: None.

**Fishway Entrances and Collection Channel:**

Yes	No	Sill	Location	Criteria	Measurement
X			South Shore Entrance (SSE-1) Weir Depth	$\geq$ 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	$\geq$ 8.0'	
	X		South Shore Channel/Tailwater Differential	1.0' – 2.0'	0.9
		X	North Powerhouse Entrance (NPE-1) Weir Depth	$\geq$ 7.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	$\geq$ 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	$\geq$ 6.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	$\geq$ 6.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: The adult fishway continues to operate in manual mode. Project staff have struggled to maintain entrance criteria during spill. The SSE channel/tailwater differential was found out of criteria during the August 01 inspection. Subsurface water velocity was measured near NPE on July 11 using a Rickly velocity meter and averaged 3.4 feet per second.

**Auxiliary Water Supply System:**

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None.

### Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	
	X		Trash rack differentials measured this week?	
		X	Trash rack differentials acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: Trash rack differential for Units 1 was measured on July 28 and was in criteria. There is approximately 300 square feet of floating woody debris inside the trash shear boom in the immediate forebay.

ESBS/VBS:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
	X		VBSs differentials checked this week?
		X	VBSs differentials acceptable?

Comments: ESBS's were manually operated on July 3 and operated satisfactorily. VBS differential for Unit 1 was measured on July 28 and was in criteria.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	22
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Collection Facility: The juvenile bypass system is currently operating in criteria. Daily collection for condition sampling began on April 23 at 07:00. The last every other day barge departed on July 30 and every other day truck transport commenced on August 01.

Transport Summary: The collection and transportation facility operated within criteria this report period. A total of 2,533 fish were collected, of which 2,545 were transported via barge and 704 transported via truck, which includes fish collected on July 25. The descaling and mortality rates were 0.6% and 0.6% respectively. There were 3 adult lamprey removed from the separator, raceways, and sample and released one mile above the Dam at Little Goose Landing.

Spillway Weir: The adjustable spillway weir (ASW) was closed on July 23 at 15:17 per the guidance outlined in the Columbia Basin Teletype (CBT). The ASW will remain closed for the season.

### River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
34.2	30.6	10.5	8.5	68.2	67.3	6.0	5.1

\*Ladder temperature.

### Other

Inline Cooling Water Strainers: Cooling water strainers were last inspected on July 3 with no lamprey being observed. Inspections will resume in December per the Fish Passage Plan.

Avian Activity: Daily Piscivorous bird counts at Little Goose Dam will started on April 01.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
7-26	0730	16	1	0	0
7-27	0800	23	1	0	1
7-28	1230	28	4	0	0
7-29	1315	9	3	0	0
7-30	1305	14	2	0	0
7-31	1220	6	2	0	0
8-1	1300	15	4	0	0

Invasive Species: No zebra or Quagga mussels were observed.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by Oregon Department of Fish and Wildlife and Anchor, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Little Goose Dam for this reporting period are reported below.

Date	Sample	Collection*
7-26	263	526
7-27	553	1106
7-28	499	998
7-29	369	738
7-30	581	581
7-31	518	518
8-1	596	596
Totals	3379	5063

\*Collection and sample numbers are the same as the facility when sampling at 100%

Gas Bubble Trauma (GBT): The last gas bubble monitoring occurred on July 15.

Fish Rescue/Salvage: None.

Research: N/A

**Project: Lower Granite**

Biologists: Elizabeth Holdren

Dates: July 26-August 1, 2019

**Turbine Operation**

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 6 turbine units available for service (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

## Lower Granite Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
5	07/08	0722	08/01	1415	Annual Maintenance/OPTO22 upgrade

Comments:

**Adult Fish Passage Facility**

Lower Granite Corps biologist's and Anchor Environmental biologist's inspected the adult fish ladder July 26, 27, 29, and 31.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head $\leq$ 0.5'	
X			Fish Ladder Picketed Lead Differential	Head $\leq$ 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X			Fish Ladder Cooling Water Pumps in Service		
X			Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments: Fish ladder temperature control pumps remain in operation.

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
	X		South Shore Entrance (SSE-1) Weir Depth	$\geq$ 8.0'	7.7'
	X		South Shore Entrance (SSE-2) Weir Depth	$\geq$ 8.0'	7.7'
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	$\geq$ 8.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	$\geq$ 8.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	$\geq$ 7.0' or on sill	
			North Shore Entrance (NSE-2) Weir Depth	$\geq$ 7.0' or on sill	Closed
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: Since May 4 the fish ladder control system screen and local reading for the south shore channel/tailwater and depth over the SSEs have been inconsistent. SSE gates remain in local operation until Operation and District engineering can resolve the control system issues. SSEs were lowered to sill elevation following the our of criteria reading July 31.



NPE channel velocity sensor readings have consistently read below 1.5 fps for several weeks. Surface velocity is being verified using tape measure and stopwatch and found to be in criteria. Surface velocities and/or NSE velocities will be used until the fish ladder control system NPE velocity issues are resolved.

Current spill and powerhouse operations result in variable tailwater elevations at fish ladder entrances. Tailwater conditions may be impacting the fish ladder control systems ability to maintain criteria particularly at the NSE channel/tailwater head differentials.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
Yes			AWS Fish Pump 1
	Yes		AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments: AWS pump 1 remains in slow speed.

**Juvenile Fish Passage Facility**

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
X			Any debris seen in gatewells (% coverage)	<1%
	X		Any oil seen in gatewells?	

Comments:

ESBSs/VBSs:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments:

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: The collection channel is operating with sixteen of the 14" orifices and two 10" orifices open to maintain optimal flume flow at current forebay elevation. The north makeup water valve remains in local control due to an automatic control motor hardware failure. Intermittent issues with local and remote operation of orifices for back flushing continue to be observed. Problems are reported to operations when they are identified.

Collection Facility: The facility is in collection mode.

Transport Summary: Every-other-day barge transport ended with the last barge departing Lower Granite July 30. The first truck departed for transport to below Bonneville Dam August 1.

Spillway Weir: Summer spill operation continues.

### River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
34.4	31.0	18.6	17.4	65.5	64.0	5+	5+

\*Cooling water intake temperature.

### Other

Inline Cooling Water Strainers: Unit cooling water strainers were inspected July 31. Two live lamprey were recovered.

Invasive Species: There were 2511 Siberian prawns collected in the sample this week. Of these, 2107 were live collected and euthanized and 404 were mortalities when sampled.

Avian Activity: Biologist daily piscivorous bird counts at Lower Granite Dam are listed below.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
26-Jul	1445	1	9	0	0
27-Jul	1230	2	9	0	0
28-Jul	1045	1	11	0	0
29-Jul	1215	1	0	0	0
30-Jul	0630	0	0	0	0
31-Jul	1036	2	9	0	0
1-Aug	0735	4	0	0	0

Gas Bubble Trauma (GBT) Monitoring:

Adult Fish Trap Operations: The adult trap is operating Monday-Friday at a 28% sample rate.

Fish Rescue/Salvage:

Research:

National Marine Fisheries Service (NMFS) PIT tagging of Adult Wild Chinook and Adult Steelhead for ISEMP-Related Dispersal Monitoring:

The goal of this project is to PIT tag up to 4000 unclipped adult Chinook and 4000 unclipped adult steelhead collected in the adult trap daily sample for dispersal monitoring.

National Marine Fisheries Service (NMFS) Ancillary Adult Passage Monitoring:

Fish that were PIT as juveniles at LWG are monitored as returning adults through the river and LWG facility. For each returning adult the following is estimated; 1) passage time between sets of detection PIT tag coils, 2) whether

the fish was handled at the adult trap, 3) duration the fish was held at the adult trap, 4) overall passage time from ladder entrance to exit, 5) whether the turnpool gate was open or closed during passage. This will be the last year of this evaluation.

Sampling of Steelhead, Chinook salmon, and Sockeye salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating steelhead, spring/summer Chinook salmon, and sockeye salmon are collected from the adult trap beginning April 4 through December 15. The goal is to collect 5-20% of adult steelhead, spring/summer Chinook salmon, and sockeye salmon ascending the ladder April 4-December 15. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. All natural origin adult steelhead and spring/summer Chinook salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some steelhead and spring/summer Chinook salmon may be radio-tagged or spaghetti-tagged. This information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs.

PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be incidentally collected as part of the normal adult trap daily sample as well as the recaptured previously PIT tagged using adult SbyC system. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder.