

1. McNary

Yes	No	Location	Criteria	Measurements
	X	Washington Count Station Differential	0.0' to 0.5'	0.2' to 0.9'

At the Washington shore exit, weir 339 failed on August 14, at 0935 hours. With a failed encoder, weir was set to bypass mode. This allows the control system to regulate the exit without this weir moving. Multiple exit alarms occurred before the exit was reset. A regulating weir alarm came in and was reset on August 9. The out of criterion count station differential also occurred on August 9. The general maintenance staff came in twice that day to clean the leads. Multiple picketed lead differential alarms were reset after. After this, besides Saturday, August 10, general maintenance also came in Sunday, August 11, for the leads. A couple of picketed lead differential alarms were reset on August 11.

Yes	No	Sill	Location	Criteria	Measurements
	X		NFEW3 Weir Depth	≥ 8.0'	7.9' to 8.0'

NFEW3 were out of criteria on August 9 and 14. These out of criterion point may be due to low tailwater elevations and calibration drifts.

Fish pump 1 remained out of service for a scheduled 5-year overhaul. Return to service dates are subject to change. For the return of units 11 and 12, during switching, as mentioned below, fish pumps 2 and 3 were offline on August 15, from 1201 to 1239 hours.

2. Ice Harbor

South shore AWS pump #6 has been out of service since March 1, 2024, due to high vibration readings coming from the motor and gearbox. The gearbox is being replaced with a refurbished one.

Yes	No	NA	Item	Number open and in service
	x		Dewaterer and cleaning systems operating satisfactory?	

The replacement actuator for the water regulating weirs in the collection channel is in local control due to a problem with the actuator being undersized for this application. The actuator will be rebuilt to enable it to work in automatic mode. The weirs are being operated at the actuator to adjust the water level as needed until the problem can be fixed.

3. Lower Monumental

4. Little Goose

5. Lower Granite Dam

Fish ladder exit cooling pumps were cycled off/on when switching in and out of station service power as follows:

DATE	TIME OFF	TIME ON
08/12	0808	0825
08/12	1450	1524
08/13	1227	1240
08/13	1452	1509
08/14	0550	0605

Yes	No	Sill	Location	Criteria	Comments
	X		South Shore Channel/Tailwater Differential	1.0' – 2.0'	0.8'
	X		North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	0.7', 0.9'
	X		North Shore Entrance (NSE-1) Weir Depth	≥ 7.0' or on sill	
	X		North Shore Entrance (NSE-2) Weir Depth	≥ 7.0' or on sill	6.9,' 6.9'
	X		North Shore Channel/Tailwater Differential	1.0'–2.0'	0.9', 0.9', 0.8'
	X		Collection Channel Surface Velocity	1.5 – 4.0 fps	1.3, 1.1, 1.4, 1.0, 1.1

Fish ladder control system operation and configuration is an ongoing issue that began when the system was installed in 2016. LWG is moving forward with inhouse design and install of fish ladder control system based on the system used at LMN. Efforts of the electrical crew continue to bring the ladder back into criteria however the control system drifts out of calibration shortly after. The fish ladder was designed to operate between 633' and 638' MSL with a minimum operating elevation of 633.0'.

AWS Pump 1 remains in slow mode due to the inability to operate in fast mode while operating at MOP elevation. The fish ladder was designed to operate within the 633' and 638' MSL range with a minimum operating elevation of 633.0'. AWS pump 2 was returned to service August 1 at 1208 hours. AWS pump 2 supplies the collection channel with the same flow as pump 1 in fast. It is recommended that pump 2 be brought online with AWS pump 1 in standby as soon as operationally possible. An MOC has been submitted to tentatively conduct work August 19 to bring AWS 2 back online.

Fish Ladder AWS pumps were cycled off/on when switching in and out of station service power as follows:

DATE	TIME OFF	TIME ON
08/12	0814	0819
08/12	1504	1517
08/13	1132	1138
08/13	1233	1236
08/13	1459	1502
08/14	0556	0559

**U.S. ARMY CORPS OF ENGINEERS
WALLA WALLA DISTRICT
FISH FACILITIES WEEKLY REPORT
#24-2024**

Project: McNary

Biologist: Bobby Johnson and Paul Bertschinger

Dates: August 9-15, 2024

Turbine Operation

Yes	No	Turbine Unit Status	Hard	Soft
	X	All 14 turbine units available for service. (see table & comments below for details).		
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Table 1. McNary Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
14	5/13	1232	11/18	NA	Isophase replacement and headgate work
13	5/21	0955	11/18	NA	Isophase replacement and headgate work
3 & 4	5/29	0634	11/15	NA	Control system upgrades
11 & 12	7/8	0630	8/15	1252	Transformer 6 re-gasketing
2	8/12	0655	8/15	1733	Annual maintenance
1, 2 & 5	8/13	1004	8/13	1144	ESBS camera inspections, rotated through units
9 & 10	8/15	1204	8/15	1228	Switching in preparation of units 11 and 12 return

Comments: RTS dates are subject to change. The hard one percent criteria remained in place. The sawtooth unit priority pattern for temperature abatement continued.

Adult Fish Passage Facilities

McNary fisheries staff performed measured inspections of the adult fishways on August 9, 11 and 12. Adult fish counting, and video review of nighttime lamprey passage continued.

Fish Ladder Exits:

Yes	No	Location	Criteria	Measurements
X		Oregon Exit	Head over weir 1.0' to 1.3'	1.0'
X		Oregon Count Station Differential	0.0' to 0.5'	0.2'
X		Washington Exit	Head over weir 1.0' to 1.3'	1.0' to 1.1'
	X	Washington Count Station Differential	0.0' to 0.5'	0.2' to 0.9'

Comments: Debris loads were very light to light (mostly woody material and aquatic vegetation) near the Oregon exit and minimal (mostly aquatic vegetation) near the Washington exit. Due to increased aquatic vegetation, the general maintenance staff has been coming in on Saturday to clean the picketed leads at both exits.

At the Washington shore exit, weir 339 failed on August 14, at 0935 hours. With a failed encoder, weir was set to bypass mode. This allows the control system to regulate the exit without this weir moving. Multiple exit alarms occurred before the exit was reset. A regulating weir alarm came in and was reset on August 9. The out of criterion count station differential also occurred on August 9. The general maintenance staff came in twice that day to clean the leads. Multiple picketed lead differential alarms were reset after. After this, besides Saturday, August 10, general

maintenance also came in Sunday, August 11, for the leads. A couple of picketed lead differential alarms were reset on August 11.

At the Oregon shore exit, after picketed lead cleaning, two lead differential alarms were reset on August 10.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Oregon Entrance Head Differential	1.0' – 2.0'	1.4' to 1.5'
X			NFEW2 Weir Depth	≥ 8.0'	8.0' to 8.1'
	X		NFEW3 Weir Depth	≥ 8.0'	7.9' to 8.0'
X			South Oregon Entrance Head Differential	1.0' – 2.0'	1.5'
X			SFEW1 Weir Depth	≥ 8.0'	8.0' to 8.2'
X			SFEW2 Weir Depth	≥ 8.0'	8.0' to 8.3'
X			Oregon Collection Channel Velocities	1.5 to 4.0 fps	1.9 fps
X			Washington Entrance Head Differential	1.0' – 2.0'	1.4' to 1.6'
X			WFE2 Weir Depth	≥ 8.0'	10.1' to 10.5'
X			WFE3 Weir Depth	≥ 8.0'	8.8' to 9.3'

Comments: NFEW3 were out of criteria on August 9 and 14. These out of criterion point may be due to low tailwater elevations and calibration drifts.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Blade angle	Auxiliary Water Supply System (AWS)
X				WA shore Wasco County PUD Turbine Unit
	X			WA shore Wasco PUD Bypass
		X	NA	Oregon Ladder Fish Pump 1, return to service August 30
X*			22° to 23°	Oregon Ladder Fish Pump 2
X*			24° to 25°	Oregon Ladder Fish Pump 3
X				OR North Powerhouse Pool from juvenile fishway

*Comments: Fish pump 1 remained out of service for a scheduled 5-year overhaul. Return to service dates are subject to change. For the return of units 11 and 12, during switching, as mentioned above, fish pumps 2 and 3 were offline on August 15, from 1201 to 1239 hours.

Juvenile Fish Passage Facility

The juvenile system alternates between primary and secondary bypass every 24 hours at 0700 hours. There were no interruptions in this schedule. The sawtooth unit pattern remained in effect. Sample tank mortality remained below three percent.

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	Very light to light near the powerhouse
X			Gatewell drawdown measured this week?	Daily
X			Gatewell drawdown acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments: The powerhouse debris was very light. Debris (woody material and aquatic vegetation) did move from the Oregon shore and back. Spillway debris remained minimal due to much of it being spilled. New debris loads (mostly aquatic vegetation) were minimal.

No trash rack cleaning is scheduled.

The emergency bulkhead remained in 14A slot. The slots in unit 7, 11C slot, 12A and 12B slots remained covered. Algae blooms remained in units 3, 4 and 13 along with slots 12C and 14C slot. Blooms also began in slots 11A and 11B this week. The blooms in 11A, 11B and 12C slot dissipated when the units returned to service on August 15.

Extended-length submersible bar screen (ESBSs)/Vertical barrier screen (VBSs):

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
X			ESBSs inspected this week?
X			ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: ESBS's are installed in all units except 14A slot. With the emergency bulkhead in 14A slot, the ESBS remained uninstalled. The control program for the fish screens in unit 10 is not currently communicating with the panel view on the 8th floor. When the unit is in service, the brush cycle sequences will be monitored in the control room until repairs can occur in the future. With units 3, 13 and 14 being out of service, the ESBS's remained in manual mode so the brush cycle sequence would not occur. Camera inspections occurred in units 1, 2 and 5 on August 13. No issues were found. Testing of ESBS screen brush programming continued with the screens in unit 4.

Daily VBS monitoring continued, and no high differentials were recorded. Two screens were cleaned on August 15. VBS inspections, which included cleaning, occurred in unit 1, 5C slot and 7C slots on August 12, 13 and 15, respectively. During all cleaning and inspections no fish were observed.

Orifices, Collection Channel, Dewatering Structure, and Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	42
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: With headgate testing in 14A slot, the orifices in unit 14 and in 13C slot remained closed. Make-up north orifices were opened in 12B, 12C, 13A, and 13B slots. Orifices were adjusted for VBS cleaning and inspection as required. The channel elevation and the transition screen brush continued to be monitored.

Bypass Facility:

Yes	No	NA	Item
X			Sample gates on?
		X	PIT-tag sampling system on?

Comments: The sample system is being used when in secondary bypass for sample collection. The PIT tag system will not be in use again this season, which is similar to past years.

There were 38 juvenile lamprey and 2,145 smolts bypassed with subyearling Chinook being the dominate race/species this week. Juvenile shad were the predominate species seen overall.

TSW Operations: The TSW's in bays 19 and 20 remained open. Both TSW's are attached to a hoist. New this year, both TSW's will remain open through the spill season. No switch to standard gates occurred.

River Conditions

Table 2. River Conditions at McNary Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
133.2	111.4	45.2	20.2	71.4	70.2	6.0	6.0

Comments: The above data is from the smolt monitoring staff, with the data day starting at 0700 hours. Water clarity comes from the control room.

The smolt monitoring staff continues to monitor water temperature throughout the juvenile system. Their results are stated daily and weekly in separate reports. Adult ladder water temperatures are reported by an automated system year-round.

The summer spill season continued with 20 kcfs (both TSW's open in bays 19 and 20) being spilled. However, due to flow in excess of available powerhouse capacity, the spill volume was generally above that value. The FPP spill pattern is being followed except as described next. As has been stated before, rehabilitation of spillgate wall dogs is critical. As part of this, downstream wall dogs were installed in bay 22 on August 6 and 7. The bay was closed for safety for 9 and 7 hours, respectively. The downstream wall dogs were removed from bay 17 on August 8 and 12. The bay was closed for safety for 8 and 4 hours, respectively. When bays 17 and 22 were part of the spill pattern on a given day, the next available bay(s) were opened to compensate for the closures of bays 17 or 22.

Rehabilitated of downstream wall dogs continued. The dogs for bay 21 will be reinstalled in the near future. Also, dogs maybe removed from bay 14 next week.

Other

Inline Cooling Water Strainers: The next cooling water strainer inspections will occur on December 3.

Avian Activity: Bird counting continued, and the results are reflected in Table 3 below.

Table 3. McNary Project's Daily Avian Count.

Date	Zone	Gull	Cormorant	Tern	Pelican	Grebe
August 9	Spill	0	0	4	0	0
	Powerhouse	0	0	0	0	0
	Outfall	17	0	6	0	0
	Forebay	2	0	0	4	0
August 10	Spill	4	0	1	0	0
	Powerhouse	0	0	0	0	0
	Outfall	12	0	9	0	0
	Forebay	2	0	0	2	0
August 11	Spill	2	0	0	1	0
	Powerhouse	0	0	0	0	0
	Outfall	15	0	0	0	0
	Forebay	0	0	0	3	0
August 12	Spill	125	1	0	0	0
	Powerhouse	0	0	0	0	0
	Outfall	16	1	0	0	0
	Forebay	0	0	0	1	0
August 13	Spill	375	8	0	4	0
	Powerhouse	0	0	0	0	0
	Outfall	31	1	0	0	0
	Forebay	0	0	0	0	0
August 14	Spill	22	0	0	1	0
	Powerhouse	1	0	0	0	0
	Outfall	16	0	0	0	0
	Forebay	0	0	0	1	0
August 15	Spill	54	0	0	2	0
	Powerhouse	4	0	0	0	0
	Outfall	35	0	0	0	0
	Forebay	0	0	0	0	0

In the spill zone, pelicans, cormorants, ospreys, and terns were noted in low numbers. Most birds were feeding though some were roosting. Gull numbers increased with juvenile shad numbers. The gulls were roosting and feeding.

In the powerhouse zone, a few roosting gulls were noted.

In the outfall zone, gulls, cormorants, and terns were noted roosting. Only gulls showed an increase in numbers. No feeding was observed. Occasionally, the ospreys still roosted on the pipe.

For the forebay zone, a few gulls and pelicans were observed. Only the pelicans were feeding. A few terns, gulls, pelicans, cormorants, and ospreys were noted outside the zone.

The LRAD remains out of service. Reinstalling the unit may occur in the near future.

The laser on the navigation lock wing wall opposite the outfall was shipped to the manufacture for a repair evaluation on August 9.

The two distress calls on the navigation lock wing wall remained in service and have been functioning well.

There is no other hazing.

Invasive Species: The next mussel station examinations will occur in August 21.

Siberian Prawn: Four prawns were observed in the sample this week. This brings the season total to 14.

Fish Rescue/Salvage: None occurred this week.

Research: PNNL removed their powerhouse equipment and winterized their tanks at the tagging site this week. Their trailers and spillway equipment will be moved at a later.

For a CRITFC study, there were tissue samples removed from five juvenile lamprey collected at the facility this week. The yearly total is 499 fish, which were returned to the river unharmed.

Owing to the lack of fish, the last GBT sampling day was August 12. Due to previous high mortality, the fish examined were immediately release back into the river. This resulted in no mortalities. The data was reported the next day. Eleven juvenile shad were also examined. No smolts or shad showed signs of trauma.

Project: Ice Harbor

Biologist: Ken Fone

Biological Science Technician: Ben McArthur

Dates: August 9-15, 2024

Turbine Operation

Yes	No	Turbine Unit Status
	x	All 6 turbine units available for service (see table & comments below for details).
x		All available turbine units are operated in accordance with Appendix C of the Fish Passage Plan

Ice Harbor Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
1	6/27/23	0708	---	---	Turbine runner replacement and stator rewind
5	7/15/24	0700	8/14/24	1532	Annual maintenance

Comments: None.

Adult Fish Passage Facility

Ice Harbor Fish Facility staff inspected the adult fishways on August 12, 13, 14.

Fish Ladders:

Yes	No	Location	Criteria	Measurements
x		North ladder exit differential	Head \leq 0.3'	
x		North ladder picketed lead differential	Head \leq 0.3'	
x		North ladder depth over weirs	Head over weir 1.0' to 1.3'	
x		South ladder exit differential	Head \leq 0.3'	
x		South ladder picketed lead differential	Head \leq 0.3'	
x		South ladder depth over weirs	Head over weir 1.0' to 1.3'	

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
x			South fish entrance (SFE-1) weir depth	\geq 8.0' or on sill	
x			South fish entrance channel/tailwater differential	1.0' – 2.0'	
x			South shore channel velocity	1.5 – 4.0 fps	
x			Central fish entrance (CFE-2) weir depth	\geq 8.0' or on sill	
x			Central fish entrance channel/tailwater differential	1.0' – 2.0'	
x			North fish entrance (NFE-1) weir depth	\geq 8.0' or on sill	
x			North fish entrance channel/tailwater differential	1.0' – 2.0'	

Comments: None.

Auxiliary Water Supply (AWS) System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System
6 pumps	1 pump	1 pump	Status of the 8 south shore AWS pumps
2 pumps	0-1 pump	0-1 pump	Status of the 3 north shore AWS pumps

Comments: South shore AWS pump #6 has been out of service since March 1, 2024, due to high vibration readings coming from the motor and gearbox. The gearbox is being replaced with a refurbished one.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
x			Forebay debris load acceptable? (amount)	Average of 1 square yards
x			Gatewell drawdown measured this week?	
x			Gatewell drawdown acceptable	
x			Any debris seen in gatewells (% coverage)	0-3% coverage
	x		Any oil seen in gatewells?	

Comments: None.

Submersible Traveling Screens (STSs) / Vertical Barrier Screens (VBSs):

Yes	No	NA	Item
x			STSs deployed in all slots that are in service?
	x		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
	x		STSs inspected this week?
		x	STSs inspection results acceptable?
		x	VBSs differentials checked this week?
		x	VBSs differentials acceptable?

Comments: None.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
x			Orifices operating satisfactory?	20
	x		Dewaterer and cleaning systems operating satisfactory?	

Comments: The replacement actuator for the water regulating weirs in the collection channel is in local control due to a problem with the actuator being undersized for this application. The actuator will be rebuilt to enable it to work in automatic mode. The weirs are being operated at the actuator to adjust the water level as needed until the problem can be fixed.

Juvenile Fish Facility: The fish facility is in primary bypass mode.

Fish Sampling: Juvenile fish sampling has ended for the season.

Removable Spillway Weir (RSW): Summer spill for fish passage is occurring. The RSW is closed due to project outflows being below 30 kcfs.

River Conditions

River conditions at Ice Harbor Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
29.9	23.7	9.0	9.0	73	72	8.0	6.0

*Unit 1 scroll case temperature.

Other

Inline Cooling Water Strainers: Cooling water strainer differential pressure is routinely monitored. The strainers will be cleaned if there is indication of clogging caused by debris or juvenile shad, and inspection results will be reported.

Avian Activity: There were moderate numbers of piscivorous birds observed around the dam. Most of the birds were roosting on Eagle Island.

Invasive Species: No exotic species that are new to the area have been found.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by the fish sampling contractor, frozen and properly disposed of in a landfill. Fish sampling has ended for the season.

Fish Rescue/Salvage: None.

Research: No on-site research is occurring.

Project: Lower Monumental

Biologists: Denise Griffith and Raymond Addis

Dates: August 2 - 8, 2024

Turbine Operation

Yes	No	Turbine Unit Status
	X	All 6 turbine units available for service (see table & comments below for details).
X		Available turbines operated within 1% peak efficiency? Constraint in effect.

Comments: See Unit Outages and Return to Service comments below.

Lower Monumental Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
Unit 1	8/07/24	0720	8/07/24	0910	STS Inspection
Unit 2	8/06/24	0745	8/06/24	1010	STS Inspection
Unit 3	8/06/24	1015	8/06/24	1305	STS Inspection
Unit 4	8/07/24	0925	8/07/24	1145	STS Inspection
Unit 5	5/01/24	0624	8/31/24	ERTS	T2/Rooftop bus out of service due to BPA Line outage
Unit 6	5/01/24	0624	8/31/24	ERTS	T2/Rooftop bus out of service due to BPA Line outage

Comments: BPA line tripped at 0624 hours on May 1. Units 5 and 6 remain out of service until T2 line is repaired. Estimated return to service date is August 31.

Adult Fish Passage Facility

Lower Monumental fish facility and EAS staff inspected the adult fishways on August 2, 3, 4 and 5.

Fish Ladder Exit:

Yes	No	Location	Criteria	Measurements
X		North Ladder Exit Differential	Head \leq 0.5'	
X		North Ladder Picketed Lead Differential	Head \leq 0.4'	
X		North Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X		South Ladder Exit Differential	Head \leq 0.5'	
X		South Ladder Picketed Lead Differential	Head \leq 0.3'	
X		South Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	

Comments: None.

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			North Shore Entrance (NSE-1) Weir Depth	≥ 8.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	≥ 8.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
		X	South Powerhouse Entrance (SPE-1) Weir Depth	≥ 8.0' or on sill	
		X	South Powerhouse Entrance (SPE-2) Weir Depth	≥ 8.0' or on sill	
X			South Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
		X	South Shore Entrance (SSE-1) Weir Depth	≥ 8.0'	
		X	South Shore Entrance (SSE-2) Weir Depth	≥ 6.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	

Comments: South Powerhouse Entrance SPE-1 weir was at sill during all inspections with readings of 5.8, 6.1, 6.1 and 6.2 feet respectively. South Powerhouse Entrance SPE-2 weir was at sill during all inspections with 5.8, 6.1, 6.1 and 6.2 feet respectively. South Shore Entrance SSE-1 weir was at sill during all inspections with readings of 6.6, 7.1, 6.8 and 7.0 feet respectively.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: None

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	7 yrd ²
X			Gatewell drawdown measured this week?	
X			Gatewell drawdown acceptable	
X			Any debris seen in gatewells (% coverage)	0 – 3%
		X	Any oil seen in gatewells?	

Comments: None

STSs/VBSs:

Yes	No	NA	Item
X			STSs deployed in all slots and in service?
	X		STSs in continuous-run mode (Note: if not, then STSs are in cycle-run mode)?
X			STSs inspected this week?
X			STSs inspection results acceptable?
		X	VBS screens checked this week?
		X	VBS screens acceptable?

Comments: STSs were running on cycle-run mode due to the average sub-yearling Chinook and sockeye lengths being greater than 120 mm. The STSs were inspected between August 6 and 7. All were in good working condition.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
	X		Orifices operating satisfactory?	18
	X		Dewaterer and cleaning systems operating satisfactory?	

Comments: None.

Collection Facility: The facility switched from running in primary bypass for one day and secondary bypass for condition sampling the next day, every-other day, to running in primary bypass for two days and secondary bypass for condition sampling the third day, every-third day, starting August 2. A total of 44 fish were collected with 44 being bypassed.

The flush water pipe for the truck transport recovery tank was removed during a repair and the truck tank cannot be used until this is addressed.

Due to the issues with the lamprey overshoot system, raceways 2 through 4 were drained to take the pressure off the system. An engineer from the powerhouse said the lamprey overshoot pipe adds so much water to the main flume piping that it creates a pressurized system. This issue will move forward with plans to work on funding and plans to repair in the future. It is not deemed as a critical issue and will not impede fish passage.

The HVAC system for the second floor of the JFF building is no longer functioning. Two swamp cooler type devices were placed in the wet lab to lower the temperature on the second floor until the system can be repaired. The parts arrived to replace/repair the second floor's HVAC this week and work started on August 8.

Machine guards to cover sample gates finished being installed on August 8.

Transport Summary: Transport at Lower Monumental has ended for the season.

Spillway Weir: Late Summer 8 kcfs spill continues.

River Conditions

River conditions at Lower Monumental Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature (°F)*		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
30.5	22.3	8.1	7.9	70.1	70.0	6.3	5.8

*Scrollcase temperatures.

Other

Inline Cooling Water Strainers: Cooling water strainers inspections are done until December.

Avian Activity: Tailrace counts of foraging piscivorous birds at Lower Monumental Dam began on April 1.

Date	Time	Gulls	Cormorants	Terns	Grebes	Pelicans
8/2/2024	1515	15	1	0	0	2
8/3/2024	1330	15	3	0	0	3
8/4/2024	1330	24	9	0	0	0
8/5/2024	1115	14	2	0	0	0
8/6/2024	1100	6	2	2	0	0
8/7/2024	920	10	0	0	0	2

8/8/2024	1030	14	1	0	0	0
----------	------	----	---	---	---	---

Comments: Bird hazing by USDA personnel ended on June 30.

Invasive Species: Zebra or quagga mussel traps were examined on August 2. None were found.

Siberian Prawn: Siberian prawns collected in the sample at the Juvenile Fish Facility are humanely euthanized by EAS personnel, frozen and properly disposed of in a landfill. Daily and total Siberian prawn counts at Lower Monumental Dam for this reporting period are reported below.

Date	Sample (euthanized)	Collection*
8/2/2024	83	83
8/3/2024	---	---
8/4/2024	---	---
8/5/2024	66	66
8/6/2024	---	---
8/7/2024	---	---
8/8/2024	46	46
Total	195	195

*Collection refers to extrapolated values based on sampling percent.

Fish Rescue/Salvage: No fish rescues were performed during this reporting period.

Research: The collection of lamprey for the PNNL study of the behavior and survival of Pacific lamprey has ended.

GBT sampling has been concluded for the 2024 season.

The Nez Perce steelhead kelt study and rehabilitation collection ended on for the season.

Temperature Probes: The adult passage temperature probes operated correctly during this reporting period.

Project: Little Goose Dam

Biologist: Deb Snyder, Brooke Gerard

Dates: August 9 – August 15, 2024

Turbine Operation

Yes	No	Turbine Unit Status
	X	All 6 turbine units available for service? (See table and comments below for details)

*All available turbine units are operated in accordance with Appendix C of the Fish Passage Plan

Little Goose Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
2	7/29/2024	06:30	8/15/2024	1552	Unit annual maintenance
5	4/14/2017	14:11	11/30/2024	ERTS	Spider and upper guide bearing repair.

Comments: Contractual obligations, performance issues, and projected flow data once again realigned the Unit 5 ERTS date into late fall 2024.

Adult Fish Passage Facility

EAS Bio staff inspected the adult Fishway on August 10, 12, 13.

Fish Ladder:

Yes	No	NA	Location	Criteria	Measurements
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X			Fish Ladder Cooling Water Pumps in Service		
X			Fish Ladder Exit Cooling Water Pumps Operating Satisfactorily		

Fishway Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Measurements
X			South Shore Entrance (SSE-1) Weir Depth	\geq 8.0'	
X			South Shore Entrance (SSE-2) Weir Depth	\geq 8.0'	
X			South Shore Channel/Tailwater Differential	1.0' – 2.0'	
		X	North Powerhouse Entrance (NPE-1) Weir Depth	\geq 7.0' or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	\geq 7.0' or on sill	
X			North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	
X			North Shore Entrance (NSE-1) Weir Depth	\geq 6.0' or on sill	
X			North Shore Entrance (NSE-2) Weir Depth	\geq 6.0' or on sill	
X			North Shore Channel/Tailwater Differential	1.0'–2.0'	
X			Collection Channel Surface Velocity	1.5 – 4.0 fps	

Comments: The adult fishway was returned to service on February 15. The AWS pumps returned to service on February 22. The Collection Channel Surface Velocity is measured at NPE. The fish system control program is proving unreliable and inadequate to balance the adult fishway in “automated” mode. Biologist personnel are manually adjusting and balancing the adult fishway with increasing frequency. EAS Bio personnel report the FSC board reflects weir and channel height readings with notable discrepancies compared to actual physical hand measurements taken during inspection periods. FSC board readings of SSE Channel elevation continue to report discrepancies an average of 8.2 feet below physical staff gauge measurements documenting the same channel

elevation. Criteria evaluations default to physical staff gauge measurements in this area. All other channel staff gauge and NPE and NSE FSC board channel heights reflect similar and corresponding readings. On May 29 the new fish ladder cooling pump installation was completed. The newly installed pump unit was commissioned for seasonal use June 9 at 1420 hours upon reaching criteria per FPP 2.4.2.14.i the prior evening of June 8 at 1900 hours.

Auxiliary Water Supply System:

Operating Satisfactory	Standby	Out of Service	Auxiliary Water Supply System (AWS)
X			AWS Fish Pump 1
X			AWS Fish Pump 2
X			AWS Fish Pump 3

Comments: Fish pumps 1 and 3 were returned to service February 22. Fish pump 2 was returned to service on February 28.

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comment
X			Forebay debris load acceptable? (amount)	High 25 ft ² - Low 0 ft ²
	X		Gatewell drawdown measured this week?	
		X	Gatewell drawdown acceptable	
X	X		Any debris seen in gatewells (% coverage)	8/13- 2C:1%
	X		Any oil seen in gatewells?	

Comments: The forebay had minimal floating debris inside the trash shear boom with the highest measurement occurring on August 13 at 20 ft². The overall total forebay debris high occurred on August 10 at 25 ft².

ESBS/VBS:

Yes	No	NA	Item
X			ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
	X		VBSs differentials checked this week?
		X	VBSs differentials acceptable?
	X		VBSs inspected this week?

Comments: Installation of ESBS's were fully functional and deployed the week of March 18. The third round of gatewell camera inspections was completed July 8-11. Unit 2 annual camera inspections were completed July 31.

Orifices, Collection Channel, Dewatering Structure, and Flume:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	19
X			Dewaterer and cleaning systems operating satisfactory?	

Comments: The juvenile bypass system was watered up on March 7 without incident.

Collection Facility: The juvenile collection facility was successfully watered up on March 20. Every other day collection for condition monitoring in conjunction with secondary bypass commenced March 25 with the first sample being conducted on March 26. Every day collection began April 23 coinciding with barge transportation operations. Every-other day collection was initiated on July 8 due to water temperatures above 68°F. Every day collection resumed at 0700 on August 1st corresponding with the start of every other day trucking operations as per the FPP. During this reporting period a total of 624 fish were collected, 674 were trucked, 0 were bypassed, and

there were 11 sample or facility mortalities. The descaling and mortality rates were 3.6% and 1.8%, respectively. The collection and transport facility operated within criteria; 48 adult lampreys were removed from the collection facility during this report period.

Transport Summary: Collection for fish transportation began April 23 with the first barge departure on April 24. Every day barging continued through May 16 upon transition to every other day barge operations. The last barge for the season departed on June 19. Collection for truck transport operations began August 1 with the first truck departure on August 3.

Spillway Weir: Little Goose began operation of the adjustable spillway weir (ASW) on March 1 to facilitate passage of adult steelhead overshoots. On March 21, the ASW transitioned to 625 ft. crest height spilling 24 hours 7 days per week per CBR LGS R 022724 1735. Spring spill operations began on April 3 spilling 24/7 up to the 125% gas cap. On April 16th we hit the 50 adult Chinook threshold at Ice Harbor and began spilling at performance spill (30% of outflow) from 0400 to 1200 to facilitate adult fish passage. On May 14 the ASW was positioned to Low Crest. On June 13 the ASW position changed to High Crest. Summer spill operations began as scheduled on June 21. On August 1 at 00:15 hours the ASW was closed per FPP Chapter 8 section 2.3.2.7.e.i, diminished outflows below the 35 kcfs threshold.

River Conditions

River conditions at Little Goose Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
29.0	23.1	6.6	6.4	70.4	69.6	6.0	5.0

*Ladder temperature.

Other

Inline Cooling Water Strainers: Inline cooling strainer inspections commenced on December 1, 2023. Inspections will continue in accordance with the Fish Passage Plan (FPP) and results will be submitted to the District.

Avian Activity: Daily piscivorous bird counts at Little Goose Dam are scheduled to begin April 1, while USDA-APHIS bird abatement contract services are in place.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
8-9	0730	0	0	0	0
8-10	1230	0	0	0	0
8-11	1140	0	0	0	0
8-12	1350	0	0	0	0
8-13	1130	1	0	0	0
8-14	0745	2	0	0	0
8-15	1115	0	0	0	0

Invasive Species: No invasive species have been observed on the mussel station.

Siberian Prawn: Juvenile fish collection will begin March 25. Siberian prawns collected in the sample at the Juvenile Fish Facility will be humanely euthanized by Oregon Department of Fish and Wildlife and EAS Bio personnel, frozen and properly disposed of in a landfill.

Date	Sample	Collection*
8-9	66	66
8-10	125	125
8-11	138	138
8-12	312	312
8-13	448	448
8-14	427	427
8-15	452	452
Totals	1,968	1,968

*Collection and sample numbers are equal when sample rates change to 100%

Gas Bubble Trauma (GBT): Oregon Department of Fish and Wildlife began GBT monitoring on April 4 and completed final monitoring activities on July 23.

Fish Rescue/Salvage: No fish rescue activities took place during the report period.

Research: The Nez Perce Tribe (NPT) commenced adult steelhead kelt collection efforts on March 27 and concluded July 1.

Project: Lower Granite

Biologists: Elizabeth Holdren and Steve Lee

Dates: August 9-15, 2024

Turbine Operation

Yes	No	Turbine Unit Status		
	X	All 6 turbine units available for service (see table & comments below for details).	Hard	Soft
X		Available turbines operated within 1% peak efficiency? Constraint in effect.	X	

Lower Granite Unit Outages (OOS) and Return to Service (RTS)

Unit	OOS		RTS		Outage Description
	Date	Time	Date	Time	
6	07/08	0700	08/09	1247	Annual
2	08/05	0705			Annual
4	08/08	1516	***		Brake solenoid issues – Forced Outage
4	08/12	0606	***		***Unit 4 “rolled” into Planned Outage for T1 work at this time along with other planned outage units
1, 3, 4, 5, 6	08/12	0606	08/12	1625	T1 Transformer
1, 3, 4	08/14	0606	08/16	1726	T1 Transformer
5, 6	08/14	0606	08/14	1816	T1 Transformer
5, 6	08/15	0558	08/15	1476	T1 Transformer

Comments: LWG Doble testing scheduled for August 12-16 as noted in Appendix A, *Section 9.1.3 Doble Testing* of the 2024 Fish Passage Plan was canceled due to a faulty setting on a relay installed this spring. Annual transformer PMs and contracted installation of transformer monitoring equipment were also scheduled during this outage period to minimize outages required during the fish passage season are being completed as scheduled.

Adult Fish Passage Facility

Lower Granite Biologists and EAS staff inspected the adult fishway August 9, 10, 12, 14 and 15.

Fish Ladder:

Yes	No	NA	Location	Criteria	Comments
X			Fish Ladder Exit Differential	Head \leq 0.5'	
X			Fish Ladder Picketed Lead Differential	Head \leq 0.3'	
X			Fish Ladder Depth over Weirs	Head over weir 1.0' to 1.3'	
X			Fish Ladder Cooling Water Pumps in Service		
X			Fish Ladder Cooling Water Pumps Operating Satisfactorily		

Comments:

Fish ladder exit cooling pumps were cycled off/on when switching in and out of station service power as follows:

DATE	TIME OFF	TIME ON
08/12	0808	0825
08/12	1450	1524
08/13	1227	1240
08/13	1452	1509
08/14	0550	0605

Fish Ladder Entrances and Collection Channel:

Yes	No	Sill	Location	Criteria	Comments
X			South Shore Entrance (SSE-1) Weir Depth	$\geq 8.0'$	
X			South Shore Entrance (SSE-2) Weir Depth	$\geq 8.0'$	
	X		South Shore Channel/Tailwater Differential	1.0' – 2.0'	0.8'
		X	North Powerhouse Entrance (NPE-1) Weir Depth	$> 8.0'$ or on sill	
		X	North Powerhouse Entrance (NPE-2) Weir Depth	$> 8.0'$ or on sill	
	X		North Powerhouse Entrance Channel/Tailwater Differential	1.0'–2.0'	0.7', 0.9'
	X		North Shore Entrance (NSE-1) Weir Depth	$> 7.0'$ or on sill	
	X		North Shore Entrance (NSE-2) Weir Depth	$> 7.0'$ or on sill	6.9', 6.9'
	X		North Shore Channel/Tailwater Differential	1.0'–2.0'	0.9', 0.9', 0.8'
	X		Collection Channel Surface Velocity	1.5 – 4.0 fps	1.3, 1.1, 1.4, 1.0, 1.1

Comments: Fish ladder control system operation and configuration is an ongoing issue that began when the system was installed in 2016. LWG is moving forward with inhouse design and install of fish ladder control system based on the system used at LMN. Efforts of the electrical crew continue to bring the ladder back into criteria however the control system drifts out of calibration shortly after. The fish ladder was designed to operate between 633' and 638' MSL with a minimum operating elevation of 633.0'.

Auxiliary Water Supply System:

Operating Satisfactorily	Standby	Out of Service	Auxiliary Water Supply (AWS)
Yes			AWS Fish Pump 1
No	X		AWS Fish Pump 2
Yes			AWS Fish Pump 3

Comments: AWS Pump 1 remains in slow mode due to the inability to operate in fast mode while operating at MOP elevation. The fish ladder was designed to operate within the 633' and 638' MSL range with a minimum operating elevation of 633.0'. AWS pump 2 was returned to service August 1 at 1208 hours. AWS pump 2 supplies the collection channel with the same flow as pump 1 in fast. It is recommended that pump 2 be brought online with AWS pump 1 in standby as soon as operationally possible. An MOC has been submitted to tentatively conduct work August 19 to bring AWS 2 back online.

Comments: Fish Ladder AWS pumps were cycled off/on when switching in and out of station service power as follows:

DATE	TIME OFF	TIME ON
08/12	0814	0819
08/12	1504	1517
08/13	1132	1138
08/13	1233	1236
08/13	1459	1502
08/14	0556	0559

Juvenile Fish Passage Facility

Forebay Debris/Gatewell Debris/Oil:

Yes	No	NA	Item	Comments
X			Forebay debris load acceptable? (amount)	35 yd ²
X			Trash rack differentials measured this week?	
X			Trash rack differentials acceptable	
	X		Any debris seen in gatewells (% coverage)	
	X		Any oil seen in gatewells?	

Comments:

ESBSs/VBSs:

Yes	No	NA	Item
	X		ESBSs deployed in all slots and in service?
	X		ESBSs inspected this week?
		X	ESBSs inspection results acceptable?
X			VBSs differentials checked this week?
X			VBSs differentials acceptable?

Comments: VBS mesh is being replaced in gatewell slot 2A during the annual unit outage.

Orifices, Collection Channel, Dewatering Structure, Bypass Pipe:

Yes	No	NA	Item	Number open and in service
X			Orifices operating satisfactory?	18 minimum
X			Dewaterer and cleaning systems operating satisfactory?	

Comments:

Collection Facility: Collection for truck transport began at 0700 on Aug 1.

Transport Summary: Truck transport continues with LWG is supporting transport from LGO as necessary.

Spillway Weir: Late summer spill continues.

PIT tag interrogations: RSW detections included 64,371 juvenile and 103 adult Chinook salmon, 48,218 juvenile and 600 adult steelhead, 8,864 juvenile and 3 adult sockeye, and 2,592 juvenile coho salmon. Juvenile bypass system detections included 10,154 juvenile and 11 adult Chinook salmon, 14,579 juvenile and 49 adult steelhead, 220 juvenile and 4 adult sockeye, and 240 juvenile coho salmon through August 15 (DART).

River Conditions

River conditions at Lower Granite Dam.

Daily Average River Flow (kcfs)		Daily Average Spill (kcfs)		Water Temperature* (°F)		Water Clarity (Secchi disk - feet)	
High	Low	High	Low	High	Low	High	Low
27.6	25.3	10.0	6.1	68.0	62.0	5.0	5.0

*Cooling water intake temperature.

Other

Inline Cooling Water Strainers: N/A

Introduced Species: No zebra/quagga muscles were detected on the trap substrate. Siberian prawns collected in the sample included 55,658 live and 6,184 mortalities this report week. All live Siberian prawns are euthanized.

Avian Activity: Biologist daily piscivorous bird counts began April 1. Bird hazing concluded June 30.

Date	Time	Gulls	Cormorants	Caspian Terns	Pelicans
August 9	1215	1	8	0	0
August 10	1230	0	12	0	0
August 11	1025	2	12	0	0
August 12	1205	1	15	0	0
August 13	1300	11	15	0	0
August 14	1114	0	3	0	0
August 15	1015	2	7	0	0

Gas Bubble Trauma (GBT) Monitoring: N/A

Idaho Department of Fish and Game (IDFG) Adult Fish Trap Operations: Collection for sampling continues with fish being collected 24-hours per day Sunday-Thursday and sampled Monday- Friday at a 25% (18% /week) sample rate. Monday through Friday sample collection will continue until broodstock collection begins August 18.

IDFG adult sockeye salmon collection and transport to Eagle Fish Hatchery due to high river temperature concerns in the Salmon River basin concluded July 25. This effort was conducted in cooperation with USACE Lower Granite Fisheries and NOAA Fisheries. Fish were collected Monday through Thursdays and transported Tuesdays and Thursdays July 9-25. Fish collected on Mondays and Wednesdays were held overnight in an adult holding tank until transport the next day. Through July 25, 254 sockeye (113 clipped and 141 unclipped) were collected and transported from LWG.

Fish Rescue/Salvage: The adult trap was flushed August 10 to remove accumulated American shad and debris that collect on screens and reduce trap operational flows.

Research:

National Marine Fisheries Service (NMFS) PIT tagging of Adult Wild Chinook and Adult Steelhead for ISEMP-Related Dispersal Monitoring:

The goal of this project is to PIT tag up to 4000 unclipped adult Chinook and 4000 unclipped adult steelhead collected in the adult trap daily sample for dispersal monitoring.

Sampling of Steelhead, Chinook salmon, and Sockeye salmon by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries for Biological data collection.

Upriver migrating steelhead, spring/summer Chinook salmon, and sockeye salmon are collected from the adult trap beginning March 1 through November 30. The goal is to collect 5-20% of adult steelhead, spring/summer Chinook salmon, and sockeye salmon ascending the ladder March 1-November 30. Data collection includes fish scales, genetics tissue, sex and length, wild/hatchery composition, and non-adipose clipped hatchery fish assessment. All natural origin adult steelhead and spring/summer Chinook salmon trapped will be PIT tagged to estimate headwater tributary escapement. Sockeye salmon may be PIT tagged in the future to estimate metrics regarding conversion rates. Some steelhead and spring/summer Chinook salmon may be radio-tagged or spaghetti-tagged. This information on adult fish forms the basis for status information used in several forums including BiOp-RPA identified needs.

Sampling and PIT tagging of Walleye by the Idaho Department of Fish and Game (IDFG) and NOAA Fisheries.

Walleye collected in the adult fish trap will be PIT tagged to investigate movement and ascension rate of walleye that successfully exit the fish ladder into the upstream reservoir. PIT tag data collected will be used to gain an understanding of the potential expansion and threat of walleye upstream of LWG to ESA-listed salmonids and guide future management actions of walleye in the Snake River Basin.

PIT Tagging and Genetic Sample Collection from Bull Trout for USFWS:

Bull trout will be collected as part of the normal adult trap daily sample and using the adult SbyC system to recapture previously PIT tagged fish. Untagged bull trout will be PIT tagged, fin clipped for genetic analysis, and have morphometric data collected including weight and length etc. Fin clips will be sent to USFWS to determine the fish's origin. Previously PIT tagged bull trout will only have morphometric data collected. All fish will be released back into the adult fish ladder.

United States Geological Survey (USGS) Wild Juvenile Fall Chinook Salmon Genetics Sampling:

The goal of this study is to determine the origin of unmarked subyearling Chinook salmon in LWG sample. The USGS has developed an approach to estimate the daily abundance of natural origin subyearling Chinook salmon passing LWG each year. The goal is to collect fin clips from 15 unmarked subyearling on Monday's, Wednesday's, and Friday's May 15 to August 31. Genetic samples will be used to determine origin of unclipped subyearling Chinook salmon thus validating estimates of origin and model abundance.

PNNL Juvenile Pacific Lamprey Passage Behavior and Survival study:

Juvenile lamprey (macrophthalmia) were collected from LWG sample, as needed, to meet PNNL downriver study objectives. LWG collected a total of 1502 juvenile lamprey this season to support this study.

Columbia River Inter-Tribal Fisheries Commission (CRITFC) Pacific Lamprey Genetic Study:

CRITFC has requested that the SMP collect non-lethal tissue samples from up to 1000 juvenile and 500 larval Pacific lamprey, not to exceed 10 juvenile and 5 larvae daily during the routine smolt monitor condition sampling from March through September. The purpose of this study is to fill two objectives; 1) Determine relative proportion of translocation offspring among the total abundance of larval and juvenile lamprey passing the juvenile bypass systems at BON, JDA, MCN, and LWG. 2) Describe life history characteristics of larval and juvenile lamprey emigrating from the Columbia and Snake River basins. The genetic information collected will be used to evaluate the tribal Pacific lamprey program's efficacy and assist with guiding future management. LWG SMP have collected genetic samples from 852 juvenile and 500 larval lamprey this season.

Idaho Power Hells Canyon Sturgeon Recruitment:

LWG Corps bio techs continue collecting passage and estimated lengths and of White Sturgeon prior to removing them from the separator in support of Idaho Power Sturgeon program.