

MEMORANDUM FOR THE RECORD

SUBJECT: 21JDA05 MFR Spill Bay 10 Out of Service

At 0630 on 4/23/2021, spill bay 10 didn't respond to commands from the control room to open. The operation of the gate remotely didn't open or close the gate. However, remote operation cause cables to unwind making the gate inoperable. John Day Maintenance crews were able to rewind the cable and the gate returned to service at 1200 on 4/26/21. During the spill bay outage, flow was distributed to adjacent bays to maintain gas cap spill or flex spill depending on time of day.

- A. Species – na
- B. Origin – na
- C. Length – na
- D. Marks and tags – na
- E. Marks and Injuries found on carcass – na
- F. Cause and Time of Death – No fish were found dead or injured
- G. Future and Preventative Measures – Spill bay 10 will need to be operated manually until controls are fixed to allow remote operation.

Sincerely,
JD Project Fisheries