

FPP Change Form

9/14/07

Change Request Number: 09BON004

Date: 6/4/2008

Proposed by: Project Fisheries

Location of Change: BON-18 2.4.2.2.n.1

Proposed Change:

2.4.2.2.n.1 says “coordinate gatewell cleaning with smolt monitoring personnel operating the downstream juvenile sampling facilities”. It should be moved to 2.4.2.2.m.3, which is the section on what to do when cleaning gatewells.

Reason for Change:

2.4.2.2.n.1 is in the wrong location.

Comments from others:

Record of Final Action: Approved at 4 December FPOM meeting.