

Change Request Number: 11BON006 PH2 Unit Priority

Date: September 29, 2010

Proposed by: CRITFC

Location of Change- BON-34 Section 5 Table Bon-13

Proposed Language:

Table BON-13. Turbine unit operating priorities, Bonneville Powerhouses One and Two.

PERIOD	PRIORITY
Year-round; adult fish ladders are in service	11,18,15,12,17,14,13,<u>14,15</u>,16,1,10,3,6,2,4,5,8,7,9
First Powerhouse Adult Fish Ladder out of service	11,18,15,12,17,14,13,<u>14,15</u>,16,1,10,3,6,2,4,5,8,7,9
Second Powerhouse Adult Fish Ladder out of service	1,10,3,6,2,4,5,8,7,9 11,18,15,12,17,14,13,<u>14,15</u>,16
Split flows unit priority (all units available)	1,10,11,18,15,12,17,14,13,<u>14,15</u>,16,3,6,2,4,5,8,7,9
PH1 unit priority	1,10,3,6,2,4,5,8,7,9
PH2 unit priority	11,18,15,12,17,14,13,<u>14,15</u>,16

Reason for Change: After reviewing the passage data for Bonneville Powerhouse 2 and noting unit priority it appears that flow and thus fish were more directed towards the middle and north section of the powerhouse. When unit 11 was operated it appeared to have a significant effect on guidance of fish to the sluiceway. We recommend prioritizing the southern units to better aid fish in finding and using the Corner Collector.

Comments from others:

Record of Final Action: approved at the 12 October 2010 FPOM.