

FPP Change Form

9/14/07

Change Request Number: 09BON003

Date: April 16, 2008

Proposed by: Bonneville Project

Location of Change- BON 5.4.6-5.4.7 and BON 6.5.1-6.5.2 (sections re-numbered as required)

Proposed Change:

5.4.6. *From 1 December through 30 April, priority turbine units will be scheduled for any necessary extended outages. Priority units are 1, 3, 11, and 18. During this time, non-priority units should not be scheduled for routine or extended outages if the outage will delay or conflict with maintenance on a priority unit.*

5.4.7. *From 1 December through 30 April, turbines which have been idle/out of service for more than 12 hours will be started by slow rolling the unit after manually tipping turbine blades from flat to steep back to flat.*

After including the two sections above as 6.5.1 and 6.5.2-

The current 6.5.2 will be re-numbered to 6.5.4. Add "*bottom tail logs should be placed first.*"

The current 6.5.3 will be re-numbered to 6.5.5. Add "*It is recommended adjacent units be operated to flush fish prior to placing tail logs in the unit to be OOS. It is also recommended that units located adjacent to OOS units not be voluntarily taken out of service until the adjacent units return to service.*"

Reason for Change: To better protect sturgeon in the draft tube and turbine environment.

Comments from others: FPOM doesn't want priority units OOS during fish passage season. FPOM requests better clarity for 5.4.6.

Record of Final Action: Approved at January 2009 meeting.