

**CENWP-OD-B**

**06/29/2020**

**MEMORANDUM FOR THE RECORD**

**SUBJECT: 20BON25 PH2 F1 Outage.**

On Monday, 22 June, water was found to be leaking into the turbine bearing of F1. The leak was discovered during nighttime lamprey operations, so F2 was brought back into service early in order to take F1 out of service for investigation and repair. F1 was returned to service on the same day at 1143.

Sincerely,  
Project Fisheries