

**MEMORANDUM FOR THE RECORD**

**SUBJECT: 21BON003 Bonneville Powerhouse 2: Unit 18 delayed in-service date**

On 11/30/20 at 0700, Unit 18 was taken out of service for a planned 4-Year Overhaul. The planned in-service date was 03/01/2021. Upon initial startup on 03/01/2021, the unit was discovered to have an internal oil leak. This oil leak was contained within the unit itself and no oil discharge occurred in the river. Unit 18 remained out of service until 03/11/2021 at 0956 due to repairs. The only fish impact is the loss of attraction flow from Unit 18. Unit 17 took the place of Unit 18 in unit priority and functioned as attraction flow for the fish ladder entrance.

Sincerely,  
Project Fisheries