

**MEMORANDUM FOR THE RECORD**

**SUBJECT: 19JDA11 Spillgate #11 forced OOS**

On the morning of 22 May, spill gate 11 began raising by itself uncontrollably. The gate was forced out of service and closed at 0915. A faulty electrical controller is believed to have failed causing the gate to open by itself. The gate is expected to return to service next week.

- A. Species –
- B. Origin – unknown
- C. Length – unknown
- D. Marks and tags – none
- E. Marks and Injuries found on carcass – none
- F. Cause and Time of Death – unknown
- G. Future and Preventative Measures –

Sincerely,  
JD Project Fisheries