

**MEMORANDUM FOR THE RECORD**

**SUBJECT: 20JDA03 Spill gate #10 OOS**

On Tuesday, 7 April, JDA Fisheries was informed that spill gate #10 is OOS. The spill gate is not correctly responding to commands. The exact nature of the problem is being determined and the RTS is unknown at this time. As a reminder, the project has limited staff due to the current pandemic guidelines for social distancing and spill starts 10 April. Once more information is made available, an updated MFR will be circulated. JDA fisheries will provide an update at FPOM this week if additional information is available.

UPDATE 200416: Maintenance identified a broken shear pin and replaced it. The pin broke again due to a bind. Crews are still trying to diagnose the problem. JDA will manually open the gate on Monday, April 20, 2020 if a solution is not found soon.

UPDATE 200420: Spill bay 10 is dogged off to 3.0'.

UPDATE 200423: Spill gate 10 is manually adjusted to the pattern in the FPP.

- A. Species –
- B. Origin –
- C. Length –
- D. Marks and tags –
- E. Marks and Injuries found on carcass –
- F. Cause and Time of Death –
- G. Future and Preventative Measures – TBD

Sincerely,  
JD Project Fisheries