

MEMORANDUM FOR THE RECORD

SUBJECT: 21JDA06 MFR Spill Bay 3 Out of Service

At 0503 on 6/5/21 Spill Gate 3 failed to operate. The breaker tripped and was reset, but the spill gate still failed to operate. Spill Gate 3 is closed, and the spill was distributed to adjacent spill bays to maintain gas cap spill or flex spill depending on time of day. Estimated return to service is unknown.

A. Species – NA

B. Origin – NA

C. Length – NA

D. Marks and tags – NA

E. Marks and Injuries found on carcass – NA

F. Cause and Time of Death – No fish were found dead or injured

G. Future and Preventative Measures – A preventative measure is not operate the 50-year-old gates as often as we do during the flex spill operation. They were not designed for this type of operation and it is apparent they are failing.

Sincerely,

JD Project Fisheries