

MEMORANDUM FOR THE RECORD**SUBJECT: 23JDA09 Submersible Traveling Screen (STS) Oil Leak in Rollergate Slot 12B**

On 29 March 2023, at approximately 1600, John Day operations personnel noticed a pearlescent sheen surrounding an STS screen located in rollergate slot 12B. Environmental, Health, and Safety (EHS) and Oil Accountability Program (OAP) personnel investigated and confirmed. Control Room was informed as well as Command. Command decision was to leave STS screen in slot as STS pit was unavailable. EHS personnel deployed absorbent boom around STS screen to contain and absorb sheen. The amount of oil lost will be determined once the STS is able to be removed and inspected.

- A. Species – NA
- B. Origin – NA
- C. Length – NA
- D. Marks and tags – NA
- E. Marks and Injuries found on carcass – NA
- F. Cause and Time of Death – NA
- G. Future and Preventative Measures – Monitor during winter maintenance periods

Sincerely,
JDA Project Fisheries

Comments –

-----Original Message-----

From: Grosvenor, Eric G CIV USARMY (USA) <Eric.Grosvenor@usace.army.mil>

Sent: Thursday, March 30, 2023 11:26 AM

To: Mackey, Tammy M CIV USARMY CENWP (USA) <Tammy.M.Mackey@usace.army.mil>; Lotspeich, Michael D CIV USARMY CENWP (USA) <Michael.D.Lotspeich@usace.army.mil>; Ricketts, Laura A CIV USARMY CENWP (USA) <Laura.A.Ricketts@usace.army.mil>

Subject: RE: FPOM: Official Coordination - 23JDA08 and 23JDA09 STS oil leaks

We're planning on replacing the oil with an EAL, we just haven't heard anything from the gearbox manufacturer on acceptable lubricants. Also, apparently IHR has pulled their accumulator tanks and don't use them anymore??? Our engineers are reaching out to investigate that option too, which would be even more ideal.

"Don't worry everything is OK" - Miro
Have fun on your time off.
-Eric

-----Original Message-----

From: Tom Lorz <lorz@critfc.org>

Sent: Thursday, March 30, 2023 9:10 AM

To: Mackey, Tammy M CIV USARMY CENWP (USA) <Tammy.M.Mackey@usace.army.mil>

Subject: [URL Verdict: Neutral][Non-DoD Source] Re: FPOM: Official Coordination - 23JDA08 and 23JDA09 STS oil leaks

So is this an early april fools oil spill.....If we can get an update on these oil spills and see if it is related to aging structures or a need from more maintenance.ah John Day, thinking of the Miro response its "ok"

Photos of the STSs. Taken by T. Mackey on 29 March 2023 at JDA.

