

**MEMORANDUM FOR THE RECORD**

**SUBJECT: 24TDA05 MFR Fish unit 1 Temporarily Out of Service**

On 29 April Fish Unit 1 was taken out of service to replace the DC pump for the lower guide bearing which had failed. The AWS backup system was activated to provide supplemental flow for fish attraction in the East fish ladder. The outage lasted from 0717 – 1017 for 3 hours and the fish ladder entrance weirs were raised to keep head differentials within criteria.

- A. Species – NA
- B. Origin – NA
- C. Length – NA
- D. Marks and tags – NA
- E. Marks and Injuries found on carcass –NA
- F. Cause and Time of Death – NA
- G. Future and Preventative Measures

Sincerely,

Project Fisheries