

MEMORANDUM FOR THE RECORD

SUBJECT: 23 LMN 08 Spillbay 5

Spillbay 5 closed on August 15 at 0720 hours after it was found to have a damaged lower gasket, causing a large spray of water to shoot out in an irregular pattern. Spillbay 4 was opened to accommodate the flow required. Spillbay 5 will remain closed until after the parts arrive and the spillbay can be dogged off and closed for repairs.

Due to the low volume of water that Lower Monumental Dam is currently spilling, the spill pattern in the Fish Passage Plan requests that spillbay 2, 5, and 7 be open at 1 stop. With spillbay 5 removed, Lower Monumental Dam is now using spillbays 2, 4, and 7 open at 1 stop. The current spill pattern ends August 31, 2023.

- A. Species – N/A
- B. Origin – N/A
- C. Length – N/A
- D. Marks and tags – N/A
- E. Marks and Injuries found on carcass – N/A
- F. Cause and Time of Death – N/A
- G. Future and Preventative Measures –Continue to monitor and perform maintenance on spillbay gates.

Denise Griffith
Supervisory Fish Biologist
Lower Monumental Dam
(509) 282-7211
Denise.S.Griffith@usace.army.mil