

Change Request Number: 11AppG003

Date: 11/3/2010

Proposed by: BON Fisheries

Location of Change: Appendix G 1.1.9

Proposed Change:

Remove language.

1.9 ~~The brail pool shall remain in the lowered position except during winter maintenance activities.~~

Reason for Change: Maintenance crews will be fixing the seal problem during the 2010/11 winter maintenance period that allowed steelhead to get under the brail pool. The brail pool needs to be raised and lowered during the sampling season for proper operation of the AFF.

Comments from others:

NOAA Fisheries- Agree, as long as the project is able to decisively fix the escapement problem.

USFWS- support

Record of Final Action: approved 21 January 2011. Rerecich will send photos or plans.

Formatted: Font: 12 pt, Not Italic

Formatted: Font: 12 pt, Not Bold, Not Italic

Formatted: Font: 12 pt, Not Italic

Formatted: Font: 12 pt, Not Bold, Not Italic

Formatted: Font: 12 pt, Not Italic