## **FPP Change Form**

**Change Request Number: 11BON003** 

**Date:** 6/25/10

Proposed by: BON Fisheries

**Location of Change:** Table BON-9

## **Proposed Change:**

Table BON-9. Bonneville Dam first powerhouse weir gate requirements.

Weir Gate	Submergence Requirement	Differential Requirement	Sill Elevation
1	>8'	1'-2'	8.5'
2	>8' <u>*</u>	1'-2'	2'
64	8'-8.4'	1'-2'	2'
65	8'-8.4'	1'-2'	8.5'

<sup>\*</sup> When tailwater is <13.5', the 8' submergence requirement can not be satisfied due to pressure limitations on the AWS conduit.

**Reason for Change:** Correct outdated language. WG 2 is programmed to maintain >8' submergence and entrance head differential, it does not adjust to AWS conduit pressure.

## **Comments from others:**

**Record of Final Action:** Approved at August 2010 FPOM.