

Draft FPP Change Form

9/14/07

Change Request Number: 08JDA 013

Date: 1/25/2008

Proposed by: Project Fisheries

Location of Change

JDA 2.5.1.2.d.2

Proposed Change:

Add "During the fish turbine #3 overhaul in 2008, floating orifice gates 18 and 19 will be closed."

Reason for Change:

1. Due to the long term overhaul of fish turbine #3, the John Day south ladders' AWS will be provided by only two turbines (they will be operated at maximum RPMs) during the entire 2008 adult passage season.
2. According to the internal two pumps' test performed by JD Fisheries in the fall of 2007, it is expected that at times of low tailrace the south ladder entrances maybe experiencing criteria deficiencies/shortages (less than optimal or even slightly below criteria.)
3. To assure the proper operational criteria at the main powerhouse entrances (SE and NE,) the two FOGs closest to the NE entrance (bays 19& 18) are required to be closed (they were selected per Uofl adult salmon tracking data.)
4. The benefits of this action include an ability to achieve an optimal passage criteria during the spring and at least minimum criteria during the summer and fall seasons.

Comments from others:

Record of Final Action:

Language changed as proposed.