

MEMORANDUM FOR THE RECORD

SUBJECT: 19JDA16 Spill gate #9 out of service

On the morning of 2 July, spill gate 9 was forced out of service. The gate would not respond to controls from the control room. JD Maintenance is assessing the problem this afternoon. A return to service time is yet to be determined.

- A. Species –
- B. Origin – unknown
- C. Length – unknown
- D. Marks and tags – none
- E. Marks and Injuries found on carcass – none
- F. Cause and Time of Death – unknown
- G. Future and Preventative Measures –

Sincerely,
JD Project Fisheries