

Internal Incident # (CY-#): External 05 2023					
1. Reporting Name: Phelps, Glyn E.			2. Responsible Party: USACE		
3. Location: John Day Dam, Rufus, OR, Sherman County, River Mile 215.6					
3A. Specific Project Location: Rollergate Slot 12B					
4. Spill Description (Date, Time, Equipment, Product, Amount, etc): Slots 10B-Upstream					
Incident Date / Time: 29 March 2023, 1600 Reported Amount: Unknown.					
<p>On 29 March 2023, at approximately 1600, OPS personnel noticed a pearlescent sheen surrounding an STS screen located in rollergate slot 12B. EHS and OAP POSI investigated and confirmed. Control Room was informed as well as Command. Command decision was to leave STS screen in slot as STS pit was unavailable.</p> <p>EHS personnel deployed absorbent boom around STS screen to contain and absorb sheen.</p>					
5. Environmental Impacts (air, surface water, groundwater, fish, wildlife):					
No visible wildlife impacts.					
6. Reporting:					
	Contact	Phone	Date & Time	Incident #	Contact
1	National Response Center	800-424-8802	29 March 2023 @ 1754	1363481	Williams
2	Oregon Emergency Response Services (OERS)	800-452-0311	29 March 2023 @ 1809	2023-0819	Burroughs
3	Washington Emergency Management Division (WEMD)	800-258-5990	29 March 2023 @ 1813	23-1130	Medeiros
3a	WDOE Spill Program	509-969-7750			
4	Sherman County Sheriff	541-565-3622			
5	Oregon State Police	503-731-3131			
6	CENWP-ODD, EHS Lead	541-506-8300			
6	CENWP-OD, District ECC	503-784-7469	29 March 2023 @ 1710		Freels
7. Incident Action Plan: Strategic Goals (what to do) and Tactical Objectives (who & how)					
Strategic Goals			Tactical Objectives		
a. Establish Site Security			YES		
b. Evacuate Injured/Exposed			N/A		
c. Establish Incident Command			N/A		
d. Contain/Isolate Spill			YES		
e. Initiate Spill Response			YES		
f. Perform Hazard Assessment			YES; Immediate Response by COB;		

	Finalize spill material accountability by COB 30 March 2023.
--	--